

CC3/ARW 600 9086 / Keb392-1

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0133/2016
DATE : 13-MAY-2016

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL :
FAX :

OWNER'S NAME : DOWNTOWN TRAVEL SERVICES PTE LTD
ADDRESS : 911 BURIT TIMAH ROAD

S(589622)
TELEPHONE NO : 9691 0696 JASON

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : D
VEHICLE NO : SXB4061G
MODEL CODE : BR9AKCV
MODEL/YEAR : LEGACY 2.5 GT AWD WAGON SAT
ENGINE NO : EJ25E033429
CHASSIS NO : JF1BR9KVJAG008150
MILEAGE : 1 KM
DATE IN : 13/05/2016
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : WONG GOO XIANG
ACCIDENT DATE : 13/05/2016

Print Date : 18/05/2016
Print Time : 11:04:46

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKH4061G

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPLACE & REPAIR FRT BUMPER, FRT BUMPER BEAM, FRT PANEL, REAR BUMPER, REAR BUMPER BEAM, REAR END PANEL,	2000.00	1000 (1600)
2	ZZ/002	SPARE WHEEL PANEL, TAILGATE		
3	ZZ/003	RESPRAY FRT BUMPER, FRT BUMPER BEAM, FRT PANEL, REAR BUMPER, REAR BUMPER BEAM, REAR END PANEL, TAILGATE	2400.00	1200 1,440
4	ZZ/004	, SPARE WHEEL PANEL		
5	ZZ/005	REMOVE & REFIX REAR UNDERCARRIAGE	456.00	✓
6	ZZ/006	TO CONDUCT WATER SEEPAGE TEST	85.00	✓
7	ZZ/007	REMOVE & REPLACE EXHAUST	114.00	✓
8	ZZ/008	COOLING SYSTEM PRESSURE TEST	95.00	✓
9	ZZ/009	TRANSFER TAILGATE MECHANISM	95.00	✓
10	ZZ/011	WHEEL ALIGNMENT	171.00	✓
11	ZZ/012	REMOVE & REFIX REAR SEAT & CARPET	342.00	✓
12	ZZ/013	REMOVE & REFIX REAR BOOT GARNISH & TRIMS	114.00	✓
13	ZZ/014	REMOVE & REFIX A/C CONDENSER & RADIATOR	171.00	✓
14	ZZ/015	REMOVE & REPLACE REAR WINDSCREEN	342.00	✓
15	ZZ/016	TO SUPPLY & INSTALL REAR WINDSCREEN TINTED FILM	120.00	✓
16	ZZ/017	TO CONDUCT CAR 'O' TRONIC CHASSIS ALIGNMENT & MEASUREMENT	na 1000.00	✗
17	ZZ/018	REMOVE & REFIX FUEL TANK	na 171.00	✗
18	ZZ/019	CONDUCT FRONT & REAR LIGHTING TEST	56.00	✓
19	ZZ/020	TO SUPPLY & INSTALL REVERSE SENSOR - 2 EYES	na 300.00	✓
20	ZZ/021	TO CONDUCT FRT & REAR PORTION ANTI-RUST COATING	290.00	✓
21	ZZ/022	TO CONDUCT FRT & REAR PORTION PROTECTANT COATING	250.00	✓
22	ZZ/10	SUNDRIES	120.00	506
TOTAL LABOUR CHARGES			E662.00	

TO SUPPLY & INSTALL SPARE TYRE PAN MAT (SUPP) 150 ✓
VEHICLE TOWED TO MOTOR IMAGE DUE TO ACCIDENT (SUPP) 200 ✓

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO EXB4061G

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
------	----------	---------------	----------------------	------------------------------

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKB4061G

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 PIPE CUTTER AY	44070AC010	Sn	51.00	X
2 EXH PIPE AY R BST	44200AJ180	B7	1080.00	✓ 540.00
3 MUFFLER ASSY LH 6WL	44300AJ393	B7	738.00	✓ 369.00
4 MUFFLER ASSY RH 6W	44300AJ403	R	738.00	?
5 FLOOR PANL RR	52122YC0529P	B7	414.00	✓ 207.00
6 SKIRT COMPL R WGN	52401AJ0109P	B7	288.00	✓ 144.00
7 BMRP PUNCHING 2.5GTS	57702AJ071	B7	594.00	✓ 297.00
8 BUMPER FACE R W	57704AJ000	T7	594.00	✓ 297.00
9 PRT BUMPER FOAM	57705AJ000	CM	180.00	✓ 90.00
10 BRKT SD UP R W	57707AJ000	R	18.00	?
11 BRKT SD UPR R W LH	57707AJ010	R	18.00	?
REAR 12 FRT RH SIDE BRACKET	57707AJ240	Di	18.00	✓ 9.00
REAR 13 FRT LH SIDE BRACKET	57707AJ250	Di	18.00	✓ 9.00
14 FRT BUMPER BEAM	57711AJ0109P	R	421.00	X
15 BEAM CPL R	57711YC0109P	B7	208.80	✓ 104.40
16 COVER INTAKE F	57731AJ500	NEC	92.80	✓ 82.80 41.40
17 PANEL COMPL R GAT	60809AJ0109P	B7	1072.80	✓ 536.40
18 GLASS AY R/G	63011AJ020	Me	1350.00	✓ 675.00
19 STRIKER R/G	63264AG100	B7	21.60	✓ 10.80
20 REFLEX AY RH	84281FG000	CM	21.60	✓ 10.80
21 REFLEX ASSY LH	84281FG010	Sn	21.60	X
22 FRT GRILLE ASSY	91121AJ011	Sn	576.00	X
23 FRT GRILLE EMBLEM	93011SA072	Sn	81.60	X
24 LETTER MK R	93071AJ000	Me	64.80	✓ 32.40
25 LETTER MK R AND	93073AJ500	Me	108.00	✓ 54.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKB4061G

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
26	FRONT NUMBER PLATE	WN001		By 45.00 ✓
27	REAR NUMBER PLATE	WN002		By 45.00 ✓
SUB TOTAL			92.00	8697.00 90.00
LESS DISCOUNT (NETT-20 % LIST-50 %)			18.40	4348.50 0.00
GRAND TOTAL			73.60	4348.50 90.00
OVERALL TOTAL			4512.10	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

FLOOR SD R CP RH (SUPP)	By	\$41.40	\$82.80
BRKT CORNER W RRH (SUPP)	By	\$14.40	\$28.80
BRKT CORNER W RLH (SUPP)	By	\$14.40	\$28.80
FRT RH CORNER BRACKET (SUPP)	By	\$21.60	\$43.20
COVER HOOK R WG (SUPP)	By	\$7.20	\$14.40
COVER EXH R RH (SUPP)	By	\$44.00	\$88.00
MUD GUARD RRH (SUPP)	By	\$36.00	\$72.00
LATCH & ACT AY RG (SUPP)	By	\$88.20	\$176.40
WSTR DR R G (SUPP)	By	\$72.00	\$144.00
GRILL AIR VENT (SUPP)	By	\$28.80	\$57.60
LAMP ASSY-H/MOUNT (SUPP)	By	\$125.80	\$251.60
LENS&BODY CPL (SUPP)	By	\$144.50	\$289.00
RH TAILLAMP (SUPP)	By	\$144.50	\$289.00
LENS&BODY CPL (SUPP)	By	\$144.50	\$289.00
BRKT RH (SUPP)	By	\$11.90	\$23.80
TRIM PNL AY R/G (SUPP)	By	\$199.80	\$399.60
EDGE FLR R AY (SUPP)	By	\$21.60	\$43.20
SUPPORTER HOLDER (SUPP)	By	\$2.70	\$5.40
HLDR ASSY SP WHL (SUPP)	By	\$5.40	\$10.80

MOTOMIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 119255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKB4061G

TOTAL LABOUR CHARGES	8682.00
TOTAL SPARE PARTS CHARGES	4512.10
GRAND TOTAL	13194.10 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Not Authenticated
1.B.1
Resurvey B4 paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date: