

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 7220T

DATE 23/8/2018 22:21

MAKE :

DOT: 19.08.18

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>X rep. r</i>			\$ 603.60
	Rear Bumper Reinforcement <i>X su</i>			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) <i>X su</i>		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket <i>X su</i>			\$ 49.00
	Rear Bumper Clips <i>X 11</i>			\$ 22.00
	Rear Bumper Sponge <i>X su</i>			\$ 143.40
	Rear Bumper Under Cover <i>X su</i>			\$ 225.00
	SUB TOTAL			\$ 1,907.35
	LESS 20%			\$ 381.47
	DISCOUNTED TOTAL			\$ 1,525.88
	Rear Bumper Reverse Sensor <i>X su</i>			\$ 135.70
	Rear Bumper Rubber Mat <i>X 11</i>			\$ 50.00
				\$ 185.70
	Labour Charge			
	Panel Beating			\$ 350.00 <i>100</i>
	Spray Painting Charge			\$ 250.00 <i>200</i>
	Wiring Charge			\$ 50.00 <i>X 11</i>
	R/Refix Reverse Sensor			\$ 120.00 <i>X 11</i>
	TOTAL LABOUR			\$ 770.00
	ESTIMATE TOTAL			\$ 2,481.58

Kalki LKK14

23/8/18 15:15hrs

2 days

4s

After Repair photo

Larry Ng

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.