



進友成汽車服務私人有限公司 CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR HOE YONG SOON CONSTRUCTION PTE LTD
8B ADMIRALTY STREET #04-15
8B@ADMIRALTY, (S) 757440

POLICY NO : THIRD PARTY CLAIMS
YOUR REF : GBG4439G (AIG)
OUR REF : TP5931
VEHICLE NO : SLS4732C
MAKE/MODEL : Honda CRV 2.4
DATE OF ACCIDENT : 21.Aug.18

SURVEY BY

DATE : 23.Aug.18

1 PC TAILGATE		S\$	931.20	DD
1 PC TAILGATE " CRV" EMBLEM			29.40	rec
1 PC TAILGATE OUTER CHROME			238.40	rec
1 PC TAILGATE CENTRE EMBLEM			24.10	rec
1 PC TAILGATE GARNISH			368.80	CRA
4 PCS TAILGATE GLASS MOUDLING			98.50	rec
1 PC TAILGATE OUTER LOCK			151.80	BROKEN
1 PC TAILGATE TOP LOCK			178.50	BROKEN
1 PC TAILGATE INNER TRIM BOARD			175.10	CRA
1 PC TAILGATE WEATHERSTRIP			133.70	BT
1 PC TAILGATE WIPER MOTOR			255.30	?
2 PCS TAILGATE ABSORBER	151.8		303.60	?
2 PCS TAILGATE HINGES	68.10		136.20	?
1 PC REAR END PANEL			535.40	?
1 PC REAR END PANEL TOP GARNISH			85.40	CRA
1 PC SPARE TYRE FLOOR PANEL			1,045.50	DD
1 PC SPARE TYRE FLOOR PANEL SCREW			17.00	rec
2 PCS SPARE TYRE SIDE GARNISH	80.80		161.60	?
1 PC SPARE TYRE HARDBOARD			462.10	BT
2 PCS REAR FENDER INNER TRIM BOARD			189.30	?
1 PC REAR BUMPER			599.50	BT
2 PCS REAR BUMPER SIDE	153.40		306.80	X LIT RA?
2 PCS REAR BUMPER SIDE RETAINERS	17.40		34.80	X LIT RIT?
1 PC TAILLAMP ASSY L/H			420.60	CRA
		S\$	6,882.60	
			1,376.52	
		S\$	5,506.08	
1 PC INSULATOR PADDING		S\$	120.00	S/NETT
8 PCS TAILGATE GARNISH CLIPS			33.60	rec
2 PC SEALANT			80.00	" rec
1 SET REAR BUMPER CLIPS			35.00	" rec
1 SET REVERSE SENSOR			350.00	200" rec
		S\$	618.60	
		S\$	30.00	20
			80.00	60
			80.00	60
			60.00	30
			140.00	120
			80.00	60
			1,600.00	1,400
			1,600.00	1,400
		S\$	9,794.68	

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed 4.20
• Supplementary item(s) must be resurveyed 40.00
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TO CHECK WIRING FUNCTION

TO APPLY RUST PROOFING ON REPLACED/ REPAIRED PANEL

TO TRANSFER TAILGATE

TO REMOVE AND REFIX CAMERA

TO REMOVE AND REFIX TAILGATE GLASS

TO REMOVE AND REFIX CUSHION SEAT

LABOUR CHARGES

TO PUTTY AND SPRAY PAINTING CHARGES

NAZ LKK
24/4/18 1245
LIS.

10 days.
ARTBL REPAIR PHOTO

SIN DOLLARS: NINE THOUSAND SEVEN HUNDRED NINETY-FOUR AND CENTS SIXTY-EIGHT ONLY.

YOUR FAITHFULLY, 38 Woodlands Industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700
Tel: 6219 2098 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

CYS AUTOMOBILE SERVICES PTE LTD