



Co. Reg: 200922097K GST Reg.No: 200922097K  
Auto Bay @ Kaki Bukit Blk 1 Area "D" Kaki Bukit Ave 6 #01-90 (S) 417883  
• Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

Date : 24/08/2018

Total Pages : 2

TO: INDIA INTERNATIONAL INSURANCE PTE LTD  
64 Cecil Street  
#04/#05 IOB Building  
Singapore 049711

Our Customer : TEOH BENG TECK  
Vehicle No : **SLC8427S**  
Model : KIA FORTE K3 1.6A SX  
Manufacture Year : 7/8/1905  
Date of Accident : 23/08/2018  
Total Estimate Repair Days : 14

Attn : Motor Claim Department  
Fax : 62244174

Re: Repair Estimate For Third Party Claim against : SHC8931A

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
<b>A.</b>	<b>Spare Parts</b>				
1	Front number plate <i>w/holder</i>	1	\$50.00	\$50.00	<i>Sal 40 S.W</i>
2	Front number plate base garnish	1	\$78.50	\$78.50	<i>ch 7</i>
3	Rear number plate	1	\$50.00	\$50.00	<i>Sal 40 S.W</i>
4	Rear boot	1	\$695.50	\$695.50	<i>Bob 300</i>
5	Rear boot hinges	2	\$95.60	\$191.20	<i>R X</i>
6	Rear boot lock	1	\$85.20	\$85.20	<i>Tw 1</i>
7	Rear boot 'cycle and carriage' badge	1	\$45.00	\$45.00	<i>rec</i>
8	Rear boot logo	1	\$98.10	\$98.10	<i>rec</i>
9	Rear boot 'K3' emblem	1	\$48.10	\$48.10	<i>rec</i>
10	Rear boot 'FORTE' emblem	1	\$92.10	\$92.10	<i>rec</i>
11	Rear boot lamp RH	1	\$405.90	\$405.90	<i>cm</i>
12	RH taillamp	1	\$595.90	\$595.90	<i>cm</i>
13	Rear boot trim clips	12	\$3.00	\$36.00	<i>11 X</i>
14	Rear boot rubber beading	1	\$368.20	\$368.20	<i>Tw 1</i>
15	Rear bumper	1	\$685.20	\$685.20	<i>D.S</i>
16	Rear bumper clips	10	\$3.00	\$30.00	<i>rec</i>
17	Rear bumper retainer	2	\$79.20	\$158.40	<i>rec</i>
18	Rear bumper lower garnish <i>210</i>	1	\$480.20	\$480.20	<i>D.S</i>
19	Rear bumper reflector RH	1	\$110.50	\$110.50	<i>cm</i>
20	Rear bumper reinforcement	1	\$350.50	\$350.50	<i>D.S</i>
21	Rear bumper reinforcement bracket	2	\$112.20	\$224.40	<i>Sal</i>
22	Rear bumper parking sensor	1	\$250.00	\$250.00	<i>shad</i>
23	Rear bumper lower bracket	4	\$38.20	\$152.80	<i>Sal</i>
24	Rear end panel	1	\$580.10	\$580.10	<i>2130</i>
25	Rear end panel garnish	1	\$110.50	\$110.50	<i>Tw 1</i>
26	Front bumper reinforcement	1	\$310.10	\$310.10	<i>11 X</i>
27	Front bumper sponge	1	\$210.50	\$210.50	<i>11 X</i>
	<b>Sub Total</b>			<b>\$6,492.90</b>	
	<b>Less 10%</b>			<b>\$649.29</b>	
	<b>Sub-Total 1</b>			<b>\$5,843.61</b>	
<b>A.</b>	<b>Spare Parts (S/Nett)</b>				
1	Rear end panel sealant	2	\$25.00	\$50.00	<i>rec</i>
	<b>Sub-Total 2</b>			<b>\$50.00</b>	
	<b>Total Spare Parts</b>			<b>\$5,893.61</b>	
<b>B.</b>	<b>Labour</b>				
1	To knock and straighten spare tyre compartment. Cut & weld damaged panel. Adjust & realign then same			\$1,300.00	<i>1180</i>
2	To putty and spray RH front fender, LH front fender, Rear boot (Inner & outer), Rear end panel, Spare tyre compartment and Rear bumper			\$1,200.00	<i>1100</i>

5374.9  
4837.41

*Not Authorized  
Lph*



Co. Reg: 200922097K GST Reg.No: 200922097K

Auto Bay @ Kaki Bukit Blk 1 Area "D" Kaki Bukit Ave 6 #01-90 (S) 417883

• Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

3	To jack and straighten RH rear chassis	\$250.00	11X
4	To jack and straighten rear exhaust pipe	\$50.00	✓
5	To remove boot compartment both side trim garnish to assist workload	\$80.00	60
6	To rust proof the affected areas	\$80.00	60
7	To check wiring and all lighting	\$60.00	30
Total Labour		\$3,020.00	
(* The above quoted are exclusive of GST.) Total Repair Cost		\$8,913.61	

2480

Yours faithfully,

Darla

f Auto N Cars Services Pte Ltd

Surveyor's Details	
Name	marcus fletcher
Contact	90096600
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No
Signature	

7367-41  
5897

DATE	Remark From MR CHOO
24/08/2018	Please arrange for survey asap

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Affected  
2/5 #5810/-  
7 days.  
Take photo after rep-