



8131 6518

lucas

Vehicle No : SJK9848K
 Make & Model : HYUNDAI, HD AVANTE 1.6
 A, KMHDU41BR9U613116
 Year of Manufacture : 2008

Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Estimation No. : E18080012
 DOA : 23/08/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bumper	1.00	698.00	698.00
2	Rear bumper reinforcement	1.00	492.70	492.70
3	Rear bumper bracket (LH)	1.00	118.80	118.80
4	Rear bumper bracket (RH)	1.00	118.80	118.80
5	Rear bumper retainer (LH)	1.00	92.90	92.90
6	Rear bumper retainer (RH)	1.00	92.90	92.90
7	Rear bumper sponge	1.00	92.90	92.90
8	Bootlid	1.00	885.00	885.00
9	Bootlid emblem - logo	1.00	120.00	120.00
10	Bootlid license lamp garnish	1.00	142.00	142.00
11	License lamp (RH)	1.00	98.00	98.00
12	License lamp (LH)	1.00	98.00	98.00
13	Bootlid lamp (LH)	1.00	202.40	202.40
14	Bootlid lamp (RH)	1.00	202.40	202.40
15	Bootlid lock	1.00	210.20	210.20
16	Bootlid lock catch	1.00	0.00	0.00
17	Bootlid key lock	1.00	380.00	380.00
18	Bootlid hinge (LH)	1.00	198.00	198.00
19	Bootlid hinge (RH)	1.00	198.00	198.00
20	Bootlid rubber beading	1.00	112.00	112.00
21	Bootlid insulator	1.00	240.00	240.00
22	Tail lamp (LH)	1.00	619.20	619.20
23	Tail lamp (RH)	1.00	619.20	619.20
24	Tail lamp inner panel (LH)	1.00	271.70	271.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJK9848K
Make & Model : HYUNDAI, HD AVANTE 1.6
A, KMHDU41BR9U613116
Year of Manufacture : 2008

Estimation No. : E18080012
DOA : 23/08/2018

No	Description	Qty	U/P	Amt
25	Tail lamp inner panel (RH)	1.00	271.70	271.70
26	End panel	1.00	319.20	319.20
27	End panel top garnish	1.00	512.70	512.70
28	Spare tyre panel	1.00	1,053.90	1,053.90
29	Spare tyre top board	1.00	392.00	392.00
30	Tail lamp garnish (LH)	1.00	0.00	0.00
31	Tail lamp garnish (RH)	1.00	0.00	0.00
32	Front bumper	1.00	633.00	633.00
33	Radiator grille	1.00	473.00	473.00
34	Front bumper retainer (LH)	1.00	43.00	43.00
35	Front bumper retainer (RH)	1.00	43.00	43.00
36	Front bumper bracket (LH)	1.00	53.80	53.80
37	Front bumper bracket (RH)	1.00	53.80	53.80
38	Front bumper reinforcement	1.00	293.00	293.00
39	Front bumper sponge	1.00	134.00	134.00
40	Front bumper lower grille	1.00	75.00	75.00
41	Front bumper emblem - logo	1.00	120.00	120.00
42	Fog lamp (LH)	1.00	195.00	195.00
43	Fog lamp (RH)	1.00	195.00	195.00
44	Head lamp (LH)	1.00	645.00	645.00
45	Head lamp (RH)	1.00	645.00	645.00
46	Head lamp bracket (LH)	1.00	49.00	49.00
47	head lamp bracket (RH)	1.00	49.00	49.00
48	Bonnet	1.00	1,108.00	1,108.00
49	Bonnet insulator	1.00	0.00	0.00

Continue on next page...

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJK9848K
Make & Model : HYUNDAI,HD AVANTE 1.6
A,KMH DU41BR9U613116
Year of Manufacture : 2008

Estimation No. : E18080012
DOA : 23/08/2018

No	Description	Qty	U/P	Amt
50	Bonnet lock	1.00	115.00	115.00
51	Bonnet hinge (LH)	1.00	91.70	91.70
52	Bonnet hinge (RH)	1.00	91.70	91.70
53	Front support panel	1.00	882.00	882.00
54	Front support panel side garnish (LH)	1.00	0.00	0.00
55	Front support panel side garnish (RH)	1.00	0.00	0.00
56	A/C Condenser	1.00	1,174.00	1,174.00
57	Radiator	1.00	885.00	885.00
58	Radiator fan cowling	1.00	820.00	820.00
59	Radiator fan motor	1.00	0.00	0.00
60	Radiator fan blade	1.00	0.00	0.00
61	Radiator bracket	2.00	0.00	0.00

Amt S\$ 17,719.60
Discount (0.00%) S\$ 0.00
Subtotal S\$ 17,719.60

Section: Special Nett Items

62	Rear bumper clip set	1.00	40.00	40.00
63	End panel top garnish clip set	1.00	30.00	30.00
64	Bootlid insulator clip set	1.00	40.00	40.00
65	Tail lamp clip set	1.00	20.00	20.00
66	Bootlid spoiler	1.00	600.00	600.00
67	Bootlid spoiler LED lamp	1.00	300.00	300.00
68	End panel sealant	1.00	50.00	50.00
69	Spare tyre insulator matt	1.00	250.00	250.00

Continue on next page...

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJK9848K
Make & Model : HYUNDAI, HD AVANTE 1.6
A, KMHDU41BR9U613116
Year of Manufacture : 2008

Estimation No. : E18080012
DOA : 23/08/2018

No	Description	Qty	U/P	Amt
70	Rear bumper reverse sensor	1.00	250.00	250.00
71	Rear number plate & casing	1.00	45.00	45.00
72	front bumper clip set	1.00	40.00	40.00
73	Bonnet insulator clip set	1.00	30.00	30.00
74	Engine coolant 4L	1.00	80.00	80.00
75	Horn set	1.00	180.00	180.00

Amt S\$ 1,955.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 1,955.00

Section: Labour Items

76	To remove and refit rear bumper reverse sensor	1.00	60.00	60.00
77	To apply undercoating on affected areas	1.00	100.00	100.00
78	To check wiring and lighting system front & rear	1.00	120.00	120.00
79	To remove and replace radiator and a/c condenser assy	1.00	200.00	200.00
80	To top up 134a refrigerant	1.00	100.00	100.00
81	To R&R rear garnish and trims	1.00	100.00	100.00
82	To repair, replace and realign damage areas	1.00	1,800.00	1,800.00
83	To spray painting on affected areas	1.00	1,600.00	1,600.00
84	To check water seepage after repair	1.00	120.00	120.00

Amt S\$ 4,200.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 4,200.00

List Items Subtotal S\$ 17,719.60
Special Nett Items Subtotal S\$ 1,955.00
Labour Items Subtotal S\$ 4,200.00
Total S\$ 23,874.60