



Prime Auto Claims Service Pte Ltd

6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948
GST Reg. No: 201606560M
Reg No. 201606560M

Date: 23.08.2018

India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Attn: Motor Claims Dept

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2873T TOYOTA VELLFIRE (2013)

Taufik 97415749
-WP
02 days
Resurvey the repair
SURVEILLANCE.com
24/8/18 @ 1015

To Supply

1) 1pc	Rear bumper	\$ de 1,785.00
2) 1set	Rear bumper clip	\$ net 30.00
3) 1pc	Rear bumper right side retainer	\$? 130.00
4) 1pc	Rear bumper left side retainer	\$? 130.00
5) 1pc	Rear end panel top garnish	\$ x 400.00
6) 1set	Rear end panel top garnish clip	\$ x 30.00
7) 1pc	Rear bumper center right parking sensor (Genuine)	\$ net 290.00
8) 1pc	Rear bumper center left parking sensor (Genuine)	\$ net 290.00
9) 1pc	Rear bumper center right parking sensor cover (Genuine)	\$ net 25.00
10) 1pc	Rear bumper center left parking sensor cover (Genuine)	\$ net 25.00

Sub total parts	\$ 3,135.00
Less: 25% discount	\$ 783.75
	\$ 2,351.25

L/charges

1) To tuff kote	\$ x 100.00
2) To remove & refit center reverse sensor & sensor, reset reverse sensor light. Check wiring	\$ 30 60.00
3) To remove rear bumper. Repair tail gate, knock rear end panel. Replace the above parts. Align & adjust rear bumper & tail gate.	\$ 300 800.00
4) To putty, respray painting rear bumper, end panel, tail gate & reverse sensor cover in pearl white. To polish	\$ 250 850.00

Sub total L/charges	\$ 1,810.00
Estimated Grand total	\$ 4,161.25