

Prime Auto Claims Service Pte Ltd

GST Reg. No: 201606560M 6 Benoi Place Singapore 629927 Tel: 6861 0908 Fax: 6515 2948

Date: 10.09.2018

Our Ref: SHD2873T Your Ref: Please advice

India International Insurance Pte Ltd 64 Cecil Street #04/#05 IOB Building Singapore 049711 Without prejudice

Attn: Ms. Sundari (Motor Claims Dept)

Dear Madam,

ACCIDENT ON 21.08.2018 INVOLVING VEHICLE NO SHD2873T & SHA4833L

We are on behalf of M/s Prime Car Rental & Taxi Services Pte Ltd the owner of vehicle SHD2873T in their third party claim against your insured / driver of SHA4833L negligence caused the accident.

Appended below our client's claim:

1.	Cost of repair		\$ 2,636.21
	Loss of rental @\$142.80 x 3 days (Inc	I. 1 Sun)	\$ 428.40
		Total	\$ 3,064.61

We enclose herewith copy of our invoice no 2445, Letter of authority & Letter of Certification for your retention. Please acknowledge receipt.

For an amicable settlement, please let us have your offer.

Yours faithfully,

Alice Leong

e-mail: aliceleong@primeautoclaims.com

Encl.

LETTER OF AUTHORITY

To: PRIME AUTO CLAIMS SERVICE PTE. LTD.

Re: ACCIDENT ON 21.08.2018 INVOLVING SHD2873T & SHA4833L ALONG AIRPORT BOULEVARD TERMINAL 3 TAXI HOLDING AREA

I/ We, M/S Prime Car Rental & Taxi Services Pte Ltd hereby authorized you to carry out repairs of the damage caused to my / our vehicle no. SHD2873T in the above accident.

I/ We further also confirm and agree that all sums of money to be recovered by you on my/ our behalf shall be paid to you. I/ We hereby also authorise the third party insurer to release to you such sums of money recovered on my / our behalf.

Signature (Company's stamp if applicable)

Name: NRIC:



Prime Auto Claims Service Pte Ltd

6 Benoi Place Singapore 629927 Tel: 6861 0908 Fax: 6515 2948 GST Reg. No: 201606560M Reg No. 201606560M

64 Cecil Street

MESSRS

India International Insurance Pte Ltd

31/8/2018

Date:

2407


Works Order No:

Make/Model : Toyota Vellfire Repair Date : 23/8/2018 Terms of Payment: COD Third Party Claims To Supply 1. 1 pc rear bumper. 2. 1 set rear bumper clip. 3. 1 pc rear bumper center right parking sensor (Genuine). 4. 1 pc rear bumper center left parking sensor (Genuine).	Vehicle No:UNIT PRICE	SHD2873T
Make/Model : Toyota Vellfire Repair Date : 23/8/2018 Terms of Payment: COD Third Party Claims To Supply 1. 1 pc rear bumper. 2. 1 set rear bumper clip. 3. 1 pc rear bumper center right parking sensor (Genuine). 4. 1 pc rear bumper center left parking sensor (Genuine).	UNIT PRICE	ALAOLIA
Third Party Claims To Supply 1. 1 pc rear bumper. 2. 1 set rear bumper clip. 3. 1 pc rear bumper center right parking sensor (Genuine). 4. 1 pc rear bumper center left parking sensor (Genuine).		AMOUN'
Repair Date Terms of Payment: 23/8/2018 COD Third Party Claims To Supply 1. 1 pc rear bumper. 2. 1 set rear bumper clip. 3. 1 pc rear bumper center right parking sensor (Genuine). 4. 1 pc rear bumper center left parking sensor (Genuine).		
Third Party Claims To Supply 1. 1 pc rear bumper. 2. 1 set rear bumper clip. 3. 1 pc rear bumper center right parking sensor (Genuine). 4. 1 pc rear bumper center left parking sensor (Genuine).		
Third Party Claims To Supply 1. 1 pc rear bumper. 2. 1 set rear bumper clip. 3. 1 pc rear bumper center right parking sensor (Genuine). 4. 1 pc rear bumper center left parking sensor (Genuine).		
Third Party Claims To Supply 1. 1 pc rear bumper. 2. 1 set rear bumper clip. 3. 1 pc rear bumper center right parking sensor (Genuine). 4. 1 pc rear bumper center left parking sensor (Genuine).		
To Supply 1. 1 pc rear bumper. 2. 1 set rear bumper clip. 3. 1 pc rear bumper center right parking sensor (Genuine). 4. 1 pc rear bumper center left parking sensor (Genuine).		
To Supply 1. 1 pc rear bumper. 2. 1 set rear bumper clip. 3. 1 pc rear bumper center right parking sensor (Genuine). 4. 1 pc rear bumper center left parking sensor (Genuine).		
To Supply 1. 1 pc rear bumper. 2. 1 set rear bumper clip. 3. 1 pc rear bumper center right parking sensor (Genuine). 4. 1 pc rear bumper center left parking sensor (Genuine).		
 1 pc rear bumper. 1 set rear bumper clip. 1 pc rear bumper center right parking sensor (Genuine). 1 pc rear bumper center left parking sensor (Genuine). 		
 1 set rear bumper clip. 1 pc rear bumper center right parking sensor (Genuine). 1 pc rear bumper center left parking sensor (Genuine). 	150	\$ 1,785.0
 1 pc rear bumper center right parking sensor (Genuine). 1 pc rear bumper center left parking sensor (Genuine). 		\$ 30.0
 1 pc rear bumper center left parking sensor (Genuine). 		\$ 290.0
		\$ 290.0
1 pc rear bum per center right parking sensor cover (Genuine).		\$ 25.0
6. 1 pc rear bumper center left parking sensor cover (Genuine).		\$ 25.0
Sub Total Parts:		\$ 2,445.0
Less: 25 % discount		(\$ 611.25
		\$ 1,833.7
Labour Charges		
 To remove & refit center reverse sensor & sensor, reset reverse sensor 		\$ 30.0
Light. Check wiring.		
 To remove rear bumper. Repair tailgate, knock rear end panel. Replace 		\$ 300.0
The above parts. Align & adjust rear bumper & tailgate.		
 To putty, respray painting rear bumper, end panel, tailgate & reverse 		\$ 300.0
Sensor cover in pearl white. To polish.		
Sub Total L/Charges:		\$ 630.0
	-	
	9	
mpound interests at the rate of 1% per month I be charged on late payment.		\$ 2,463.7
7	SUB TOTAL	
	SUB TOTAL GST 7%	\$ 172.46

\$ 2,636.21

Prepared by

Prime Auto Claims Service Pte Ltd



PRIME CAR RENTAL & TAXI SERVICES PTE LTD

Prime Taxi Office 5, Benoi Place Singapore 629926 Tel: 6898 2000

Fax: 6862 2628

Email: primetaxi@singnet.com.sg Website: www.primetaxi.com.sg

Co. Cert. No: 199606293Z Gst Reg. No: 19-9606293-Z

Your Ref: Please advise

Our Ref: SHD2873T

Date

: 28.08.2018

To

: Whom It May Concern

From

: Prime Car Rental & Taxi Services Pte Ltd

RE: LETTER OF CERTIFICATION FOR MR. ABD RASHID KHAN BIN ABD HAMID

This letter serves to confirm that Mr. Abd Rashid Khan Bin Abd Hamid Nric Number S1733368B is a Taxi Master for Prime Car Rental & Taxi Services Pte Ltd hiring the Vehicle Registration Number SHD2873T Singapore Dollar One Hundred Forty Two and Cents Eighty (\$142.80) Only.

Should clarification require I can be contacted at 94524182.

Thank you with Best Regards

Yours Sincerely

CHAN KONG LOONG

S7630106I

WORKSHOP MANAGER NO. 5 BENOL PLACE

Mr Chan Kong Loong

Workshop Manager