

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 619P**AAD1808-156***Not Authorized
L1 Imp \$5650k*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHF 619P

VF1ABL15AUC278506

RENAULT

LATITUDE

19.8.2018

AXA

		PART		LIST	
1	1	BUMPER COVER FRT	\$	<i>Bulena</i> 1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75	X
3	1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68	X
4	1	BUMPER RETAINER FRT LH	\$	<i>Dir</i> 151.41	✓
5	1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88	} X
6	1	BUMPER RETAINER FRT RH	\$	<i>Sn</i> 150.77	
7	1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88	
8	1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83	
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80	
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i> 207.21	
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21	
12	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08	
13	1	TOW COVER FRT	\$	<i>Sn</i> 28.61	
14	1	RADIATOR GRILLE	\$	<i>Sn</i> 1,707.78	
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36	} X
16	1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75	
17	1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90	
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79	
19	1	FRONT BRACE PANEL	\$	<i>R</i> 177.22	
20	1	HORN	\$	<i>Sn</i> 314.17	
21	1	HORN BRACKET	\$	<i>R</i> 40.45	
22	1	HEADLAMP LH	\$	<i>ngjrm</i> 1,184.43	✓
23	1	HEADLAMP RH	\$	<i>Sn</i> 1,184.43	X
24	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15	X
25	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15	X
26	1	BONNET	\$	<i>R</i> 1,941.63	X
27	1	BONNET INSULATOR	\$	<i>Sn</i> 405.73	X
28	1	BONNET STRUT LH	\$	<i>Sn</i> 88.61	X

Trans-cab Auto Services Pte Ltd**AAD1808-156**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 619P

29	1	BONNET STRUT RH	\$	Sn	88.61	}	X
30	1	BONNET HINGE LH	\$	Sn	348.31		
31	1	BONNET HINGE RH	\$	Sn	348.31		
32	1	BONNET LOCK	\$	Sn	305.48		
33	1	BONNET CABLE	\$	Sn	119.19		
34	1	BONNET CABLE COVER	\$	Sn	161.03		
35	1	BONNET SEAL OUTER	\$	Sn	92.36		
36	1	BONNET SEAL INNER	\$	Sn	157.28	}	✓
37	1	FENDER PANEL FRT LH	\$	Sn	783.83		
38	1	WHEELARCH FRT LH	\$	CM	278.84	}	X
39	1	FENDER BRACKET LOWER LH	\$	Sn	15.79		
40	1	FENDER INSULATOR LH	\$	Sn	130.84		
41	1	FENDER INSULATOR RH	\$	Sn	130.84		
42	1	WIPER RESERVOIR	\$	Sn	348.25		
43	1	WIPER RESERVOIR NECK	\$	Sn	136.11		
44	1	WIPER RESERVOIR MOTOR	\$	Sn	270.06		
45	1	AIR CLEANER LOWER	\$	Sn	271.26		
46	1	AIR CLEANER HOSE	\$	Sn	76.14		
47	1	BASE BATTERY TRAY	\$	Sn	363.40		
48	1	AIR CLEANER BOX	\$	Sn	464.20		
49	1	TURBO DUCT	\$	Sn	1,027.80		
50	1	A/C HEATER VALVE	\$	Sn	484.50		
51	1	SUBFRAME OUTER FRT	\$	Sn	2,652.45		
52	1	SUBFRAME BRACKET OUTER LH	\$	Sn	92.36		
53	1	ENGINE UNDERTRAY	\$	Sn	564.98		
54	1	A/C CONDENSER	\$	Sn	2,020.37		
55	1	A/C CONDENSER GARNISH LH UPPER	\$	Sn	39.67		
56	1	A/C CONDENSER GARNISH RH UPPER	\$	Sn	39.67		
57	1	A/C CONDENSER GARNISH LH	\$	Sn	58.81		
58	1	A/C CONDENSER GARNISH RH	\$	Sn	59.60		
59	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	Sn	208.39		
60	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	Sn	658.72		
61	1	A/C PIPE COMPRESSOR	\$	Sn	334.29		
62	1	A/C PIPE	\$	Sn	658.72		
63	1	A/C COMRPESSOR	\$	Sn	2,684.61		
77	1	AIR COOLER	\$	Sn	792.60		
78	1	AIR INTERCOOLER HOSE (LONG)	\$	Sn	1,014.13		
79	1	AIR INTERCOOLER HOSE (Short)	\$	Sn	375.14		

Trans-cab Auto Services Pte Ltd**AAD1808-156**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 619P

80	1	TRANSMISSION COOLER	\$	Sin	1,219.30	
81	1	TRANSMISSION COOLER PAD	\$	Sin	17.96	
82	1	RADIATOR	\$	Sin	1,202.20	
83	2	RADIATOR STUD UPPER	\$	Sin	14.41	
84	2	RADIATOR BUSH UPPER	\$	Sin	50.12	
85	2	RADIATOR MTG LOWER	\$	Sin	55.85	
86	1	RADAIOR FAN COWLING	\$	Sin	820.54	
87	1	RADIATOR FAN MOTOR LH	\$	Sin	967.36	
88	1	RADIATOR FAN MOTOR RH	\$	Sin	1,479.46	
89	1	RADIATOR TANK	\$	Sin	324.62	
90	1	RADIATOR HOSE UPPER	\$	Sin	240.56	
91	1	RADIATOR HOSE LOWER	\$	Sin	491.18	
92	1	RADIATOR TANK HOSE	\$	Sin	61.18	
93	1	AUTO COMPUTER	\$	Sin	5,032.17	
94	1	INJECTION COMPUTER	\$	Sin	4,706.30	
95	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	Sin	5,154.52	
96	1	STEERING PUMP ELECTRIC L70Y	\$	Sin	2,306.90	
97	1	STEERING PINION RACK L70Y	\$	Sin	4,413.11	
98	1	DOOR PANEL FRT LH	\$	B	2,844.66	✓
99	1	LOWER ARM LH L70Y	\$	Sin	685.76	X
100	1	KUNCKLE ARM LH L70Y	\$	Sin	846.98	X
101	1	ABSORBER FRT LH L70Y	\$	Sin	360.54	X
102	1	AIR CLEANER BOX	\$	Sin	464.20	X
103	1	AIR CLEANER HOSE	\$	Sin	175.85	X
104	1	DOOR HARNESS WIRE LH	\$	Sin	2,670.00	X
105	1	DOOR MIRROR ASSY LH	\$	Sin	1,483.40	X
106	1	DOOR PANEL FRT LH	\$	Replaces B	2,844.66	X
TOTAL			\$		70,862.14	
10%			\$		7,086.21	
			\$		63,775.92	

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	nn	52.00	X
2	1SET	BUMPER CLIP FRT	\$	nn	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	nn	12.00	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	nn	10.50	X
5	1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	X

Trans-cab Auto Services Pte Ltd

AAD1808-156

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 619P

6	1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	}	X
7	1	TOW COVER FRT	\$	sn	14.50		
8	1SET	RADAIOR GRILLE SCREW	\$	nn	16.00		
9	1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00		
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00		
11	2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00		
12	2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00		
13	1	Windscreen moulding	\$	nn	100.00		
14	1SET	Front licence plate with holder	\$	sn	80.00		
15	1	Front left tyre	\$	sn	330.00		
16	1	Front left tyre rim	\$	sn	380.00		
17	1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00		
18	1	FRONT DOOR STICKER 'Chassis'	\$	nn	50.00		

TOTAL	\$	1,402.50
TOTAL PARTS	\$	65,178.42

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	5,400.00	5000
Towing Fees.	\$	nn	120.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	nn	380.00 X
Putty and spray painting of the affected portion.	\$		6,000.00 6600
To rust-proofing of the affected areas.	\$		170.00 600
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00 X
To check steering geometry and computer wheel alignment	\$		220.00 600

Trans-cab Auto Services Pte Ltd

AAD1808-156

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 619P

To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To lift-up engine with gear box and refit.	\$	440.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00	X
To remove and refit air bag system and reset.	\$	480.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00	X
To vacuum, replace, refix and recharge air condenser	\$	380.00	X
To replace, refix and top up coolant for radiator	\$	170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	X

TOTAL \$ 16,400.00**Over All Total \$ 81,578.42****Repair Days (LUMP SUM)****20 DAYS**
3 days

Acknowledged by Repairer

Signature:

Date:

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company