19/5/2000		1 2	tun. k	2 Mb / LKK	
INS. CASE OWNER	R:	CC 1/CTI1801	94111	IDAC:	A
Surveyor:	Faluta	DOE ASSIGN	KIK	Date / Time / Yh	V/18
Pre-assign / CCU Insured Vehicle N Name of Insured Insured Tel No. Excess Sec II : S5	um Fim	+6P = 147- HP: 97643787 D.O.A: 70 8 18.	Clarm No. Policy No. Make / Model Place of Acciden	und Maria Maria	13451701
Is driver the owner If NO. Driver Na Driver Tel	me / Age :	(V/L: (ES) NO)	Of GIA REPOR	T. VE / NO . TP GIA REPO	ORT (YE) / NO
INSRS: WSP: Tet: Liability: RMKS:	the INSR WSP Tel: Liabil RMK	iny:	INSRS: WSP: Tel: Liability: RMKS:	Tei Liah RM	P. sility :
Date/ Time	SHAGANC- WA	Labracon Na	SHOWN	STAGE	DATE/PIC
PRELIMINARY ADVICE	3 1134 W/O	BUT FOR LENG	EVELONOUS PARTO	Non-Reporting lir (1st) Non-Reporting lir (2st) Non-Reporting lir (2st) Non-Reporting lir (2st) Non-Reporting lir (3st) Non-Reporting lir (3st) Non-Reporting lir (3st) Call Ol. Documentation Check List: H Nonification lir (if non-pickup) After call lir to Ol. Authorisation lir (if non-pickup) Authorisation lir (if non-pickup) Authorisation lir (if non-pickup) Car Rental lirvince: Final Repair Bill Car Rental lirvince: Towing lirvince LTA / GIA: Medical Bill Pfin Mandate/Reject lisstruction LOD Payment Breakdown Form: Post-Repair Photos.	andler Typist
				Others: Sa Engli	
FINALIZATION	Date/Time:	Confirm with:		Confirm by:	Tout I
Repair Cost: FINAL SETTLEMENT Final Liability: Repair Cost: Loss of Rental (LOR): Loss of Use (LOU): Loss of Income (LOI): LOR only LOU only	Dute/Time: (Algredd SS 32) X 4 (SS 3 1 X 1 X 1 X 1 X 1 X 1 X 1 X 1 X 1 X 1		阿	Email Cal III NO or B 28: Ass. Liu	
GIAILTA Search Medical: Disbursement: Legil Cost	SS 7 49 SS = 9/		()	Claim status: Normal/Rejes Report Format Survey fee	n/Private Settle
Total:	S\$ 5 4 5 1	Global Sum SS:		David Love	
Payce 1: Payce 2: (Strike if N.A.)	SS 850 Z K	Name 1: LOMFORTO Name 2:		NO WELLING	PAL LIN
Payor 3: (Strike if N.A.)	55	Name 3:			

Bineur:	Kalvin

61	ASSIG	NMENT				
From: Date:	Í	eh No:	SHA	6921C	Yr Ragn: 9A	pr , 2014
Estimate/Cost	T	ype: M.Cat /	M.Cycle / Bu	s / Van / Lon	ry IT @ I Prime M	lover /
ODITPIWS ITPRES / OD RES / EVA / INV / MV		Truck /	Trailer or .			
To Insped Vahicle No:	× 1	Make:	H.	udi Z	Yo co	1685
at Workshop m/s		Colour	Blu	t	A/C: Insu	/Std/NI/NA
of	1.1	Sp.Reading	73,	844	T/Radio: Inside	S/Std/NI/NA
Insured;		Eng/No:				
Policy No.		C/No:	K	AHLE	1414MEY	052502
Claims No.		Gen. Cond: G	-			
Sum In suitd: . Excess:		Steering: Inci	Gr I Jammi	ed / Leaked /	Burnt or	
(Client's Record)			*	ed / Leaked /		
Make of Veh:		Modi: Nil	ISIRim IS	TO/WRIM or		
		Tyre Size;			-/6xR16	
(Pelicy Condition)		111-1-1-1	R:		٠,	
Remark: The veh had commenced its N/S	0/8	BS / DUN / B	EXNOVA / GY	//FS/LIZA/	MIC/OHTSU/P	RISUMII y
repair at the time of Inspection.		TOYOTYO			Sert LE	
Bal. or Market Value:		Front	_		Rear	
iDAC Accident Rport Consistent? : Yes or No		R/Bal,	7	mm	R/Ball,	J
GIA / PR Seen: Consistent? : Yes or No		L/Bal.	+	mm 4	L/Ball	+ mm
Est Repairs: 2 days Res.: Yes or No		D.O.A. 2	0/8/2		0.0.1. 23	18/18
Lum Sum:% 3 Val.: Yes or No		Survey held	al	CI	HE (Loy	ang)
CA / REV / REP. / 24 HRS		Des. of Dan	nages: Frt /	Rear / O/S	NIST VICTR	politop or
Dale: Person Contacted: Vehicle:	MIOUT				Pler	had does to entirion
Date / Time Action / Instruction		The U/C	; / Chassis	frame / bod	y Structure anec	ted due to collision.
Acquir instruction		70A 20	× M6	3	CTI	
29-8-18 L/C \$300	1	33			45	
(A) H		22	MED			
		1.3	max			
	- 9	UT 24	1930			
		17	0.6	- 1	000	
***	101	1-(1	2,13	11.28	88101	
	10	3/				
Oale/Time, File Pass to? : Prell. Report		Days Of R				
1) : Final Report		Resurvey	No. of Tri	p:	Survey Fee:	
Osta/Tine, File Return to?					Transportation	
	Add Fe	e: :Sit	e insp (\$		5+RS_	SI
**		-	erview (\$) Photos	
Report Format :			ch. Invs (\$		Others	
Lump Sum / LB.3: (\$		-	eekend (\$			
Composite som to		1_1.			TOTAL.	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

0111	NA TAIRING INGLI		Ref : CC3/CT118015		
CHI	NA TAIPING INSU	RANCE (S) PTE LTD	Ref : CC3/CTI18015	421/1/103	
201 (0.7)	NSON ROAD #16-0 RINGLEAF TOWER	00 RSINGAPORE 079909	Date: 24-08-2018		
			Code: CTI		
1.		Policy Particul	Policy Particulars :- THIRD PARTY CLA		
	Insured Veh.	SLG 1676P	Veh. Inspected	SHA 6921C	
	Policy No.		Coverage (\$)	0.00	
	Claim No.		Excess (\$)	0.00	
	Assign From		Assign Date	24/08/2018	
2.		Vehicle P	articulars & Condition		
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	*	Steering		
	Brakes		Modification		
	General				
3.	-10	Cor	nditions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4.		Descr	iption of Damages		
5.		Gen	eral Information		
	Accident Date	20/08/2018	Inspection Date	23/08/2018	
	Survey held at	COMFORTDELGRO ENGIN	EERING PTE LTD		
		59 LOYANG DRIVE SINGAPORE 508969			
5a.			Remarks		



Company Registration No. 199607198R

\$1 UH AVE 1, 602-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : 1065 (6256356) FAX : 1065) 62564315

Your ref: To Be Advised

Our ref: CC3/CTI18015421/K1jb3

Date:

24.08.2018

The Motor Claims Department

M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHA6921C

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23.08.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	2,481.58
Revised Estimate Amount	: SS	300.00
"Check" Items Amount	; SS	730.68
Market Value	: S\$	9
LTA Reimbursement Value	: S\$	*
Nett Value	: SS	

Description of Damage:

The vehicle sustained damages at the

Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully.

KALVIN ANG

Licensed Appraiser

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305202918 ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 28/08/18 Date FINALIZATION FORM LKK Fax: KALVIN Attn : Vehicle Reg No: : SHA6921C 20/08/2018 The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-The repair job shall bill to: CHINA SLG1676P 1. 2 The finalized amount shall be: Spare Parts after List discount \$300.00 (b) Labour Charges Total for Part-By-Part Repair Cost \$300.00 (c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost 2 working days. 3. Estimated normal period for repairs: 4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days 5. Thank you for your assistance. We confirm the estimates and finalized amount. Signature : Signature: Calus : CHIANG Name Name 29/8/2 62148314 Tel Date Fax 65468156 For Official Use Only Document Confirm By Item Attached Remarks Amount (Signature) Yes or No Rental Rate P/Day YES 2. Loss of Income Paid N Survey Fees LTA Search Fee 7.49 Medical Fees (on behalf of driver, if applicable) Overrun Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 28.08.2018 Time: 16:48:01

Page: 1

REPAIR ESTIMATE

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO MILEAGE MAKE

: SHA6921C : 00000000000 : HYUNDAI

305202918

MODEL : 1-40

: 09.04.2014 DATE OF REGN : 21.08.2018 11:50 DATE/TIME IN

ACCIDENT DATE : 20.08.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

T REQUISITION

SUB-TOTAL: 0.00

JOB NATURE

0000 L PANEL BEATING

100.00

0001 23-502 SPRAYPAINT ON AFFECTED AREA

200.00

SUB-TOTAL: 300.00

TOTAL : 300.00

A NAME & SIGNATURE

AUTHORISED : YES / NO SURVEYOR NAME & SIGNATURE

DATE:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHA 6921C

China - 45

DATE 23/8/2018

LKK-Kalvin

DDEL	: HYUNDAI i40		LKK-K	_		1
Qty	Parts Description/ Labour	Type	Unit Price	·	Amount	
	Rear Bumper X 1412			S	603.60	
	Rear Bumper Reinforcement			\$	504.35	
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 180.00	\$	360.00	
	Rear Bumper Side Bracket **			S	49.00	
	Rear Bumper Clips × *			\$	22.00	
	Rear Bumper Sponge			S	143.40	
	Rear Bumper Under Cover			S	225.00	
	SUB TOTAL			s	1,907.35	1
	LESS 20%			S	381.47	
	DISCOUNTED TOTAL			\$	1,525.88	
	nt					
	Rear Bumper Reverse Sensor			S	135.70	1868
	Rear Bumper Rubber Mat 😕 **			S	50.00	Ne
				s	185.70	
	Labour Charge Panel Beating Spray Painting Charge Wiring Charge R/Refix Reverse Sensor			\$ \$ \$ \$	700 350:00 250:00 50:00 120:00	50
	TOTAL LABOUR			\$	770.00	
	ESTIMATE TOTAL			5	2,481.58	-
					2,101.50	1
	Kahriller 123/8/18 1145/21 2 By. Us Alle Reinples	the R To re To d Part Thin No ii	Auto Consultants hence in depairer of the following: survey before/after opray porollistay damaged cantal during relative and survey is on a "Whole Plagar not feet in 1999 and a whole plagar not feet in 1999 an	og survey on reputio	e" basis and	
	Affer Kgarples	Signal				

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Shu Pei (LKKAuto)

From:

Lucas Lee <lucas.lee@sg.cntaiping.com>

Sent:

Thursday, 30 August 2018 2:22 PM

To:

Shu Pei (LKKAuto)

Subject:

RE: Direct Settlement - Accident Involving SLG1676P (OI : CTI - SNM18D04078C02)

AND SHA6921C (TP: LKK REF - CC3/CTI18015421/K1jb3) on 20.08.2018

Attachments:

IeeSZ_SNM18D04078C01-SLG1676P-LKKDirectSettlementAccidentLtr_CLCR95.376.pdf;

MCHM18108559-SLG1676P.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Irene Tay

Lucas Lee

Claims Department (Motor)

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181

Fax (65) 6222 7175/6224 7478 Email: lucas.lee@sg.cntaiping.com Website: www.sg.cntaiping.com



Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAuto) [mailto:shupei@lkkauto.com]

Sent: Friday, 24 August, 2018 4:20 PM

To: Claims Dept of CTI

Cc: Irene Tay; Lucas Lee; Joy Irene (LKKAuto); Admin A

Subject: Direct Settlement - Accident Involving SLG1676P (OI: CTI - TBA) AND SHA6921C (TP: LKK REF -

CC3/CTI18015421/K1jb3) on 20.08.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SHA 6921C at M/s ComfortDelGro Engineering Pte Ltd (Loyang).

Enclosed for your perusal is:

- TP GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action

Kindly take note that the case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

Thank you.

Best Regards.

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupe:@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security cloud service. For more information please visit http://www.symanteccloud.com



中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springins/ Tower Singapure 1/16056 Tul. 6389-6111 Fax. 6272 1033 Website www.sg.pnaging.com Co Reg No 200208384E

Our Reference: SNM18D04078/C01/6

Date: 30 AUGUST 2018

via Ordinary & Registered Mail

LIM KIM KIAT **BLK 364 WOODLANDS AVENUE 5** #07-468 SINGAPORE 730364

Dear Sir / Madam

ACCIDENT INVOLVING SLG1676P AND SHA6921C ON 20 AUGUST 2018 ALONG YISHUN AVE 2 TOWARDS CANBERRA LINK

We refer to the abovementioned accident.

Please be advised that the third party vehicle, SHA6921C, is filing a third party property claim against your vehicle.

We have appointed LKK Auto Consultants Pte Ltd, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly, Claims Department

(This is a computer generated letter and no signature is required.)

CC LKK Auto Consultants Pte Ltd

Attn JOY

Ref

CC3/CTI18015421/K1JB3

Contact No : 68412409

via Email : JOY@LKKAUTO.COM

CC : Agent - (AN0582A) - COSMO INSURANCE AGENCY PTE LTD

F01/LKKDS-2013

OMFORIDELGRO ENGINEERING

member of COMFORTDELCRO

ComfortDelGro Engineering Pte Ltd

205 Brastolii Road Singapone ETR701 Mainline v 65 5353 6285 Paracrile v 65 5287 9715

Markshops 58 Layang Drive Bingspore 008805 585 Sin Mag Drive Bingspore 57371 45 Bandan Road Singspore 608788 45 Bandan Road Singspore 608788

Lis Sensio Logi Singapore 788156 7. Bungai Habal Way Bingapore 736161 501 Vision Industrial Fork A Singapore 756

Date/Time: 21.08.2018 17:55

Page : 1


JOB CARD JC NO.: 305202918 Sales Order: ARC Repair TP(CLSO)1 Team: MILEAGE REGN NO. DMER. SHA6921C COMFORT TRANSPORTATION PTE LTD FUEL MAKE: HYUNDAI 7010045 E 1/2 383 SIN MING DRIVE 21.08.2018 11:50 MODEL Singapore SINGAPORE 575717 I - 40YR OF MANU 09.04.2014 65508755 TARGET DATE (R) (P) COMPLETION DATE/TIME CHASSIS CODE KMHLB41UMEU052502 JUNT CARD NO.

JOB DESCRIPTION

Accident Date: 20.08.2018 NATURE: 3P 20.08.2018

S/NO

LABOR CODE



KED & PASSED OUT BY:		
SERVICE ADVISOR		CUSTOMER'S SIGNATURE
ledgement Slip	Exit Pass	
No.: SHA6921C CHIANG	Vehicle No.: SHA6921C	
f Service Advisor Signature/Date	Name of Service Advisor	Date
sturned to Service Reception upon collection	To be kept by Security Guard	



COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHA 6921C

DATE 23/8/2018

China - 45

MAKE

MODEL

: HYUNDAI i40

LKK-Kalvin

Qty	Parts Description/ Labour	Type	Unit Price		Amount]
	Rear Bumper × 14.1-			S	603.60	1
	Rear Bumper Reinforcement 2			\$	504.35	L
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 180.00	S	360.00	ı
	Rear Bumper Side Bracket 2			S	49.00	L
	Rear Bumper Clips ×			\$	22.00	ı
	Rear Bumper Sponge 😓			S	143.40	L
	Rear Bumper Under Cover 😾			\$	225.00	
	SUB TOTAL			s	1,907.35	1
	LESS 20%			S	381.47	ı
	DISCOUNTED TOTAL			s	1,525.88	
	Rear Bumper Reverse Sensor 🗶			S	135.70	N
	Rear Bumper Rubber Mat 😕			\$	50.00	N
				s	185.70	
	Labour Charge				/00	
	Panel Beating			S	350.00	L
	Spray Painting Charge			S	280.00	20
	Wiring Charge			S	50.00	150
	R/Refix Reverse Sensor			S	120.00	×
	TOTAL LABOUR			\$	770.00	
	ESTIMATE TOTAL	La Consulta	nts hence notify	8	2,481.58	
	k / / //ck the Rd	nvey before a play damaged	ter spray painting part(s) during resurvey			
	11 27/8/8 11 11/2 NO	party survey a	ect to constructions on a "Nithout Prejudice" basis onts) is allowed (is) must be resurveyed and proval from insurance Compar		V	
		wiledged by R	epaires			
	Athe Reinpld					
	V					

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING

Our F	Ref :	T 0818 / SHA69210	(MT(st)		ENGI	NEERINC
Park and William	r Ref :			Cor	nfartDelGro E	ngineering Pte Ltd
Date	4	03-Sep-18	CDGE Taxi Claims De	ept 201	Breddell Road	d Singapore 57970
CUIN	IA TAIRIN	NG INSURANCE CO LTD	59 Loyang Drive 4th F Singapore 508969	· IF.	Man	nime +65 6383 628 milie +65 6280 975
					0.00	www.cdge.com.a
	SON RO	NGLEAF TOWER			Congress to	
						Workshop
	SAPORE					Bradde
Attn	: Motor	Claims Department	WITHOUT PREJUDICE			205 Braddell Roa Singapore 57970
Dea	r Sir					Loyan 65 Loyang Driv
ACC	IDENT	NVOLVING OUR TAX	SHA6921C YOUR INSURE	ED SLG	1676P	Singspore 50096
	OTHER			ON 2	0.08.18	Sin Min 353 Sin Ming Driv
Mar	ore the au	thorised renair workshop	for Comfort Transportation Pte L	td, the ow	ner of motor	Singapore 57571 Panda
	cle No :	SHA6921C which was	involved in the captioned accider	nt with you	r insured	
veni	cle The ve	shicle owner and the taxi	driver concerned have requested	and author	orized us to	Singapore 60928
neek	at them in	presenting their claims a	gainst the party responsible for al	l applicab	le matters	320 Ubi Road
arieir	na from th	ne damage to the vehicle.				Singapore 40864
				SI G1676		24 Senoko Loo
As th	ne accide	nt was caused by the neg	ligent act of your insured driving	aimants	-	Singapore 75815
we a	ire submi	tting these claims for your	consideration on behalf of the cla	antionics.		Sungei Kada
TAX		R'S CLAIM			321.00	7 Sungei Kadut Wa Singapore 72679
1	Cost of	Repair	0 442.00	\$		hun Industrial Park
2	4	days Loss of Rental @	\$ 113.00 per day	\$	402000	Singapore 7687
3		Report Fees (Surveyed	by Mrs LRR)	\$	7.49	•
5		folice Report Fees		\$	-	-
6		/ Medical / Transporation	Fees	\$		
	, owning	T Modern	Sub To	otal: \$	780.49	
HIR	ER'S CL	AIM		1/25	720000	
7	4	days Loss of Income @	② \$ 80.00 per days	_\$_	320,00	-
			Total Clai	ms:_\$	1,100.49	•
We	enclose h	nerewith the following doc	uments to support the claims: -		4	
a)	Origina	al repair bill and photocopi	ies of photographs :	_	4	pcs.
b)		earch slip/s of :	SLG1676P			
c)		Police report/s of :	SHA6921C			
d)	Letter	of authority from owner / h	nirer / operator			

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

() Traffic Compound () Towing/Medical bill/receipts () Certificate of Insurance

(X) Photograph/s of Accident Scen (x) Downtime/Mileage record

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully 'William 'Lan

Deputy Manager

CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email: williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

A member of



(x) Rental Rate letter





Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)

Sent: Wednesday, 7 November 2018 11:39 AM

To: 'tile_link@yahoo.com.ag'

Cc: Admin A

Subject: ACCIDENT INVOLVING SLG 1676P AND SHA 6921C ON 20/08/2018

Our ref: CC3/CTI18015421/K1jb3

LIM KIM KIAT

Policy Holder

Dear Sir,

ACCIDENT INVOLVING SLG 1676P AND SHA 6921C ON 20/08/2018

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: <u>joyirene@lkkauto.com|</u>Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING

140 SHA6921C , SLG1676P **YISHUN AVE 2 BF AVE 7**

ON 20-Aug-18 18:40

I/We

ALONG

LIM KIAM KIONG

(Hirer) NRIC No.:

S1687556B

and/or

(Relief) NRIC No .:

Taxi Number

SHA6921C

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

21-Aug-2018

Name of Hirer

LIM KIAM KIONG

Hirer NRIC

S1687556B

Signature:

Address

833 YISHUN STREET 81 #10-404

760833

Contact No.

83280972

MOTOR CLAIMS DISCHARGE VOUCHER

Policy No : DMPCSN3113951701 Claim No : SNM18D04078/C01/6
Claimant : COMFORT TRANSPORTATION PTE LTD

Amount : S\$850.00
SINGAPORE DOLLARS EIGHT HUNDRED FIFTY ONLY.

I/We agree to accept the above mentioned amount to be paid to me/us in full & final settlement of all claims, costs & disbursements for injuries / damages sustained by me/us through an accident involving

Claimant Vehicle No. : SHA 6921C Insured Vehicle No. : SLG 1676P

Date of Loss : 20/08/2018 Place of Accident : YISHUN AVE 2

IN CONSIDERATION of the payment made to me/us of the aforementioned sum by CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., I/We agree absolutely to discharge CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. and/or

Insured Name : LIM KIM KIAT Driver Name : LIM KIM KIAT

from all claims, present or future in respect of all loss, injury or damage sustained by me/us arising out of the said accident.

I acknowledge that this payment is made without admission of liability on the part of CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

(1) Global Sum TOTAL		S\$ 850.00 S\$ 850.00
Claimant Name:	CLAYES DEPARTMENT CONFORTING OF EACH OF THE LTD SHILD AND THE SHIP OF THE LTD SHILD AND THE SHIP OF THE LTD SHILD AND THE SHIP OF THE SHIP	NRIC No :
Signature :	1- rupe	Date : >0-11-/8

The contents of this document apply to vehicle damages only.

All personal injuries and damages arising therefrom are excluded from the ambit and application of this document.

Ploase forward your cheque made payable to COMFORTDELGRO ENGINEERING PTE IT?

COMFORTDELGRO ENGINEERING

A member of COMFORDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

200 Bracomii Hond Singapore 579701 Mainfins + 85 6283 6280 Faccimite + 65 6280 9769

Workshops

Williams Drive Singapore 588969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 220 Ubi Road 3 Singapore 409840 24 Senate Losp Singapore 738150 7 Sunge Kadul Wey Singapore 72875 501 Yebun Industria Park A Singapore 1

> COMPANY REG. NO.: 1995060481 Page:

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE SG 079909

CONTACT NO: 62222366

Description: 3P 20.08.2018

VKHCLR NO SHA6921C

INV. NO/DATK 91392712 30.08.2018

JOB NO. 305202918

%Disc

MODEI. T - 40

ODOMRTER READING

DATE OF REG 09.04.2014

DATE/TIME IN 21.08.2018 11:50

CHASSIS CODE

KMHLB41UMKU052502

S/No Part No.

Oty Unit Price

Net.

PART REQUISITION

SUB-TOTAL

0.00

300,00

JOB NATURE

0001 L

PANEL BRATTING

100,00

100.00

0002 23-502

SPRAYPAINT ON AFFECTED AREA

200.00

200.00

SUB-TOTAL

Items total

300.00

Add GST @

7,000 %

21.00

Invoice amount

321.00

mfortDelGro Engineering Pte Ltd

nember of COMFORTDELCRO

ad Office:

i Braddell Road gapore 579701

dly note that no receipt shall be issued unless requested.

STOMER'S COPY

INVOICE No.	AMOUNT	BANK/CHQ No
91392712	321.00	
		STATE OF THE STATE

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Float Singapore 579701 Mantine + 65 8363 6280 Facsinite + 85 6260 is/hij.

Workshops

24 Sense Luco Segueros 738150 383 Sin Ming Drive Singapore 578717 45 Pandan Read Singapore 60098 330 Uts Road 3 Singapore 400849

COMPANY REG. NO.: 1995060481

Page:

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE SG 079909

CONTACT NO: 62222366

VICHCLR NO SHA6921C

TNV. NO/DATK 91392712 30.08.2018

MAKE HYUNDAT

JOB NO. 305202918

MODRI. T-40

ODOMKTER READING

DATE OF REG 09.04.2014

DATK/TIME IN 21.08.2018 11:50

CHASSIS CODE KMHLB41UMEU052502

: KATHERINETAN 30.08.2018 11:45:10

Issued by : KATHERINETAN 30 Repair type : CLSO/57/57 Payment Type/Term: /Credit 30 days

mfortDelGro Engineering Pte Ltd nember of COMFORDELGING

ad Office: Braddell Road gapore 579701

dly note that no receipt shall be issued unless requested.

STOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No
8010012	91392712	321.00	
train upwel	CALL DESCRIPTION		
Marine Spirit			

Our Ref: CT18080627

Date: 30 August 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

20/08/2018 @ 18:40 hrs

ALONG

YISHUN AVE 2 BF AVE 7

INVOLVING

SLG1676P

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHA6921C (the "Taxi"). The Taxi was hired to LIM KIAM KIONG IC NO S1687556B a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$113.00 per day (inclusive of GST).

Please be advised that the Taxi was insured with India International Insurance Pte Ltd on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

Alexander of the second

THAMELED FROM TO DATE NAME OF DRIVER MILEAGE HE DING INVESTIGED (CM) 20 08-18	2 000	FAME	HOLIDS OPER	SATED (TB)	してもされ	7516	20	MILEAGE	HOURS OPE	HOURS OPERATED (TIME)
1000 FFOM TO 20.08-18 LIM 7=31 24 168 21-08-18 LIM 7=31 4 4 168		FILED	2000		NAME OF DRIVER	MILEAGE RE	DING	CKM	FROM	OT
11M 731 24 168 LIM 731 44 Accident 731 44 S repair (a)		(M)	FROM	ot			_	C to the control of t		F. C.
Accident 731 44 I				20.08-18	LIM 1	731	$\overline{}$	168.2	17.00 00:17	05,12
Accident we repair				81-10	MI		_	20.	20.11 11.20 11.55	11.55
<u>≫</u>				BI 10-13				t	177	1
<u>≫</u>				8/10	Accident			{	200	V -
				SHC	repair	3		E.	\	1430
				0						

(9)

Enquire Vehicle Insurer

Vehicle No. Incident Date/Time Search Status Insurance Company Code Insurance Company Name

SLG1676P 20 Aug 2018 / 18:40:00 Successful

C01

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Previous

OK

SHA 6921C



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Intern	ationale Des Experts En Autom	obile
CHII	NA TAIPING INSU	RANCE (S) PTE LTD	Ref : CC3/CTI180154	21/K1jb3q2
	ISON ROAD #16-0 INGLEAF TOWER	00 SINGAPORE 079909	Date: 22-11-2018 Code: CTI	
1.		Policy Particula	rs :- THIRD PARTY CLAIR	M
	Insured Veh.	SLG 1676P	Veh. Inspected	SHA 6921C
	Policy No.	DMPCSN3113951701	Coverage (\$)	0.00
	Claim No.	SNM18D04078/C01/6	Excess (\$)	0.00
	Assign From		Assign Date	23/08/2018
	ATTICON TO	Vehicle Pa	articulars & Condition	
	Make & Model	HYUNDAI I40	c.c	1685
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	KMHLB41UMEU052502	Colour	BLUE
	Odometer	731844	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	WEST LAKE	7 mm
	L/H Front Tyre	205/60 R16	WEST LAKE	7 mm
	R/H Rear Tyre	205/60 R16	WEST LAKE	7 mm
	L/H Rear Tyre	205/60 R16	WEST LAKE	7 mm
Ų.		Descri	ption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	REAR PORTION.	
	DAMAGES SEE D	ETAILS.		
	I SELECTION IN	Gen	eral Information	
	Accident Date	20/08/2018	Inspection Date	23/08/2018
	Survey held at	COMFORTDELGRO ENGIN	EERING PTE LTD	
		59 LOYANG DRIVE SINGAPORE 508969		
ia.			Remarks	
		ON WAS CONDUCTED ON A"		
5b.			ate Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	2 Working Day	5



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 6921C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	603.60	
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	504.35	
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00	SERVICEABLE	360.00	
1	REAR BUMPER SIDE BRACKET	SERVICEABLE	49.00	
1	REAR BUMPER CLIPS	NOT NECESSARY	22.00	
1	REAR BUMPER SPONGE	SERVICEABLE	143.40	
1	REAR BUMPER UNDER COVER	SERVICEABLE	225.00	
	LESS 20% DISCOUNT		-381.47	-
			1,525.88	
	SPECIAL NETT ITEMS			
1	REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	135.70	
1	REAR BUMPER RUBBER MAT (SN)	NOT NECESSARY	50.00	,-
			185.70	
	LABOUR			
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF REAR BUMPER .		350.00	100.00
	SPRAY PAINTING CHARGE .		250.00	200.00
	WIRING CHARGE.	NOT NECESSARY	50.00	
	R/REFIX REVERSE SENSOR .	NOT NECESSARY	120.00	
			770.00	300.00
	GRAND TOTAL		2,481.58	300.00

RECOMMENDED COST OF REPAIRS	300.00
-----------------------------	--------

Report Ref No. CC3/CTI18015421/K1jb3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own tisk.