

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5072Z**AAD1808-192***Not Authorized
11 Sep @ 9500h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5072Z

VF1ABL15AUC276166

RENAULT

LATITUDE

23.8.2018

III**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>DIT</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>DIT</i> 113.47	✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>SL</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	<i>SL</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>SL</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>DIT</i> 225.95	✓
13	1 BOOT REAR	\$	<i>Bu</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>SL</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05	X
16	1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35	X
17	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35	X
18	1 BOOT BADGE 'RENAULT'	\$	<i>Me</i> 225.36	✓
19	1 BOOT BADGE	\$	<i>Me</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08	X
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08	X
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	X
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	X
24	1 BOOT INNER TRIM	\$	<i>SL</i> 586.45	X
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13	X
26	1 BOOT LOCK	\$	<i>Me</i> 202.67	✓
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	X
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52	X
29	2 BOOT RUBBER PLUG	\$	<i>SL</i> 221.81	X

Trans-cab Auto Services Pte Ltd

AAD1808-192

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5072Z

30	1 FENDER PANEL REAR LH	\$	R	3,299.13	X
31	1 WHEELARCH REAR LH	\$	SL	543.47	X
32	1 FENDER PANEL INNER TRIM REAR RH	\$	SL	671.45	X
33	1 FENDER PANEL REAR RH	\$	R	3,299.13	X
34	1 WHEELARCH REAR RH	\$	SL	543.47	X
35	1 TAILLAMP RH	\$	mgcm	552.55	✓
36	1 TAILLAMP PANEL RH	\$	R	986.70	X
37	1 TAILLAMP LH	\$	mgcm	552.55	✓
38	1 TAILLAMP PANEL LH	\$	R	986.70	X
39	1 OUTER PANEL REAR (End Panel)	\$	Bj	1,471.77	✓
40	1 OUTER PANEL REAR (End Panel)TRIM	\$	nd	404.56	✓
41	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
42	1 SPARE WHEEL PANEL TRIM	\$	SL	612.21	X
43	1 EXHAUST REAR	\$	R	7,489.05	X
44	1 EXHAUST CAP REAR	\$	R	230.49	X

TOTAL	\$	35,197.49
10%	\$	3,519.75
	\$	31,677.74

Special Nett

1	1SET PARKING AID	\$	Shon	700.00	Boosa
2	1SET REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	SL	17.82	X
11	1SET BOOT FINISHER CLIP	\$	na	24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	na	30.00	✓
13	1 BOOT STICKER "6555-3333"	\$	na	30.00	✓
14	1 BOOT INNER TRIM CLIP	\$	na	45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X

Trans-cab Auto Services Pte Ltd**AAD1808-192**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5072Z

18	1 FENDER INNER TRIM CLIP LH	\$	<i>nn</i> 28.00 <i>X</i>
19	1 TAILLAMP CLIP RH	\$	<i>nn</i> 5.00 <i>—</i>
20	1 TAILLAMP CLIP LH	\$	<i>nn</i> 5.00 <i>—</i>
21	2 REAR WINDSCREEN SELANT	\$	<i>nn</i> 80.00 <i>X</i>
22	1 WINDSCREEN MOULDING	\$	<i>nn</i> 100.00 <i>X</i>
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00 <i>X</i>
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>nn</i> 385.00 <i>X</i>
25	1 SPARE TYRE	\$	<i>nn</i> 330.00 <i>X</i>

TOTAL \$ 2,225.02**TOTAL PARTS \$ 33,902.76****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 <i>11000</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>9000</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>600</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>600</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>600</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 <i>} 800</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 <i>} 800</i>

Trans-cab Auto Services Pte Ltd**AAD1808-192**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5072Z

To supply and re-do rear luggage floor panel
insulation padding.

\$ *nn* 380.00 *X*

To transfer of rear fender fittings, attachment and
perform water seepage test.

\$ *nn* 380.00 *X*

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ *nn* 170.00 *X*

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 *X*

To transfer of rear door fittings, attachment and
perform water seepage test.

\$ *nn* 380.00 *X***TOTAL \$ 12,540.00****Over All Total \$ 46,442.76****(LUMP SUM)****Repair Days*****20 DAYS****6 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: