

Trans-cab Auto Services Pte Ltd

AAD1808-202

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9342M

*Not Authored
Proposed L / Imp & Focul.*

Vehicle No.:

SHD 9342M

Chassis No.:

KL1LA69RJB074463

Vehicle Make:

CHEVROLET

Vehicle Model:

EPICA 2.0

Date of Accident :

23.8.2018]

Third Party Insurer :

III

PART		LIST		
1	1	Front Bumper	\$	<i>Bu Item</i> 1,202.00 ✓
2	1	Front Bumper Reinforcement	\$	<i>Bu</i> 295.25 ✓
3	1	Front Bumper Lower Absorber	\$	<i>Sm</i> 180.00 X
4	1	Front Bumper Lower Grille	\$	<i>Sm</i> 78.00 X
5	1	Front Bumper Retainer RH	\$	<i>Sm</i> 102.00 ✓
6	1	Front Bumper Retainer LH	\$	<i>Sm</i> 102.00 X
7	1	Front Bumper Lower Stiffener	\$	<i>n</i> 134.37 X
8	1	Front Headlamp RH	\$	<i>ngent</i> 816.00 ✓
9	1	Front Headlamp LH	\$	<i>ngent</i> 816.00 ✓
10	1	Front Support Panel Assy (Panel A-Frt)	\$	<i>n</i> 1,222.32 X
11	1	Bonnet (Panel A-Hood)	\$	<i>n</i> 1,250.00 X
12	1	Centre 'CHEVROLET' Logo Badge	\$	<i>n</i> 144.30 ✓
13	1	Bonnet Moulding	\$	<i>nd</i> 257.00 ✓
14	1	Radiator Grille (Grille A-Rad)	\$	<i>CMA</i> 367.00 ✓
15	1	Radiator Assembly (Radiator A)	\$	<i>Sm</i> 618.00 X
16	1	Aircon Condenser (Condenser A)	\$	<i>Sm</i> 600.00 X
17	1	Air Intercooler	\$	<i>Sm</i> 652.00 X
18	1	Fan Blade (Small)	\$	<i>CMA</i> 536.00 ✓
19	1	Fan Blade (Big)	\$	<i>Sm</i> 634.00 X
20	1	Front Fender LH	\$	<i>n</i> 837.60 X
21	1	Front Fender RH	\$	<i>n</i> 837.60 X
22	1	Rear Bumper	\$	<i>Bu</i> 1,202.00 ✓
23	1	Rear Bumper Beam	\$	<i>Bu</i> 239.94 ✓
24	1	Rear Bumper Centre Absorber	\$	<i>CMA</i> 260.00 ✓
25	1	Rear Bumper Side Retainer RH	\$	<i>Sm</i> 68.76 X
26	1	Rear Bumper Side Retainer LH	\$	<i>Diy</i> 68.76 ✓
27	1	Rear Bumper side support RH	\$	<i>Sm</i> 25.00 X

Trans-cab Auto Services Pte Ltd

AAD1808-202

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9342M

28	1	Rear Bumper side support LH	\$	SL	25.00	X
29	1	Rear Bumper Reflectors RH	\$	SL	119.74	X
30	1	Rear Bumper Reflectors LH	\$	CM	119.74	✓
31	1	Rear Bumper Tow Hook Cover	\$	SL	93.00	X
32	1	Rear Luggage Floor Panel	\$	R	973.00	X
33	1	Rear Luggage Floor Panel Insulator	\$	SL	63.50	X
34	1	Rear Luggage Floor Panel Trim Board	\$	SL	378.00	X
35	1	Rear End Panel Inner	\$	R	336.84	X
36	1	Rear End Panel Outer	\$	Bu	623.76	✓
37	1	Rear End Panel Inner Trim	\$	Dis	263.84	✓
38	1	Bootlid	\$	R	973.00	✓
39	1	Bootlid inner trim board	\$	SL	400.00	X
40	1	Bootlid Weatherstrip	\$	CM	344.28	50% SL
41	1	Bootlid Lock - Top	\$	R	466.56	✓
42	1	Bootlid lock - bottom	\$	R	39.40	X
43	1	Bootlid 'CHEVROLET' Badge	\$	R	120.62	✓
44	1	Bootlid Logo	\$	R	138.84	✓
45	1	Bootlid 'EPICA LT' Badge	\$	R	119.84	✓
46	1	Bootlid inner handle	\$	SL	45.55	X
47	1	Bootlid Reflector Centre	\$	SL	217.97	X
48	1	Bootlid Reflector RH	\$	SL	128.40	X
49	1	Bootlid Reflector LH	\$	CM	128.40	✓
50	1	Bootlid Hinge RH	\$	R	120.00	X
51	1	Bootlid Hinge LH	\$	R	120.00	X
52	1	Rear Tail Lamp RH	\$	CM	479.30	✓
53	1	Rear Tail Lamp Panel RH	\$	R	359.00	X
54	1	Rear Tail Lamp Panel LH	\$	CM	479.30	✓
55	1	Rear Tail Lamp Panel LH	\$	R	359.00	X
56	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	R	1,110.00	X
57	1	Rear Fender RH	\$	R	1,145.00	X
58	1	Rear Fender Inner Cowling RH	\$	SL	298.00	X
59	1	Rear Fender Inner Trim RH	\$	SL	418.44	X
60	1	Rear Fender LH	\$	R	1,145.00	X
61	1	Rear Fender Inner Cowling LH	\$	SL	298.00	X
62	1	Rear Fender Inner Trim LH	\$	CM	418.44	✓

Trans-cab Auto Services Pte Ltd

AAD1808-202

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9342M

TOTAL	\$	26,414.66
10%	\$	2,641.47
	\$	23,773.19

Specical Nett

1	1Set	Front Bumper Fastener Clip	\$	<i>na</i>	24.00	✓
2	1Set	Front Licence Plate With Holder	\$	<i>nd</i>	192.00	<i>205n</i>
3	1Set	Bonnet Insulator Clip	\$	<i>na</i>	40.00	X
4	1Set	Radiator Grille Clip	\$	<i>na</i>	18.00	✓
5	1Set	Bootlid inner trim board Clip	\$	<i>na</i>	40.00	X
6	1Set	Radiator Grille Top Cover Clip	\$	<i>na</i>	10.00	X
7	1Set	Front Fender Liner Clip	\$	<i>na</i>	40.00	X
8	1Set	Rear Bumper Parking Sensor	\$	<i>nd</i>	300.00	✓
9	1Set	Rear Bumper Fastener Clip	\$	<i>na</i>	30.00	✓
10	2Set	Rear Fender inner cowling clip	\$	<i>na</i>	30.00	X
11	1Set	Rear Fender Inner Trim Clip RH	\$	<i>na</i>	30.00	X
12	1Set	Rear Fender Inner Trim Clip LH	\$	<i>na</i>	30.00	X
13	1Set	Rear Bumper End Dust Cover Clip	\$	<i>na</i>	30.00	X
14	1	Rear Boot Sticker 'Trans-cab'	\$	<i>na</i>	30.00	✓
15	1	Rear Boot Sticker '6555-3333'	\$	<i>na</i>	30.00	✓
16	1	Rear Exhaust Mounting	\$	<i>sn</i>	10.00	X
17	1	Rear Bumper End Sealant	\$	<i>na</i>	80.00	X
18	2	Rear Windscreen Sealant	\$	<i>na</i>	80.00	X
19	1	Rear Windscreen Inner Sponge Seal	\$	<i>na</i>	100.00	X

TOTAL	\$	1,144.00
--------------	-----------	-----------------

TOTAL PARTS	\$	24,917.19
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$ 6,000.00 *1200n*

To Check Electrical Lighting Concerned.

\$ 170.00 *401*

Trans-cab Auto Services Pte Ltd

AAD1808-202

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9342M

To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>601</i>
Putty And Spray Painting Of The Affected Portion.	\$	4,800.00 ^{<i>14001</i>}
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 <i>601</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of end panel fittings and conduct water seepage test.	\$	170.00 <i>801</i>
Towing fees	\$	120.00 <i>501</i>
To transfer of boot fittings and conduct water seepage test.	\$	170.00 <i>601</i>
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00 <i>X</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>na</i> 170.00 <i>X</i>
To check ABS brake efficiency, final checking and testing.	\$	<i>na</i> 380.00 <i>X</i>

\$ 13,050.00

TOTAL \$ 37,967.19

20-DAYS

8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Repair Days

Acknowledged by Repairer
Signature:
Date: