

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 498G**AAD1808-177**

Not Authored
Resony B4 paint 8 3860.91

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 498G

VF1ABL15AUC283432

RENAULT

LATITUDE

21.8.2018

AIG

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bu/Ch</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68
1	BUMPER RETAINER FRT RH	\$	<i>Sn</i> 150.77
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 } X
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21
1	BUMPER BEAM FRT	\$	<i>N</i> 914.08
1	HEADLAMP RH	\$	<i>ngim</i> 1,184.43 ✓
1	HEADLAMP PANEL FRT RH	\$	<i>N</i> 152.15 X
1	HEADLAMP LH	\$	<i>Sn</i> 1,184.43 X
1	HEADLAMP PANEL FRT LH	\$	<i>N</i> 152.15 X
1	FENDER PANEL FRT RH	\$	<i>Bu</i> 783.83 ✓
1	WHEELARCH FRT RH	\$	<i>Sn</i> 278.84
1	FENDER BRACKET LOWER RH	\$	<i>Sn</i> 15.79
1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84
1	DOOR PANEL FRT RH	\$	<i>N</i> 2,844.66
1	RADIATOR GRILLE	\$	<i>Sn</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75 } X
1	RADIATOR FAN COWLING	\$	<i>Sn</i> 820.54
1	RADIATOR FAN MOTOR LH	\$	<i>Sn</i> 967.36
1	RADIATOR FAN MOTOR RH	\$	<i>Sn</i> 1,479.46
1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90
1	FRAME FULL SUPPORT BRACKET	\$	<i>N</i> 89.79
1	DOOR MIRROR ASSY RH	\$	<i>Sn</i> 1,483.40
1	DOOR PANEL FRT RH	\$	<i>N</i> 2,844.66
1	BONNET	\$	<i>N</i> 1,941.63
1	BONNET INSULATOR	\$	<i>Sn</i> 405.73

Trans-cab Auto Services Pte Ltd**AAD1808-177**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 498G

1	BONNET STRUT LH	\$	88.61
1	BONNET STRUT RH	\$	88.61
1	BONNET HINGE LH	\$	348.31
1	BONNET HINGE RH	\$	348.31
1	BONNET LOCK	\$	305.48
1	BONNET CABLE	\$	119.19
1	BONNET CABLE COVER	\$	161.03
1	BONNET SEAL OUTER	\$	92.36
1	BONNET SEAL INNER	\$	157.28
1	SUBFRAME OUTER FRT	\$	2,652.45
1	SUBFRAME BRACKET OUTER LH	\$	92.36
1	SUBFRAME BRACKET OUTER RH	\$	92.36
1	ENGINE UNDERTRAY	\$	564.98
1	A/C CONDENSER	\$	2,020.37
1	A/C CONDENSER GARNISH LH UPPER	\$	39.67
1	A/C CONDENSER GARNISH RH UPPER	\$	39.67
1	A/C CONDENSER GARNISH LH	\$	58.81
1	A/C CONDENSER GARNISH RH	\$	59.60
1	LOWER ARM RH	\$	685.76
1	KUNCKLE ARM RH	\$	846.98
1	ABSORBER FRT RH	\$	360.54
1	STABILIZER BAR FRT	\$	604.65
1	DRIVESHAFT RH	\$	1,747.45
1	WIPER RESERVOIR	\$	348.25
1	WIPER RESERVOIR NECK	\$	136.11
1	WIPER RESERVOIR MOTOR	\$	270.06

TOTAL	\$	36,963.11
10%	\$	3,696.31
	\$	33,266.80

Specical Nett

1SET	BUMPER CLIP FRT	\$	66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	12.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	X
1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	X

Trans-cab Auto Services Pte Ltd**AAD1808-177**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 498G

2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	} X
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
1SET	WHEELARCH CLIP FRT RH	\$	na	30.50	
6	BONNET INSULATOR CLIP L70Y	\$	na	7.30	
2	BONNET STRUT L70Y	\$	na	88.61	
2	BONNET CABLE CLIP L70Y	\$	na	6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	na	10.85	
1	WINDSCREEN SEALANT	\$	na	253.80	
1	FRONT WINDSCREEN MOULDING	\$	na	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	\$	na	80.00	
1	FRONT RIGHT DOOR STICKER '6555-3333'	\$	na	50.00	
1	FRONT RIGHT TYRE	\$	Sh	330.00	}
1	FRONT RIGHT TYRE RIM	\$	Sh	380.00	

TOTAL	\$	1,734.88
--------------	-----------	-----------------

TOTAL PARTS	\$	35,001.68
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	4000
Putty and spray painting of the affected portion.	\$	4,000.00	4400
To rust-proofing of the affected areas.	\$	170.00	300
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00 X
To check steering geometry and computer wheel alignment	\$	na	220.00 X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00 X

Trans-cab Auto Services Pte Ltd

AAD1808-177

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 498G

To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	nn X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	380.00	7 X
To vacuum, replace, refix and recharge air condenser	\$	380.00	5 X
To replace, refix and top up coolant for radiator	\$	170.00	5 X
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	5 X
To transfer of front windscreen fittings and conduct water seepage test	\$	170.00	5 X

TOTAL	\$	11,090.00
--------------	-----------	------------------

Over All Total	\$	46,091.68
-----------------------	-----------	------------------

PART-BY-PART (REPAIR DAY)~~15 DAYS~~

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: