

PLATINUM WERKZ PTE LTD

LKK Auto Consultants Pte Ltd 53, UBI AVENUE 1, #01-25 , PAYA UBI INDUSTRIAL PARK , SINGAPORE 408934

the Repairer of the following: **Contact: +65 6741 0610**

Email:platinumwerkz@gmail.com FAX: 67410892

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Vehicle: **SLU 1206P**

Make & Model: **TOYOTA AXIO**

Estimate

Adnan hiny
2/5 24/08/18
039ays.

No	Particular	Qty	Amount
	<u>List Price</u>		
1	Bootlid	1 PC	806.35
2	Bootlid outer garnish (CLOME)	1 PC	190.12
3	Bootlid "TOYOTA" logo	1 PC	52.52
4	Bootlid "AXIO" emblem	1 PC	48.10
5	Bootlid "COROLLA" EMBLEM	1 PC	30.65
6	Bootlid inner lock	1 PC	259.74
7	Bootlid inner trim	1 PC	251.16
8	Bootlid rubber w/strip	1 PC	212.49
9	Rear bumper	1 PC	1,142.47
10	Rear bumper brackets @ \$91.28 per pcs	2 Pcs	182.56
11	Rear bumper side retainers @ \$85.82 per pcs	2 Pcs	171.64
12	Taillamps RH	1 PC	531.03
13	Taillamp lower brackets -RH	1 PC	81.76
	Total		3,960.59
	Less 25%		(990.00)
	Sub-Total cost for parts		2,970.59
	<u>Part Replacement - Special</u>		
	<u>Nett Item</u>		
1	Rear bumper clips @ \$3.50 per pcs	8 Pcs	28.00
2	Reverse sensor	1 Set	250.00
	Sub-Total cost for parts		278.00
	<u>Labour & MISC Charges</u>		
1	Labour to panel beat,remove,refix & repair		800.00
2	Wiring charges		60.00
3	To remove & refix rear cushion seat & upholstery		180.00
4	To remove & refix reverse sensor		100.00
5	To putty & spray painting to the necessary accident parts		800.00
6	To apply undercoating to above affected areas		150.00
	Sub-Total Labour		2,090.00
	Grand Total		5,338.59