

ASS. REC. BY:

REF: CS/CTI18015448/TItd3<sup>n2</sup>

Special Instruction

menmen

Tawhida

ASSIGNMENT (Office)

From (Person):

Irene Jay

of

CFI

Date/Time:

24/8/18 @ 1:34pm

Estimated Cost:

Bill to:

OD / TP / WS / EP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT 3580A

Insured:

8JN17K

at Workshop m/s

SK Automobile

Tel:

81210478

of

1800 Lee Street # 04-44/45

Policy No:

DMPCSN 3096711701

Claim No:

SNM18DD4079C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/08/2018

CA / REV / REP. / REV 24 HRS

cup

H.O.D. Endorsement:

Date/Time:

2:10pm @ 24/8/18

Person Contacted:

Xiong

Vehicle IN/OUT

Date/Time

Action/Instruction

( Estimate

SLT 3580A - NA / CTI18015368 / 24

DOA: 20/8/18

8JN17K - X


Tanph

CT1

SLT 3580A

Type:  Car /  M Cycle /  Bus /  Van /  Lorry /  Taxi /  Prime Mover /  Truck /  Trailer  
 Make: Mazda 3  
 Colour: Grey  
 Sp. Pouch: 88333  
 Eng No: JM66N 22A8H 0149942  
 C/N: 6  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 205/60K16  
                   R: 205/60K16  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Hankook  
 Front: R/Bal: 6 mm      L/Bal: 6 mm  
           D.O.A.: 6 mm      D.O.L: 24/8/18 @ 1745  
 Survey held at: SK Auto Sun Lee  
 Des. of Damages: Frnt / Rear / O/S / N/S / UIC / Rooftop or  
 The UIC / Chassis frame / Body Structure affected due to collision.

Reg No: SLT 3580A      Expiry: 2017 April  
 Type: Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer  
 Make: Mazda 3      No: 1496  
 Colour: Grey      Insured / Std / NI / NA  
 Sp. Pouch: 88333      Radio: Insured / Std / NI / NA  
 Eng No: JM66N 22A8H 0149942  
 C/N: 6  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 205/60K16  
                   R: 205/60K16  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Hankook  
 Front: R/Bal: 6 mm      Rear: R/Bal: 6 mm  
           L/Bal: 6 mm      L/Bal: 6 mm  
 D.O.A.: 6 mm      D.O.L: 24/8/18 @ 1745  
 Survey held at: SK Auto Sun Lee  
 Des. of Damages: Frnt / Rear / O/S / N/S / UIC / Rooftop or  
 The UIC / Chassis frame / Body Structure affected due to collision.



Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: 274K  
 IDAC Accident Report: Consistent? Yes or No  
 GIA / PP Seen: Consistent? Yes or No  
 Est. Repairs: days Res.: Yes or No  
 Lump Sum: % 3 Val: Yes or No  
 CA / REV / REP: / 24 HRS  
 Date: Person Contacted: Vehicle IN / OUT

Date / Time: 14/6      Action / Instruction: Rebate 948, 987:  
4598500, 8 days - confirm with workshop. An Xiong  
(Red: 27282.44, 76%)

RECEIVED 01 JUL 2019

Date/Time: 14/6      Date/Time: 28/6  
 Action/Instr:  Preli. Report       Final Report  
 Report Format: TP  
 Lump Sum / L/S: 8500

Days Of Repair: 8  
 Resurvey No. of Trip: 1  
 Add Fee:  Gate-keep: \$  
            Information: \$  
            Tech fee: \$  
            Material: \$  
 Survey Fee:  Transport: \$  
            1st day: \$  
            2nd day: \$  
            3rd day: \$  
            4th day: \$  
            5th day: \$  
            6th day: \$  
            7th day: \$  
            8th day: \$  
            9th day: \$  
            10th day: \$  
            11th day: \$  
            12th day: \$  
            13th day: \$  
            14th day: \$  
            15th day: \$  
            16th day: \$  
            17th day: \$  
            18th day: \$  
            19th day: \$  
            20th day: \$  
            21st day: \$  
            22nd day: \$  
            23rd day: \$  
            24th day: \$  
            25th day: \$  
            26th day: \$  
            27th day: \$  
            28th day: \$  
            29th day: \$  
            30th day: \$  
            31st day: \$  
            32nd day: \$  
            33rd day: \$  
            34th day: \$  
            35th day: \$  
            36th day: \$  
            37th day: \$  
            38th day: \$  
            39th day: \$  
            40th day: \$  
            41st day: \$  
            42nd day: \$  
            43rd day: \$  
            44th day: \$  
            45th day: \$  
            46th day: \$  
            47th day: \$  
            48th day: \$  
            49th day: \$  
            50th day: \$  
            51st day: \$  
            52nd day: \$  
            53rd day: \$  
            54th day: \$  
            55th day: \$  
            56th day: \$  
            57th day: \$  
            58th day: \$  
            59th day: \$  
            60th day: \$  
            61st day: \$  
            62nd day: \$  
            63rd day: \$  
            64th day: \$  
            65th day: \$  
            66th day: \$  
            67th day: \$  
            68th day: \$  
            69th day: \$  
            70th day: \$  
            71st day: \$  
            72nd day: \$  
            73rd day: \$  
            74th day: \$  
            75th day: \$  
            76th day: \$  
            77th day: \$  
            78th day: \$  
            79th day: \$  
            80th day: \$  
            81st day: \$  
            82nd day: \$  
            83rd day: \$  
            84th day: \$  
            85th day: \$  
            86th day: \$  
            87th day: \$  
            88th day: \$  
            89th day: \$  
            90th day: \$  
            91st day: \$  
            92nd day: \$  
            93rd day: \$  
            94th day: \$  
            95th day: \$  
            96th day: \$  
            97th day: \$  
            98th day: \$  
            99th day: \$  
            100th day: \$

220



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18015448/T1td3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERSINGAPORE 079909

Date : 24-08-2018



Code : CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJN 17K	Veh. Inspected	SLT 3580A
Policy No.	DMPCSN3096711701	Coverage (\$)	0.00
Claim No.	SNM18D04079C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	24/08/2018

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	20/08/2018	Inspection Date	24/08/2018
Survey held at	SK AUTOMOBILE PTE LTD 23 KAKI BUKIT AVE 4 # 03-01 SINGAPORE 415933		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Aug 2018		24 Aug 2018 13:39 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TAN JINYEOW DAVID, ID: S1734737C		
Main Claimant:	JESSIECHAI, Co. Reg. No.: 53358731W		
Vehicle Reg. No.:	SLT3580A	Date of Loss:	20/08/2018 15:00 - :59
Claim Type:	TP / SNM18D04079C02	Policy/Cover Note No.:	DMPCSN3096711701 (Comprehensive)
Vehicle Reg. No. (Insured):	SJN17K	Policy No. (Claimant):	5095149997
		Excess:	S\$0.00
Repairer:	SK Automobile Pte Ltd (Pioneer) 1 Soon Lee Street #04-44/45, Pioneer Centre, 627605 Pioneer - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/09/2018]		
Driver/Custodian (Insured):	TAN JINYEOW DAVID (52 / Male), NRIC: S1734737C		
Adj Asg. Remarks:	NO EST, ASSIGN CHUA WEIJIE AS SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Denise Tay (LKKAuto)

---

**From:** Pioneer Workshop <pioneer@skauto.com.sg>  
**Sent:** Thursday, 13 December 2018 2:51 PM  
**To:** SUR; Admin A; Hsiao Tong (LKKAuto)  
**Cc:** JING XIONG KHOO; Simon Koh; SK Admin; Julie Johari; Susan Koh  
**Subject:** Re: FINALISED\_SLT 3580A\_DOA 20.08.2018\_MAZDA 3

Dear Taufikh

Further to our email for accident involving SLT3580A on 20 Aug 2018.

Todate we have yet to receive any reply from your side. Please do understand that the accident had occurred since 20 Aug 2018 which is almost 4 months ago. As the After Survey Calculation less 20% is \$ 11,065.60 , please advise if we can close the case at \$ 11,060.00 ?

Appreciate your understanding and expedite FINALIZATION asap please.....

Best Regards  
Susan  
C/O SK Automobile Pte Ltd

On Wed, Oct 3, 2018 at 10:28 AM Pioneer Workshop <pioneer@skauto.com.sg> wrote:

Dear Sir / Madam

Please assist to finalize the case.

Vehicle No. : SLT 3580A  
D.O.A : 20.08.2018  
Date Surveyed : 24.08.2018

Parts : 10,849.20 after less 20%  
S/Nett : 200.00  
Labour : 2,340.00  
Total 10,711.36  
Total After Less 20% : 11,065.60

Can we close the case at \$ 11,060.00

Please acknowledge finalization asap.

--

Thanks & Regards,  
Prasanna Kumar,  
SK Automobiles,  
Hp.no - 98973736.

**Lucas Lee**

---

**From:** SK Admin <admin@skauto.com.sg>  
**Sent:** Tuesday, 21 August, 2018 5:33 PM  
**To:** Claims Dept of CTI; Irene Tay; Lucas Lee  
**Cc:** JING XIONG KHOO  
**Subject:** PRI for SLT3580A Your Ref:SJN17K  
**Attachments:** SLT3580A GIA REPORT.pdf; SLT3580A PRI PC CN TP.pdf

Dear Sir / Mdm,

We the repairers of motor vehicle no. SLT3580A  
Please provide a list of surveyor for further inspection.

Location : 1 Soon Lee St #04-44/45  
Pioneer Centre  
Singapore 627605

Contact No : 8121 0478 Xiong

We appreciate your early reply.  
Thanks.

--  
Regards,  
*Huey Lee*  
SK Automobile Pte Ltd  
Tel: 6789 5155 Fax: 6783 5155

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## Denise Tay (LKKAuto)

---

**From:** Susan Koh <susan@skauto.com.sg>  
**Sent:** Monday, 22 April 2019 4:43 PM  
**To:** Denise Tay (LKKAuto)  
**Cc:** Pioneer Workshop; JING XIONG KHOO; SUR; Admin A; Hsiao Tong (LKKAuto); Simon Koh; SK Admin; Julie Johari  
**Subject:** Re: FINALISED\_SLT 3580A\_DOA 20.08.2018\_MAZDA 3

Dear Denise

Please be advise that we are unable to accept your Offer as no adjustment was made on the following Parts which were email to you on 02 Jan 2019. Please note that these List Price of Parts were from suppliers back then.

NO11-FRONT FOG LAMP \$631.00  
NO24-HEAD LAMP \$3,598.00  
NO43-BOOT LID \$1,268.80  
NO47-BOOT LID LOCK ASSY \$270.00  
NO54-TAIL LAMP \$924.00

Please confirm if we can close the case at \$ 11,060.0 ?

Appreciate your immediate settlement please.....

Best Regards  
Susan  
C/O SK Automobile Pte Ltd

On Mon, Apr 22, 2019 at 11:27 AM Denise Tay (LKKAuto) <[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)> wrote:

Dear Sir/Madam,

Our best final offer \$8500/, 8days.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

**SELL YOUR CAR BY BIDDING  
HIGHEST SELLING PRICE GUARANTEED!  
OR GET \$100 CASH!**



Mazda 3 Price Range Depreciation 2017 Vehicle Type 

Advanced Search

Home » Used Cars » Motor Universe Credit Pte Ltd » Mazda 3 1.5A

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Mazda 3 1.5A

Overview Financial Accessories Similar Research Photos Map

# MOTOR UNIVERSE CREDIT PTE LTD

Add to Shortlist Add to Compare Add a Note Report Error

More Actions Share

Car Details

<b>Price</b>	\$69,800 <i>411963 70,996.00</i>	
<b>Depreciation</b>	\$7,180 /yr <small>View models with similar depreciation</small>	
<b>Reg Date</b>	29-Aug-2017 <small>(9yrs 7days COE left)</small>	
<b>Manufactured</b>	2017	
<b>Mileage</b>	7,700 km	
<b>Transmission</b>	Auto	
<b>Engine Cap</b>	1,496 cc	
<b>Road Tax</b>	\$682 /yr	
<b>Power</b>	88.0 KW (118 bhp) <small>View specs of the Mazda 3 Sedan (2014)</small>	
<b>Curb Weight</b>	1,310 kg	
<b>Features</b>	1.5L 4 Cylinders 16 Valves DOHC SkyActiv-G Engine, 118 BHP, 6 Speed Automatic, ABS, SRS, Electric Auto Retractable Side Mirrors, Keyless Start.	
<b>Accessories</b>	Sunroof, Sports Rims, Factory Fitted Audio System Reverse Sensor, Keyless Start, Solar Films, Immobilizer.	
<b>Description</b>	1 Owner, Low Mileage At 7700km, Flexible Repayment With In House Financing. 100% Accident Free. Superb Condition Inside Out. Large Boot Space. Call Now!	
<b>COE</b>	\$46,489	
<b>OMV</b>	\$14,934	
<b>ARF</b>	\$9,934	
<b>Dereg Value</b>	\$49,405 as of today (change)	
<b>No. of Owners</b>	1	
<b>Type of Veh</b>	Mid-Sized Sedan	
<b>Category</b>	PARF Car, Almost New Car, Low Mileage Car	
<b>Availability</b>	Available	

Add to Shortlist Add to Compare Add a Note

Posted on: 03-Jul-2018 | Last Updated on: 21-Aug-2018

Tags: Mazda 3, 2017 Mazda 3, Mazda, Mazda 3, Used Mazda



Seller Information

<b>Company</b>	<b>Motor Universe Credit Pte Ltd</b> » dealer's pricelist » 61 vehs sold   57 vehs available
<b>Address</b>	210 Turf Club Road Lot A32 Search cars nearby this location
<b>Location</b>	Car Mall @ The Grandstand
<b>Office No</b>	64655595
<b>Contact Person(s)</b>	Lawrence 90260951 Benson Hu 97997507 Johnson 97376599 John Tan 98895558

Upfront Payment [» more Financial info](#)

**Transfer Fee** \$25 

**Car Tyres**




Qoo10

Buy 3 Free shipping



**Daily Deal**

Only at **\$9.5**

SHOP NOW >>

www.qoo10.sg

Compare

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Business  
Owner ID: 8731W

### Vehicle Details

Vehicle No.: SLT3580A  
Vehicle to be Exported: No  
Intended De-registration Date: 21 Aug 2018  
Vehicle Make: MAZDA  
Vehicle Model: MAZDA3 HATCHBACK 1.5 AT DELUXE EU6  
Primary Colour: Grey  
Manufacturing Year: 2017  
Engine No.: P520466676  
Chassis No.: JM6BN24A8J0176922  
Maximum Power Output: 88.0 kW (118 bhp)  
Open Market Value: \$19,603.00  
Original Registration Date: 26 Oct 2017  
First Registration Date: 26 Oct 2017  
Transfer Count: 0  
Actual ARF Paid: \$14,603.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 25 Oct 2027  
PARF Rebate Amount: \$10,952.00

### Intended COE Rebate Details

COE Expiry Date: 25 Oct 2027  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$42,902.00  
COE Rebate Amount: \$39,372.00  
**Total Rebate Amount: \$50,324.00**

The information contained herein is correct as at 21 Aug 2018

OK

\$ 70,996.00

\$ 50,324.00

\$ 20,672.00

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/08/2018 12:09
Date Of Accident	20/08/2018 15:45
Exact Location Of Accident	AYE > CITY AFTER PORTSDOWN EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT3580A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	JESSIECHAI
Co Reg No	53358731W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90000000

### Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.5 HATCHBACK L SP.6EAT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095149997
Cover Note Number	

### Driver

Name of Driver	LEE JUN MING
NRIC No	S9106000J
Date Of Birth	18/02/1991
Occupation	OUTDOOR
Date Of Driving Pass	20/07/2010
Driving Experience	8 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-82238099
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 662C #14-308 JURONG WEST STREET 64
Postcode	643662
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - SOLE-PROPIETOR
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJN17K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJR7577J
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name LEE JUN MING  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SLT3580A  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance?  
Address BLK 662C #14-308 JURONG WEST STREET 64  
Postcode 543662

## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

JESSIECHAI  
Co Reg No: 53358731W

Policyholder's Signature  
Date & Time:

JESSIECHAI  
Co Reg No: 53358731W


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

21 AUG 2018

IDAC KAKI BUKIT (VAC)

33 KAKI BUKIT AVE 4  
Reporting Centre Personal Signature  
Name: Singapore 415933  
NRIC/FIN No: Tel: 67416697  
Fax: 67492305  
Email: vackb@singnet.com.sg

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20/08/2018 at 03:45pm, I was driving at NKF towards city after portdown exit. I was on lane 1 my front car slow down and stop I follow suit suddenly vehicle B (S1N17K) hit into my rear caused my vehicle A (S1T3580A) moved forwards and collided into vehicle C (S1P15777). Due to the impact my vehicle A (S1T3580A) front and rear badly damaged. total 3 vehicle involved in the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

JESSIECHAI  
Co Reg No: 53358731W

Policyholder's Signature  
Date & Time:

JESSIECHAI  
Co Reg No: 53358731W

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

21 AUG 2018

IDAC KAKI BUKIT (VAC)

Reporting Centre Person's Signature  
Name: Singapore 415933  
Tel: 67416697  
NRIC/FIN No. Fax: 67492305  
Email: vackb@singnet.com.sg



24	HEADLAMP	1/2	\$ 1,623.30	\$ 3,246.60	LH-X, RH- <del>cm</del>
25	FRONT FENDER INNER SHIELD	1/2	\$ 115.30	\$ 230.60	X LH-X, RH- <del>cm</del>
26	FRONT SUPPORT PANEL	1	\$ 886.90	\$ 886.90	x nn
27	RADIATOR AIR GUIDE	2	\$ 135.30	\$ 270.60	de-
28	A/C CONDENSER	1	\$ 976.30	\$ 976.30	X
29	HORN	2	\$ 96.30	\$ 192.60	X
30	RADIATOR	1	\$ 1,527.50	\$ 1,527.50	X } nn
31	RADIATOR FAN MOTOR	2	\$ 460.10	\$ 920.20	X
32	RADIATOR FAN MOTOR COWLING	1	\$ 611.60	\$ 611.60	X
33	RADIATOR FAN BLADE	2	\$ 311.60	\$ 623.20	X
34	REVERSE SENSOR	2	\$ 290.00	\$ 580.00	2000mm SN
35	REVERSE SENSOR WIRE HARNESS	1	\$ 610.00	\$ 610.00	X nn
36	REAR BUMPER	1	\$ 1,023.90	\$ 1,023.90	de-
37	REAR BUMPER REFLECTOR	2	\$ 154.30	\$ 308.60	x nn 58.30 nn
38	REAR BUMPER TOWING COVER	1/2	\$ 58.30	\$ 116.60	LH-mis, RH-X
39	REAR BUMPER RETAINER	2	\$ 79.80	\$ 159.60	de-
40	REAR BUMPER CENTER BRACKET	1	\$ 19.80	\$ 19.80	x nn
41	REAR BUMPER REINFORCEMENT	1	\$ 796.70	\$ 796.70	bt-538
42	REAR BUMPER SIDE COVER	1	\$ 72.30	\$ 72.30	x nn
43	BOOT LID	1	\$ 1,499.40	\$ 1,499.40	bt-958 1150
44	BOOT LID OUTER GARNISH	1	\$ 410.00	\$ 410.00	de-235.70
45	BOOT LID INNER TRIM	1	\$ 712.00	\$ 712.00	x nn
46	BOOT LID HINGE	2	\$ 120.80	\$ 241.60	x nn
47	BOOT LID LOCK ASSY	1	\$ 280.40	\$ 280.40	bt-153 198
48	BOOT LID STRIKER	1	\$ 56.20	\$ 56.20	x nn
49	BOOT LID STOPPER	2	\$ 18.10	\$ 36.20	x nn
50	BOOT LID EMBLEM	1	\$ 108.90	\$ 108.90	ner-
51	BOOT LID EMBLEM "MAZDA 3"	1	\$ 94.70	\$ 94.70	ner-
52	BOOT LID EMBLEM "SKYACTIVE"	1	\$ 87.50	\$ 87.50	ner-
53	BOOT LID WEATHER STRIP	1	\$ 172.80	\$ 172.80	x nn 766
54	TAILLAMP	1/2	\$ <sup>509.40</sup> 1,040.40	\$ 2,080.80	X LH-cut, RH-X 509.40 nn
55	REAR END PANEL	1	\$ 676.30	\$ 676.30	Rx
56	REAR END PANEL TOP GARNISH	1	\$ 180.10	\$ 180.10	X
57	REAR FENDER SIDE INNER TRIM	2	\$ 644.00	\$ 1,288.00	X
58	REAR FENDER COWLING	2	\$ 218.00	\$ 436.00	X
59	BOOT LID INNER TRIM	1	\$ 398.70	\$ 398.70	X
60	REAR FLOOR PANEL TOP BOARD	1	\$ 245.70	\$ 245.70	X } nn
61	REAR FLOOR PANEL TOOLS SPONGE	1	\$ 487.00	\$ 487.00	X
62	REAR EXHAUST PIPE	1	\$ 879.20	\$ 879.20	X
63	REAR EXHAUST MOUNTING	2	\$ 19.20	\$ 38.40	X

TOTAL PRICE \$ 33,479.30

9494.70  
20% 7595.76

LESS 20%                    \$ 6,695.86  
**SUB TOTAL PRICE**       **\$ 26,783.44**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	NUMBER PLATE	✓2	\$ 50.00	\$ 100.00
2	FRONT BUMPER CLIP SET	1	\$ 65.00	\$ 65.00
3	FRONT BUMPER LOWER GRILLE CLIP SET	1	\$ 38.00	\$ 38.00
4	BONNET INSULATOR CLIP SET	1	\$ 65.00	\$ 65.00
5	FRONT GRILLE CLIP SET	1	\$ 30.00	\$ 30.00
6	FRONT FENDER INNER COWLING CLIP SET	1	\$ 78.00	\$ 78.00
7	FRONT SUPPORT PANEL SEALANT	1	\$ 80.00	\$ 80.00
8	BATTERY	1	\$ 250.00	\$ 250.00
9	RADIATOR COOLANT	3	\$ 45.00	\$ 135.00
10	REAR BUMPER CLIP SET	1	\$ 65.00	\$ 65.00
11	BOOT LID INNER TRIM CLIP SET	1	\$ 65.00	\$ 65.00
12	BOOT LID OUTER GARNISH CLIP SET	1	\$ 60.00	\$ 60.00
13	TAIL LAMP CLIP SET	1	\$ 35.00	\$ 35.00
14	REAR WHEELARCH LINER CLIP SET	1	\$ 58.00	\$ 58.00
15	REAR WINDSCREEN SEALANT	1	\$ 60.00	\$ 60.00
16	REAR WINDSCREEN INNER SEALANT	1	\$ 60.00	\$ 60.00
17	REAR FENDER SIDE INNER TRIM RH CLIP SET	1	\$ 65.00	\$ 65.00
18	REAR END PANEL SEALANT	1	\$ 80.00	\$ 80.00
19	REAR FLOOR PANEL INSULATOR	1	\$ 250.00	\$ 250.00

30  
 Frt-ut ✓  
 30 over  
 X un  
 X un  
 ✓  
 X }  
 X } un  
 X }  
 30 over  
 X un  
 20 over  
 X un  
 X un  
 X 30 over  
 30 over  
 X }  
 X } un  
 X }  
 200.

**TOTAL**                    **\$ 1,639.00**

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)**

1	CUT OFF AND REPLACE FRONT SUPPORT PANEL. RESTRUCTURE FRONT CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS.	\$ 1,400.00	400	
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	\$ 1,300.00	500	
3	DISMANTLE AND REPLACE A/C CONDENSER ASSY. REFILL, RECHARGE A/C REFRIGERANT GAS AND PERFORM PRESSURE TEST.	\$ 180.00	X un	
4	REMOVE AND INSTALL RADIATOR ASSY. PERFORMED RADIATOR PRESSURE TEST	\$ 150.00	X un	
5	ADJUST AND FOCUS FRONT LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION	\$ 80.00	30	
6	REMOVE AND INSTALL ENGINE WIRE HARNESS. RESET ENGINE WARNING LIGHT SYSTEM WITH ON-BOARD DIAGNOSTIC COMPUTER.	\$ 150.00	X un	

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

1	CUT OFF, REPLACE REAR END PANEL AND FLOOR PANEL. STRAIGHTEN, REALIGN REAR CHASSIS FRAME AND RENEW OTHER DAMAGE PARTS.	\$ 1,600.00	600	
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	\$ 1,500.00	600	
3	DISMENTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS.	\$ 120.00	X hr	
4	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY TESTING.	\$ 150.00	30	
5	DISMENTLE AND INSTALL REAR SEATS, SPEAKER BOARD AND SEATS TRIMMING.	\$ 150.00	60	
6	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUCTION.	\$ 80.00	30.	
7	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA.	\$ 100.00	X hr	
8	TRANSFER BOOT LID ATTACHMENT AND MECHANISM INTO NEW POWER BOOT LID ASSY. RE-ALIGN TO POSITION.	\$ 200.00	60.	
9	APPLY TUFF COATING TREATMENT.	\$ 200.00	30	

**TOTAL**

**\$ 7,360.00**

2340

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 28,422.44  
 TOTAL LABOUR COST : \$ 7,360.00  
 TOTAL REPAIR COST : \$ 35,782.44

Part - 7595.76

SN - 200

Labour - 2340

10,135.76

10635.76

45/8100 #

8 days

45/8500 #

**APPROVED DETAILS**

EXCESS :  
 NO. OF WORKING DAY :  
 RE-SURVEY

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY  
 SURVEYED BY  
 CONTACT NUMBER  
 FAX NUMBER

**LKK Auto Consultants** hence notify the Repairer of the following:  
 • Resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modifications allowed  
 • Supplementary items, not for resurvey, and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Taufik 97495749

WP

24/8/18 @ 1745

8 days

Resurvey after repair 27/8/18

sur@lkkauto.com



SK Automobile Pte Ltd  
 (Co Reg. No. 201500047H)  
 1 Soon Lee Street #04-44/45  
 Pioneer Centre  
 Singapore 627605

Tel: 6262 4438 Fax: 6484 1111

TO	: CHINA TAIPING	DATE	: 23-Aug-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SLT3580A
ADDRESS	:	MODEL	: MAZDA 3
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT : KUMAR 9897 3736			

P: 9801  
 SN: 200  
 LB: 2340  
 12,341  
 - 2,468 20%  
 9,873

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER	1	\$ 1,264.40	\$ 1,264.40
2	FRONT BUMPER TOWING COVER	1	\$ 45.60	\$ 45.60
3	FRONT BUMPER LOWER GRILLE	1	\$ 308.50	\$ 308.50
4	FRONT BUMPER REINFORCEMENT	1	\$ 750.10	\$ 750.10
5	FRONT BUMPER REINFORCEMENT COVER	1	\$ 285.60	\$ 285.60
6	FRONT BUMPER SIDE RETAINER	2	\$ 86.50	\$ 173.00
7	FRONT BUMPER LOWER SUPPORT	1	\$ 190.00	\$ 190.00
8	FRONT SIGNAL LAMP	2	\$ 340.00	\$ 680.00
9	FRONT FOG LAMP GARNISH	2	\$ 277.80	\$ 555.60
10	FRONT BUMPER FOG LAMP CHROME	2	\$ 118.00	\$ 236.00
11	FRONT BUMPER FOG LAMP	2	\$ 318.00	\$ 636.00
12	FRONT BUMPER FOG LAMP BRACKET	2	\$ 72.00	\$ 144.00
13	FRONT BUMPER LOWER COVER	1	\$ 189.20	\$ 189.20
14	FRONT GRILLE	1	\$ 970.10	\$ 970.10
15	FRONT GRILLE UPPER GARNISH	1	\$ 318.00	\$ 318.00
16	FRONT GRILLE CHROME MOULDING	2	\$ 276.40	\$ 552.80
17	FRONT GRILLE EMBLEM	1	\$ 104.90	\$ 104.90
18	FRONT GRILLE TOP GARNISH	1	\$ 320.50	\$ 320.50
19	FRONT GRILLE SUPPORT BRACKET	2	\$ 58.00	\$ 116.00
20	BONNET	1	\$ 1,458.40	\$ 1,458.40

825  
 de  
 xnn  
 xnn  
 xnn  
 xnn  
 67  
 140  
 x LH-X, RH-CR  
 351  
 nn. 205.50  
 x LH-X, RH-CR  
 72  
 x LH-X, RH-CR  
 de  
 325  
 xnn  
 LH-X, RH-CR 276.4  
 de  
 LH-X RH-CR 58  
 1068

\$631

11.2

1300  
1157.90  
1020

\$ 3598

24	HEADLAMP	1/2	\$ 1,623.30	\$ 3,246.60
25	FRONT FENDER INNER SHIELD	1/2	\$ 115.30	\$ 230.60
26	FRONT SUPPORT PANEL	1	\$ 886.90	\$ 886.90
27	RADIATOR AIR GUIDE	2	\$ 135.30	\$ 270.60
28	A/C CONDENSER	1	\$ 976.30	\$ 976.30
29	HORN	2	\$ 96.30	\$ 192.60
30	RADIATOR	1	\$ 1,527.50	\$ 1,527.50
31	RADIATOR FAN MOTOR	2	\$ 460.10	\$ 920.20
32	RADIATOR FAN MOTOR COWLING	1	\$ 611.60	\$ 611.60
33	RADIATOR FAN BLADE	2	\$ 311.60	\$ 623.20
34	REVERSE SENSOR	2	\$ 290.00	\$ 580.00
35	REVERSE SENSOR WIRE HARNESS	1	\$ 610.00	\$ 610.00
36	REAR BUMPER	1	\$ 1,023.90	\$ 1,023.90
37	REAR BUMPER REFLECTOR	2	\$ 154.30	\$ 308.60
38	REAR BUMPER TOWING COVER	1/2	\$ 58.30	\$ 116.60
39	REAR BUMPER RETAINER	2	\$ 79.80	\$ 159.60
40	REAR BUMPER CENTER BRACKET	1	\$ 19.80	\$ 19.80
41	REAR BUMPER REINFORCEMENT	1	\$ 796.70	\$ 796.70
42	REAR BUMPER SIDE COVER	1	\$ 72.30	\$ 72.30
43	BOOT LID	1	\$ 1,499.40	\$ 1,499.40
44	BOOT LID OUTER GARNISH	1	\$ 410.00	\$ 410.00
45	BOOT LID INNER TRIM	1	\$ 712.00	\$ 712.00
46	BOOT LID HINGE	2	\$ 120.80	\$ 241.60
47	BOOT LID LOCK ASSY	1	\$ 280.40	\$ 280.40
48	BOOT LID STRIKER	1	\$ 56.20	\$ 56.20
49	BOOT LID STOPPER	2	\$ 18.10	\$ 36.20
50	BOOT LID EMBLEM	1	\$ 108.90	\$ 108.90
51	BOOT LID EMBLEM "MAZDA 3"	1	\$ 94.70	\$ 94.70
52	BOOT LID EMBLEM "SKYACTIVE"	1	\$ 87.50	\$ 87.50
53	BOOT LID WEATHER STRIP	1	\$ 172.80	\$ 172.80
54	TAILLAMP	2	\$ 509.40 1,040.40	\$ 2,080.80
55	REAR END PANEL	1	\$ 676.30	\$ 676.30
56	REAR END PANEL TOP GARNISH	1	\$ 180.10	\$ 180.10
57	REAR FENDER SIDE INNER TRIM	2	\$ 644.00	\$ 1,288.00
58	REAR FENDER COWLING	2	\$ 218.00	\$ 436.00
59	BOOT LID INNER TRIM	1	\$ 398.70	\$ 398.70
60	REAR FLOOR PANEL TOP BOARD	1	\$ 245.70	\$ 245.70
61	REAR FLOOR PANEL TOOLS SPONGE	1	\$ 487.00	\$ 487.00

LH-X, RH-CH  
X LH-X, RH-CH  
X nn  
de-  
X  
X } nn  
X  
X }  
200 nn  
X nn  
de-  
X nn  
58.30, nn  
LH-mis, RH-X  
de-  
X nn  
bt-538  
X nn  
bt-958 X 1150  
de-235.70  
X nn  
X nn  
bt-153 X 198  
X nn  
X nn  
de-  
de-  
de-  
X nn  
509.40 nn  
X LH-CH, RH-X  
Ry.  
X  
X  
X  
X }  
10076.50  
8061.20  
X  
101197.  
207.-8095.76.

\$ 1265

\$ 270

\$ 924

9494.70

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CT118015448/T1TD3N2

**Date:** 01/07/2019

#### REFERENCE

<b>Handling Insurer:</b>	China Taiping Insurance (Singapore) Pte. Ltd.	<b>Policy No:</b>	DMPCSN3096711701
<b>Claimant Vehicle No :</b>	SLT3580A	<b>Insured Vehicle No :</b>	SJN17K
<b>Date of Loss:</b>	20/08/2018	<b>Nature of Claim:</b>	TP
		<b>Claim No:</b>	SNM18D04079C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	SLT3580A	<b>Engine No:</b>	P520466676
<b>Make &amp; Model:</b>	MAZDA 3, 1.5 HATCHBACK L SP.6EAT (A)	<b>Chassis No:</b>	JM6BN24A8J0176922
<b>Reg. Date:</b>	26/10/2017 (Man. Year: 2017)	<b>Odometer:</b>	88333 km
<b>Colour:</b>	Grey		
<b>Engine Capacity:</b>	1496 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (S\$):</b>	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

<b>General Condition:</b>	<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>	

#### CONDITION OF TYRES

<b>Front Tyre Size:</b>	205/60R16	<b>Rear Tyre Size:</b>	205/60R16
<b>Front Left Side:</b>	Hankook 6 mm	<b>Rear Left Side:</b>	Hankook 6 mm
<b>Front Right Side:</b>	Hankook 6 mm	<b>Rear Right Side:</b>	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	28,422.44	8,461.20	19,961.24	70.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,360.00	2,340.00	5,020.00	68.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>35,782.44</b>	<b>10,801.20</b>	<b>24,981.24</b>	<b>69.81</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,500.00</b>		
	(S\$)	35,782.44	8,500.00	27,282.44
	<b>+ GST 7.00/7.00% (S\$)</b>	2,504.77	595.00	1,909.77
	<b>Nett Amount (S\$)</b>	<b>38,287.21</b>	<b>9,095.00</b>	<b>29,192.21</b>

#### INSPECTION

<b>Date of Assignment:</b>	24/08/2018	<b>Inspected At:</b>	1 Soon Lee Street #04-44/45 Pioneer Centre Singapore 627605 Repairer:SK Automobile Pte Ltd
<b>Date Inspected:</b>	24/08/2018		

**Estimated Period of Repair:** 8.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 01 Jul 2019)
<b>Parts:</b> 144	MAZDA 3 1.5 HATCHBACK L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLT3580A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,264.40 FL	*825.00 FL
2	1		*FRONT BUMPER TOWING COVER	Not Necessary	45.60 FL	*- FL
3	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	308.50 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	750.10 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT COVER	Cracked	285.60 FL	*67.00 FL
6	2		*FRONT BUMPER SIDE RETAINER	Necessary	173.00 FL	*173.00 FL
7	1		*FRONT BUMPER LOWER SUPPORT	Not Necessary	190.00 FL	*- FL
8	1		*FRONT SIGNAL LAMP	O/s Cracked/N/s Not Necessary	680.00 FL	*140.00 FL
9	2		*FRONT FOG LAMP GARNISH	Not Necessary	555.60 FL	*- FL
10	2		*FRONT BUMPER FOG LAMP CHROME	Not Necessary	236.00 FL	*- FL
11	1		*FRONT BUMPER FOG LAMP	O/s Cut/N/s Not Necessary	636.00 FL	*351.00 FL
12	1		*FRONT BUMPER FOG LAMP BRACKET	O/s Cracked/N/s Not Necessary	144.00 FL	*72.00 FL
13	1		*FRONT BUMPER LOWER COVER	Deformed	189.20 FL	*189.20 FL
14	1		*FRONT GRILLE	Cracked	970.10 FL	*325.00 FL
15	1		*FRONT GRILLE UPPER GARNISH	Not Necessary	318.00 FL	*- FL
16	1		*FRONT GRILLE CHROME MOULDING	O/s Cracked/N/s Not Necessary	552.80 FL	*276.40 FL
17	1		*FRONT GRILLE EMBLEM	Necessary	104.90 FL	*104.90 FL
18	1		*FRONT GRILLE TOP GARNISH	Deformed	320.50 FL	*320.50 FL
19	1		*FRONT GRILLE SUPPORT BRACKET	O/s Cracked/N/s Not Necessary	116.00 FL	*58.00 FL
20	1		*BONNET	Bent	1,458.40 FL	*1,068.00 FL
21	1		*BONNET LOCK	Not Necessary	208.60 FL	*- FL
22	2		*BONNET HINGE	Repair	311.20 FL	*- FL
23	1		*BONNET WEATHERSTRIP	Not Necessary	77.30 FL	*- FL
24	1		*HEADLAMP	O/s Cracked/N/s Not Necessary	3,246.60 FL	*1,300.00 FL
25	1		*FRONT FENDER INNER SHIELD	O/s Torn/N/s Not Necessary	230.60 FL	*115.30 FL
26	1		*FRONT SUPPORT PANEL	Not Necessary	886.90 FL	*- FL
27	2		*RADIATOR AIR GUIDE	Deformed	270.60 FL	*270.60 FL
28	1		*A/C CONDENSER	Not Necessary	976.30 FL	*- FL
29	2		*HORN	Not Necessary	192.60 FL	*- FL
30	1		*RADIATOR	Not Necessary	1,527.50 FL	*- FL
31	2		*RADIATOR FAN MOTOR	Not Necessary	920.20 FL	*- FL
32	1		*RADIATOR FAN MOTOR COWLING	Not Necessary	611.60 FL	*- FL
33	2		*RADIATOR FAN BLADE	Not Necessary	623.20 FL	*- FL
34	1		*REVERSE SENSOR WIRE HARNESS	Not Necessary	610.00 FL	*- FL
35	1		*REAR BUMPER	Deformed	1,023.90 FL	*1,023.90 FL
36	2		*REAR BUMPER REFLECTOR	Not Necessary	308.60 FL	*- FL
37	1		*REAR BUMPER TOWING COVER	N/s Missing/O/s Not	116.60 FL	*58.30 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	2		*REAR BUMPER RETAINER	Necessary Deformed	159.60 FL	*159.60 FL
39	1		*REAR BUMPER CENTER BRACKET	Not Necessary	19.80 FL	*- FL
40	1		*REAR BUMPER REINFORCEMENT	Bent	796.70 FL	*538.00 FL
41	1		*REAR BUMPER SIDE COVER	Not Necessary	72.30 FL	*- FL
42	1		*BOOT LID	Bent	1,499.40 FL	*1,150.00 FL
43	1		*BOOT LID OUTER GARNISH	Deformed	410.00 FL	*235.70 FL
44	1		*BOOT LID INNER TRIM	Not Necessary	712.00 FL	*- FL
45	2		*BOOT LID HINGE	Not Necessary	241.60 FL	*- FL
46	1		*BOOT LID LOCK ASSY	Bent	280.40 FL	*198.00 FL
47	1		*BOOT LID STRIKER	Not Necessary	56.20 FL	*- FL
48	2		*BOOT LID STOPPER	Not Necessary	36.20 FL	*- FL
49	1		*BOOT LID EMBLEM	Necessary	108.90 FL	*108.90 FL
50	1		*BOOT LID EMBLEM MAZDA 3	Necessary	94.70 FL	*94.70 FL
51	1		*BOOT LID EMBLEM SKTACTIVE	Necessary	87.50 FL	*87.50 FL
52	1		*BOOT LID WEATHERSTRIP	Not Necessary	172.80 FL	*- FL
53	1		*TAILLAMP	N/s Cut/O/s Not Necessary	2,080.80 FL	*766.00 FL
54	1		*REAR END PANEL	Repair	676.30 FL	*- FL
55	1		*REAR END PANEL TOP GARNISH	Not Necessary	180.10 FL	*- FL
56	2		*REAR FENDER SIDE INNER TRIM	Not Necessary	1,288.00 FL	*- FL
57	2		*REAR FENDER COWLING	Not Necessary	436.00 FL	*- FL
58	1		*BOOT LID INNER TRIM	Not Necessary	398.70 FL	*- FL
59	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	245.70 FL	*- FL
60	1		*REAR FLOOR PANEL TOOLS SPONGE	Not Necessary	487.00 FL	*- FL
61	1		*REAR EXHAUST PIPE	Not Necessary	879.20 FL	*- FL
62	2		*REAR EXHAUST MOUNTING	Not Necessary	38.40 FL	*- FL
63	2		*REVERSE SENSOR	Not Working	464.00 FS	*200.00 FS
64	1		*NUMBER PLATE (2 Pcs)	Frt Cut	100.00 FS	*30.00 FS
65	1		*SET FRONT BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
66	1		*SET FRONT BUMPER LOWER GRILLE CLIP	Not Necessary	38.00 FS	*- FS
67	1		*SET BONNET INSULATOR CLIP	Not Necessary	65.00 FS	*- FS
68	1		*SET FRONT GRILLE CLIP	Necessary	30.00 FS	*30.00 FS
69	1		*SET FRONT FENDER INNER COWLING CLIP	Not Necessary	78.00 FS	*- FS
70	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
71	1		*BATTERY	Not Necessary	250.00 FS	*- FS
72	3		*RADIATOR COOLANT	Not Necessary	135.00 FS	*- FS
73	1		*SET REAR BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
74	1		*SET BOOT LID INNER TRIM CLIP	Not Necessary	65.00 FS	*- FS
75	1		*SET BOOT LID OUTER GARNISH CLIP	Necessary	60.00 FS	*20.00 FS
76	1		*SET TAIL LAMP CLIP	Not Necessary	35.00 FS	*- FS
77	1		*SET REAR WHEELARCH INNER CLIP	Not Necessary	58.00 FS	*- FS
78	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*30.00 FS
79	1		*REAR WINDSCREEN INNER SEALANT	Necessary	60.00 FS	*30.00 FS
80	1		*SET REAR FENDER SIDE INNER TRIM RH CLIP	Not Necessary	65.00 FS	*- FS
81	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
82	1		*REAR FLOOR PANEL INSULATOR	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>35,002.30</b>	<b>10,476.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>6,579.86</b>	<b>2,015.30</b>
<b>Total Parts (\$\$)</b>	<b>28,422.44</b>	<b>8,461.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CUT OFF AND REPLACE FRONT SUPPORT PANEL.RESTRUCTURE FRONT CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS	New	1,400.00	400.00
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA	New	1,300.00	500.00
3	DISMANTLE AND REPLACE A/C CONDENSER ASSY,REFILL.RECHARGE A/C REFRIGERANT GAS AND PERFORM PRESSURE TEST	New	180.00	0.00
4	REMOVE AND INSTALL RADIATOR ASSY.PERFORMED RADIATOR PRESSURE TEST	New	150.00	0.00
5	ADJUST AND FOCUS FRONT LIGHTING SYSTEM.PERFORM HEADLAMP ADJUSTMENT TO POSITION	New	80.00	30.00
6	REMOVE AND INSTALL ENGINE WIRE HARNESS.RESET ENGINE WARNING LIGHT SYSTEM WITH ON-BOARD DIAGNOSTIC COMPUTER	New	150.00	0.00
7	CUT OFF REPLACE REAR END PANEL AND FLOOR PANEL.STRAIGHTEN,REALIGN REAR CHASSIS FRAME AND RENEW OTHER DAMAGE PARTS	New	1,600.00	600.00
8	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA	New	1,500.00	600.00
9	DISMANTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS	New	120.00	0.00
10	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS.PERFORM DISTANCE SENSORY TESTING	New	150.00	30.00
11	REMOVE AND INSTALL REAR SEATS,SPEAKER BOARD AND SEATS TRIMMING	New	150.00	60.00
12	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUNCTION	New	80.00	30.00
13	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA	New	100.00	0.00
14	TRANSFER BOOT LID ATTACHMENT AND MECHANISM INTO NEW POWER BOOT LID ASSY.RE-ALIGN TO POSITION	New	200.00	60.00
15	APPLY TUFF COATING TREATMENT	New	200.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,360.00</b>	<b>2,340.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >