

BOTAK DEE AUTO

Repair for all kinds of Motor Vehicle
 Workshop : No. 10 Industrial Park 2A #04-11
 Ang Mo Kio Autopoint Singapore 568047
 Company Reg No. 53203907J Hp 91004390 / Hp 91254449 Fax 64841482
 Email : botakbeeauto@gmail.com

M/s First Capital Insurance Ltd	DATE	21.08.2018
36 Robinson Road #16-01 City House	CAR NO	SDV 1694 C
Singapore 068877	MAKE	Honda Jazz

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.

YOUR INSURED : ~~SKD 1536D~~ SHC 7455 P

Pc	Pcs	Description	UNIT PRICE	AMOUNT
		Continue from page one.		\$4,407.10
		Remove and replace front bumper, cut and replace new left front fender & support panel, panel beat and realign front bonnet and all accident affected portion into correct position.		\$1,400.00 800
		Respray painting for front bonnet cover, front bumper, front support panel, front brace panel and front left side fender.	2030	\$1,200.00 900
		Computer alignment and jack camber.		\$120.00 60
		To check head lamp electrical wiring system include performing water leakage test.		\$80.00 30
		Check electrical wiring and head lamp focusing for proper functions.		\$100.00 30
		To spray anti-rust coating on new & affected panels.		\$150.00 60
		Remove and replace new under carriage parts such as knuckle arm, lower arm, wheel hub & bearing and etc.		\$350.00 150

Rasul
 Hp 90060068

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pg 2 of 2

8 days

4/5
 24/08/18 @ 1600

Resurvey after repair

Total 7,807.10

2167.12
 300
 2030
 4497.12
 200
 3597.69

4/5 - 3,600 8 days