



Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005 90219187

ESTIMATE

Repair Code : CLM14728

Date in : 14/08/2018

Vehicle Num. : SLP6967U

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31218309/LEB5918318

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR RH DOOR ✓	1	930.60	930.60
REAR RH DOOR BLACK TAPE ✓	1	35.00	35.00
REAR RH DOOR CHECKER X	1	57.50	57.50
REAR RH DOOR GLASS OUTER MOULDING X	1	65.00	65.00
REAR RH DOOR HINGE (LOWER) X	1	45.60	45.60
REAR RH DOOR HINGE (TOP) X	1	45.60	45.60
REAR RH DOOR MECHANISM LOCK ?	1	253.30	253.30
REAR RH DOOR OUTER HANDLE X ?	1	98.00	98.00
REAR RH DOOR TRANSPARENT STICKER ✓	1	35.00	35.00
REAR RH DOOR WEATHER STRIP X	1	85.00	85.00
Subtotal before discount			1,650.60
Percentage discount 20%			330.12
Sub-total 1			1,320.48
Parts-total			1,650.60

LABOUR

To remove, reinstall window glass. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

600 80.00
80.00
300 450.00
200 400.00



Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005 90219187

ESTIMATE

Repair Code : CLM14728

Date in : 14/08/2018

Vehicle Num. : SLP6967U

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31218309/LEB5918318

To apply anti-rust chemical on repaired and replaced panel.

	40	100.00
Labour Total		1,110.00
Parts & Labour Total		2,760.60

*** This is a computer-generated document which requires no signature.***

page 2

3 Days.
Lump sum repair.
After repair photos.
Gmo Riap - 82880282
28/8/18

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: