

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG	DATE	: 24/08/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SGU3223K		
MODEL	: TOYOTA ESTIMA 2.4A		
CHASSIS NO			Thin Thin.
ACCIDENT DETAILS		DATE	: 21-Aug-18
		TIME	: 14:00HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR <i>dent</i>	1	\$ 1,455.90	\$ 1,455.90
2	REAR DOOR OUTER CHROME <i>new</i>	1	\$ 320.00	\$ 320.00
3	REAR DOOR OUTER PROTECTOR <i>dent</i>	1	\$ 620.00	\$ 620.00
4	REAR FENDER <i>Repair</i>	1	\$ 1,300.00	\$ 1,300.00
5	REAR FENDER OUTER PROTECTOR <i>missing</i>	1	\$ 180.00	\$ 180.00
6	REAR QUARTER GLASS MOULDING <i>new</i>	1	\$ 189.00	\$ 189.00
7	REAR SHOCK ABSORBER <i>2</i>	1	\$ 480.00	\$ 480.00
8	REAR KNUCKLE ARM	1	\$ 320.00	\$ 320.00
9	REAR KNUCKLE ARM BEARING	2	\$ 260.00	\$ 520.00
10	REAR UPPER ARM	1	\$ 390.00	\$ 390.00
11	REAR LOWER ARM	1	\$ 280.00	\$ 280.00
12	REAR BUMPER <i>dent</i>	1	\$ 1,230.00	\$ 1,230.00
13	REAR BUMPER SIDE RETAINER (FRONT) <i>new</i>	1	\$ 105.00	\$ 105.00
14	REAR BUMPER SIDE RETAINER (REAR) <i>new</i>	1	\$ 105.00	\$ 105.00
15	REAR BUMPER SIDE SPONGE <i>new</i>	1	\$ 190.00	\$ 190.00

359090

269317

TOTAL PRICE	\$ 7,684.90
LESS 25%	\$ 1,921.23
SUB TOTAL PRICE	\$ 5,763.68

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS(SET) <i>Net</i>	1	\$ 20.00	\$ 20.00
2	REAR QUARTER GLASS SEALANT <i>Not Rec</i>	1	\$ 30.00	\$ 30.00
3	WHEEL TYRE <i>Not Rec</i>	1	\$ 550.00	\$ 550.00
4	WHEEL RIM <i>Lot</i>	1	\$ 2,800.00	\$ 2,800.00

570

TOTAL

\$ 3,400.00

+ 550
+ 550

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,600.00	500.
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	700.
3	TUFF COAT	\$ 250.00	x
4	WIRING BULB CHECKING	\$ 80.00	30
5	REMOVE & REFIX REAR DOOR FITTING	\$ 180.00	80
6	REMOVE & REFIX REVERSE SENSOR & DISTANCE SETTING	\$ 80.00	60.
7	REMOVE & REFIX REAR QUARTER GLASS	\$ 80.00	x
8	FOUR WHEEL ALIGNMENT	\$ 250.00	80.
9	TO REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 80.00	x
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL

\$ 3,980.00

1450

ESTIMATE REPORT

TOTAL PARTS COST : \$ 9,163.68

TOTAL LABOUR COST : \$ 3,980.00

TOTAL REPAIR COST : \$

APPROVED DETAILS

SURVEYOR

CONTACT NO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King.
1/5 24/08/18
04 Days

total: 4713.17.
1/5 3.7K