

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7999S**AAD1808-184***Not Authorized
L1 By @*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7999S

KL1LA69RJBB122371

CHEVROLET

EPICA 2.0

23.8.2018

III**PART****LIST**

1	1	Front Fender LH	\$	<i>R</i>	837.60	} X
2	1	Front Fender Liner LH	\$	<i>Su</i>	47.00	
3	1	Front Fender Inner Wheel House Panel LH	\$	<i>R</i>	1,437.00	
4	1	Front Shock Absorber Assy LH	\$	<i>Su</i>	216.17	
5	1	Front Shock Absorber Top Mounting LH	\$	<i>Su</i>	48.32	
6	1	Front Lower Arm LH	\$	<i>Su</i>	283.00	} X
7	1	Front Knuckle Arm LH	\$	<i>Su</i>	230.00	
8	1	Front Door LH	\$	<i>warp / By</i>	1,133.00	
9	1	Front Door Glass Guide RH Chrome Moulding	\$	<i>Su</i>	60.00	} X
10	1	Front Door Outer Moulding	\$	<i>Su</i>	220.00	
11	1	Front Door Outer Handle	\$	<i>Su</i>	125.00	
12	1	Front Door Handle Support	\$	<i>Su</i>	3.00	
13	1	Front Door outer handle inner seal	\$	<i>Su</i>	89.15	
14	1	Front Door outer key lock	\$	<i>R</i>	25.00	
15	1	Front Door Hinge Upper	\$	<i>R</i>	65.00	
16	1	Front Door Hinge Lower	\$	<i>R</i>	65.00	
17	1	Front Door inner lock	\$	<i>R</i>	586.00	
18	1	Front Door Inner Lock Latch LH	\$	<i>R</i>	206.00	
19	1	Front Door Check / Arrestor	\$	<i>Su</i>	67.50	
20	1	Front Door Weatherstrip LH	\$	<i>Su</i>	138.79	
21	1	Front Door glass channel weatherstrip	\$	<i>Su</i>	160.00	
22	1	Front Door inner trim board	\$	<i>Su</i>	455.69	
23	1	Front Door window glass	\$	<i>Su</i>	456.12	
24	1	Front Door Power Window Motor (Master) LH	\$	<i>Su</i>	284.97	
25	1	Front Door power window motor switch	\$	<i>Su</i>	145.00	
26	1	Front Door Window Regulator Gear LH	\$	<i>Su</i>	84.58	
27	1	Front Door Outer Pillar Panel LH	\$	<i>R</i>	715.00	

Trans-cab Auto Services Pte Ltd

AAD1808-184

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7999S

28	1	Front Door Pillar Inner Panel LH	\$	R	850.00	X
29	1	Front Door Center Pillar Panel LH	\$	R	698.15	X
30	1	Front Side View Mirror Assy LH	\$	Bu	1,191.00	✓
31	1	Rear Door LH (Panel A-RR DR LH)	\$	Bu	1,133.00	✓
32	1	Rear door weatherstrip - Inner	\$	Sn	41.40	} X
33	1	Rear door weatherstrip - 2nd Frame	\$	Sn	25.90	
34	1	Rear door top hinge	\$	R	35.00	
35	1	Rear door bottom hinge	\$	R	35.00	
36	1	Rear door inner lock	\$	R	425.00	
37	1	Rear door check / arrestor	\$	Sn	65.00	
38	1	Rear door lock striker / latch	\$	R	120.00	} X
39	1	Rear door outer weatherstrip moulding	\$	Sn	85.00	
40	1	Side Rocker Panel Garnish LH	\$	R	236.40	} X
41	1	Rear Fender LH	\$	Bu	1,145.00	✓
42	1	Rear Fender Inner Trim LH	\$	Sn	418.44	X
43	1	Front Side Rocker Panel Garnish LH	\$	Sn	236.40	X
44	1	Front Side Rocker Panel Outer LH	\$	R	600.00	X
45	1	Front Side Rocker Panel Inner LH	\$	R	519.30	X
46	1	Rear Bumper	\$	Bu	1,202.00	✓
47	1	Rear Bumper Beam	\$	R	239.94	X
48	1	Rear Bumper Centre Absorber	\$	Sn	260.00	X
49	1	Rear Bumper Side Retainer RH	\$	Sn	68.76	X
50	1	Rear Bumper Side Retainer LH	\$	Dis	68.76	✓
51	1	Rear Bumper Reflectors RH	\$	Sn	119.74	X
52	1	Rear Bumper Reflectors LH	\$	Sn	119.74	X
53	1	Rear Bumper Tow Hook Cover	\$	Sn	93.00	X

TOTAL	\$	18,215.82
10%	\$	1,821.58
	\$	16,394.24

Specical Nett

1 Set	Front Fender Liner clip	\$	nn	30.00	X
1	Front Fender RR Bracket LH	\$	R	7.10	X
1	Rear Wheel Rim Hub Cap LH	\$	Se	166.30	X

Trans-cab Auto Services Pte Ltd

AAD1808-184

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7999S

1	Rear Tyre LH	\$	144SN	Pu	180.00	803SN
1	Rear Tyre Rim LH	\$		B	126.00	50SN
1	Front left door sticker 'Trans-cab'	\$		na	80.00	60SN
1	Rear rear door sticker '6555-3333'	\$		na	80.00	60SN
1Set	Rear Bumper Parking Sensor	\$		SN	300.00	X
1Set	Rear Bumper Fastener Clip	\$		na	44.00	✓
1Set	Rear Fender Inner Trim Clip LH	\$		na	30.00	X
1Set	Rear Bumper End Dust Cover Clip	\$		na	30.00	X

TOTAL	\$	1,073.40
--------------	-----------	-----------------

TOTAL PARTS	\$	17,467.64
--------------------	-----------	------------------

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00	201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	9001
Putty and spray painting of the affected portion.	\$	4,000.00	12001
Towing Fees.	\$	120.00	501
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	?
To check steering geometry and computer wheel alignment	\$	220.00	601
To transfer of tire, rim and on wheel balancing.	\$	170.00	201
To rust-proofing of the affected areas.	\$	170.00	901

Trans-cab Auto Services Pte Ltd

AAD1808-184

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7999S

To check steering geometry and computer wheel alignment

\$ *Repaired* 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ 170.00 X

To transfer of door fittings, attachment and perform water seepage test.

\$ 170.00 *1201*

To transfer of fender fittings, attachment and perform water seepage test.

\$ 170.00 *1001*

TOTAL \$ 10,460.00

Over All Total \$ 27,927.64

Repair Days (Lump Sum)

15 days

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: