

ASS. REC. BY:

REF:

CS/TP18015505/KHber

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

09 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 5830C

Yr Regn:

08, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1995

Colour:

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

286271

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VI-1ABC15AUC-282211

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modl:

M11 / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

R/Bal.

2

mm

Rear

R/Bal.

2

mm

L/Bal.

2

mm

L/Bal.

2

mm

D.O.A.

17/8/18

D.O.I.

21/8/18

Survey held at

Des. of Damages:

Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/8

File pass to Catherine

11 Pm 813,400 (Red: 52947-53 : 79%)

24.08.2018

Kenneth say submit Independent report

SHC 5830C - 08 / 07 / 18 / 14562 / Kpob

Handler with.

Email Invoice first then give report after payments

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

11.30/8 Typist

Date/Time, File Return to?

2)

Days Of Repair:

9

Resurvey No. of Trlp:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fixins

Others

TOTAL

36x15=

1704840

50

16

80

1156

Report Format:

Lump Sum / I.B.I: (\$

TP

13400

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2018 10:45
Date Of Accident	17/08/2018 19:35
Exact Location Of Accident	T-JUNCTION OF MARINA GARDEN DRIVE & CENTRAL BLVD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5830C
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	TOH KOK PHENG
NRIC No	S7322297D
Date Of Birth	22/06/1973
Occupation	OUTDOOR
Date Of Driving Pass	21/08/2009
Driving Experience	8 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96682356
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 615B EDGEFIELD PLAINS #11-339
Postcode	822615
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 4	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 17/08/18 AT ABOUT 1935HRS, I WAS STATIONARY ALONG THE FIRST LANE AT THE JUNCTION OF MARINA GARDEN DRIVE AND CENTRAL BLVD. WHEN THE TRAFFIC LIGHT TURNS GREEN, I PROCEED TO MAKE THE TURN INTO CENTRAL BLVD. AS THERE WERE PEDESTRIAN CROSSING THE ROAD, I STOPPED MY VEHICLE AND SHORTLY AFTER THAT I FELT AN IMPACT FROM THE REAR. VEHICLE B(SHC7601J) HAD FAILED TO STOP IN TIME AND COLLIDED ONTO THE REAR OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE TOO LARGE
Was there any audio recorded?	NO

Vehicle Registration Number	SHC7601J
Vehicle Make/Model/Colour	CITY CAB
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TOH KOK PHENG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHC5830C
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GIA Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 3878K

Vehicle Details

Vehicle No.: SHC5830C

Vehicle to be Exported: Yes

Intended De-registration Date: 20 Aug 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour: Red

Manufacturing Year: 2015

Engine No.: M9R8839C002827

Chassis No.: VF1ABL15AUC282211

Maximum Power Output: 127.0 kW (170 bhp)

Open Market Value: \$19,998.00

Original Registration Date: 03 Aug 2015

First Registration Date: 03 Aug 2015

Transfer Count: 0

Actual ARF Paid: \$19,998.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 02 Aug 2023

PARF Rebate Amount: \$14,998.00

Intended COE Rebate Details

COE Expiry Date: 02 Aug 2023

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$50,236.00

COE Rebate Amount: \$31,093.00

Total Rebate Amount: \$46,091.00**Message**

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 20 Aug 2018

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5830C**AAD1808-150**

Not Notarized
1/ Sep @ 13, 400h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5830C

VF1ABL15AUC282211

RENAULT

LATITUDE

17.8.2018

III**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>Not / Bu</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>CM</i> 113.47	✓
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sm</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sm</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>Sm</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>CM</i> 135.97	✓
8	1 BUMEP R RETAINER LH REAR	\$	<i>CM</i> 44.99	✓
9	1 BUMPER REFLECTOR LH	\$	<i>Bu</i> 43.61	✓
10	1 BUMPER BEAM REAR	\$	<i>Bu</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	X
13	1 BOOT REAR	\$	<i>Bu</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>Sm</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>D. J. / Bu</i> 323.05	✓
16	1 BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35	X
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sm</i> 493.35	✓
18	1 BOOT BADGE 'RENAULT'	\$	<i>Me</i> 225.36	✓
19	1 BOOT BADGE	\$	<i>Me</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>Sm</i> 276.08	} X
21	1 BOOT STRUT RH	\$	<i>Sm</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>Sm</i> 586.45	
25	1 BOOT SWITCH	\$	<i>Sm</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>Sm</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>Sm</i> 221.81	

11364.36

Trans-cab Auto Services Pte Ltd**AAD1808-150**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5830C

30	1 FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13	✓
31	1 WHEELARCH REAR LH	\$	<i>CM</i> 543.47	✓
32	1 FENDER PANEL INNER TRIM REAR RH	\$	<i>R</i> 671.45	X
33	1 FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13	X
34	1 WHEELARCH REAR RH	\$	<i>SL</i> 543.47	X
35	1 TAILLAMP RH	\$	<i>SL</i> 552.55	X
36	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70	X
37	1 TAILLAMP LH	\$	<i>BR</i> 552.55	✓
38	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70	✓
39	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77	✓
40	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>CM</i> 404.56	✓
41	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i> 2,189.88	X
42	1 SPARE WHEEL PANEL TRIM	\$	<i>SL</i> 612.21	X
43	1 EXHAUST REAR	\$	<i>R</i> 7,489.05	} X
44	1 EXHAUST CAP REAR	\$	<i>SL</i> 230.49	
45	1 CHASSIS PANEL REAR LH	\$	<i>R</i> 3,766.43	
46	1 KUCKLE ARM REAR LH	\$	<i>SL</i> 736.67	
47	1 BRAKE DISC REAR L70Y	\$	<i>SL</i> 525.91	
48	1 WHEEL HUB NUT L70Y	\$	<i>SL</i> 51.11	
49	1 WHEEL HUB CAP L70Y	\$	<i>SL</i> 57.82	
50	1 ABS SENSOR REAR LH	\$	<i>SL</i> 255.75	
51	1 REAR AXLE L70Y	\$	<i>SL</i> 4,167.03	
52	1 AXLE ARM LH	\$	<i>SL</i> 117.22	
53	1 LOWER ARM REAR LH	\$	<i>SL</i> 905.99	} 49160.63
54	1 ABSORBER REAR	\$	<i>SL</i> 389.75	
55	1 STABILIZER BAR REAR LH	\$	<i>SL</i> 604.65	
56	1 BRAKE CALIPER REAR LH	\$	<i>SL</i> 1,300.67	
57	1 WHEEL HOUSING PANEL REAR LH	\$	<i>R</i> 4,682.09	
58	1 CHASSIS PANEL REAR LH	\$	<i>R</i> 3,766.43	
TOTAL		\$	56,525.01	56524.99
10%		\$	5,652.50	5652.50
		\$	50,872.51	50872.50

Special Nett

1	1SET PARKING AID	\$	<i>Short</i> 700.00	<i>Good</i>
2	1SET REAR BUMPER CLIP	\$	<i>RM</i> 66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>RM</i> 33.00	✓
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>RM</i> 10.00	X

Trans-cab Auto Services Pte Ltd**AAD1808-150**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5830C

5 1SET BUMPR RETAINER RH CLIP RR	\$	na	20.00	X
6 1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7 1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	X
8 1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10 1 EXHAUST MOUNTING REAR	\$	sn	17.82	X
11 1SET BOOT FINISHER CLIP	\$	na	24.20	X
12 1 BOOT STICKER "Trans-cab"	\$	na	30.00	✓
13 1 BOOT STICKER "6555-3333"	\$	na	30.00	✓
14 1 BOOT INNER TRIM CLIP	\$	na	45.00	X
15 1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
16 1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	✓
17 1 FENDER INNER TRIM CLIP LH	\$	na	28.00	✓
18 1 FENDER INNER TRIM CLIP RH	\$	na	28.00	X
19 1 TAILLAMP CLIP RH	\$	na	5.00	X
20 1 TAILLAMP CLIP LH	\$	na	5.00	✓
21 2 REAR WINDSCREEN SELANT	\$	na	80.00	40sn
22 1 WINDSCREEN MOULDING	\$	na	100.00	✓
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	30sn
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn	385.00	X
25 1 SPARE TYRE	\$	sn	330.00	X
26 1 LEFT REAR TYRE	\$	sn	330.00	X
27 1 LEFT REAR TYRE RIM	\$	sn	380.00	X

TOTAL \$ 2,935.02**TOTAL PARTS \$ 53,807.53** 53807.51**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	1100l
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	1200l
To Rust-Proofing Of The Affected Areas.	\$	170.00	90l

Trans-cab Auto Services Pte Ltd

AAD1808-150

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5830C

To reinstall rear bumper parking sensor.	\$	170.00	602
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 100
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	nn 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	nn 380.00	X

TOTAL \$ 12,540.00 12920**Over All Total \$ 66,347.53** 66727.51**(LUMP SUM)****Repair Days****20 DAYS**

9 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TRANS-CAB AUTO SERVICES PTE LTD		Ref : CS/TP18015505/Ktbe2		
NO.2 ANG MO KIO STREET 63SINGAPORE 569111		Date : 03-09-2018		
		Code : TP378		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SHC 5830C	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		21/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	VF1ABL15AUC282211	Colour	METALLIC WHITE / RED	
Odometer	286271	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	8 mm	
L/H Front Tyre	215/60 R16	GITI	8 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/08/2018	Inspection Date	21/08/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5830C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER REAR	BENT	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED / CUT	768.84	768.84
1	BUMPER BRACKET CTR REAR	CRACKED	113.47	113.47
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	CRACKED	135.97	135.97
1	BUMPER RETAINER LH REAR	CRACKED	44.99	44.99
1	BUMPER REFLECTOR LH	BROKEN	43.61	43.61
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR	BENT	2,872.68	2,872.68
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	DISTORTED / DENTED	323.05	323.05
1	BOOT REFLECTOR LAMP LH	CRACKED	493.35	493.35
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-

Report Ref No. CS/TP18015505/Ktbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER PANEL REAR LH	BENT	3,299.13	3,299.13
1	WHEELARCH REAR LH	CRACKED	543.47	543.47
1	FENDER PANEL INNER TRIM REAR RH	TO REPAIR SEE LABOUR	671.45	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	BROKEN	552.55	552.55
1	TAILLAMP PANEL LH	BENT	986.70	986.70
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	CRACKED	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	SERVICEABLE	230.49	-
1	CHASSIS PANEL REAR LH	TO REPAIR SEE LABOUR	3,766.43	-
1	KNUCKLE ARM REAR LH	SERVICEABLE	736.67	-
1	BRAKE DISC REAR L70Y	SERVICEABLE	525.91	-
1	WHEEL HUB NUT L70Y	SERVICEABLE	51.11	-
1	WHEEL HUB CAP L70Y	SERVICEABLE	57.82	-
1	ABS SENSOR REAR LH	SERVICEABLE	255.75	-
1	REAR AXLE L70Y	SERVICEABLE	4,167.03	-
1	AXLE ARM LH	SERVICEABLE	117.22	-
1	LOWER ARM REAR LH	SERVICEABLE	905.99	-
1	ABSORBER REAR	SERVICEABLE	389.75	-
1	STABILIZER BAR REAR LH	SERVICEABLE	604.65	-
1	BRAKE CALIPER REAR LH	SERVICEABLE	1,300.67	-
1	WHEEL HOUSING PANEL REAR LH	TO REPAIR SEE LABOUR	4,682.09	-
1	CHASSIS PANEL REAR LH	TO REPAIR SEE LABOUR	3,766.43	-
	LESS 10% DISCOUNT		-5,652.50	-1,439.08
			50,872.49	12,951.76

Report Ref No. CS/TP18015505/Ktbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>SPECIAL NETT ITEMS</u>				
1	SET PARKING AID (SN)	SHORTED	700.00	600.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NECESSARY	35.00	35.00
1	FENDER INNER TRIM CLIP LH (SN)	NECESSARY	28.00	28.00
1	FENDER INNER TRIM CLIP RH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NECESSARY	5.00	5.00
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	30.00
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
1	LEFT REAR TYRE (SN)	SERVICEABLE	330.00	-
1	LEFT REAR TYRE RIM (SN)	SERVICEABLE	380.00	-
			2,935.02	1,063.00
<u>LABOUR</u>				
PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.			6,000.00	1,100.00

Report Ref No. CS/TP18015505/Ktbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK, BOOT LOCK CATCH, FENDER PANEL INNER TRIM REAR RH, FENDER PANEL REAR RH, TAILLAMP PANEL RH, SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL), EXHAUST REAR, CHASSIS PANEL REAR LH, WHEEL HOUSING PANEL REAR LH AND CHASSIS PANEL REAR LH.		4,200.00	1,200.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	90.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	100.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST. }		170.00	-
	TO SUPPLY AND RE-FO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			12,920.00	2,730.00
GRAND TOTAL			66,727.51	16,744.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,400.00

Report Ref No. CS/TP18015505/Ktbe2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.