T & T Auto Services Pte Ltd

160 Sin Ming Drive #08-14 Sin Ming AutoCity Singapore 575722 Tel: 6266 6876 Fax: 6266 6861

Not Notharr **ESTIMATE** 16 C/Ly & 7 DATE VEHICLE NO MAKE/MODE ACC DATE STELLA KUEK YIXIN : 27/08/2018 34 WOODLANDS DRIVE 16 VEHICLE NO : SJT 8664 H MAKE/MODEL : Toyota Harrier **SINGAPORE 737771** : 08/08/2018 PARTICULAR AMOUNT S\$ LIST ITEMS:

		EIDT TIENID.				
1	1	REAR BUMPER			Bur 665.60	_
2	1	REAR BUMPER REINFORCEMENT			795.90	
3	1	REAR BUMPER SPONGE			CM 180.20	_
4	2	REAR BUMPER REFLECTOR	MISSWX	115.20	ols 7 230.40	•
5	1	REAR SILENCER BOX			885.60	7
6	2	REAR SILENCER MOUNTING		85.60	nr 171.20	-
7	1	REAR EXHAUST PIPE MUFFLER (CHROM	E)		ne 140.20	
8	1	REAR END PANEL			717.20	
9	1	REAR END PANEL TOP GARNISH			255.40	
					4,041.70	
			Less Discount:	25%	1,010.43	
					3,031.28	

SPECIAL NETT ITEMS: Ma 50.00 1 10 REAR BUMPER CLIP 2 4 REAR END PANEL TOP GARNISH CLIP 20.00 7 2 REAR REVERSE SENSOR 350.00 7 420.00

	LABOUR CHARGES:		
1	TO CHECK WIRING	50.00	15/
2	TO TUFF KOTE	250.00	7
3	TO REMOVE EXHAUST PIPE	150.00	601
4	TO REMOVE/REFIX REVERSE SENSOR	100.00	501
5	TO REMOVE/REFIX UPHOLSTERY, CUSHION SEAT & ROOF LINING	150.00	7
6	TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS	1,100.00	7
7	TO SPRAY PAINTING ON AFFECTED AREA	1,000.00	45d
		2,800.00	(

GRAND TOTAL:

6,251.28

Singapore Dollars: Six Thousand Two Hundred And Fifty One And Cents Twenty Eight Only.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

T & T Auto Services Pte Ltd