



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 27.08.2018

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01/02
AXA Tower
Singapore 068811

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2991K TOYOTA VELLFIRE (2012)

To Supply

1) 1pc	Rear bumper	\$	1,785.00	DE
2) 1set	Rear bumper clip	\$	30.00	me
3) 1pc	Rear right bumper tow hook cover	\$	59.80	act
4) 1pc	Rear left bumper tow hook cover	\$	59.80	act
5) 1pc	Tail gate	\$	2,200.00	PH
6) 1pc	Tail gate "Vellfire" emblem	\$	80.00	me
7) 1pc	Tail gate "Toyota" logo	\$	90.00	me
8) 1pc	Tail gate "Hybrid Synergy Drive" emblem	\$	60.00	me
9) 1pc	Tail gate "E-Four" emblem	\$	70.00	me
10) 1pc	Tail gate weatherstrip	\$	282.00	me
11) 1pc	Tail gate lamp	\$	326.80	?
12) 1pc	Rear end panel	\$	804.10	repair
13) 1pc	Rear end panel top garnish	\$	400.00	?
14) 1set	Rear end panel top garnish clip	\$	30.00	me
15) 1pc	Rear bumper center right parking sensor (Genuine)	\$	290.00	me
16) 1pc	Rear bumper center left parking sensor (Genuine)	\$	290.00	me
17) 1pc	Rear bumper center right parking sensor cover (Genuine)	\$	25.00	me
18) 1pc	Rear bumper center left parking sensor cover (Genuine)	\$	25.00	me
19) 1pc	Spare wheel carrier	\$	470.00	repair
20) 1pc	Spare wheel carrier bolt	\$	85.00	X

Sub total parts	\$	7,462.50
Less: 25% discount	\$	1,865.62
	\$	5,596.88

To Supply S.Nett Parts

1) 1pc	"Prime Taxi" sticker	\$	55.00 125
2) 1set	Rear glass seal	\$	1000 245.10 1000 X
3) 1tube	Rear glass sealant	\$	45.00 125

Sub total S.Nett Parts \$ 345.10

L/charges

1)	To tuff kote	\$	100.00 60
2)	To remove & refit rear glass	\$	120.00 ✓
3)	To remove & refit center reverse sensor & sensor, reset reverse sensor light. Check wiring	\$	60.00 ✓
4)	To transfer tail gate trim cover, handle, glass & mechanism part.	\$	120.00 80
5)	To cut / welding rear end panel, knock / repair floor panel. Remove rear bumper, tail gate & etc. Replace the above parts. Align & adjust rear bumper and tail gate.	\$	1,000.00 700
6)	To putty, respray painting rear bumper, end panel, tail gate inlet & outer, floor panel, tow hook cover & reverse sensor cover in pearl white. To polish	\$	1,200.00 850

Sub total L/charges \$ 2,600.00
Estimated Grand total \$ 8,541.98

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

RASUL
Hp 9001068
6 days
43
28/08/18 @ 0955
Reg after repair