

SLP Motoring Services

Blk 10 Ang Mo Kio Industrial Park 2A AMK Autopoint #03-08

Singapore 568047 HP 91004390/HP 91254449 Fax 64841482

Email: slpmotoring@gmail.com

M/s	AXA Insurance Pte Ltd	DATE	03.09.2018
	8 Shenton Way #27-02	CAR NO	SKV 547 T
	Singapore 068811	MAKE	Honda Mobilio

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SLP 1082 E

Pc	Pcs	Chassis No. : MRHDD4870FP000204	UNIT PRICE	AMOUNT
1	pc	Rear boot lid		\$886.30
1	pc	Rear boot lid "H" logo		\$27.50
1	pc	Rear boot lid "Mobilio"		\$25.00
1	pc	Rear boot lid rubber		\$96.70
1	pc	Rear bumper		\$463.70
1	pc	Rear bumper left side reflector		\$25.00
1	pc	Rear end panel		\$314.70
1	pc	Rear end panel top garnish		\$60.80
1	pc	Rear end panel top garnish clips	\$3.80	\$22.80
		Rust-proofing on the rear accident affected portions	60	\$120.00
		Straightening, repairing and realigning onto rear two side mudguard, cutting rear end panel, dismantle and replace the above mentioned parts	500	\$1,100.00
		To spray painting on tail gate inner/outer, rear end panel & rear bumper in pearl white.	600	\$1,100.00
		To apply silicon onto rear wind screen (2 tube).	60	\$120.00
		To dismantle & refix rear wind screen.	120	\$180.00
			Total	\$4,542.50

SLP Motoring Services

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: