

(INSUR)

INS. CASE OWNER:

JNS

CCV ASM
/AXA1801

5518

K J 352

LKK:
IDAC:

Surveyor:

KSL

DOI:

ASSIGNMENT

26/8/18

Date / Time:

27/8/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMA 4855P

Name of Insured:

TAM LOR MEN

Insured Tel No.:

HP:

86.29294

Excess Sec II :SS

D.O.A:

20/8/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

88MUUSWT 65142

Policy No.:

CW873750

Make / Model:

TOYOTA

Place of Accident:

SERRANON RD

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SJM 247E

INSRS:
WSP:
Tel:
Liability:
RMKS:

TAT

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

26/8/18
204

SJM 247E - X

SMA 4855P - X

* Amv claim.

10-9-18 @ 325 W/OI MR TAN. (CONFIRMED)
AGREED & AWARE NCD
ISSUE. HE HAS NCD PROTECTION

RECEIVED 12 SEP 2018

STAGE	DATE / PIC	
Non-Reporting ltr (1st):		
Non-Reporting ltr (2nd):		
Non-Reporting ltr (Final):		
Notification ltr (if non-pickup):		
Call OI:	204 10-9-18	
After call ltr to OI:		
Documentation Check List: Handler Typist		
Notification ltr (if non-pickup):	☒	☐
After call ltr to OI:	☒	☐
Authorisation To Act:	☒	☐
Release Voucher:	☒	☐
Final Repair Bill:	☒	☐
Car Rental Invoice:	☒	☐
Towing Invoice:	☒	☐
LTA / GIA :	☒	☐
Medical Bill:	☒	☐
PIR:	☒	☐
Mandate/Reject Instruction:	☒	☐
LOD:	☒	☐
Payment Breakdown Form:	☒	☐
Post-Repair Photos:	☒	☐
Others:	☒	☐

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	SS	(days) Reduction:	%
FINAL SETTLEMENT		Date/Time:	Confirm with:
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:	27
Repair Cost:	SS	4,012.50	
Loss of Rental (LOR):	SS	360	3 days x 120
Loss of Use (LOU):	SS	(S x days)	
Loss of Income (LOI):	SS	(S x days)	
LOR only ☐ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	[Tick only one]	
GIA/LTA Search:	SS	7.45	
Medical:	SS		
Disbursement:	SS	(e.g. Tow/Independent)	
Legal Cost:	SS		
Total:	SS	4,379.95	Global Sum SS: 4,350.00
FINAL PAYMENT		Date/Time:	Confirm with:
Payee 1:	SS	4,350	Name 1: T&T AUTO SERVICES PTE LTD
Payee 2: (Strike if N.A.)	SS	X	Name 2: X
Payee 3: (Strike if N.A.)	SS		Name 3: X

COPY SENT
27/8/18

REF: ASM (AXA)

ASSIGNMENT

From: Date: 28082018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: SM 2443E

at Workshop m/s

at: 160 Sin Ming Dr # 08-14

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

29/8 15k pass to Customer

L/S \$3,750

R(\$3,745.20/50%)

Veh No: SM 2443E Yr Reg: 16/12 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal:

L/Bal:

D.O.A:

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Prel. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Report Format:

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + P + SI

Photos

Other

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18015518/jb3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 27-08-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMA 4855P	Veh. Inspected	SJM 2443E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	27/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/08/2018	Inspection Date		
Survey held at	T&T AUTO SERVICES PTE LTD BLK 160 SIN MING DRIVE #08-14 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

T & T Auto Services Pte Ltd

160 Sin Ming Drive
#08-14 Sin Ming AutoCity
Singapore 575722
Tel: 6266 6876 Fax: 6266 6861

STARS RENTAL & LEASING
50 SERANGOON NORTH AVE 4
#02-19 FIRST CENTRE
SINGAPORE 555856

Not withain
61 hr 837501

ESTIMATE

DATE : 27/08/2018
VEHICLE NO : SJM 2443 E
MAKE/MODEL : Mercedes E200
ACC DATE : 20/08/2018

PARTICULAR

- LIST ITEMS:
- 1 1 REAR BUMPER
 - 2 1 REAR BUMPER INNER FRAME
 - 3 1 REAR BUMPER REINFORCEMENT
 - 4 1 REAR BUMPER CHROME - CENTER
 - 5 2 REAR BUMPER CHROME - SIDE
 - 6 2 REAR BUMPER SIDE BRACKET
 - 7 1 REAR END PANEL
 - 8 1 REAR END PANEL TOP GARNISH

AMOUNT S\$

<i>Br</i>	1,670.00	<i>✓</i>
<i>cm</i>	265.00	<i>✓</i>
<i>Br</i>	655.00	<i>2</i>
<i>Br</i>	245.00	<i>✓</i>
<i>Br</i>	310.00	<i>✓</i>
155.00	72.00	<i>✓</i>
36.00	786.00	<i>✓</i>
	225.00	<i>✓</i>
	4,228.00	
Less Discount:	10%	422.80
		3,805.20

- SPECIAL NETT ITEMS:
- 1 10 REAR BUMPER CLIP
 - 2 8 REAR END PANEL TOP GARNISH CLIP
 - 3 1 REAR REVERSE SENSOR (SET)

<i>Br</i>	50.00	<i>✓</i>
<i>Br</i>	40.00	<i>✓</i>
<i>shan</i>	850.00	<i>600.00</i>
	940.00	

- LABOUR CHARGES:
- 1 TO CHECK WIRING
 - 2 TO TUFF KOTE
 - 3 TO REMOVE/REFIX REAR SENSOR
 - 4 TO REMOVE/REFIX UPHOLSTERY, CUSHION SEAT & ROOF LINING
 - 5 TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS
 - 6 TO SPRAY PAINTING ON AFFECTED AREA

<i>Br</i>	50.00	<i>150</i>
<i>Br</i>	250.00	<i>✓</i>
	100.00	<i>600</i>
	150.00	<i>500</i>
	1,100.00	<i>600</i>
	1,100.00	
	2,750.00	

GRAND TOTAL: 7,495.20

Singapore Dollars Seven Thousand Four Hundred And Ninety Five And Cents Twenty Only.

T & T Auto Services Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

T & T Auto Services Pte Ltd

160 Sin Ming Drive
#08-14 Sin Ming AutoCity
Singapore 575722
Tel: 6266 6876 Fax: 6266 6861

STARS RENTAL & LEASING
50 SERANGOON NORTH AVE 4
#02-19 FIRST CENTRE
SINGAPORE 555856

Not Withain
6/1/18

ESTIMATE

DATE : 27/08/2018
VEHICLE NO : SJM 2443 E
MAKE/MODEL : Mercedes E200
ACC DATE : 20/08/2018

PARTICULAR

AMOUNT S\$

LIST ITEMS:				
1	1 REAR BUMPER		<i>Bu</i> 1,670.00	✓
2	1 REAR BUMPER INNER FRAME		265.00	?
3	1 REAR BUMPER REINFORCEMENT		655.00	?
4	1 REAR BUMPER CHROME - CENTER		<i>m</i> 245.00	—
5	2 REAR BUMPER CHROME - SIDE	155.00	<i>m</i> 310.00	—
6	2 REAR BUMPER SIDE BRACKET	36.00	<i>MSD</i> 72.00	✓
7	1 REAR END PANEL		786.00	?
8	1 REAR END PANEL TOP GARNISH		<i>m</i> 225.00	X
			4,228.00	
Less Discount:		10%	422.80	
			3,805.20	

SPECIAL NETT ITEMS:

1	10 REAR BUMPER CLIP		<i>m</i> 50.00	✓
2	8 REAR END PANEL TOP GARNISH CLIP		<i>m</i> 40.00	X
3	1 REAR REVERSE SENSOR (SET)		850.00	?
			940.00	

LABOUR CHARGES:

1	TO CHECK WIRING		50.00	15/
2	TO TUFF KOTE		250.00	?
3	TO REMOVE/REFIX REAR SENSOR		100.00	60/
4	TO REMOVE/REFIX UPHOLSTERY, CUSHION SEAT & ROOF LINING		150.00	?
5	TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS		1,100.00	?
6	TO SPRAY PAINTING ON AFFECTED AREA		1,100.00	60/
			2,750.00	

GRAND TOTAL: 7,495.20

Singapore Dollars: Seven Thousand Four Hundred And Ninety Five And Cents Twenty Only.


T & T Auto Services Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Service Request Details

Claim

S8M00SWT

Reference

None 

Loss Date

August 20, 2018

Request Date

August 24, 2018

Due Date

August 31, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

27082018 @ 1138am
Vincent veh not in

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJM2443E

Make

TPVD MERCEDES-BENZ

Model

E200

Service Address

...

Primary Contact/Insured

TAN CHOR HIEN

BLK 417 PASIR RIS DRIVE 6, #10-313, 510417, Singapore

86129399

DANNY@DURAMETAL_ALLOY.COM

Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE



SENT

8/24/18 2:02 PM

FROM

TAN Jas

SUBJECT

DS

BODY

hi, please explore DS



Re:

KINDLY ADVISE MANDATE FOR QUANTUM-IA
UPLOADED

Type

 Question

Message

Hi, please proceed as IA proposed.

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563261 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 10/9/2018

Survey Details:

Date of loss	20-Aug-18
Date of appointment	27-Aug-18
Date of survey	28-Aug-18
Location of survey	T & T AUTO SERVICES

Vehicle Details:

Claim Type:	Third party
Vehicle number	SJM 2443E
Make and Model	MERCEDES BENZ E200K 1796CC
Date of registration	26-Dec-08
Excess	
Market Value	\$ 32,000.00
Parf Rebate	\$ 25,847.00
Nett Loss	\$ 6,153.00

Repair details:

Initial Estimate	\$ 7,495.20
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 3,512.90
Check items (estimate)	
Labour	\$ 1,235.00
Total	\$ 4,747.90
Lump Sum(if applicable)	3750

Number of days for repair	<u>3</u>
---------------------------	----------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

HEAD-TO-REAR- (BOLA 27) 100% ; ID FROM REAR. / RENTAL
CAR.PARF/COE REBATE ENQUIRY,OWNER ID TYPE: BUSINESS

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	4,012.50
Loss of rental	\$	450.00
LTA search fees	\$	7.45
Proposed Total	\$	4,469.95
		GST included
		(\$150 x 3 days)

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMA 4855P (Insd veh)	Model:	MERCEDES BENZ
	SJM 2443E (TP veh)		E200K
Date of Accident:	20/08/2018		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	8,019.86
Final Repair Cost	:	\$	4,012.50
Loss of Use	:	\$	days at \$00.00 per day
Rental (if any)	:	\$	360.00 3 days
LTA / GIA Search Fee	:	\$	7.45

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	4,350.00

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	T&T AUTO SERVICES PTE LTD	:	\$ 4,350.00

NUR SHAQILAH BTE ABDOL
WAHAB

12/09/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

SERVICE REQUESTS MESSAGES CLAIMS

<< Service Request Details

Claim	S8M00SWT
Reference	
CC4/ASM18015518K(p3s2)	Loss Date
August 20, 2018	Request Date
August 24, 2018	Due Date
August 27, 2019	Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)	Type of Loss
Third Party Vehicle Damage	Services
Pending verification - Direct Settlement	
Additional Instructions	

Actions

Next Step

Finish the work

Complete Work

Document Type

Document Sub Type

Upload Documents

Vehicle Information	
Incident Vehicle Registration #	SJM2443E
Make	Service Address
TPVD MERCEDES-BENZ	Model
E200	Primary Contact/Insured
TAN CHOR HIEN	
BLK 417 PASIR RIS DRIVE 6, #10-313, 510417, Singapore	
86129399	
DANNY@DURAMETAL_ALLOY.COM	
Claim Handler	
TAN Jas	
6568804844	
jas.tan@axa.com.sg	

Messages	Invoices	History	Documents
Assessment	Metrics	Notes	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	---------------

<< Service Request Details

Claim

S8M10SWT

Reference

CC4/ASM18015518/Kp3s2 

Loss Date

August 20, 2018

Request Date

August 24, 2018

Due Date

August 27, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Additional Instructions

Actions

Next Step

Finish the work

Complete Work

More

Add

Vehicle Information

Incident Vehicle Registration #

SJM2443E

Make

TPVD MERCEDES-BENZ

Model

E200

Primary Contact/Insured

TAN CHOR HIEN
BLK 417 PASIR RIS DRIVE 6, #10-313, 510417,
Singapore
861293399
DANNY@DURAMETAL_ALLOY.COM

Claim Handler

TAN Jas
6568804844
jas.tan@axa.com.sg

MESSAGES

INVOICES

HISTORY

DOCUMENTS

ASSESSMENT

NOTES

STATUS

SHARE

CLONE



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	SJM2443E	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	12/26/2008
Mileage	84952	Age of Vehicle	9

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Manufacturing Year		2008	Driver Name	AL AMIN BIN AHMAD	
Make	TPVD MERCEDES-BENZ	MERCEDES BENZ	Date of Birth	August 11, 1972	mm/dd/yy
Model	E200	E200K	Age	46	
Type			Occupation	Unknown	
Type of Paint			Education Qualification	Other	
Chassis No		WDB2110412B344228	Driving Experience	0	
Engine No		27195631078567	Driver License #		
Engine Capacity		1796 cc			

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *	08/28/2018		General condition	Good
Total Loss	Yes	No	Steering (Serviceable)	Yes No
Towing Charges	0		Footbrake (Serviceable)	Yes No
Voluntary Excess	0		Handbrake (Serviceable)	Yes No
Compulsory Excess	0		Engine Modification	Yes No
Young/Inexperienced/Unarmed Driver Excess	0		Pre-accident condition	Good
Other Excess				

Tyre Condition

Age of Tyres		Spare wheel	
Front Tyre Size	225/50R17	Rear Tyre Size	225/50R17
Front left side	KUMHO 9mm	Rear left side	KUMHO 7mm
Front right side	KUMHO 9mm	Rear right side	KUMHO 7mm

Assessment Details

General & Workshop Details				Vehicle & Driver Details		Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary		Parts	
EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTRY%	DISC QUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE		
	1	1			REAR BUMPER			Buckled	1670		10		1503	Reviewing			
	2	1			REAR BUMPER INNER FRAME			Cracked	265		10		238.5	Reviewing			
	3	1			REAR BUMPER REINFORCEMENT			Bent	655		10		589.5	Reviewing			
	4	1			REAR BUMPER CHROME - CENTER			Necessary	245		10		220.5	Reviewing			
	5	2			REAR BUMPER CHROME - SIDE			Necessary	155		10		279	Reviewing			
	6	1			REAR BUMPER SIDE BRACKET (N/S)			Damaged	36		10		32.4	Reviewing			
	7	1			REAR END PANEL			Repair	0		10		0	Reviewing			
	8	1			REAR END PANEL TOP GARNISH			Serviceable	0		10		0	Reviewing			
Labour																	
EDIT	SR NO	REPAIR/REPLACE (LABOUR)		PART NAME		LABOUR R&R		LABOUR REPAIR		PAINT		ACTION (LABOUR)		COMMENT		REMOVE	
	1			TO CHECK WIRING		15		0		0		Reviewing					
	2			TO TUFF KOTE		0		0		0		Reviewing					
	3			TO REMOVE / REFIX REAR SENSOR		60		0		0		Reviewing					

SERVICE REQUESTSMESSAGESCLAIMS

<< Assessment Details

General & Workshop DetailsVehicle & Driver DetailsVehicle ConditionTaxes & RateParts & LabourMiscellaneousSummary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing		3	
	2	REAR BUMPER CLIP	Reviewing	50	NECESSARY	
	3	REAR END PANEL TOP GARNISH CLIP	Reviewing	0	NOT NECESSARY	
	4	SET REAR REVERSE SENSOR	Reviewing	600	SHORTED	

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount	\$4,747.90					
Claim Amount	\$4,747.90					
Claim Amount	\$4,747.90					
CATEGORY	ESTIMATE	REVISED AMOUNT				
Spare Parts	\$2,862.90	\$2,862.90				
Labour	\$1,235.00	\$1,235.00				
Miscellaneous	\$650.00	\$650.00				

Submit for Review

SERVICE REQUESTSMESSAGESCLAIMS

<< Assessment Details

General & Workshop DetailsVehicle & Driver DetailsVehicle ConditionTaxes & RatioParts & LabourMiscellaneousSummary

Add

Approve

Deny

Submit All

REMOVE

COMMENT

AMOUNT

ACTION

NAME

SIR NO

EDIT

FINAL LUMP SUM

1

Reviewing

3750

