

9/12/2018

Claim Portal

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
☐		4		TO REMOVE / REFIX UPHOLSTERY CUSHION SEAT & ROOF LINING.	60	0	0	Reviewing		
☐		5		TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS.	500	0	0	Reviewing		
☐		6		TO SPRAY PAINTING ON AFFECTED AREA.	600	0	0	Reviewing		

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	ENCL INFORMATION	POST SURVEY INFORMATION
Sum Insured	0		License Type		
Market Value	0		License Issue Date		mm/dd/yy
			License Expiration Date		mm/dd/yy
			Address	BLK 362A, SEMBAWANG CRESCENT, #06-847, 751362, Singapore	
			Address type	Personal Correspondence	
			Gender	Male	
			Marital status	Unknown	
			Identification #	572274191	

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	9/12/18 2:13 PM	3750	3750	Open	Share	Clone
DHAKAL Raghav	8/24/18 1:18 PM	4747.9	4747.9	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	September 10, 2018
IA - FOR QUANTUM MANDATE-T&T.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	September 10, 2018
SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	September 10, 2018
RE-SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	September 10, 2018
TP ESTIMATE-MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	August 30, 2018
SMA4855P INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	August 24, 2018
SJM2443E TP GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	August 24, 2018
TP T&T-PRI FROM WORKSHOP.msg	Letters and Correspondence	Workshop	DHAKAL Raghav	August 24, 2018