

REPAIR ESTIMATE*

VEHICLE NO : SHD 4485S

DATE 21/8/2018 11:07

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>X422</i>			\$ 538.80
	Front Bumper Bracket (RH) <i>X</i>			\$ 20.10
	SUB TOTAL			\$ 558.90
	LESS 20%			\$ 111.78
	DISCOUNTED TOTAL			\$ 447.12
	Labour Charge			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 250.00
	TOTAL LABOUR			\$ 600.00
	ESTIMATE TOTAL			\$ 1,047.12
<p><i>Kahr 11/11/14</i></p> <p><i>24/8/18 1235 hrs</i></p> <p><i>26/11</i></p> <p><i>4/1</i></p> <p><i>After Repair</i></p> <div data-bbox="790 1268 1250 1654" data-label="Text"> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				