DATE : 28.08.2018

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHA 7094H (Supplementary)

MAKE

TEL: 6542 5119 : HYUNDAI i40 FAX : 6542 6039

	**************************************	166	. 0542 5119	
ODEL	: HYUNDAI i40	FAX	: 6542 6039	
Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender (LH/RH) Dente		\$ 619.00	\$ 1,238.00
	NO METALONICA PROPERTY AND		0	
	SUB TOTAL			\$ 1,238.00
	LESS 20%			\$ 247.60
	DISCOUNTED TOTAL			\$ 990.40
	21/10/20			
	109/2018			
	3			
	01/09/2018	12		
	2th And	}		
	2th And	1		
		1		
	2.			
			=	
				1
	II,			
		'		
				-
			e .	
			i i	
		1	15	
	2			
				9
				E
	2			
		200	- 1,	
	This is an initial estimate based on a visual inspection of t	I	L	l

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHA 7094A (Supplementary)

MAKE

DATE: 1.09.2018

TEL: 6542 5119

ODEL	: HYUNDAI i40	FAX	: 6542 6039	
Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Horn Unit (LH/RH) torn		\$ 73.80	\$ 147.60
	Horn Wire books		75.00	\$ 156.50
	8			
	Air Cleaner Assy brace			\$ 118.60
	Air Duct breen			\$ 134.60
	Air Flow Sensor broken	1.		\$ 502.20
	Actuator - Swirl Control books			\$ 814.60
	Front Safety Belt Adjuster, LH action		-	\$ 285.50
	Solenoid Valve			\$ 408.90
				0 0 00 00
	SUB TOTA			\$ 2,568.50
	LESS 20			\$ 513.70
	DISCOUNTED TOTA	L		\$ 2,054.80
	1 1 2 2			
	61/04/2018			
	orlog/2018			1
				1
	2 F E Auto			
				1
		1		
	· ·			
			. /	
				1
	,, ,			1
	· · · · · · · · · · · · · · · · · · ·			
W.			100	* -
		W 8	* 30	
		1	1	1

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

1/ 1 (Beel