

Bryon

ASSIGNMENT (Office)

From (Person)

Chan su Hui Agnes

of

SMD

Date/Time 27/8/2018 @ 9:25 am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 3780B

Insured:

812 92882

at Workshop m/s

Chunni Motor

Tel:

6542 5119

of

10 Amk Ind. Park 2A # 03-19

Policy No:

D18MTpv 01005192

Claim No:

CMTD1803612

Sum Insured:

Excess:

Make of Veh:

D.O.A.

21/08/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time: 10:57 am @

Person Contacted:

Lym

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

Repairer agreed byron to survey.

SHC 3780B - 003/11/12015835/H16/1292 DOA: 13/8/12

812 92882-X

11/9/18 - Revert via merimen preli advice.


ASSIGNMENT

CoB July 2022

Form: _____ Date: _____
 Estimated Cost: _____
 ODI / TP / W5 / TP RES / ODI RES / EVA / RV / MV
 To be paid to back file:
 a) Write up only:
 b) _____
 Insured:
 Policy No:
 Claim No:
 Sum Insured: _____ Loss:
 (Client's Record)
 Make of Vehicle:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Est. of Market Value:

IDAC Accident Report

Consistent? : Yes or No

GIA / PR Seen

Consistent? : Yes or No

Est. Repairs

10 ~~7~~

days

Res: Yes or No

Lump Sum

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Vehicle: **SHC 37803** Yr Began: **July 2014**
 Type: **M/Gar / M/Cycle / Bus / Van / Lorry / Car / Prime Mover /**
 Truck / Trailer or
 Make: **Hyundai I40** Yr: **1685**
 Colour: **Blue** A/C: **Insured / Std / FR / NA**
 Sp. Reading: **452677** T/Ratio: **Insured / Std / FR / NA**
 Engine No: **D4FDEU429968**
 Chassis No: **KMHLB41UMEU056145**
 Cam Cond: **6** / Fair / Poor / Burnt
 Steering: **6** / Jammed / Leaked / Burnt or
 Brakes: **6** / Jammed / Leaked / Burnt or
 Mod: **6** / S/Rim / STD A/Rim or
 Tyre Size: F: **205/60 R16**
 R: **— 16 —**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

 Hankook

Front

Rear

R/Bal

S

mm

R/Bal

S

mm

L/Bal

S

mm

L/Bal

S

mm

D.O.A.

21/08/2018

D.O.I.

27/08/2018

Survey held at

Chunni AMK

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

N/S Rm

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Sompo 828 92882**25/09/18****Findings 2/3 10700/- 07. 10 days 2 rev****Cred: 5560.88: 340/-**

RECEIVED 2 OCT 2018

Date/Time, File Pass to?

24/9 Typist

Date/Time, File Return to?



Preli. Report



Final Report

Days Of Repair: **10**Resurvey No. of Trip: **2**

Add Fee:



Site Insp (\$)



Interview (\$)



Tech Insp (\$)



Workload (\$)

Report Format:

TP

Lump Sum / L33: (\$)

10700/-

Survey For:

Transportation

450**10**

Dishes

Others

460



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|-------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------|---------------------------|------------|-------------------------------------------------------------------------------------|
| SOMPO INSURANCE SINGAPORE PL | | Ref : CS/SMO18015547/Dtd3 | | |
| 50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERS SINGAPORE 048623 | | Date : 27-08-2018 | |  |
| | | Code : SMO | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SLZ 9288Z | Veh. Inspected | SHC 3780B | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | CMTD1803612 | Excess (\$) | 0.00 | |
| Assign From | CHAN SU HUI AGNES | Assign Date | 27/08/2018 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | | c.c | 0 | |
| Engine No. | HIDDEN | Year of Reg. | | |
| Chassis No. | | Colour | | |
| Odometer | - | Steering | | |
| Brakes | | Modification | | |
| General | | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | | | mm | |
| L/H Front Tyre | | | mm | |
| R/H Rear Tyre | | | mm | |
| L/H Rear Tyre | | | mm | |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| Accident Date | 21/08/2018 | Inspection Date | 27/08/2018 | |
| Survey held at | CHUNNI MOTOR REPAIRS PTE LTD BLK 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTOPOINT #03-19 SINGAPORE 568047 | | | |
| 5a. Remarks | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 11 Sep 2018

Preliminary Advice

| | | | |
|--------------------|-----------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SLZ9288Z | Accident Date | : 21/08/2018 |
| TP Vehicle No | : SHC3780B | Assignment Date | : 27/08/2018 |
| Make | : | Est. Duration of Repair | : 7.00 |
| Date of Inspection | : 27/08/2018 | | |
| Inspection At | : CHUNNI MOTOR PTE LTD (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 16,266.88 |
| Revised Amount | :S\$ | 13,397.60 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 13,397.60 |

| | | |
|-----------------|------|--|
| Lump Sum Repair | :S\$ | |
|-----------------|------|--|

Total Loss Consideration

| | | |
|--------------------|------|--|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | |
| COE / PARF Rebate | :S\$ | |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : survey on "wp"

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|------------------------------------------------|---------|---------------|------------|------------------------------------------------------|
| Main | 21 Aug 2018 | | 27 Aug 2018 09:25 Assign | | | | New Assignment Cancel Case |

| | | | | |
|------|-----------|---------------|-----------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|--------------------------|

CLAIM SUBFOLDER DETAILS [Created by insurer]

| | | | |
|-----------------------------|------------------------------------------------------------------------------------------------------------|------------------------|------------------------|
| Insured: | ALEXANDER CARL MELCHERS, ID: S2721422C | | |
| Main Claimant: | COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R | | |
| Vehicle Reg. No.: | SHC3780B | Date of Loss: | 21/08/2018 08:00 - :59 |
| Claim Type: | TP / CMTD1803612 | Policy/Cover Note No.: | D18MTPV01005192 |
| Vehicle Reg. No. (Insured): | SLZ9288Z | Policy No. (Claimant): | |
| | | Excess: | |
| Repairer: | Chunni Motor Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel: | | |
| Handling Insurer: | Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327] | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/09/2018] | | |
| Adj Asg. Remarks: | Please assign to Mohd Taufik as the single joint expert as requested by workshop. | | |

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHC 3780 B

Technician:

Mileage: 452677

Time Printed 29.8.18 4:31 PM

HYUNDAI I40

Front : Left

| Actual | BEFORE | Specified Range |
|--------|--------|-----------------|
| -0°22' | | -3°00' 3°00' |
| 4°02' | | -0°19' 5°41' |
| -0°40' | | -1°30' 1°30' |
| 19°25' | | |
| 19°03' | | |

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

| Actual | BEFORE | Specified Range |
|--------|--------|-----------------|
| 0°42' | | -3°00' 3°00' |
| 4°13' | | -0°19' 5°41' |
| 0°11' | | -1°30' 1°30' |
| 15°07' | | |
| 15°49' | | |

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

| Actual | BEFORE | Specified Range |
|--------|--------|-----------------|
| -1°03' | | -3°00' 3°00' |
| -0°11' | | -3°00' 3°00' |
| 4°18' | | -3°00' 3°00' |
| -0°29' | | -3°00' 3°00' |

Rear : Left

| Actual | BEFORE | Specified Range |
|--------|--------|-----------------|
| 11°15' | | -3°30' 2°30' |
| 27°02' | | -1°30' 1°30' |

Camber
Toe

Rear : Right

| Actual | BEFORE | Specified Range |
|--------|--------|-----------------|
| 0°07' | | -3°30' 2°30' |
| 0°14' | | -1°30' 1°30' |

Rear

Cross Camber
Total Toe
Thrust Angle

| Actual | BEFORE | Specified Range |
|--------|--------|-----------------|
| 11°08' | | -3°00' 3°00' |
| 27°16' | | -3°00' 3°00' |
| 13°24' | | -3°00' 3°00' |

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Company |
| Owner ID: | 3821R |
| Vehicle Details | |
| Vehicle No.: | SHC3780B |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 11 Sep 2018 |
| Vehicle Make: | HYUNDAI |
| Vehicle Model: | I40 1.7L CRDI AT ABS AIRBAG 4DR |
| Primary Colour: | Blue |
| Manufacturing Year: | 2014 |
| Engine No.: | D4FDEU429968 |
| Chassis No.: | KMHLB41UMEU056145 |
| Maximum Power Output: | 100.0 kW (134 bhp) |
| Open Market Value: | \$18,608.00 |
| Original Registration Date: | 10 Jul 2014 |
| First Registration Date: | 10 Jul 2014 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$11,108.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 09 Jul 2022 |
| PARF Rebate Amount: | \$8,331.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 09 Jul 2022 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 8 |
| PQP Paid: | \$53,269.00 |
| COE Rebate Amount: | \$25,482.00 |
| Total Rebate Amount: | \$33,813.00 |
| Message | |
| Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. | |

The information contained herein is correct as at 11 Sep 2018

OK

MCD818108395 / ComfortDelGro Engineering Pte Ltd - Luyang
 ENTRY DATE & TIME: 21/08/2018 13:45
 SUBMITTED BY: Janet Lim Siang Gek

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 21/08/2018 13:45
 Date Of Accident 21/08/2018 08:50
 Exact Location Of Accident WALLICH ST
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHC3780B
Insured/Policyholder
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 199303821R
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
Vehicle Particulars
 Manufacturer HYUNDAI
 Model I40
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
Insurance Company
 Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number D-18088936MFSH
 Cover Note Number
Driver
 Name of Driver LAI SCHE LOUNG LOUIS (LAI XUELONG)
 NRIC No S7470044F
 Date Of Birth 30/05/1974
 Occupation OUTDOOR
 Date Of Driving Pass 28/05/1994
 Driving Experience 24 YEARS AND 2 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-90589258
 Fax Number
 Contact Number
 EMail Address LOUISLSL@GMAIL.COM

Address BLK 68 LORONG 5 TOA PAYOH
#12-478
Postcode 310068
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1 NAME: : -
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER ATTACHED * TYPE OF ACCIDENT :- HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLZ9288Z
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver PARASKEVI SIDERI
NRIC/Passport Number S7764208J
Contact Number 97257091
Address
Postcode
Insurance Company Name
Nature Of Damage FRONT

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

| | |
|-----------------------------------------------------|------------------------------------|
| Name | LAI SCHE LOUNG LOUIS (LAI XUELONG) |
| Approximate Age | |
| Injuries Sustain | GIDDY |
| Injured person in which vehicle? | SHC3780B |
| Were seat belts worn? | YES |
| Was this injured conveyed to hospital by ambulance? | NO |
| Address | |
| Postcode | |

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 21.08.2018
@ 11:00 hrs

Reporting Centre Personnel's Signature
Name: Regina Choo
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

| |
|-------------------------------------------------------------------------------------------|
| On 21.08.2018 at about 08:50 hours I was travelling along Wallich Street with one |
| Female Passenger onboard . |
| I was travelling straight along Wallich Street , suddnely Veh B - SLZ 9288Z dash out from |
| my left and collided into my taxi Left Rear Portion |
| After the accident we then alighted and exchange our particulars . |
| After the accident i suffered giddness , will consult the doctor later on . |
| I have company video and photos at scene to support my claims . |
| Veh B - Ms Paraskevi Sideri I/C : S 7764208J H/P : 9725 7091 |
| |
| |
| |
| |
| |
| |
| |
| |

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 21.08.2018
@ 11:00 hrs

Reporting Centre Personnel's Signature

Name: Regina Choo

NRIC/FIN No.:

CHUNNI MOTOR WORK PTE LTD

So Survey by LK

REPAIR ESTIMATE*

VEHICLE NO : SHC 3780B

DATE : 21.08.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039 SOMPO

| Qty | Parts Description/ Labour | Type | Unit Price | Amount | |
|-----|------------------------------------------------------|------|------------|-------------|--------|
| | Rear Bumper Cnt | | | S 603.60 | ✓ |
| | Rear Bumper Clip 10 pcs H/c | | | S 22.00 | ✓ |
| | Rear Bumper Bracket, LH Svc | | | S 49.00 | X |
| | Rear Fender With Housing (LH) <i>Demol</i> | | | S 4,736.80 | ✓ |
| | Rear Fender Inner Lining (LH) Svc | | | S 164.40 | X |
| | Rear Windscreen Moulding H/c | | | S 60.00 | ✓ |
| | Rear Door (LH) <i>Demol</i> | | | S 2,201.10 | ✓ |
| | Rear Door Rubber (LH) H/c | | | S 280.50 | ✓ |
| | Rear Door Gear/Regulator (LH) <i>broken</i> | | | S 785.50 | ✓ |
| | Rear Door Power Motor (LH) H/c | | | S 530.50 | X |
| | Rear Door Trim Board (LH) <i>check</i> | | | S 892.55 | ✓ |
| | Rocker Panel Outer Garnish (LH) <i>check morning</i> | | | S 483.60 | ✓ |
| | Rear Tyre Rim (LH) <i>check</i> | | | S 351.90 | ✓ |
| | Rear Wheel Hub-Cap (LH) Cnt | | | S 150.70 | ✓ |
| | Rear Wheelbearing IN & Hub <i>Demol</i> | | | S 401.40 | ✓ |
| | Rear Trailing Arm (LH) <i>distorted</i> | | | S 120.00 | ✓ |
| | Rear Assist (LH) <i>distorted</i> | | | S 120.00 | ✓ |
| | Rear Shock Absorber (LH) <i>distorted</i> | | | S 342.20 | ✓ |
| | Rear Shock Absorber Mounting (LH) H/c | | | S 57.70 | X |
| | Rear Crossmember <i>distorted</i> | | | S 1,190.00 | ✓ |
| | Stabilizer Bar <i>distorted</i> | | | S 204.60 | ✓ |
| | Stabilizer Link <i>distorted</i> | | | S 68.15 | ✓ |
| | Rear Upper Arm (LH) <i>distorted</i> | | | S 335.75 | ✓ |
| | Rear Lower Arm (LH) <i>distorted</i> | | | S 204.35 | ✓ |
| | Rear Knuckle Arm (LH) <i>distorted</i> | | | S 574.80 | ✓ |
| | | | 14129.60 | | |
| | | | 11303.60 | | |
| | SUB TOTAL | | | S 14,931.10 | |
| | LESS 20% | | | S 2,986.22 | |
| | DISCOUNTED TOTAL | | | S 11,944.88 | |
| | | | | | |
| | Rear Bumper Rubber Mat H/c | | | S 50.00 | Nett ✓ |
| | Rear Windscreen Sealant H/c | | | S 46.00 | Nett ✓ |
| | Rear Door Comfortdelgro & Apps Sticker (LH) H/c | | | S 80.00 | Nett ✓ |
| | Rear Tyre (LH) <i>50% distorted</i> | | | S 216.00 | Nett ✓ |
| | | | 284.00 | | |
| | | | | S 392.00 | |

SHC 3780B

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|-----|----------------------------------------|------|------------|-------------------|
| | Labour Charge | | | |
| | Panel Beating | | | \$ 1,500.00 700/- |
| | Spray Painting Charge | | | \$ 1,250.00 600/- |
| | Wiring Charge | | | \$ 50.00 40/- |
| | Tuff Kote | | | \$ 100.00 40/- |
| | Towing Charge | | | \$ 50.00 40/- |
| | Remove/Refix Cushion & Upholstery Rear | | | \$ 150.00 80/- |
| | Remove/Refix Rear Windscreen Glass | | | \$ 120.00 80/- |
| | Remove/Refix Reverse Sensor | | | \$ 120.00 40/- |
| | Remove/Refix Fuel Tank | | | \$ 150.00 40/- |
| | Transfer of Door | | | \$ 120.00 60/- |
| | Remove/Refix Undercarriage (RR) | | | \$ 200.00 150/- |
| | Rear Wheel Alignment | | | \$ 120.00 60/- |
| | | | 1810.00 | |
| | TOTAL LABOUR | | | \$ 3,930.00 |
| | ESTIMATE TOTAL | | | \$ 16,266.88 |
| | | | | 13397.60 |
| | | | | 41510700/- |
| | 27/08/2018 @ 1400hrs | | | |
| | HA Antenna | | | |
| | 1/5mm | | | |
| | 1 ryan | | | |
| | 2kk auto | | | |
| | 10 days. | | | |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18015547/DTD3N2

Date: 04/10/2018

REFERENCE

| | | | |
|-----------------------|-------------------------------------|----------------------|-----------------|
| Handling Insurer: | Sompo Insurance Singapore Pte. Ltd. | Policy No: | D18MTPV01005192 |
| Claimant Vehicle No : | SHC3780B | Insured Vehicle No : | SLZ9288Z |
| Date of Loss: | 21/08/2018 | Nature of Claim: | TP |
| | | Claim No: | CMTD1803612 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------------------|-------------|-------------------|
| Reg No: | SHC3780B | Engine No: | D4FDEU429968 |
| Make & Model: | HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A) | Chassis No: | KMHLB41UMEU056145 |
| Reg. Date: | 10/07/2014 (Man. Year: 2014) | Odometer: | 452677 km |
| Colour: | Blue | | |
| Engine Capacity: | 1685 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 205/60R16 | Rear Tyre Size: | 205/60R16 |
| Front Left Side: | Hankook 5 mm | Rear Left Side: | Hankook 5 mm |
| Front Right Side: | Hankook 5 mm | Rear Right Side: | Hankook 5 mm |

The above values represent the remaining tyre treads depth

COST OF CLAIMS

| | Repairer's | Adjuster's | Difference | Diff % | |
|-------------------------------------------|------------------|------------------|-----------------|--------------|-------|
| Parts | 12,336.88 | 11,587.60 | 749.28 | 6.07 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | | |
| Labour | 3,930.00 | 1,810.00 | 2,120.00 | 53.94 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | | |
| Towing | 0.00 | 0.00 | 0.00 | | |
| Calculated Gross Total (\$\$) | 16,266.88 | 13,397.60 | 2,869.28 | 17.64 | |
| Approved Total (Overridden) (\$\$) | | 10,700.00 | | | |
| | (\$\$) | 16,266.88 | 10,700.00 | 5,566.88 | 34.22 |
| + GST 7.00/7.00% (\$\$) | 1,138.68 | 749.00 | 389.68 | 34.22 | |
| Nett Amount (\$\$) | 17,405.56 | 11,449.00 | 5,956.56 | 34.22 | |

INSPECTION

Date of Assignment: 27/08/2018

Date Inspected: 27/08/2018 Inspected At:

Chunni Motor Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A, #03-19
AMK Autopoint
Singapore 568047

Estimated Period of Repair: 10.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 04 Oct 2018) |
| Parts: | 143 | HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SHC3780B) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|----------------------------------------------|------------------|-------------|--------------|
| 1 | 1 | | *REAR BUMPER | Cut | 603.60 FL | *603.60 FL |
| 2 | 10 | | *REAR BUMPER CLIP | Necessary | 22.00 FL | *22.00 FL |
| 3 | 1 | | *REAR BUMPER BRACKET, LH | Serviceable | 49.00 FL | *- FL |
| 4 | 1 | | *REAR FENDER WITH HOUSING (LH) | Dented | 4,736.80 FL | *4,736.80 FL |
| 5 | 1 | | *REAR FENDER INNER LINING (LH) | Serviceable | 164.40 FL | *- FL |
| 6 | 1 | | *REAR WINDSCREEN MOULDING | Necessary | 60.00 FL | *60.00 FL |
| 7 | 1 | | *REAR DOOR (LH) | Dented | 2,201.10 FL | *2,201.10 FL |
| 8 | 1 | | *REAR DOOR RUBBER (LH) | Necessary | 280.50 FL | *280.50 FL |
| 9 | 1 | | *REAR DOOR GEAR/REGULATOR (LH) | Broken | 785.50 FL | *785.50 FL |
| 10 | 1 | | *REAR DOOR POWER MOTOR (LH) | Not Necessary | 530.50 FL | *- FL |
| 11 | 1 | | *REAR DOOR TRIM BOARD (LH) | Cracked | 892.55 FL | *892.55 FL |
| 12 | 1 | | *ROCKER PANEL OUTER GARNISH (LH) | Mounting Cracked | 483.60 FL | *483.60 FL |
| 13 | 1 | | *REAR TYRE RIM (LH) | Distorted | 351.90 FL | *351.90 FL |
| 14 | 1 | | *REAR WHEEL HUP-CAP (LH) | Cut | 150.70 FL | *150.70 FL |
| 15 | 1 | | *REAR WHEELBEARING ING & HUB | Damaged | 401.40 FL | *401.40 FL |
| 16 | 1 | | *REAR TRAILING ARM (LH) | Distorted | 120.00 FL | *120.00 FL |
| 17 | 1 | | *REAR ASSIST (LH) | Distorted | 120.00 FL | *120.00 FL |
| 18 | 1 | | *REAR SHOCK ABSORBER (LH) | Distorted | 342.20 FL | *342.20 FL |
| 19 | 1 | | *REAR SHOCK ABSORBER MOUNTING (LH) | Not Necessary | 57.70 FL | *- FL |
| 20 | 1 | | *REAR CROSS MEMBER | Distorted | 1,190.00 FL | *1,190.00 FL |
| 21 | 1 | | *STABILIZER BAR | Distorted | 204.60 FL | *204.60 FL |
| 22 | 1 | | *STABILIZER LINK | Distorted | 68.15 FL | *68.15 FL |
| 23 | 1 | | *REAR UPPER ARM (LH) | Distorted | 335.75 FL | *335.75 FL |
| 24 | 1 | | *REAR LOWER ARM (LH) | Distorted | 204.35 FL | *204.35 FL |
| 25 | 1 | | *REAR KNUCKLE ARM (LH) | Distorted | 574.80 FL | *574.80 FL |
| 26 | 1 | | *REAR BUMPER RUBBER MAT | Necessary | 50.00 FS | *50.00 FS |
| 27 | 1 | | *REAR WINDSCREEN SEALANT | Necessary | 46.00 FS | *46.00 FS |
| 28 | 1 | | *REAR DOOR COMFORTDELGRO & APPS STICKER (LH) | Necessary | 80.00 FS | *80.00 FS |
| 29 | 1 | | *REAR TYRE (LH)(50%) (DEPRECIATION) | Cut | 216.00 FS | *108.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|------------------------------------------------------------|------------------|------------------|
| Sub Total (\$\$) | 15,323.10 | 14,413.50 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 2,986.22 | 2,825.90 |
| Total Parts (\$\$) | 12,336.88 | 11,587.60 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|----------------------------------------|----------|------------|----------|
| Labour Items | | | | |
| 1 | PANEL BEATING | New | 1,500.00 | 700.00 |
| 2 | SPRAY PAINTING CHARGE | New | 1,250.00 | 600.00 |
| 3 | WIRING CHARGE | New | 50.00 | - |
| 4 | TUFF KOTE | New | 100.00 | 40.00 |
| 5 | TOWING CHARGE | New | 50.00 | - |
| 6 | REMOVE/REFIX CUSHION & UPHOLSTERY REAR | New | 150.00 | 80.00 |
| 7 | REMOVE/REFIX WINDSCREEN GLASS | New | 120.00 | 80.00 |
| 8 | REMOVE/REFIX REVERSE SENSOR | New | 120.00 | 40.00 |
| 9 | REMOVE/REFIX FUEL TANK | New | 150.00 | - |
| 10 | TRANSFER OF DOOR | New | 120.00 | 60.00 |
| 11 | REMOVE/REFIX UNDERCARRIAGE (RR) | New | 200.00 | 150.00 |
| 12 | REAR WHEEL ALIGNMENT | New | 120.00 | 60.00 |
| Gross Labour Cost (\$\$) | | | 3,930.00 | 1,810.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >