

ASS. REC. BY:

REF: CS/CTI/8015549/Ds d3

Special Instruction:

Survivor:
Mehmen

Bryan

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTI

Date/Time:

27/8/18 @ 2:33pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBB 2773E

Insured:

SKP 75312

at Workshop m/s:

Teamwork

Tel:

6844 2475

of

53 Ubi Ave 1 #01-24

Policy No:

DMCV SN3036331801

Claim No:

SNM18D04101C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/8/18

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

3:41pm @ 27/8/18

Person Contacted:

Demen

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBB 2773E - NA/CTI/8015376/24

DOA: 22/8/18

SKP 75312 - NA/CTI/8015376/24

DOA: 22/8/18

22/10/18


Confirmed R/s \$ 2,000/- @ 5 days with Bryan.
(\$ 9,905.19 - Red - 83%)

REF:

ASSIGNMENT

COE Nov 2018

Make: _____ Date: _____
 Insured: _____
 OPI / TP / WS / TP / RES / OD RES / LVA / RV / MV
 Vehicle / Vehicle No.
 Model / Year
 of _____
 Location: _____
 Policy No.
 Claim No.
 Sum Insured: _____
 (Client's Record)
 Make of Veh:



(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value:
 IDAC Accident Report Consistent? Yes or No
 GIA / PR Seen Consistent? Yes or No
 Est. Repairs: 5 days Res: Yes or No
 Lim Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBB 2773 E Yr Equip: 2008 / Nov
 Type: B / Car / M / Cycle / Bus / Van / Truck / Taxi / Prime Mover /
 Truck / Trailer or

Make: Nissan Cabstar CC: 2963
 Color: Silver ABC: Insured / 5d / 10 / 11A
 Tip / Loading: 339824 T / Ratio: Insured / 5d / 10 / 11A

Engine: ED30202971K
 GLE: JH19C2F24Z0800632

Car / Cond: 0 / Fair / Poor / Burnt
 Steering: 0 / Jammed / Leaked / Burnt or
 Brakes: 0 / Jammed / Leaked / Burnt or
 Model: 0 / SRim / STD A/Rim or

Tyre Size: F: 195 R15C
 R: 165 R13 (double)

BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Dunlop

Front: _____ Rear: _____
 R/Bal: 5 mm R/Bal: 5/5 mm
 L/Bal: 5 mm L/Bal: 5/5 mm
 D.O.A: 22/08/2018 D.O.I: 04/09/2018

Survey held at: Teamwork Page ubi

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time: _____ Action / Instruction:
 China Teiping SKP 75312
 MV.
 LTA 230.00 Vehicle b-line est 2 mths plus.
 yln require 2k for rep.
 19/10/18 Jmnyul 2/5 2000/- with 5 days of rep.

RECEIVED 22 OCT 2018

Date/Time: 22/10/18

Typist

Date/Time: 22/10/18

1

Report Format:

Lump Sum / H.D. / 2,000/- R/S



Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Insp (\$)☐ Weekend (\$)

Survey Fee

Transportation

5 x 100 = 500

Phone

Others

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Aug 2018		27 Aug 2018 14:33 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	SINCOM ENGINEERING PTE LTD, Co. Reg. No.: 201220546R		
Vehicle Reg. No.:	GBB2773E	Date of Loss:	22/08/2018 15:00 - :59
Claim Type:	TP / SNM18D04101C02	Policy/Cover Note No.:	DMHCSN1739361700
Vehicle Reg. No. (Insured):	SKP7531Z	Policy No. (Claimant):	DMCVSN3036331801
		Excess:	S\$0.00
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/09/2018]		
Adj Asg. Remarks:	NO EST, CASE WITH SJE,		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18015549/Dsd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 27-08-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKP 7531Z	Veh. Inspected	GBB 2773E	
Policy No.	DMHCSN1739361700	Coverage (\$)	0.00	
Claim No.	SNM18D04101C02	Excess (\$)	0.00	
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	27/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/08/2018	Inspection Date	04/09/2018	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/08/2018 19:26
Date Of Accident	22/08/2018 15:30
Exact Location Of Accident	SLIP RD PIE TWDS TPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBB2773E
Insured/Policyholder	
Name Of Registered Owner	SINCOM ENGINEERING PTE LTD
Co Reg No	201220546R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999
Vehicle Particulars	
Manufacturer	NISSAN
Model	CABSTAR 3.0 5M/T ABS 2DR 2WD 3.4T
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3036331801
Cover Note Number	
Driver	
Name of Driver	HAQUE IKRAMUL
Passport No/FIN	G7976878U
Date Of Birth	01/01/1980
Occupation	OUTDOOR
Date Of Driving Pass	13/06/2017
Driving Experience	1 YEAR AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87872966
Fax Number	
Contact Number	OFFICE-87872966
Email Address	NOEMAIL

Address 7 TOH GUAN ROAD EAST
#06-04 ALPHA INDUSTRIAL BUILDING

Postcode 608599

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 6

Passenger 1 NAME: : -
GENDER: : MALE

Passenger 2 NAME: : -
GENDER: : MALE

Passenger 3 NAME: : -
GENDER: : MALE

Passenger 4 NAME: : -
GENDER: : MALE

Passenger 5 NAME: : -
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKP7531Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

1. Policyholder's Name:

2. The accident occurred on the road between the following two points:

3. The accident occurred on the road between the following two points:

4. The accident occurred on the road between the following two points: Any verbal interpretation or withholding of material facts may cause insurance companies to rescind the policy.

5. The accident occurred on the road between the following two points: It is an admission of policy liability on the part of the signatory.

6. The accident occurred on the road between the following two points:

7. The report will be displayed by the Insurers of the GSA Records Management Centre established by the General Insurance Association of Singapore (GIA) for accident and that copies of this report will for a fee be made available upon application by the insured parties.

8. In the event of any dispute, you hereby consent to the withholding of this report at the centre and to copies of this report being made available as stated.

9. (Consent to the use of this report for the purpose of the Act)

I understand, acknowledge, agree and consent that:

- (a) my insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan



REASON FOR ACCIDENT

I, the undersigned, being the driver of the vehicle, hereby declare that the facts and circumstances leading to the accident are as stated above.

Signature: _____

Date: _____

DECLARATION
 I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature: _____
 Date & Time: _____

Driver's Signature (If driver is not the policyholder): _____
 Date & Time: _____

Reporting Centre Personnel's Signature: _____
 Name: _____
 NRIC/PIN No.: _____

China Taiping Insurance (Singapore) Pte Ltd
105 Cecil Street #19-00
The Octagon
Singapore 069534

Vehicle number	GBB2773E
Make / Model	NISSAN/CABSTAR
Chassis number	JN1SC2F24Z0800632
Accident date	22 August 2018
Reference	1808-24

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	TAILGATE <i>Dent</i>	1788.40 ✓
1	TAILGATE LOWER MEMBER <i>Dent</i>	451.40 ✓
2	TAILLAMP PANEL <i>Ren</i>	358.00 X
1	REAR CHASSIS CENTRE MEMBER <i>Ren</i>	539.00 X
1	REAR TOW HOOK BRACKET <i>NH</i>	134.90 X
		3271.70
		981.51
		2290.19
1	REAR EXHAUST PIPE <i>NH</i>	573.20 X
2	REAR EXHAUST MOUNTING <i>NH</i>	48.00 X
2	LICENSE PLATE LAMP <i>NH</i>	123.60 X
1	LICENSE PLATE BRACKET <i>SVC</i>	121.60 X
2	REAR TAILGATE STOPPER <i>O/S missing N/S SVC</i>	20.00 40.00 ✓
2	REAR TAILGATE LOCK CATCH <i>O/S BT N/S SVC</i>	56.00 112.00 ✓
2	REAR TAILGATE BRACKET <i>O/S BT N/S SVC</i>	96.80 193.60 ✓
2	REAR TAILGATE HINGE <i>O/S BT N/S SVC</i>	60.00 120.00 ✓
2	TAILLAMP <i>broken O/S N/S NH</i>	221.00 442.00 ✓
1	SPARE TYRE RETAINING CHAIN <i>SVC</i>	216.30 X
1	REAR NISSAN STICKER <i>NH</i>	60.00 ✓
		2050.30
		205.03
		1845.00
		27
	Subtotal	4135.19
	Balance C/F	4135.19
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
	Balance B/F	4135.19
1	REAR NUMBER PLATE <i>BT</i>	60.00 30.00 ✓
1	ALUMINIUM FLOOR PANEL <i>NH</i>	2500.00 X
1	TAILGATE ALUMINIUM PANEL <i>NH</i>	1500.00 X
1 SET	REVERSE SENSOR <i>Dent</i>	300.00 150.00 ✓
1	70KM/H STICKER <i>NH</i>	50.00 25.00 ✓
1	13 PAX STICKER <i>NH</i>	50.00 25.00 ✓
	Subtotal	4460.00
	Balance C/F	8595.19

S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	8595.19
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30/-
2	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 NH
3	REMOVE AND RENEW EXHAUST ASSY	150.00 NH
4	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	200.00 80/-
5	PANEL BEATING ON AFFECTED AREAS	1400.00 600/-
6	SPRAY PAINTING ON AFFECTED AREAS	1200.00 500/-
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
	1250/-	
	Subtotal	3310.00
	Grand total	46 11905.19

04/09/2018 @ 1300h

Not Author

2/1 saw

5 days.

3500.28

R/s 2000/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Ryan

LKK Auto

Check MV

repair limit ??

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18015549/DSD3N2

Date: 26/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSN1739361700
Claimant Vehicle No :	GBB2773E	Insured Vehicle No :	SKP7531Z
Date of Loss:	22/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D04101C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB2773E	Engine No:	ZD30202971K
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Chassis No:	JN1SC2F24Z0800632
Reg. Date:	12/11/2008 (Man. Year: 2008)	Odometer:	339824 km
Colour:	Silver		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	165 R13 (D)
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5/5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,595.46	2,250.28	6,345.18	73.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,310.00	1,250.00	2,060.00	62.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,905.46	3,500.28	8,405.18	70.60
Approved Total (Overridden) (\$\$)		2,000.00		
(\$\$)	11,905.46	2,000.00	9,905.46	83.20
+ GST 7.00/7.00% (\$\$)	833.38	140.00	693.38	83.20
Nett Amount (\$\$)	12,738.84	2,140.00	10,598.84	83.20

INSPECTION

Date of Assignment: 27/08/2018

Date Inspected: 04/09/2018 Inspected At:

Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi
Industrial Park
Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Oct 2018)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB2773E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Dented	1,788.40 FL	*1,788.40 FL
2	1	*TAILGATE LOWER MEMBER	Dented	451.40 FL	*451.40 FL
3	2	*TAILLAMP PANEL	Repair	358.00 FL	*- FL
4	1	*REAR CHASSIS CENTRE MEMBER	Repair	539.00 FL	*- FL
5	1	*REAR TOW HOOK BRACKET	Not Necessary	134.90 FL	*- FL
6	1	*REAR EXHAUST PIPE	Not Necessary	573.20 FN	*- FN
7	2	*REAR EXHAUST MOUNTING	Not Necessary	48.00 FN	*- FN
8	2	*LICENSE PLATE LAMP	Not Necessary	123.60 FN	*- FN
9	1	*LICENSE PLATE BRACKET	Serviceable	121.60 FN	*- FN
10	1	*REAR TAILGATE STOPPER	O/s Missing/N/s Serviceable	40.00 FN	*20.00 FN
11	1	*REAR TAILGATE LOCK CATCH	O/s Bent/N/s Serviceable	112.00 FN	*56.00 FN
12	1	*REAR TAILGATE BRACKET	O/s Bent/N/s Serviceable	193.60 FN	*96.80 FN
13	1	*REAR TAILGATE HINGE	O/s Bent/N/s Serviceable	120.00 FN	*60.00 FN
14	1	*TAILLAMP	O/s Broken/N/s Not Necessary	442.00 FN	*221.00 FN
15	1	*SPARE TYRE RETAINING CHAIN	Serviceable	216.30 FN	*- FN
16	1	*REAR NISSAN STICKER	Necessary	60.00 FN	*60.00 FN
17	1	*REAR NUMBER PLATE	Bent	60.00 FS	*30.00 FS
18	1	*ALUMINIUM FLOOR PANEL	Not Necessary	2,500.00 FS	*- FS
19	1	*TAILGATE ALUMINIUM PANEL	Not fitted	1,500.00 FS	*- FS
20	1	*SET REVERSES ENSOR	Damaged	300.00 FS	*150.00 FS
21	1	*70KM/H STICKER	Necessary	50.00 FS	*20.00 FS
22	1	*13 PAX STICKER	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	9,782.00	2,973.60
- List Item Discount on L Items 30.00/30.00% (S\$)	981.51	671.94
- Nett Item Discount on N Items 10.00/10.00% (S\$)	205.03	51.38
Total Parts (S\$)	8,595.46	2,250.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	-
3	REMOVE AND RENEW EXHAUST ASSY	New	150.00	-
4	TRANSFER PARTS,ATTACHMENT FROM OLD TAILGATE TO NEW	New	200.00	80.00
5	PANEL BEATING ON AFFECTED AREAS	New	1,400.00	600.00
6	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	500.00
7	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	40.00
Gross Labour Cost (\$\$)			3,310.00	1,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >