威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32, SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com Business Regn No: 269436/00J

Not Norhasses
USing 8?
Runny Afre Pains
Felage

5,151.28

23, July 2018

AXA Insurance PL 143 Cecil street #01-01 GB Building S 069542

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: SKU8796T
Accident involving vehicle no: SLZ3219M/SKU8796T
DOA: 18/08/2018 AT Chun Tin Rd junction To Jalan Seh Chuan

Dear officer incarge

To supply--

Description	Qty	Amount
Rear fender,Lh	1	By 1,605.00 —
Rear door,Lh	1	B 872.30
Rear bumper	1	By 491.80 -
Bumper retainer	1	P-7 36.00 —
Bumper clip		nc 42.00 —
Fender cowling	1	EM 76.50 -
Cowling clip	10	va 38.00
Rim	1	R 280.00
Tyre	1	Por 160.00 dol
	Parts	3,601.60
	Parts less 20%	720.32
		2,881.28

To remove/transfer doorboard, power window mechanism, door glass to new door 160.00 To remove rear speaker board ,inner garnish enable repair job carry out. Reinstall after job done. 150.00 1201 To remove/replace rear fender glass. 100.00 801 To remove damaged parts and attachments, cut n weld damaged panel. Repair/reshape damaged/dented areas. 900.00 7501 Replace/align all parts into position. LKK Auto Consultants hence notify 800.00 6001 To spray paint. the Repairer of the following: Computer wheel alignment. 80.00 606 · To resurvey before/after spray painting To display damaged part(s) during resurvey 80.00 501 Tow fee Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed
 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: