

Surveyor:

mpeens

DOI:

ASSIGNMENT

2/18/18

Date / Time:

2/18/18

Registered in Merimen:

2/18/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHB 4034X

Name of Insured:

CTM

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

2/18/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

ONG Tien Koi

Driver Tel No.:

9132 6103

(V/L: YES / NO)

Claim No.:

Policy No.:

MCOMOTI

Make / Model:

H-140

Place of Accident:

BUL 630 Senja Rd

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Yun Lee



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

DATE / PIC

2/18/18
Ow

SHB 4034X-X

SHB 4034X - 11/11/17 1306319 / Hwa392, 08/11/17
- 11/11/17 1306319 / Hwa392, 08/11/17

07/09/18

SEEK NAME FOR LIBRARY.

07/09/18

NAME APPROVE LIBRARY.

12/09/18

EMAIL WSP LIBRARY CLEAR.

20/9/18

FILE PPD TO TYPST TO PREPARE REPORT.

of m amount not fully in settlement amount.

(LOW ISSUED)

STAGE

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: CKS

Repair Cost:

45

S\$950

(2)

days) Reduction:

59

%

Email

Call

FINAL SETTLEMENT

Date/Time: 04-04-19

Confirm with MPH

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lis:

Repair Cost:

45

S\$ 1016.50

OID REVERSED IN TP

Loss of Rental (LOR):

S\$ -

()

days)

Loss of Use (LOU):

S\$ 100.00

(\$50

x 2

days)

Loss of Income (LOI):

S\$ -

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$ 29.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 1,145.50

Global Sum S\$:

FINAL PAYMENT

Date/Time: 04-04-19

Confirm with: MPH

Email

Call

Payee 1:

S\$ 1,145.50

Name 1:

YIM THE AUTOMOBILE TECH PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COMMENT
22/4/19

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

INSURER : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTHQ/TP/1808/011
Policy No:	5096816540	Date of Loss:	20/08/2018
Vehicle Reg. No.:	SJR4498H	Driveable?	no
Driver Age:	23/04/1990	Third Party Vehicle No.:	SHB4034X
Any Injuries?	no	Contact No:	82824535
Insured/Claimant:	TAYZAR KHIN PHONE	Driver:	TAYZAR KHIN PHONE

Make/Model:	Mitsubishi, Lancer - CS3A5U/3A6U/3A7U	Vehicle Reg. Date:	24/06/2009
Vehicle Colour:	WHITE	Engine Number:	4A910124584
Chassis No:	JMYSRCY2A9U004498	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss: COLLISION - REVERSED
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

COST OF CLAIMS

	Amount
Parts	1,399.50
Miscellaneous Items	38.00
Labour	590.00
Paintwork Labour	280.00
Towing	0.00
Gross Total(\$\$):	2,307.50
GST 7.00%(\$\$):	161.53
Nett Amount(\$\$):	2,469.03

This claim is handled by: Sky Toh T C

*not Alford
LPR
L/S
2 days
27/8/18
Take photo after repair*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT FENDER RH <i>rod 502</i>	468.00	468.00	-10.00	421.20
2	1	FRONT FENDER INNER SHIELD RH <i>10-1</i>	92.00	92.00	-10.00	82.80
3	1	FRONT FENDER LAMP RH <i>1-1</i>	45.00	45.00	-10.00	40.50
4	1	FRONT KNUCKLE ARM RH <i>1-1</i>	330.00	330.00	-10.00	297.00
5	1	FRONT LOWER ARM RH <i>1-1</i>	290.00	290.00	-10.00	261.00
6	1	FRONT LOWER ARM BALL JOINT RH <i>11-</i>	110.00	110.00	-10.00	99.00
7	1	FRONT SHOCK ABSORBER RH <i>1-1</i>	220.00	220.00	-10.00	198.00
8	1	FRONT DOOR RH <i>1</i>	0.00	0.00	-10.00	0.00

Total Parts (\$\$) 1,399.50

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT FENDER INNER SHIELD CLIPS <i>10-1</i>	38.00	38.00	0.00	38.00

Sub Total (\$\$) 38.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts. <i>wheel alignment</i>	20.00	20.00	0.00	20.00
2	1	To Dismantle and Refit Front Undercarriage.	220.00	220.00	0.00	220.00
3	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	350.00	350.00	0.00	350.00

Gross Labour Cost (\$\$) 590.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	30.00	30.00	0.00	30.00
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	250.00	250.00	0.00	250.00

Gross Labour Cost (\$\$) 280.00

< END OF ESTIMATES >

11.09.2018

India International Insurance Pte Ltd
64 Cecil Street
#04-00/#05-00 IOB Building
Singapore 049711

Attn: Motor Claims Department

Dear Sirs,

ACCIDENT INVOLVING VEHICLE: SJR4498H and SHB4034X on 20.08.2018

We are the authorized repair workshop for the owner of motor vehicle no: SJR4498h which was involved in the captioned accident with your insured vehicle: SHB4034X. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

01)	Lump sum Repair	\$	950.00
02)	TP search fee	\$	27.10
		\$	977.10
	GST 7%	\$	68.40
	Sub Total	\$	1,045.50
	Loss of use 2 days @ \$80/day	\$	160.00
	Grand Total	\$	1,205.50


We enclosed herewith the following documents to support the claims:-

- a) GIA report
- b) Invoice

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you
Yours faithfully



Shaun
97432262

LETTER OF AUTHORITY

To whom it may concern,

ACCIDENT INVOLVING : SJR4498H and SHB4034X on 20/08/2018

I/We TAYZAR KHIN PHONE Reg No.: S9075754G

Owner of motor vehicle no : SJR4498H do hereby appoint M/S YEW TEE AUTOMOBILE TECH PTE LTD as my/our authorized representative to write, negotiate and settle my/our claims against the other party involved in the abovementioned accident. M/S YEW TEE AUTOMOBILE TECH PTE LTD shall have absolute discretion to settle the matter at the best terms.

I/WE also confirm and instruct that any agreed settlement sum in respect of my/our claims be paid to M/S YEW TEE AUTOMOBILE TECH PTE LTD and such payment will constitute a full and final discharge of my/our claims.

I/WE further authorize M/S YEW TEE AUTOMOBILE TECH PTE LTD to execute the discharge voucher on my/our behalf.

Signature of Owner,



LETTER OF AUTHORITY

To whom it may concern,

ACCIDENT INVOLVING : SJR4498H and SH84034X on 20/08/2018

I/We TAYZAR KHIN PHONE Reg No: S9075754G

Owner of motor vehicle no : SJR4498H do hereby appoint M/S YEW TEE AUTOMOBILE TECH PTE LTD as my/our authorized representative to write, negotiate and settle my/our claims against the other party involved in the abovementioned accident. M/S YEW TEE AUTOMOBILE TECH PTE LTD shall have absolute discretion to settle the matter at the best terms.

I/WE also confirm and instruct that any agreed settlement sum in respect of my/our claims be paid to M/S YEW TEE AUTOMOBILE TECH PTE LTD and such payment will constitute a full and final discharge of my/our claims.

I/WE further authorize M/S YEW TEE AUTOMOBILE TECH PTE LTD to execute the discharge voucher on my/our behalf.

Signature of Owner.





INDIA
INTERNATIONAL
INSURANCE
SINGAPORE
Serving the region since 1984

WITHOUT PREJUDICE to:

- (a) Insurers' Subrogated Claim and/or
(b) Any Personal Injury Claims

[Note: This Notice supersedes any inconsistencies found in this Discharge Voucher]

INDIA INTERNATIONAL INSURANCE PTE LTD
Co. Reg. No. 198703792K | GST Reg. No. M2-0078806-X
64 | Cecil Street | #04-05 | #06-02 | IOB Building | Singapore 049711
Email: insured@iil.com.sg
Website: www.iil.com.sg
Fax: [65] 62244174

EXPRESS SETTLEMENT

DISCHARGE VOUCHER

III- Direct Settlement (PODS)

India Ref: MCT18080594

Claimant Ref: SJR 4498H

We/I, YEW TEE AUTOMOBILE TECH PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 1,016.50 (repair cost), S\$ 100.00 (loss of use), S\$ 29.00 (search fee), vehicle no. SJR 4498H that was damaged pursuant to the accident which occurred on 20/08/2018 (date) at BLK EXEC SENJA ROAD (location) involving vehicle no. 9HB 4034X (insured vehicle). This is pursuant to the inspection conducted on 27/08/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner: TAYZAR KHIN PHONE ("the third party claimant") of vehicle no. SJR 4498H to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SJR 4498H (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 1,145.50 to YEW TEE AUTOMOBILE TECH PTE LTD

Dated this 14 day of April 20 19

CLAIMANT:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:

Signed by "the workshop" (with chop)

Lim Min Hui

G266559C

BLK 6, 399F Woodland Rd

Singapore 68006

Malaysian

Admin

WITNESS:

Signature:

Name:

NRIC:

Address:

Nationality:

Occupation:



CKS

Signed by appointed Surveyor

LKK AUTO CONSULTANTS PTE LTD

198607198R

51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK

#02-25 SINGAPORE 408933

**YEW TEE AUTOMOBILE TECH PTE LTD**

HQ: BLK 6 WOODLANDS ROAD 399-F YEW TEE IND EST S(678006)

BR: SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #01-61 S(417800)

BR: MEGA@WOODLANDS, 39 WOODLANDS CLOSE #01-12 S(737856)

GST Reg No. 200311009C

Singapore

67653373 67023113

INFO@YEWTEEGROUP.COM

WWW.YEWTEEGROUP.COM

Company Registration No. 200311009C

ADDRESS

INDIA INTERNATIONAL

INSURANCE PTE LTD

INDIA INTERNATIONAL

INSURANCE PTE LTD

TP TAX INVOICE MC1809005**DATE 11/09/2018****VEHICLE NO.**

SJR4498H

ACTIVITY	QTY	RATE	TAX	AMOUNT
LUMP SUM REPAIR	1	950.00	7% SR	950.00
TP SEARCH FEE	1	27.10	7% SR	27.10
LOSS OF USE	2	80.00	Out of Scope	160.00

Cheque should be crossed & made payable to "YEW TEE AUTOMOBILE TECH PTE LTD" and strictly send to our HQ address.

SUBTOTAL

1,137.10

GST TOTAL

68.40

TOTAL**SGD 1,205.50**

Accepted By

Accepted Date


ISSUED BY STAFF

E. & O.E.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-128584
Date of Request: 21/08/2018

Your Ref No: Online Purchase

Yew Tee Automobile Tech Pte Ltd
Blk 6 Woodlands Road 399F,
Yew Tee Ind Estate
Singapore 678006

Dear Sir/Madam,

Date of Accident: 20/08/2018
Vehicle No: SJR4498H
Place of Accident: BLK 633C SENJA ROAD
Involving Vehicle No: SHB4034X

With reference to your application for the accident report, we have attached the following accident reports as requested:

DOCUMENTS	ACCIDENT LOCATION	PER DOC (S\$)	QTY	AMOUNT (S\$)
SHB4034X	BLK 633C SENJA ROAD	14.00	1	13.08
GST Amount				0.92
Total Amount Due (GST Inclusive)				14.00

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-128582
Date of Request: 21/08/2018

Your Ref No: Online Purchase

Yew Tee Automobile Tech Pte Ltd
Blk 6 Woodlands Road 399F,
Yew Tee Ind Estate
Singapore 678006

Dear Sir/Madam,

Your Search Criteria:

Date of Accident: 20/08/2018
Place of Accident: BLK 633C SENJA ROAD
Client Vehicle No: SJR4498H

DESCRIPTION	AMOUNT (S\$)
E-File Search Fee (Public)	14.02
GST Amount	0.98
Total Amount Due (GST Inclusive)	15.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Aug 2018 Edit Reg		24 Aug 2018 00:00 Edit Adj Rpt	S\$950.00 Edit Estimates	S\$950.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	TAYZAR KHIN PHONE , ID: S9075754G								
Vehicle Reg. No.:	SJR4498H	Date of Loss:	20/08/2018 12:00 - :59 [109 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18080594	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHB4034X	Policy No. (Claimant):	5096816540						
		Excess:							
Repairer:	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit) Blk 25 Kaki Bukit Road 4, #01-61 SYNERGY @ KAKI BUKIT, 417800 Kaki Bukit - Tel: 67023113								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 05/09/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (19/11/2018): Alert - Adj Mandate Approved (S\$1145.50) - SJR4498H - Claim Handler: Sundari Nag... - III_SG (09/11/2018): Alert - Adj Mandate Approved (S\$0.00) - SJR4498H - Claim Handler: Sundari Nagara... - III_SG (07/09/2018): Alert - Adj Mandate Approved (S\$0.00) - SJR4498H - Claim Handler: Sundari Nagara...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJR4498H (MCT18080594)
[SHB4034X]
TP
TAYZAR KHIN PHONE
Aug 20 2018 12:00PM
[COMFORT TRANSPORTATION PTE LTD]
Yew Tee Automobile Tech Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Photos/Images			3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/11/18 10:58	General View	1	Load JPG	☒
2	19/11/18 10:58	General View	1	Load JPG	☒
3	19/11/18 10:58	General View	1	Load JPG	☒
4	19/11/18 10:58	General View	1	Load JPG	☒
5	19/11/18 10:58	General View	1	Load JPG	☒
6	19/11/18 10:58	General View	1	Load JPG	☒
7	19/11/18 10:58	General View	1	Load JPG	☒
8	19/11/18 10:58	General View	1	Load JPG	☒
9	19/11/18 10:58	General View	1	Load JPG	☒
10	19/11/18 10:58	General View	1	Load JPG	☒
11	19/11/18 10:58	General View	1	Load JPG	☒
12	19/11/18 10:58	General View	1	Load JPG	☒
13	19/11/18 10:58	General View	1	Load JPG	☒
14	19/11/18 10:58	General View	1	Load JPG	☒
15	19/11/18 10:58	General View	1	Load JPG	☒
16	19/11/18 10:58	General View	1	Load JPG	☒
17	19/11/18 10:58	Odometer Reading	1	Load JPG	☒
18	19/11/18 10:58	General View	1	Load JPG	☒
19	19/11/18 10:58	Chassis Number	1	Load JPG	☒
20	19/11/18 10:58	General View	1	Load JPG	☒
21	19/11/18 10:59	Reinspection Photo	1	Load JPG	☒
22	19/11/18 10:59	Reinspection Photo	1	Load JPG	☒
23	19/11/18 10:59	Reinspection Photo	1	Load JPG	☒
24	19/11/18 10:59	Reinspection Photo	1	Load JPG	☒
Documentation			1 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/08/18 18:34	TP GIA REPORT	1	Load PDF	
2	27/08/18 18:34	ACKNOWLEDGEMENT EMAIL TO III DD 24.08.2018	1	Load PDF	
3	29/08/18 10:26	TP ESTIMATE - MARKED	1	Load PDF	
4	30/10/18 12:49	WORKSHOP INVOICE	1	Load PDF	
5	30/10/18 12:49	GIA SEARCH	1	Load PDF	
6	30/10/18 12:49	LOD	1	Load PDF	
7	09/05/19 16:35	DISCHARGE VOUCHER	1	Load PDF	
8	09/05/19 16:35	AUTHORISATION TO ACT FORM	1	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	28/08/18 08:50	Singapore Accident Statement	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Handling Insurer	
Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18015563/JEA3Q2

Date: 09/05/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No: SJR4498H

Insured Vehicle No:

SHB4034X

Date of Loss: 20/08/2018

Nature of Claim:

TP

Claim No: MCT18080594

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJR4498H

Make & Model: MITSUBISHI LANCER, 1.5 MIVEC GLS 4A/T (A)

Engine No: 4A910124584

Reg. Date: 24/06/2009 (Man. Year: 2009)

Chassis No: JMYSRCY2A9U004498

Colour: White

Odometer: 218022 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,437.50	542.00	895.50	62.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	870.00	660.00	210.00	24.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,307.50	1,202.00	1,105.50	47.91
Approved Total (Overridden) (S\$)		950.00		
(S\$)	2,307.50	950.00	1,357.50	58.83
+ GST 7.00/7.00% (S\$)	161.53	66.50	95.03	58.83
Nett Amount (S\$)	2,469.03	1,016.50	1,452.53	58.83
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		1,145.50		

INSPECTION

Date of Assignment: 24/08/2018

Date Inspected: 27/08/2018 Inspected At:

BLK 6 WOODLANDS ROAD 399F YEW
TEE IND. ESTATE SINGAPORE 678006

Repairer: Yew Tee Automobile Tech Pte
Ltd (Kaki Bukit)

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2018)
Parts:	143	MITSUBISHI LANCER 1.5 MIVEC GLS 4A/T (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR4498H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Badly Dented	468.00 FL	*468.00 FL
2	1		*FRONT FENDER INNER SHIELD RH	Torn	92.00 FL	*92.00 FL
3	1		*FRONT FENDER LAMP RH	Not Necessary	45.00 FL	*- FL
4	1		*FRONT KNUCKLE ARM RH	Not Necessary	330.00 FL	*- FL
5	1		*FRONT LOWER ARM RH	Not Necessary	290.00 FL	*- FL
6	1		*FRONT LOWER ARM BALL JOINT RH	Not Necessary	110.00 FL	*- FL
7	1		*FRONT SHOCK ABSORBER RH	Not Necessary	220.00 FL	*- FL
8	1		*FRONT DOOR RH (NPA)	Repair	0.00 FL	*- FL
9	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	38.00 FS	*38.00 FS
					Sub Total (S\$)	1,593.00
					- List Item Discount on L Items 10.00/10.00% (S\$)	155.50
					Total Parts (S\$)	1,437.50
						598.00
						56.00
						542.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT AND RECONNECT .CHECK ELECTRICAL WIRING HARNESS WIRE ,SOCKETS ,REPLACE DAMAGED PARTS	New	20.00	20.00
2	TO DISMANTLE AND WHEEL ALIGNMENT	New	220.00	60.00
3	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS .TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	350.00	300.00
4	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	30.00	30.00
5	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPERS ,CLEANING AND SANDING OF SURFACES ,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	250.00	250.00
Gross Labour Cost (S\$)			870.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >