

ASS. REC. BY:

REF CS/CT#18015570/R1s d3⁷²

Special Instruction:

Surveyor:

Raul

ASSIGNMENT (Office)

From (Person):

Rayn Tey

of CTI

Date/Time: 27/8/18 @ 2:54pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 4045D

Insured:

GBG 3289D

at Workshop n/s:

Automotive Repair

Tel:

64688834

of

38 Woodlands Ind. Park E1 #05-18

Policy No:

DMCVSN3049221800

Claim No:

SNM18D 64132002

Sum Insured:

Excess:

Make of Vch:

(Client's Record)

D.O.A.

24/08/2018

CA / REV / REP. / REV 24 HRS

rup

28/08/2018

H.O.D. Endorsement:

Date/Time:

3:47pm @ 27/8/18

Person Contacted:

Raymond

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLN 4045D - X

GBG 3289D - X

Surveyor: P. Rau

REF:

4528A

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLN 4045D

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLN 4045D Yr Regn: 2017 / MayType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA SIENTA 1.5 c.c. 1496Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 24958 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MHE 228H3750031877

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 24/08/18 D.O.I. 28/08/18Survey held at ARCDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
12/09/18	Confirmed L/S \$5,200/- @ 8 days with Rasul. (\$5,600/- Red - 52%)
	RECEIVED 10 SEP 2018

Date/Time, File Pass to?

12/09/18

1) Typst

Date/Time, File Return to?

2) _____

☐ : Preli. Report
☒ : Final Report
Days Of Repair: 8Resurvey No. of Trip: 1
Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 5,200/- L/S)

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CS/CTI18015570/R1sd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 27-08-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 3289D	Veh. Inspected	SLN 4045D	
Policy No.	DMCVSN3049221800	Coverage (\$)	0.00	
Claim No.	SNM18D04132C02	Excess (\$)	0.00	
Assign From	MERIMEN (JOWYN TAY)	Assign Date	27/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	24/08/2018	Inspection Date	28/08/2018	
Survey held at	AUTOMOTIVE REPAIR CENTRE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 # 05-18 SINGAPORE 757700			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Aug 2018		27 Aug 2018 14:59 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	LAM BOON SEONG		
Vehicle Reg. No.:	SLN4045D	Date of Loss:	24/08/2018 00:00 - :59
Claim Type:	TP / SNM18D04132C02	Policy/Cover Note No.:	DMCVSN3049221800
Vehicle Reg. No. (Insured):	GBG3289D	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Automotive Repair Centre Pte Ltd (HQ) 38 Woodlands Industrial Park E1, #05-18, 757700 Woodlands - Tel: 64688834		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/09/2018]		
Adj Asg. Remarks:	EST \$11,556.00, ASSIGN KELVIN ANG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 18 September 2018 9:45 AM
To: 'raymond@automotiverepaircentre.com.sg'; 'Rasul (LKKAuto)'
Cc: 'Lin Shu Juan'; 'sur@lkkauto.com'; 'assignments'
Subject: RE: SLN4045D - TP Claim against GBG3289D / OUR REF: SNM18D04132C02

Hi Raymond,

Final invoice and all supporting documents sent over to **China Taiping Insurance (Singapore) Pte. Ltd.**

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: raymond@automotiverepaircentre.com.sg [mailto:raymond@automotiverepaircentre.com.sg]
Sent: Monday, 17 September 2018 5:24 PM
To: 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>; 'Rasul (LKKAuto)' <Rasul@lkkauto.com>
Cc: 'Lin Shu Juan' <shujuan@automotiverepaircentre.com.sg>; 'sur@lkkauto.com'; 'assignments' <assignments@lkkauto.com>
Subject: RE: SLN4045D - TP Claim against GBG3289D / OUR REF: SNM18D04132C02

Dear Shirley,

We confirmed Lump Sum \$5,200.00 (8 repair days)

Thank you.

Best Regards,

Raymond Tan

Automotive Repair Centre Pte Ltd

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: +65 64688834

Fax: +65 64622278

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 14 September 2018 10:52 AM
To: raymond@automotiverepaircentre.com.sg; 'Rasul (LKKAuto)' <Rasul@lkkauto.com>
Cc: 'Lin Shu Juan' <shujuan@automotiverepaircentre.com.sg>; 'sur@lkkauto.com'; 'assignments' <assignments@lkkauto.com>
Subject: RE: SLN4045D - TP Claim against GBG3289D / OUR REF: SNM18D04132C02

Dear Raymond,

Please confirm final fig \$5,200.00 (lump sum) @ 8 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: raymond@automotiverepaircentre.com.sg [mailto:raymond@automotiverepaircentre.com.sg]

Sent: Friday, 7 September 2018 12:49 PM

To: 'Rasul (LKKAuto)' <Rasul@lkkauto.com>

Cc: 'Lin Shu Juan' <shujuan@automotiverepaircentre.com.sg>; 'sur@lkkauto.com'; 'assignments' <assignments@lkkauto.com>; 'Shirley Hiew (LKK Auto)' <ShirleyHiew@lkkauto.com>

Subject: RE: SLN4045D - TP Claim against GBG3289D / OUR REF: SNM18D04132C02

Hi Rasul,

Please find attached completion photos and check items for our finalisation.

Await for your reply before to issue our LOD and support documents to insurer.

Thank you.

Best Regards,

Raymond Tan

Automotive Repair Centre Pte Ltd

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: +65 64688834

Fax: +65 64622278

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent: Tuesday, 28 August 2018 1:38 PM

To: 'Chong Boon Sen' <boonsen.chong@sg.cntaiping.com>; 'Raymond Tan' <raymond@automotiverepaircentre.com.sg>; 'assignments' <assignments@lkkauto.com>

Cc: INFO@AUTOMOTIVEREPAIRCENTRE.COM.SG; 'Lin Shu Juan' <shujuan@automotiverepaircentre.com.sg>; 'sur@lkkauto.com'

Subject: RE: SLN4045D - TP Claim against GBG3289D / OUR REF: SNM18D04132C02

Dear Boon Sen,

Thank you for your email.

Dear assignment team,

Kindly assist.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

Sent: Tuesday, 28 August 2018 1:23 PM

To: Raymond Tan <raymond@automotiverepaircentre.com.sg>

Cc: INFO@AUTOMOTIVEREPAIRCENTRE.COM.SG; Lin Shu Juan <shujuan@automotiverepaircentre.com.sg>; 'sur@lkkauto.com'

Subject: RE: SLN4045D - TP Claim against GBG3289D / OUR REF: SNM18D04132C02

Without Prejudice

We refer to the above matter.

Liability is in favor of your client and we agree to go for Direct Settlement, subject to consistency of damages, based on our appointed surveyor's findings, with supporting documents.

Aside to M/s LKK, please upload your report and bill for services rendered in Merimen at your earliest convenience.

Thank you.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Raymond Tan [<mailto:raymond@automotiverepaircentre.com.sg>]

Sent: Saturday, 25 August, 2018 7:08 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: INFO@AUTOMOTIVEREPAIRCENTRE.COM.SG; Lin Shu Juan <shujuan@automotiverepaircentre.com.sg>

Subject: SLN4045D - TP Claim against GBG3289D

Dear Sir / Mdm,

My client's vehicle **SLN4045D** wants to make a third party claim against **GBG3289D** which is insured by **China Taiping Insurance Pte. Ltd.**

Let us know the Claim officer in-charge for liability / settlement of my client's claim.

E.g. your principle's advice on the validity of the policy holder.

*Please send us your top 10 surveyor companies for survey.

Thank you.

Best Regards,
Raymond Tan
Automotive Repair Centre Pte Ltd
38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: +65 64688834
Fax: +65 64622278

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1808-078

DATE : 25-Aug-2018

POLICY NO. : FWD PNPV2018-00005552

VEHICLE REG. NO. : SLN4045D

VEHICLE MAKE : TOYOTA SIENTA 1.5 CVT STD

TO Motor Claim Department

China Taiping Insurance (Singapore) Pte. Ltd

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Rear Bumper	1	\$ 480.00	\$ DE / 480.00
2	Rear Bumper Clips	10	\$ 5.00	\$ ne / 50.00
3	Rear Bumper Center Extension	1	\$ 280.00	\$ DE / 280.00
4	Rear Bumper Right Extension	1	\$ 200.00	\$ cut / 200.00
5	Rear Bumper Upper Retainer RH	1	\$ 70.00	\$ Xsu / 70.00
6	Rear Bumper Reflector RH	1	\$ 60.00	\$ Xsu / 60.00
7	Rear Bumper Center Fog Lamp	1	\$ 180.00	\$ Xsu / 180.00
8	Rear Tail lamp RH	1	\$ 380.00	\$ Xsu / 380.00
9	Rear Tailgate lamp RH	1	\$ 280.00	\$ Buo / 280.00
10	Rear Tailgate Door	1	\$ 1,180.00	\$ Buo / 1,180.00
11	Rear Tailgate Door Chrome Garnish	1	\$ 280.00	\$ CQA / 280.00
12	Rear Tailgate License Plate Lamp	2	\$ 60.00	\$ Xsu / 120.00
13	Rear Tailgate Door Lock	1	\$ 480.00	\$ PA / 480.00
14	Rear Tailgate Door Lock Latch	1	\$ 40.00	\$ Xsu / 40.00
15	Rear Tailgate Door Rubber Seal	1	\$ 380.00	\$ ne / 380.00
16	Rear Toyota Emblem	1	\$ 80.00	\$ ne / 80.00
17	Rear Sienta Emblem	1	\$ 80.00	\$ ne / 80.00
18	Rear G Emblem	1	\$ 60.00	\$ ne / 60.00
19	Rear Wiper Arm	1	\$ 120.00	\$?Cut / 120.00
20	Rear Wiper Arm Motor	1	\$ 770.00	\$?PA / 770.00
21	Rear / End Panel Garnish	1	\$ 180.00	\$ DE / 180.00
22	End Panel Upper	1	\$ 580.00	\$ PA / 580.00
23	End Panel Lower Outer	1	\$ 480.00	\$ Repair / 480.00
24	Rear Spare Tire Pan	1	\$ 880.00	\$ Repair / 880.00
25	Rear Windscreen Moulding	2	\$ 100.00	\$ ne / 200.00
Total Spare Parts				\$ 7,890.00
SPECIAL NETT				
26	Reverse Sensor	1	\$ 200.00	\$ nw / 200.00
27	Reverse Sensor Molding	1	\$ 40.00	\$ ne / 40.00
28	Rear Number Plate with Frame	1	\$ 40.00	\$ Xnw / 40.00
29	Rear Windscreen Sealant	1	\$ 40.00	\$ ne / 40.00
Total Special Nett				\$ 320.00



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: Info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1808-078
DATE : 25-Aug-2018
POLICY NO. : FWD PNPV2018-00005552
VEHICLE REG. NO. : SLN4045D
VEHICLE MAKE : TOYOTA SIENTA 1.5 CVT STD

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	LABOUR			
30	Spray painting Whole Rear include Rear Fender Blending	1	\$ 1,000.00	\$ 800 1,000.00
31	Repair and Replace Affected Accident Parts	1	\$ 1,200.00	\$ 900 1,200.00
32	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 100.00	\$ 60 100.00
33	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 60 100.00
34	Remove and Replace Rear Exhaust Pipe and Silencer, Re-align	1	\$ 80.00	\$ 60 80.00
35	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 80.00	\$ 60 80.00
36	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour	\$ 2,590.00
Amount Before Excess	\$ 10,800.00
Add GST @ 7%	756.00
Total Amount Payable	\$ 11,556.00

Please arrange this vehicle to be surveyed soonest possible. Thank you.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4260
280
1970
6510
202
5208
45,520
8 days

Rasul
Hp 90010068
8 days
4/5
28/08/18 @ 1740
Resurvey after repair

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118015570/R1SD3N2

Date: 19/09/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3049221800
Claimant Vehicle No :	SLN4045D	Insured Vehicle No :	GBG3289D
Date of Loss:	24/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D04132C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN4045D	Engine No:	2NRX152323
Make & Model:	TOYOTA SIENTA, 1.5 (A)	Chassis No:	MHFZ28H3700031877
Reg. Date:	02/05/2017 (Man. Year: 2017)	Odometer:	24958 km
Colour:	Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,210.00	4,540.00	3,670.00	44.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,590.00	1,970.00	620.00	23.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,800.00	6,510.00	4,290.00	39.72
Approved Total (Overridden) (S\$)		5,200.00		
(S\$)	10,800.00	5,200.00	5,600.00	51.85
+ GST 7.00/7.00% (S\$)	756.00	364.00	392.00	51.85
Nett Amount (S\$)	11,556.00	5,564.00	5,992.00	51.85

INSPECTION

Date of Assignment:	27/08/2018	
Date Inspected:	28/08/2018 Inspected At:	Automotive Repair Centre Pte Ltd (HQ) 38 Woodlands Industrial Park E1, #05-18 Singapore 757700
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2018)
Parts: M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLN4045D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	480.00 F	*480.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
3	1		*REAR BUMPER CENTER EXTENSION	Deformed	280.00 F	*280.00 FL
4	1		*REAR BUMPER RIGHT EXTENSION	Cut	200.00 F	*200.00 FL
5	1		*REAR BUMPER UPPER RETAINER RH	Serviceable	70.00 F	*- FL
6	1		*REAR BUMPER REFLECTOR RH	Serviceable	60.00 F	*- FL
7	1		*REAR BUMPER CENTER FOG LAMP	Serviceable	180.00 F	*- FL
8	1		*REAR TAIL LAMP RH	Serviceable	380.00 F	*- FL
9	1		*REAR TAILGATE LAMP RH	Broken	280.00 F	*280.00 FL
10	1		*REAR TAILGATE DOOR	Buckled	1,180.00 F	*1,180.00 FL
11	1		*REAR TAILGATE DOOR CHROME GARNISH	Cracked	280.00 F	*280.00 FL
12	2		*REAR TAILGATE LICENSE PLATE LAMP	Serviceable	120.00 F	*- FL
13	1		*REAR TAILGATE DOOR LOCK	Bent	480.00 F	*480.00 FL
14	1		*REAR TAILGATE DOOR LOCK LATCH	Serviceable	40.00 F	*- FL
15	1		*REAR TAILGATE DOOR RUBBER SEAL	Necessary	380.00 F	*380.00 FL
16	1		*REAR TOYOTA EMBLEM	Necessary	80.00 F	*80.00 FL
17	1		*REAR SIENTA EMBLEM	Necessary	80.00 F	*80.00 FL
18	1		*REAR G EMBLEM	Necessary	60.00 F	*60.00 FL
19	1		*REAR WIPER ARM	Cut	120.00 F	*120.00 FL
20	1		*REAR WIPER ARM MOTOR	Bent	770.00 F	*770.00 FL
21	1		*REAR/END PANEL GARNISH	Deformed	180.00 F	*180.00 FL
22	1		*END PANEL UPPER	Bent	580.00 F	*580.00 FL
23	2		*REAR WINDSCREEN MOULDING	Necessary	200.00 F	*200.00 FL
24	1		*REVERSE SENSOR	Not Working	200.00 FS	*200.00 FS
25	1		*REVERSE SENSOR MOLDING	Necessary	40.00 FS	*40.00 FS
26	1		*REAR NUMBER PLATE WITH FRAME	Not Necessary	40.00 FS	*- FS
27	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
28	1		*REAR SPARE TIRE PAN	Repair	880.00 F	*- FL
29	1		*END PANEL LOWER OUTER	Repair	480.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,210.00	5,960.00
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,420.00
Total Parts (\$\$)	8,210.00	4,540.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING WHOLE REAR INCLUDE REAR FENDER BLENDING	New	1,000.00	800.00
2	REPAIR AND REPLACE AFFECTED ACCIDENT PARTS	New	1,200.00	900.00
3	TRANSFER DOOR FITTING AND WINDOW MECHANISM TO NEW DOOR	New	100.00	60.00
4	APPLY RUST PROOFING ON REPLACED/REPAIRED PANEL	New	100.00	60.00
5	REMOVE AND REPLACE REAR EXHAUST PIPE AND SILENCER,RE-ALIGN	New	80.00	60.00
6	REMOVE AND REFIT REAR BUMPER REVERSES SENSOR	New	80.00	60.00
7	CHECK AND RECTIFY ELECTRICAL WIRING	New	30.00	30.00
Gross Labour Cost (S\$)			2,590.00	1,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >