

22/03/2002

ASS. REC. BY:

REF:

CS3/AIG/18015582/24d3et

Special Instruction:

Surveyor:

menmen

From (Person):

Guo Dong
Chin lee Ying

ASSIGNMENT (Office)

of AIG

Date/Time: 27/8/18 @ 2:35pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 8546H

Insured:

SLX 3301T

at Workshop m/s

Lush Automotive

Tel:

97966979

of

No. 8 Kelki Bkt Ave 4 # 03-47

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/08/2018

CA / REV / REP. / REV 24 HRS

(up)

28/8/18 @ early morning

H.O.D. Endorsement

Date/Time:

4:15pm @ 27/8/18

Person Contacted:

Mr. Max

Vehicle IN OUT

Date/Time

Action/Instruction (X) Estimate

SLQ 8546H - CC1/ASM/18015401/GeqB DOA: 21/8/18

SLX 3301T - X

29/8/18

Disman/bd.

PRS
KRL

REF: ALH

ASSIGNMENT

From: Date: 28082018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLQ 8546H
at Workshop m/s Lush Automotive
of 8 Kaki Bukit Ave 4 #03-47

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 98 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLQ 8546H Yr Regn: 5EP / 2009

Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 C.C. - 1798

Colour: Silver A/C: Insured / Std / NI / NA

Sp.Reading: 161573 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAU8ZZ8KXAA 016755

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50 R17

R: H

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 28-08-18

Survey held at W/S 12:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$7000 - \$8000

3/9/18 Submit DAR Report

Repair days

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

)

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

180

20

200

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc:
Sent: 27/8/2018 2:34:00 PM
Attachments:  180823 GIA-SLQ8546H210818.SAS (ins).pdf

Hi LKK,

Did you receive this assignment?

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Chin, Lee-Ying
Sent: Monday, August 27, 2018 10:08 AM
To: assignments@lkkauto.com; admin-a@lkkauto.com
Cc: Fong, Andy-SY
Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLX3301T AND SLQ8546H ON 21/08/2018

Hi LKK,

Kindly assist to survey after 11am today.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

From: Yvonne [<mailto:yvonne@ealc.com.sg>]
Sent: Thursday, August 23, 2018 4:20 PM
To: Chan, Yoke Shi

Cc: Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; Tan, Lily (AIG)

Subject: [PRI] AIG Insured SLX3301T(4TH) - 2018.5878.MK.ya - SLQ8546H(3RD)

Our ref : 2018.5878.MK.ya - **SLQ8546H(3RD)**

Your ref : **SLX3301T(4TH)**

23 August 2018

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

AIG Asia Pacific Insurance Pte Ltd
No. 78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Department
2 DAYS' PRE-REPAIR NOTICE

Surveyor from M/s AIG Asia Pacific Insurance Pte Ltd		
Vehicle SLQ8546H(3RD) inspected as follows by Name:		
Before repair	Parts removed	After repair
_____	_____	_____
Signature	Signature	Signature
Date/ Time:	Date/ Time:	Date/ Time:

Dear Sir/Madam,

NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE

CLAIMANT: GOH WEI KIAT

ACCIDENT INVOLVING SLQ8546H(3RD) & SLX3301T(4TH) & SJK9848K(2ND) & LORRY(1ST) ON 21-Aug-18 ALONG JALAN DATOH/BALESTIER ROAD AT ABOUT 1630 HOURS

We refer to the above matter wherein we are instructed to act for **GOH WEI KIAT**, the owner of vehicle no. **SLQ8546H(3RD)**.

There is no agreement to the surveyors proposed by parties.

Our client's vehicle **SLQ8546H(3RD)** is available as follows, please call prior appointment for the pre-repair inspection:

M/s Lush Automotive Pte Ltd
No. 8 Kaki Bukit Avenue 4,
#03-47 Premier@Kaki Bukit,
Singapore 415875
Tel: 97966979 (Mr Max)

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,
Yvonne Ang

East Asia Law Corporation
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18015582/Gz4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 27-08-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLX 3301T	Veh. Inspected	SLQ 8546H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	27/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	21/08/2018	Inspection Date	28/08/2018
Survey held at	LUSH AUTOMOTIVE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-47 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details	
Vehicle No. :	SLQ8546H
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	AUDI
Vehicle Model :	A4 1.8T FSI MU CVT ABS D/AB 2WD 4DR
Chassis No. :	WAUZZZ8KXAA016755
Propellant :	Petrol
Engine No. :	CDH058403
Engine Capacity :	1798 cc
Maximum Power Output :	118.0 kW (158 bhp)
Maximum Laden Weight :	2000 kg
Unladen Weight :	1450 kg
Year Of Manufacture :	2009
Original Registration Date :	18 Sep 2009
Lifespan Expiry Date :	-
COE Category :	B - Car (1601cc & above)
Quota Premium :	\$18,890.00
COE Expiry Date :	17 Sep 2019
Road Tax Expiry Date :	17 Sep 2018
PARF Eligibility Expiry Date :	17 Sep 2019
Inspection Due Date :	17 Sep 2018
Intended Transfer Date :	29 Aug 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-
The current road tax expiry is 17 Sep 2018. You may renew the road tax from 18 Jun 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 17 Sep 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.	
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.	
Amount Payable (From 18 Sep 2018 to 17 Mar 2019)	
	Amount Before GST (S\$) GST Amount (S\$) Amount After GST (S\$)
Transfer Fee :	25.00 - 25.00
Sub Total :	25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	488.00 - 488.00
Total Amount Payable :	513.00
Amount Payable (From 18 Sep 2018 to 17 Sep 2019)	
	Amount Before GST (S\$) GST Amount (S\$) Amount After GST (S\$)
Transfer Fee :	25.00 - 25.00
Sub Total :	25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	976.00 - 976.00
Total Amount Payable :	1,001.00

You may print this page for reference.

OK

Print

MOTORCAR (Rear)

Rear Portion

Vehicle No: **SL 85464**

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	NEC	✓	
1149	993045	Rear Bumper Reinforcement	BT	✓	
1150	992970	Rear Bumper Beam	BT	✓	
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	CUT	✓	
1159	993327	Rear End Panel	R	X	
1160	993339	Rear End Panel Top Garnish	Dis	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel	DD	✓	
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD	✓	
1171	991328	Bootlid Emblem	NEC	✓	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber	CUT	✓	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
11336	990247	Sticker			

No of Items: 11

Assessor: _____

Umm TALIM 31/8/18

MOTOR CAR (Frt)

Front Portion

Vehicle No: **SLA-85464**

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	CUT ✓		
1005	992341	Frt Bumper Clips	NEC ✓		
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	NG ✓		
1008	991433	Frt Bumper Reinforcement	BT ✓		
1009	991318	Frt Bumper Beam	DD ✓		
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover	MIS ✓		
1018	991355	Frt RH Bumper Fog Lamp Cover	MIS ✓		
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	BR ✓		
1022	991328	Frt Grille Emblem	NEC ✓		
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy	BR ✓		
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	DD R		
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover	CRA ✓		
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items: **10**

AGENCY:

km, TGUm 31/8/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Aug 2018 Edit Reg		27 Aug 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

SUNRITA PRIVATE LIMITED, Co. Reg. No.: NA

Main Claimant:

GOH WEI KIAT, ID: S77056311

Vehicle Reg. No.:

SLQ8546H

Claim Type:

TP / 6227199584SG

Vehicle Reg. No. (Insured):

SLX3301T

Repairer:

LUSH AUTOMOTIVE PTE LTD (HQ) No. 8 Kaki Bukit Avenue 4,, #03-47 Premier@Kaki Bukit,, 415875 Kaki Bukit - Tel: 86662345

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 05/09/2018]

Claimant's Solicitor:

EAST ASIA LAW CORPORATION - Tel: 63232565

Date of Loss:

21/08/2018 00:00 - :59
[107 Months and 3 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

0999994691 (Comprehensive)

Policy No. (Claimant):

Excess:

[Created by adjuster]

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG_SG (28/08/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ8546H (6227199584SG)
[SLX3301T]
TP
GOH WEI KIAT
Aug 21 2018 12:00AM
[SUNRITA PRIVATE LIMITED]
LUSH AUTOMOTIVE PTE LTD

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images											3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	29/08/18 18:49	General View										Load JPG	☒	
2	29/08/18 18:49	General View										Load JPG	☒	
3	29/08/18 18:49	General View										Load JPG	☒	
4	29/08/18 18:49	General View										Load JPG	☒	
5	29/08/18 18:49	General View										Load JPG	☒	
6	29/08/18 18:49	General View										Load JPG	☒	
7	29/08/18 18:49	General View										Load JPG	☒	
8	29/08/18 18:49	General View										Load JPG	☒	
9	29/08/18 18:49	General View										Load JPG	☒	
10	29/08/18 18:49	General View										Load JPG	☒	
11	29/08/18 18:49	General View										Load JPG	☒	
12	29/08/18 18:49	General View										Load JPG	☒	
13	29/08/18 18:49	General View										Load JPG	☒	
14	29/08/18 18:49	General View										Load JPG	☒	
15	29/08/18 18:49	General View										Load JPG	☒	
16	29/08/18 18:49	General View										Load JPG	☒	
17	29/08/18 18:49	General View										Load JPG	☒	
18	29/08/18 18:49	General View										Load JPG	☒	
19	29/08/18 18:49	General View										Load JPG	☒	
20	29/08/18 18:49	General View										Load JPG	☒	
21	29/08/18 18:49	General View										Load JPG	☒	
22	29/08/18 18:49	General View										Load JPG	☒	
23	29/08/18 18:49	General View										Load JPG	☒	
24	29/08/18 18:49	General View										Load JPG	☒	
25	29/08/18 18:49	General View										Load JPG	☒	
26	29/08/18 18:49	General View										Load JPG	☒	
27	29/08/18 18:49	General View										Load JPG	☒	
28	29/08/18 18:49	General View										Load JPG	☒	
29	29/08/18 18:49	General View										Load JPG	☒	
30	29/08/18 18:49	General View										Load JPG	☒	
31	29/08/18 18:49	General View										Load JPG	☒	
32	29/08/18 18:49	General View										Load JPG	☒	
33	29/08/18 18:49	General View										Load JPG	☒	
34	29/08/18 18:49	Dismantled Parts										Load JPG	☒	
35	29/08/18 18:49	Dismantled Parts										Load JPG	☒	
36	29/08/18 18:49	Dismantled Parts										Load JPG	☒	
37	29/08/18 18:49	Dismantled Parts										Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
39	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
40	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
41	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
42	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
43	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
44	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
45	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
46	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
47	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
48	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
49	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
50	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
51	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
52	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
53	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
54	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
55	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
56	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
57	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
58	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
59	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
60	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
61	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
62	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
63	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
64	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
65	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
66	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
67	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
68	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
69	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
70	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
71	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
72	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
73	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
74	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
75	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
76	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
77	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
78	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
79	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
80	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
81	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
82	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
83	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
84	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
85	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
86	29/08/18 18:49	Dismantled Parts	 Load JPG	☒
87	29/08/18 18:49	Dismantled Parts	 Load JPG	☒

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
Documentation				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	28/08/18 10:21	OI GIA REPORT		 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST				Reset	Save	Print
There are no document checklists configured.						

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Handling Insurer	
Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18015582/GZ4D3E2

Date: 04/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994691
Claimant Vehicle No : SLQ8546H **Insured Vehicle No :** SLX3301T
 Date of Loss: 21/08/2018 Nature of Claim: TP Claim No: 6227199584SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ8546H**
 Make & Model: AUDI A4, 1.8 T FSI MU S-Line CVT ABS (A) Engine No: CDH058403
 Reg. Date: 18/09/2009 (Man. Year: 2009) Chassis No: WAUZZZ8KXAA016755
 Colour: Silver Odometer: 161573 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/08/2018
 Date Inspected: 28/08/2018 Inspected At: LUSH AUTOMOTIVE PTE LTD (HQ)
 No. 8 Kaki Bukit Avenue 4,, #03-47
 Premier@Kaki Bukit,
 Singapore 415875

Estimated Period of Repair: 9.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
5	1		*REAR BUMPER BEAM	Bent	0.00 F	*- F
6	1		*REVERSE SENSOR	Cut	0.00 F	*- F
7	1		*REAR END PANEL	Repair	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Distorted	0.00 F	*- F
9	1		*REAR LH TAILLAMP PANEL	Dented	0.00 F	*- F
10	1		*BOOTLID	Dented	0.00 F	*- F
11	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
12	1		*BOOTLID RUBBER	Cut	0.00 F	*- F
13	1		*FRT BUMPER	Cut	0.00 F	*- F
14	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
15	1		*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
16	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
17	1		*FRT BUMPER BEAM	Dented	0.00 F	*- F
18	1		*FRT LH BUMPER FOG LAMP COVER	Missing	0.00 F	*- F
19	1		*FRT RH BUMPER FOG LAMP COVER	Missing	0.00 F	*- F
20	1		*FRT GRILLE	Broken	0.00 F	*- F
21	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
22	1		*FRT SUPPORT PANEL	* Check	0.00 F	*- F
23	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
24	1		*BONNET	Repair	0.00 F	*- F
25	1		*ENGINE UNDER COVER	Cracked	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >