

ASS. REC. BY:

REF CS3/AIG180/SS90/G24d32 Special Instruction:

Surveyor:

menmen

GWO Giong

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

27/8/18 @ 10:10am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCP 6382M

Insured:

SLQ 6151B

at Workshop m/s

TwinCar Automotive

Tel:

6842 0051

of

2 Keki Bkt Ave 2 # 01-17 118

Policy No:

Claim No:

7298144127SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

24/08/2018

CA / REV / REP. / REV 24 HRS

Cup

H.O.D. Endorsement:

Date/Time:

10:47am @ 27/8/18

Person Contacted:

Gilen

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SCP 6382M -x

SLQ 6151B -x

28/8/18

Dismantled.

3/9/18

After repair.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG18015590/Gz4d3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 27-08-2018



Code : AIG

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLQ 6151B	Veh. Inspected	SCP 6382M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	27/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/08/2018	Inspection Date	27/08/2018
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying

To: assignments@lkkauto.com, admin-a@lkkauto.com

Cc: Fong, Andy-SY

Sent: 27/8/2018 10:10:27 AM

Attachments:  27082018091819.pdf  24082018151945-0001.pdf  6382.pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Ave 2, #01-17
Singapore 417921
Tel No. : +65 6744 0510 / 6842 0051 Fax No. : +65 6741 0510
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

Our Ref: **SCP 6382 M**
Your ref: **SLQ 6151 B**

24 August 2018

AIG ASIA PACIFIC INSURANCE PTE. LTD. BY EMAIL Aashweenjeetkaur.Mithoosingh@aig.com ONLY
NO: 78 SHENTON WAY
#07-16 CHARTIS BUILDING
SINGAPORE 079120
Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT : LAW MAN FAI
VEHICLE NUMBER : SCP 6382 M
YOUR INSURED VEHICLE NUMBER : SLQ 6151 B
ACCIDENT ON 24 Aug 2018 ALONG KPE TOWARDS CITY BEFORE TUNNEL
AT ABOUT 08:50 HOURS

We refer to your email/fax dated **24 Aug 2018** wherein there is no agreement to the appointment to the appointment of Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

TWINCAR AUTOMOTIVE PTE LTD
Kaki Bukit Autohub
2 Kaki Bukit Avenue 2
#01-17
Singapore 417921
6842 0051 / 6744 0510 (Melody)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



Twincar Automotive Pte Ltd

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2943E
Vehicle Details	
Vehicle No.:	SCP6382M
Vehicle to be Exported:	No
Intended De-registration Date:	28 Aug 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	P520227819
Chassis No.:	JM6BM42A8F0143332
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$18,447.00
Original Registration Date:	12 Sep 2014
First Registration Date:	12 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$8,447.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Sep 2024
PARF Rebate Amount:	\$6,335.00
Intended COE Rebate Details	
COE Expiry Date:	11 Sep 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$65,710.00
COE Rebate Amount:	\$39,679.00
Total Rebate Amount:	\$46,014.00

The information contained herein is correct as at 28 Aug 2018

OK

<u>Vehicle No.</u>	SCP 6382M		Model / Make	Mazda S
<u>Date of Accident</u>	24/08/18			
<u>Time of Accident</u>	0850 HRS			
<u>Location of Accident</u>	KPE towards City before Tunnel.			
<u>Exact purpose use during accident</u>	Private Used.			
<u>Name of Owner</u>	Law Man Fai			
<u>Telephone No.</u>	H/P: 9633 4583	Home:	Office:	
<u>NRIC</u>	S 2612943 E.			
<u>Address</u>	BLK 201B, Compassvale Drive #15-537(8) 542201			
<u>Claim type</u>	OD	<u>THIRD PARTY</u>		REPORTING ONLY
<u>Insurance Company</u>	Indra			
<u>Type of Coverage</u>	<u>Comprehensive</u>	Third Party	Third Party / Fire / Theft	
<u>Policy No.</u>	M 493071			

<u>Name of Driver</u>	<u>As Above</u> If No,		
<u>NRIC</u>	Any Passengers: N.A.		
<u>Date of birth</u>	04/07/1962		
<u>Occupation</u>	Outdoor	/	<u>Indoor</u>
<u>Driving License Pass Date</u>	18/06/1992		
<u>Gender</u>	<u>Male</u>	/	Female
<u>Contact No.</u>	H/P:	Home:	Office:
<u>Address</u>			
<u>Driver have any own vehicle</u>	No,	If yes, Reg No.	
<u>Relationship</u>	Employee,	If no, state <u>owner</u>	
<u>Weather condition</u>	<u>Clear</u>	Raining	Other
<u>Road Surface</u>	<u>Dry</u>	Wet	Other
<u>Any Injuries</u>	No,	<u>If Yes, Who?</u>	
<u>Name And Contact No.</u>	Law Man Fai (H/P: 9633 4583)		
<u>Name And Contact No.</u>			
<u>Police Report</u>	<u>No,</u>	If Yes, Where?	

<u>Vehicle B No.</u>	SLQ 6151 B	Any Passengers:	Not sure
<u>Name of Driver</u>		Contact No.:	
<u>Vehicle C No.</u>		Any Passengers:	
<u>Vehicle D No.</u>		Any Passengers:	
<u>Vehicle E no.</u>		Any Passengers:	
<u>Vehicle F No.</u>		Any Passengers:	
<u>Vehicle G No.</u>		Any Passengers:	
<u>Witness Name</u>	N.A.	Witness Contact:	
<u>Accident Portion</u>	Rear Portion		
<u>Camera Recorder</u>	<u>Yes</u> / No		
<u>Email Address</u>	johnnilaw@gmail.com		

<u>PARTICULAR WORKSHOP</u>	Twincat
<u>CONTACT NO.</u>	6842 0051 / 6744 0510
<u>CONTACT PERSON</u>	Hui Xian
<u>FAX NO</u>	6741 0510
<u>WORKSHOP Email ADDRESS</u>	Sales@n51.com.sg

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



(A) SCP 6382M

(B) SLQ 6151B


KPE towards City before Tunnel.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On 24/08/18 at @ 0850hrs, I was travelling in my vehicle (SCP 6382M) along KPE towards city before the tunnel on the extreme right lane. I slow down and stopped due to traffic jammed ahead. Suddenly, a vehicle (SLQ 6151B) from behind collided onto the rear portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish 20.00	Cut	✓	
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper 1674.80	DI	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	MIS	✓	
1146	992341	Rear Bumper Clips 50.00	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer 52.00	BR	✓	1
1149	993045	Rear Bumper Reinforcement 53.00	DD	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge 79.20	Cut	✓	
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector 50.40	BR	✓	1
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor 250.00	Cut	✓	
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	Cut	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp 915.00	BR	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel	BUC	✓	
1166	995116	Rear RH Taillamp	CRA	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel	BUC	✓	
1169	993554	Rear Apron Panel			
1170	992895	Bootlid 920.70	DD	✓	
1171	991328	Bootlid Emblem 55.40	NEC	✓	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding Inner Board	DIS	✓	
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH 444.30	CR	✓	
1176	992899	Bootlid Lamp RH	CRA	✓	
1177	995243	Bootlid Lock	BT	✓	
1178	990377	Bootlid Rubber 156.90	Cut	✓	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SCP 6382M

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board	CRA	✓	
1203	994328	Spare Tyre Panel 790.30	DD	✓	
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw 50.00	Cut	✓	
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield	DIS	✓	
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim	Cut	✓	
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille	LA	CRA	✓
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			
Labour					
1. Check electrical system					
2. RNR Bootlid and rear bumper cut, panel beat and weld affected parts					
3. Spray paint and rust proof all affected parts.					

No of Items:

Assessor:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Aug 2018 Edit Reg		27 Aug 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LCRF Pte Ltd, Co. Reg. No.: NA		
Main Claimant:	-		
Vehicle Reg. No.:	SCP6382M	Date of Loss:	24/08/2018 00:00 - :59 [47 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 7298144127SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SLQ6151B	Policy No. (Claimant):	
		Excess:	
Repairer:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chew, Mavis] Chew.Mavis@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 05/09/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (28/08/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									






































Claim Documents



















































***SCP6382M (7298144127SG)**
[SLQ6151B]
















TP

-

Aug 24 2018 12:00AM
[LCRF Pte Ltd]
Twincar Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
2	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
3	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
4	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
5	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
6	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
7	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
8	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
9	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
10	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
11	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
12	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
13	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
14	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
15	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
16	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
17	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
18	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
19	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
20	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
21	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
22	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
23	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
24	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
25	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
26	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
27	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
28	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
29	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
30	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
31	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
32	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
33	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
34	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
35	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
36	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	
37	29/08/18 10:16	General View														Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	29/08/18 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
39	29/08/18 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
40	29/08/18 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
41	29/08/18 10:16	General View	 Load JPG	<input checked="" type="checkbox"/>
42	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
84	29/08/18 10:16	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
85	05/09/18 20:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	05/09/18 20:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	05/09/18 20:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	05/09/18 20:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	05/09/18 20:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	05/09/18 20:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
91	05/09/18 20:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	05/09/18 20:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	05/09/18 20:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	05/09/18 20:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	05/09/18 20:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	05/09/18 20:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	05/09/18 20:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	05/09/18 20:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	05/09/18 20:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
100	05/09/18 20:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
101	05/09/18 20:18	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	28/08/18 10:03	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18015590/GZ4D3E2

Date: 07/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SCP6382M

Insured Vehicle No : SLQ6151B

Date of Loss: 24/08/2018

Nature of Claim: TP

Claim No: 7298144127SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCP6382M**

Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6AT (A)

Engine No: P520227819

Reg. Date: 12/09/2014 (Man. Year: 2014)

Chassis No: JM6BM42A8F0143332

Colour: Grey

Odometer: 71361 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 27/08/2018

Date Inspected: 27/08/2018 Inspected At:

 Twincar Automotive Pte Ltd (Kaki Bukit)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI
 BUKIT AUTOHUB
 Singapore 417921

Estimated Period of Repair: 7.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE GARNISH	Cut	0.00 F	*- F
2	1		*REAR BUMPER	Dented	0.00 F	*- F
3	1		*REAR BUMPER TOW COVER	Missing	0.00 F	*- F
4	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
6	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
7	1		*REAR BUMPER SPONGE	Cut	0.00 F	*- F
8	1		*REAR BUMPER REFLECTOR	Broken	0.00 F	*- F
9	1		*REVERSE SENSOR	Cut	0.00 F	*- F
10	1		*REAR END PANEL	Dented	0.00 F	*- F
11	1		*REAR END PANEL TOP GARNISH	Cut	0.00 F	*- F
12	1		*REAR LH TAILLAMP	Broken	0.00 F	*- F
13	1		*REAR LH TAILLAMP PANEL	Buckled	0.00 F	*- F
14	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
15	1		*REAR RH TAILLAMP PANEL	Buckled	0.00 F	*- F
16	1		*BOOTLID	Dented	0.00 F	*- F
17	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
18	1		*BOOTLID INNER BOARD	Distorted	0.00 F	*- F
19	1		*BOOTLID LAMP LH	Cracked	0.00 F	*- F
20	1		*BOOTLID LAMP RH	Cracked	0.00 F	*- F
21	1		*BOOTLID LOCK	Bent	0.00 F	*- F
22	1		*BOOTLID RUBBER	Cut	0.00 F	*- F
23	1		*SPARE TYRE BOARD	Cracked	0.00 F	*- F
24	1		*SPARE TYRE PANEL	Dented	0.00 F	*- F
25	1		*SPARE TYRE LOCK SCREW	Cut	0.00 F	*- F
26	1		*REAR EXHAUST HEAT SHIELD	Distorted	0.00 F	*- F
27	1		*REAR LH FENDER INNER TRIM	Cut	0.00 F	*- F
28	1		*REAR FENDER AIR GRILLE LH	Cracked	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >