

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

MISHI AUTO PTE LTD
8 KAKI BUKIT AVENUE 4
#05-25 Premier @ Kaki Bukit
Singapore 415875

'24th August 2018

TPAXA
Asher.

JTDFR12W203002057

Accident date: 20th AUGUST 2018

Estimated repair cost for vehicle no: SJN4998C Toyota Wish 1.8 A '09

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Repair</i>		\$950.00 X
2	1	Rear boot lid emble logo <i>new</i>		\$74.10 ✓
3	1	Rear Boot Lid Inner Lock		\$349.10 +
4	1	Rear boot lid inner rubber		\$276.10 +
5	1	Rear Boot Lid Number Plate		\$50.00 +
6	2	Rear Boot Lid Number Plate Lamp	\$135.10	\$270.20 +
7	1	Rear Boot Lid Inner Trim board		\$680.00 +
8	1	Rear boot lid windscreen seal <i>new</i>		\$310.10 +
9	2	Rear tail lamp <i>new</i>	\$640.10	\$1,280.20 818
10	4	Rear tail lamp clips <i>new</i>	\$8.50	\$34.00 ✓
11	2	Rear tail lamp panel <i>Repair</i>	\$320.00	\$640.00 +
12	1	Rear End Panel outer <i>Dented</i>		\$740.00 581
13	1	Rear End Panel inner <i>new</i>		\$580.00 +
14	1	Rear End Panel Top Garnish <i>Dented</i>		\$400.40 23250
15	1	Rear spare tire lock		\$536.10 +
16	2	Rear fender inner trim board	\$870.00	\$1,740.00 +
17	1	Rear floor panel top cover		\$435.70 +
18	1	Rear floor panel sealant		\$120.00 +
19	1	Rear Bumper <i>Dented</i>		\$1,077.00 575
20	2	Rear Bumper side reflector <i>new</i>	\$83.10	\$166.20 X
21	2	Rear Bumper Side Bracket <i>new</i>	\$55.60	\$111.20 ✓
22	1	Rear Bumper reverse sensor <i>Damaged</i>		\$350.00 200(SN)
23	2	Rear Bumper Bracket <i>new</i>	\$68.40	\$136.80 X
24	8	Rear bumper clips <i>new</i>	\$6.50	\$52.00 30
25	1	rear exhaust		\$971.10 X
26	1	rear exhaust aluminium cover <i>new</i>		\$212.15 X

Rear Bumper lower Spoiler *Dented*

980 500(SN)

Subtotal :- \$12,545.45

2456.20

1842.15 SN: 700

labour charges

To Check Wiring System	\$60.00 30
Tuff Kote	\$150.00 50
To Remove & refix cushion	\$150.00 60
To Remove & refix rear exhaust	\$220.00 X
To Remove & refix rear windscreen	\$120.00 X
Gum	1540 \$50.00 X
To Remove & refix reverse Sensor	\$100.00 50
Towing charges	\$100.00 X
Panel beating	\$1,200.00 600
Spray painting	\$1,200.00 750

Subtotal :- \$3,350.00

Total:- \$15,895.45

total 408215
2/5: 32k.
05 Apr

32k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: