

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref: CC4/ASM18015601/R1pa3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: YVONNE ANG			Date: 16-10-2019 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJW 4364J	Veh. Inspected	SLE 474Y
	Policy No.	VCX/P2040515	Coverage (\$)	0.00
	Claim No.	S8M00T4L	Excess (\$)	0.00
	Assign From	YVONNE ANG	Assign Date	24/08/2018
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA SIENTA 1.5	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	NSP1707027179	Colour	WHITE
	Odometer	183649	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	165/50 R16	FIRENZA	5 mm
	L/H Front Tyre	165/50 R16	FIRENZA	5 mm
	R/H Rear Tyre	165/50 R16	FIRENZA	5 mm
	L/H Rear Tyre	165/50 R16	FIRENZA	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	23/08/2018	Inspection Date	28/08/2018
	Survey held at	6 BENOI SECTOR		
	Repairer	VERMOGEN ACE PTE LTD		
5a.	a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
5b.		Estimate	Days of Repair	