



SLE474Y

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA

OWN INSURER : AIG

CLAIM TYPE : TP

Date of Accident : 23-Aug-2018

Vehicle Reg. No. : SLE474Y

Vehicle Reg. Date: 4-Jul-2016

Make / Model : SIENTA 1.5X CVT ABS D/A

Engine No. : 2NR8601761

Chassis No. : NSP1707027179

COST OF CLAIMS

Parts Cost / List Items : \$ 8,614.90

Plus/Less 25% \$ 2,153.73

Total Cost / List : \$ 6,461.18

Special Nett Items : \$ 990.00

Total Parts Amount : \$ 7,451.18

Total Labour Amount : \$ 2,800.00

Gross Total : \$ 10,251.18

GST % : 7% \$ 717.58

Nett Amount : \$ 10,968.76

Surveyor Name and Company :

RASUL

Date of survey : 28/08/18 @ 1130

Part by Part / Lump Sum 3 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : _____

Fax No : _____

HP No : 90010068

This claim is handled by : MINOKO

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE474Y**
 Vehicle Reg. Date: **4/7/2016**
 Make / Model : **SIENTA 1.5X CVT ABS D/AIRBAG 2WD 5DR**
 Engine No. : **2NR8601761**
 Chassis No. : **NSP1707027179**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Headlamp RH	SCR	\$ 2,300.00		
2	1	Headlamp panel RH	X	\$ 130.00		
3	1	Front bumper	DE	\$ 679.00		
4	1set	Front bumper clips	REC	\$ 50.00		
5	1	Front bumper logo	X	\$ 97.60		
6	1	Front bumper sponge	CRA	\$ 97.60		
7	1	Front bumper reinforcement	X	\$ 489.00		
8	1	Front bumper upper retainer	CL	\$ 92.00		
9	2	Front bumper side retainer LH/RH	X	\$ 192.00		
10	1	Front bumper grille	SCR	\$ 750.00		
11	1	Front bumper tow cover	SCR	\$ 32.00		
12	1	Fog lamp RH	X	\$ 450.00		
13	1	Fog lamp garnish RH	SCR	\$ 147.60		
14	1	Front fender RH	X	\$ 690.00		
15	1	Front fender inner shield RH	X	\$ 250.00		
16	1set	Front fender inner shield clips RH	X	\$ 50.00		
17	1	Washer tank	X	\$ 122.00		
18	1	Washer tank motor	X	\$ 235.00		
19	1	FRONT WHEEL COVER RH	X	\$ 250.00		
20	1	FRONT SHOCK ABSORBER RH	X	\$ 243.10		
21	1	FRONT SHOCK ABSORBER MOUNTING RH	X	\$ 50.00		
22	1	FRONT WHEEL BEARING RH	X	\$ 80.00		
23	1	FRONT LOWER ARM RH	X	\$ 250.00		
24	1	FRONT STABILIZER LINK RH	X	\$ 113.00		
25	1	FRONT TIE ROD END RH	X	\$ 134.00		
26	1	FRONT KNUCKLE ARM RH	X	\$ 404.00		
27	1	FRONT WHEEL HUB RH	X	\$ 237.00		
28	1	Front rim RH	X		\$ 350.00	
29	1	Front tyre RH	X		\$ 150.00	
30	01	Front Bumper Lower cover	CRA			
31	0	0				
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. :	SLE474Y
Vehicle Reg. Date:	4/7/2016
Make / Model :	SIENTA 1.5X CVT ABS D/AIRBAG 2WD 5DR
Engine No. :	2NR8601761
Chassis No. :	NSP1707027179

PAGE 1

[illegible]