

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

24-Aug-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6356 Z

1 pc	Front bumper /	\$	531.00
1 pc	Front bumper emblem /	\$	44.00
1 pc	Front bumper inner sponge X	\$	110.00
1 pc	Front bumper reinforcement X	\$	328.00
1 pc	Front bumper n/s side retainer @ \$16.00 X	\$	16.00
1 pc	Front bumper n/s upper bracket @ \$16.00 X	\$	16.00
1 pc	Front bumper n/s support bracket @ \$16.00 X	\$	16.00
1 pc	n/s head lamp /	\$	1,028.00
1 pc	Front bumper n/s fog lamp cover X	\$	66.00
1 pc	Front bumper n/s protector X	\$	51.00
1 pc	Front n/s fender inner shield X	\$	120.00
1 pc	Front n/s fender /	\$	384.00
1 pc	Front n/s wheel cover /	\$	116.00
		\$	<u>2,826.00</u>
		\$	282.60
		\$	<u>2,543.40</u>
S/NETT			
1 pc	Front bumper clips /	\$	48.00
1 pc	Front n/s head lamp lower clip /	\$	6.00
1 pc	Front n/s head lamp side clip /	\$	3.00
1 pc	Front n/s fender sticker X	\$	30.00
1 set	Front n/s fender inner shield clips X	\$	28.00
	Sundry	\$	50.00 20
	To check for wiring and to focus n/s head lamp	\$	40.00 20
	To check wheel alignment	\$	80.00 X
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	\$	700.00 400
	To putty and spray painting on front bumper, front n/s fender	\$	400.00 360
	To apply rustproofing on the repaired and replaced panels.	\$	120.00 50
		\$	<u>4,228.40</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplier's warranty must be resurveyed and is subject to approval from Insurance Company

Less 10%

Acknowledge by Repairer
Signature:
Date:

Kalvin Ullery

24/8/18 11:10am

3 Days

4/5
After Repair photo