

INS. CASE OWNER:

CC 4,111 180 15605, P1 wa39

LKK:
IDAC:

Surveyor:

RAGNI

DOI:

ASSIGNMENT

27/8/2018

Date / Time:

27/8/18

Registered in Merimen:

27/8/18

Pre-assign / CCU / FTE

SHC 1174P



Insured Vehicle No.:

Name of Insured:

CYP

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

30/3/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LAW HOCK CHAN

Driver Tel No.:

87278359

(V/L: YES / NO)

Claim No.:

MCT18070913

Policy No.:

MCOM0015

Make / Model:

H-Sonata

Place of Accident:

Anson Rd X Cecil St

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SLP 4866R



INSRS:

WSP:

Tel:

Liability:

RMKS:

Pegasus



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

30/8

SLP 4866R - X

SHC 1174P - NINE 110025741 Fu : MVA 8/2/2011

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

31/8/18

Seek liability under via merimen

4/9/18

Receive CAD video. TP reversed. reject TP claim.

4/9/18

Email to wkshop reject claim.

RECEIVED 04 SEP 2018

Reject Case

By: VIGAN

Approved by: Jm

Date: 06/9/18

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost:

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

10x14

\$350.00

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Prone

ASSIGNMENT

Veh No: SLP 4866R Yr Regn: 2017 / Gen

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA VIOS 1.5E c.c. 1496

Colour: GRN A/C: Insured / Std / NI / NA

Sp. Reading 53524 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MHF B29 F3202012104

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~Worder~~ / Jammed / Leaked / Burnt or

Brake: ~~In order~~ / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/50R16

Re:

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 1 mm L/Bal. 6 mm

D.O.A. 30/07/18 D.O.I. 27/08/18

Survey held at PEHAR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
4/9/18	Submit 2B-2 \$1766.00 with 4 working days exclude check runs & 816.00 (Red. # 8264 82%)

☐: Prell. Report

□: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

Lump Sum / I.B.I: (\$)

□: Interview (\$

Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

Photos

Others:

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLP4866R
Vehicle to be Exported:	No
Intended De-registration Date:	27 Aug 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E CVT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	2NRX160036
Chassis No.:	MHFB29F3202012104
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$12,785.00
Original Registration Date:	07 Jun 2017
First Registration Date:	07 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$7,785.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Jun 2027
PARF Rebate Amount:	\$5,838.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,600.00
COE Rebate Amount:	\$45,291.00
Total Rebate Amount:	\$51,129.00

The information contained herein is correct as at 27 Aug 2018

OK

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : QUAY SIEW TENG Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
--	---

Quotation No. : QO18/08-1317	Quotation Date : 25/08/2018	Terms : 30 DAYS
Vehicle No. : SLP4866R	Chassis No. : MHFB29F3202012104	Third Party Insurer : III
Model : VIOS	Date of Accident : 30/07/2018	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER	1	505.0000 <i>DE ✓</i>	505.00
2	REAR BUMPER SIDE RETAINER LONG	2	120.0000 <i>?</i>	240.00
3	REAR BUMPER SIDE RETAINER SHORT	2	45.0000 <i>?</i>	90.00
4	REAR BUMPER CLIPS	10	10.0000 <i>nee ✓</i>	100.00
5	REAR BUMPER REFLECTOR	2	215.0000 <i>X M</i>	430.00
6	REAR REINFORCEMENT	1	135.0000 <i>?</i>	135.00
7	REAR END PANEL	1	725.0000 <i>repair</i>	725.00
8	REAR END PANEL TOP GARNISH	1	255.0000 <i>?</i>	255.00
9	REAR END PANEL TOP GARNISH CLIPS	10	5.0000 <i>?</i>	50.00
10	BOOTLID COVER	1	825.0000 <i>repair</i>	825.00
11	BOOTLID HINGE	2	60.0000 <i>X NN</i>	120.00
12	BOOTLID LOCK	1	125.0000 <i>X NN</i>	125.00
13	BOOTLID 'TOYOTA' EMBLEM	1	60.0000 <i>repair</i>	60.00
14	BOOTLID 'VIOS' BADGE	1	55.0000 <i>repair</i>	55.00
15	BOOTLID 'E' BADGE	1	50.0000 <i>repair</i>	50.00
16	BOOTLID OUTER PROTECTOR	1	290.0000 <i>X NN</i>	290.00
17	BOOTLID INNER TRIM BOARD COVER	1	535.0000 <i>X NN</i>	535.00
18	BOOTLID INNER TRIM BOARD COVER CLIPS	10	3.5000 <i>X NN</i>	35.00
19	REAR TAILLAMP	2	325.0000 <i>X NN</i>	650.00
20	REAR TAILLAMP CLIPS	6	5.0000 <i>X NN</i>	30.00
21	REAR FENDER	2	915.0000 <i>X NN</i>	1,830.00
22	REAR FENDER SPLASH SHIELD	2	65.0000 <i>X NP</i>	130.00
23	REAR FENDER SPLASH SHIELD CLIPS	20	3.5000 <i>X NN</i>	70.00

C/F 0.00

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : QUAY SIEW TENG Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :
--	---

Quotation No. : QO18/08-1317	Quotation Date : 25/08/2018	Terms : 30 DAYS
Vehicle No. : SLP4866R	Chassis No. : MHFB29F3202012104	Third Party Insurer : III
Model : VIOS	Date of Accident : 30/07/2018	
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	REAR SPARE TYRE PANEL	1	795.0000 X ^{MP}	795.00
25	REAR SPARE TYRE PANEL FLOOR BOARD	1	265.0000 X ^{MP}	265.00
26	LESS 20% (ITEM 1-26)	1	-1,735.0000	-1,735.00
27	REAR REVERSE SENSOR	2	280.0000 ^{200?}	560.00
28	TO REMOVE AND REINSTALL REAR TRIMS, FLOOR CARPET AND SEAT TO FACILITATE REPAIR	1	150.0000 ⁶⁰	150.00
29	TO APPLY RUST PROOFING/TUFFICATING TREATMENT TO REPLACE PARTS	1	120.0000 ³⁰	120.00
30	TO REMOVE & REPLACED REAR BUMPER SENSOR	1	120.0000 ⁶⁰	120.00
31	TO REMOVE, REPLACED DAMAGED BODYPARTS, REPAIR & REALIGN BODYWORK & WHERE CONSISTENT TO THE ACCIDENT	1	1,200.0000 ⁴⁰⁰	1,200.00
32	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.	1	1,200.0000 ⁶⁰⁰	1,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurers Company

Acknowledged by Repairer
Signature:
Date:

Rasul
H/ 90010068
4 days
P/P
27/08/18 @ 1745
Resy by paint

Sub Total	10,010.00
GST(7.00%)	700.70
Total (SGD)	10,710.70

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

View Received Message

This mail is associated with :

***SLP4866R (MCT18070913)**
[SHC1174P]

TP
GRAB RENTALS PTE LTD
Jul 30 2018 3:00PM

Pegasus Engineering & Trading Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 04/09/2018 09:35 AM,
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SLP4866R - Claim Handler: Sundari Nagarajan

Approved:0.00:CCTV uploaded, To deny TP claim, TP reversed

DOCUMENTS SUMMARY

There are no documents.

Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Tuesday, 4 September, 2018 12:01 PM
To: 'ar_claims@pegasusengrg.com.sg'; lionelchua@pegasusengrg.com.sg
Subject: Your Ref: SLP 4866R, Our Ref: CC4/III18015605/R1wa3, Accident involving SLP 4866R and SHC 1174P on 30/07/2018
Attachments: Sketch Plan .pdf; SHC 1174P.MP4

WITHOUT PREJUDICE

Your Ref: SLP 4866R
Our Ref: CC4/III18015605/R1wa3

Dear Sir/Madam,

Accident involving SLP 4866R and SHC 1174P on 30/07/2018

We refer to the above matter

Our insured driver has reiterated that the accident was caused due to the entire negligence of your client. Your client reversed and hit our Insured.

We attached herewith our insured's accident report and video footage for your perusal.

Under such circumstances, we have our principal's instruction to deny liability of your client's claim.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Aug 2018 Edit Reg		27 Aug 2018 00:00 Edit Adj Rpt	S\$1,766.00 Edit Estimates	S\$1,766.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Vehicle Reg. No.:	SLP4866R	Date of Loss:	30/07/2018 15:00 - :59 [13 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18070913	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC1174P	Policy No. (Claimant):	A29069766MKF						
		Excess:							
Repairer:	Pegasus Engineering & Trading Pte Ltd (Kian Teck) 74 Kian Teck Road, 628800 Pioneer - Tel: 65137751								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 05/09/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
III_SG (04/09/2018): Alert - Adj Mandate Approved (S\$0.00) - SLP4866R - Claim Handler: Sundari Nagara...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP4866R (MCT18070913)

[SHC1174P]

TP

GRAB RENTALS PTE LTD

Jul 30 2018 3:00PM

[COMFORT TRANSPORTATION PTE LTD]

Pegasus Engineering & Trading Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Video									1 per page					
No	Finalized On	India International Insurance Pte Ltd (HQ)									Thumbnail	Print		
1	04/09/18 09:34	Video - Accident									Load MP4			
Photos/Images									3 per page					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print		
1	04/09/18 12:03	General View									Load JPG		☒	
2	04/09/18 12:03	General View									Load JPG		☒	
3	04/09/18 12:03	General View									Load JPG		☒	
4	04/09/18 12:03	General View									Load JPG		☒	
5	04/09/18 12:03	General View									Load JPG		☒	
6	04/09/18 12:03	General View									Load JPG		☒	
7	04/09/18 12:03	General View									Load JPG		☒	
8	04/09/18 12:03	General View									Load JPG		☒	
9	04/09/18 12:03	General View									Load JPG		☒	
10	04/09/18 12:03	General View									Load JPG		☒	
11	04/09/18 12:03	General View									Load JPG		☒	
12	04/09/18 12:03	General View									Load JPG		☒	
13	04/09/18 12:03	General View									Load JPG		☒	
14	04/09/18 12:03	General View									Load JPG		☒	
15	04/09/18 12:03	General View									Load JPG		☒	
16	04/09/18 12:03	General View									Load JPG		☒	
17	04/09/18 12:03	General View									Load JPG		☒	
18	04/09/18 12:03	General View									Load JPG		☒	
19	04/09/18 12:03	General View									Load JPG		☒	
20	04/09/18 12:03	General View									Load JPG		☒	
21	04/09/18 12:03	General View									Load JPG		☒	
22	04/09/18 12:03	General View									Load JPG		☒	
23	04/09/18 12:03	General View									Load JPG		☒	
24	04/09/18 12:03	General View									Load JPG		☒	
25	04/09/18 12:03	General View									Load JPG		☒	
26	04/09/18 12:03	General View									Load JPG		☒	
Documentation									1 per page					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print		
1	27/08/18 19:37	ACKNOWLEDGEMENT EMAIL TO III DD 27.08.2018									Load PDF			
2	27/08/18 19:37	TP GIA REPORT									Load PDF			
3	29/08/18 20:19	TP ESTIMATE - MARKED									Load PDF			
4	04/09/18 12:02	Email to wkshop reject claim 4.9.18									Load PDF			
No	Finalized On	India International Insurance Pte Ltd (HQ)									Thumbnail	Print		
1	28/08/18 08:44	Singapore Accident Statement									Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18015605/R1WA3Q2

Date: 07/09/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: MCOM0015

Claimant Vehicle No: SLP4866R

Insured Vehicle No: SHC1174P

Date of Loss: 30/07/2018

Nature of Claim: TP

Claim No: MCT18070913

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP4866R

Make & Model: TOYOTA VIOS, 1.5 E CVT (A)

Engine No: 2NRX160036

Reg. Date: 07/06/2017 (Man. Year: 2017)

Chassis No: MHFB29F3202012104

Colour: Grey

Odometer: 53524 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/50 R16

Rear Tyre Size: 195/50 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,276.00	616.00	6,660.00	91.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,790.00	1,150.00	1,640.00	58.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,066.00	1,766.00	8,300.00	82.46
+ GST 7.00/7.00% (S\$)	704.62	123.62	581.00	82.46
Nett Amount (S\$)	10,770.62	1,889.62	8,881.00	82.46
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 27/08/2018

Date Inspected: 27/08/2018 Inspected At:

Pegasus Engineering & Trading Pte Ltd
(Kian Teck)
74 Kian Teck Road
Singapore 628800

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Sep 2018)	
Parts: 143	TOYOTA VIOS 1.5 E CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLP4866R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	505.00 FL	*505.00 FL
2	2		*REAR BUMPER SIDE RETAINER LONG	*Check	240.00 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINER SHORT	*Check	90.00 FL	*- FL
4	10		*REAR BUMPER CLIPS	Necessary	100.00 FL	*100.00 FL
5	2		*REAR BUMPER REFLECTOR	Not Necessary	430.00 FL	*- FL
6	1		*REAR REINFORCEMENT	*Check	135.00 FL	*- FL
7	1		*REAR END PANEL	Repair	725.00 FL	*- FL
8	1		*REAR END PANEL TOP GARNISH	*Check	255.00 FL	*- FL
9	10		*REAR END PANEL TOP GARNISH CLIPS	*Check	50.00 FL	*- FL
10	1		*BOOTLID COVER	Repair	825.00 FL	*- FL
11	2		*BOOTLID HINGE	Not Necessary	120.00 FL	*- FL
12	1		*BOOTLID LOCK	Not Necessary	125.00 FL	*- FL
13	1		*BOOTLID TOYOTA EMBLEM	Necessary	60.00 FL	*60.00 FL
14	1		*BOOTLID VIOS BADGE	Necessary	55.00 FL	*55.00 FL
15	1		*BOOTLID E BADGE	Necessary	50.00 FL	*50.00 FL
16	1		*BOOTLID OUTER PROTECTOR	Not Necessary	290.00 FL	*- FL
17	1		*BOOTLID INNER TRIM BOARD COVER	Not Necessary	535.00 FL	*- FL
18	10		*BOOTLID INNER TRIM BOARD COVER CLIPS	Not Necessary	35.00 FL	*- FL
19	2		*REAR TAILLAMP	Not Necessary	650.00 FL	*- FL
20	6		*REAR TAILLAMP CLIPS	Not Necessary	30.00 FL	*- FL
21	2		*REAR FENDER	Not Necessary	1,830.00 FL	*- FL
22	2		*REAR FENDER SPLASH SHIELD	Not Necessary	130.00 FL	*- FL
23	20		*REAR FENDER SPLASH SHIELD CLIPS	Not Necessary	70.00 FL	*- FL
24	1		*REAR SPARE TYRE PANEL	Not Necessary	795.00 FL	*- FL
25	1		*REAR SPARE TYRE PANEL FLOOR BOARD	Not Necessary	265.00 FL	*- FL
26	2		*REAR REVERSE SENSOR	*Check	560.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,955.00	770.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,679.00	154.00
Total Parts (\$\$)	7,276.00	616.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL REAR TRIMS ,FLOOR CARPET AND SEAT TO FACILITATE REPAIR	New	150.00	60.00
2	TO APPLY RUST PROOFING /TUFFICATION TREATMENT TO REPLACE PARTS	New	120.00	30.00
3	TO REMOVE & REPLACED REAR BUMPER SENSOR	New	120.00	60.00
4	TO REMOVE,REPLACE DAMAGED BODYPARTS ,REPAIR & REALIGN BODYWORK & WHRE CONSISTENT TO THE ACCIDENT	New	1,200.00	400.00
5	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS	New	1,200.00	600.00
Gross Labour Cost (S\$)			2,790.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >