

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0966/2018/PH
Date : 24-Aug-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Tong Mei Lai
Address : 9 Rosewood Dr
 : #09-18
 : Singapore 737938
Telephone : (HP) +65 97603516
Type of Claim : Own Damage Claim
Policy No. : 1800017516
Vehicle No : **SDS 9809 C**
Model Code : Audi A4 2.0 TFSI
Model / Year : Feb-18
Engine No : CVK 050766
Chassis No : WAUZZZF44JA07336
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Aug-18
Place of Accident : 101 Yishun Ave 5 Chong Pang City lot 85 carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SDS 9809 C.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall ABCD pillar trims. Dislodge roof liner, remove antenna and disengage curtain air bags.	S/N \$ 1,800.00	✓
2	To remove and renew front windscreen.	S/N \$ 480.00	✓
3	To cut out and weld lhs A-pillar. Repair roof panel. Reinstall all parts removed.	\$ 3,600.00	1750.
4	To respray roof panel, lhs A-pillar, roof channel and lhs rear fender. To carry out joint sealer works.	\$ 2,500.00	1550
5	To dismantle lhs front door panel trim, carry out vacuum and removal of wood splinters. Reinstall all parts removed.	S/N \$ 480.00	✓
6	To carry out diagnostic check	S/N \$ 192.00	✓
SUB - LABOUR CHARGES		: \$ 9,052.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDS 9809 C .

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	GRAB HANDLE - FRONT	2 \$	248.00 ✗
2	GRAB HANDLE - REAR LH/RH	2 \$	248.00 ✗
3	FRONT WINDSCREEN	\$	1,004.00 ✓
4	CLAMP STRIP A-PILLAR - LH	\$	30.00 ✓
5	PRIMER	\$	19.00 ✓
6	GEL FOIL FOR RAIN SENSOR	\$	127.00 ✓
7	TRIM STRIP FOR WINDOW GUIDE - LH	\$	222.00 ✗
8	WINDSCREEN SEALANT	\$	200.00 ✓
9	ARCYLIC SEALANT	S/N \$	180.00 ✓
10	CAVITY WAX	S/N \$	140.00 ✓
11	METAL FILLER POWDER	S/N \$	280.00 ✓
12	WATER DEFLECTOR STRIP -LH	\$	58.00 ✓
13	SECTIONAL PART - PILLAR A/B	\$	2,347.00 ✓
14	SUNDRIES	\$	600.00 ?
TOTAL SPARE PARTS CHARGES		:	\$ 5,703.00
TOTAL LABOUR CHARGES		:	\$ 9,052.00
GRAND TOTAL		:	\$ 14,755.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 28/08/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 07 Days Before Paint Resurvey Required *

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant