

PDI TUAS

PDI TUAS

LIM AH JOON
56 THOMSON GREEN
Singapore, 574932
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV029073
Quote No. SER/QUO/1801371
QuoteDate 21/08/18
Salesperson Jacqueline Yong
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Golf 1.0 TSI 81 kW Trendline	866	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SKS2432T	WVWZZZAUZJW231227	26/06/18	Jacqueline Yong
Engine Code	Labor Type	Engine No.	Model Code
	1T	CHZ 940599	BQ12AZ

No.	Description	Qty.	UoM	Unit Price	Amount
<i>Bumper, Bootlid.</i>					
P B&P MACP LABOUR	LABOUR	3	UNIT		1680
P B&P MACP PAINT	SPRAY PAINT	3	UNIT		2520.00
P B&P DIAG	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	1	Time Un		480.00
P B&P MECH	CHECK WIRE HARNESS, ECU, S Nett	1	Time Un		280.00
	Sum Labor				5,680.00
P 5G0807305D	REINFORCEMENT Use Predecessor 5G0807305B	1	Pieces		? 748.02
P 5G0945093AH	LHR INNER TAIL LIGHT	1	Pieces		SCR 604.74
P 5G0945095Q	LHR OUTER TAIL LIGHT	1	Pieces		SCR 633.23
P 5G0945105C	RHR REFLECTOR	1	Pieces		? 97.34
P 5G6807393	LHR BUMPER BRACKET	1	Pieces		Net 46.13
P 5G6807393A	LHR TAILLIGHT BRACKET	1	Pieces		? 46.13
P 5G6807394	RHR BUMPER BRACKET	1	Pieces		X 46.13
P 5G6807394A	RHR TAILLIGHT BRACKET	1	Pieces		X 46.13
P 5G6807417BQGRU	REAR BUMPER	1	Pieces		DE 1,149.75
P 5G6807568Q 9B9	SPOILER	1	Pieces		? 341.82
P 5G6807863C	REAR BUMPER CENTRE BRACK	1	Pieces		? 105.80
P WHT005263	POP-RIVET	3	Pieces		Net 5.09
P WHT009007	RIVET	1	Pieces		Net 1.11
	Sum carried forward				9,551.38

Payments to: - BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

LIM AH JOON
56 THOMSON GREEN
Singapore, 574932
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV029073
Quote No. SER/QUO/1801371
QuoteDate 21/08/18
Salesperson Jacqueline Yong
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Golf 1.0 TSI 81 kW Trendline	866	Tang Shu Shi
License No.	VIN	Initial Registration	Sales Advisor
SKS2432T	WVWZZZAUZJW231227	26/06/18	Jacqueline Yong
Engine Code	Labor Type	Engine No.	Model Code
	1T	CHZ 940599	BQ12AZ

Continued 9,551.38

Sum Item 3,871.38

Sum Labor 5,680.00

Sum Item 3,871.38

Total SGD 9,551.38

7% GST 9,551.38 668.64

Total SGD Incl. GST 10,220.02

RASUL
Hp 90010068
4 1/2 days
30/08/18 @ 1400

Explanations

P = Proportionately Charged

Payment Terms No Credit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Payments to: - BBN: - Acc.-No..: