

1/1/2010

INS. CASE OWNER:

CC 6/AIG1801

5624, A job 82

LKK:  
IDAC:

Surveyor:

Admin

DOI:

ASSIGNMENT

27/8/18

Date / Time:

27/8/18

Registered in Merimen:

27/8/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLJ 9925

Name of Insured

GEA BAN PENGI

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

26/8/18

Is driver the owner?

( YES / ☒ NO )

Nature of Accident:

If NO, Driver Name / Age: GEA HUNG UM

Driver Tel No.:

(V/L: ☒ YES / NO )

Claim No.:

27261661556

Policy No.:

20048440

Make / Model:

TOYOTA

Place of Accident:

PIE TMS HONG

OI GIA REPORT: ☒ YES / NO : TP GIA REPORT: ☒ YES / NO

Insured Liability: % Final ? Yes / No

SGC 2550



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Hus  
Meng



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:



INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/ Time

5/9/18  
204

SGC 2550 - 4

5/9/18 - 4

HEAD TO REAR.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

4-9-18 JOY

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

( days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed/ Assessed) BOLA S/N No.:

27

Repair Cost:

SS

3,800

Loss of Rental (LOR):

SS

400

( 4 days)

x 100

Loss of Use (LOU):

SS

X

(S

x

days)

Loss of Income (LOI):

SS

X

(S

x

days)

LOR only

☐

LOU only

☐

LOR + LOU

☐

LOR + LO

☐

[Tick only one]

GIA/LTA Search

SS

7.49

Medical:

SS

Disbursement:

SS

X

(e.g. Tow/ Independent )

Legal Cost

SS

4,207.49

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

4,207.49

Name 1:

HUA MENG SPRAY PAINTING WORKSHOP

Payee 2: (Strike if N.A.)

SS

X

Name 2:

X

Payee 3: (Strike if N.A.)

SS

X

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

REF:

ASS. REC. BY: Abrian King

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SGC255SD Yr Regn: 2006 / Jun.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis c.c 1598Colour: Gold A/C: Insured / Std / NI / NASp. Reading: 266237. T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MROS3ZEC107109132Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60R15R: 195/60R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Crucero.

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. D.O.I. 27/08/18.Survey held at Hua Meng.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AIG.

COE Expiry: 12/01/21

MV: 18.5K  
PV: 13.5K  
Nett: 5K.

20-11-18 \$3,800 -

R(\$7,529.55/66%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos:

Others:

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                          |                            |            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------|----------------------------|------------|-------------------------------------------------------------------------------------|
| AIG ASIA PACIFIC INSURANCE PTE LTD                                                                                                     |                                                                                          | Ref : CC6/AIG18015624/Ajb3 |            |                                                                                     |
| 78 SHENTON WAY #08-16<br>CHARTIS BUILDING<br>SINGAPORE 079120                                                                          |                                                                                          | Date : 28-08-2018          |            |  |
|                                                                                                                                        |                                                                                          | Code : AIG                 |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                          |                            |            |                                                                                     |
| Insured Veh.                                                                                                                           | SLJ 992S                                                                                 | Veh. Inspected             | SGC 2555D  |                                                                                     |
| Policy No.                                                                                                                             |                                                                                          | Coverage (\$)              | 0.00       |                                                                                     |
| Claim No.                                                                                                                              |                                                                                          | Excess (\$)                | 0.00       |                                                                                     |
| Assign From                                                                                                                            |                                                                                          | Assign Date                | 28/08/2018 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                          |                            |            |                                                                                     |
| Make & Model                                                                                                                           |                                                                                          | c.c                        | 0          |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                                                   | Year of Reg.               |            |                                                                                     |
| Chassis No.                                                                                                                            |                                                                                          | Colour                     |            |                                                                                     |
| Odometer                                                                                                                               |                                                                                          | Steering                   |            |                                                                                     |
| Brakes                                                                                                                                 |                                                                                          | Modification               |            |                                                                                     |
| General                                                                                                                                |                                                                                          |                            |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                          |                            |            |                                                                                     |
|                                                                                                                                        | Size                                                                                     | Make                       | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                         |                                                                                          |                            | mm         |                                                                                     |
| L/H Front Tyre                                                                                                                         |                                                                                          |                            | mm         |                                                                                     |
| R/H Rear Tyre                                                                                                                          |                                                                                          |                            | mm         |                                                                                     |
| L/H Rear Tyre                                                                                                                          |                                                                                          |                            | mm         |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                          |                            |            |                                                                                     |
|                                                                                                                                        |                                                                                          |                            |            |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                                          |                            |            |                                                                                     |
| Accident Date                                                                                                                          | 26/08/2018                                                                               | Inspection Date            | 27/08/2018 |                                                                                     |
| Survey held at                                                                                                                         | HUA MENG SPRAY PAINTING WKSP<br>1 KAKI BUKIT AVE 6<br>#01-61 AUTOBAY<br>SINGAPORE 417883 |                            |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                          |                            |            |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                          |                            |            |                                                                                     |

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

LIM WEI TING

BLK641 BEDOK RESERVOIR ROAD

#14-65

S 410641

TPA16.  
Jay

Date

:05.09.2018

Vehicle no

:SGC 2555 D

Make/Model

:TOYOTA ALTIS

Accident date

:26.08.2018

| No                | DESCRIPTION                                          | Qty | Amount (S\$)           |
|-------------------|------------------------------------------------------|-----|------------------------|
| <u>List Items</u> |                                                      |     |                        |
| 1                 | Rear windscreen rubber <i>new</i>                    | 1   | \$ 53.8 ✓              |
| 2                 | Rear boot lid <i>Buckled.</i>                        | 1   | \$ 845.3 ✓             |
| 3                 | Rear boot lid hinges @ \$56.40 <i>new</i>            | 2   | \$ 112.8 ✓             |
| 4                 | Rear boot lid upper lock                             | 1   | \$ 81.7 ✓              |
| 5                 | Rear boot lid lower lock <i>fixer</i>                | 1   | \$ 25.5 ✓              |
| 6                 | Rear boot lid handle                                 | 1   | \$ 176.5 ✓             |
| 7                 | Rear boot lid centre logo <i>new</i>                 | 1   | \$ 65.7 ✓              |
| 8                 | Rear boot lid reflector @ \$80.60 <i>new</i>         | 2   | \$ 161.2 ✓             |
| 9                 | Rear boot lid weather strip <i>new</i>               | 1   | \$ 143.1 ✓             |
| 10                | Rear boot lid cable <i>new</i>                       | 1   | \$ 57.6 ✓              |
| 11                | Rear end panel <i>Dented.</i>                        | 1   | \$ 708.3 ✓             |
| 12                | Rear end panel inner top garnish <i>Replaced</i>     | 1   | \$ 53.6 ✓              |
| 13                | Rear lamp @ \$299.60 <i>cracked</i>                  | 2   | \$ 599.2 ✓             |
| 14                | Rear lamp housing @ \$487.00 <i>Repair</i>           | 2   | \$ 974 ✓               |
| 15                | Rear lamp lower panel @ \$92.30 <i>Best</i>          | 2   | \$ 184.6 ✓             |
| 16                | Rear lamp lower panel rivet @ \$3.00 <i>new</i>      | 6   | \$ 18 ✓                |
| 17                | Rear lamp rubber @ \$48.00 <i>new</i>                | 2   | \$ 96 ✓ <i>40(2N).</i> |
| 18                | Rear bumper <i>Replaced</i>                          | 1   | \$ 385.3 ✓             |
| 19                | Rear bumper side holder @ \$17.20 <i>new</i>         | 2   | \$ 34.4 ✓              |
| 20                | Rear bumper bracket @ \$51.00 <i>RH Dented</i>       | 2   | \$ 102.4 ✓ <i>51</i>   |
| 21                | Rear bumper clips <i>new</i>                         | 1   | \$ 25 ✓                |
| 22                | Rear LH fender <i>Repair</i>                         | 1   | \$ 758.2 ✓             |
| 23                | Rear fender inner trim @ \$161.20 <i>new</i>         | 2   | \$ 322.4 ✓             |
| 24                | Rear fender inner shield @ \$70.20                   | 2   | \$ 140.4 ✓             |
| 25                | Rear exhasut pipe <i>new</i>                         | 1   | \$ 387.4 ✓             |
| 26                | Rear exhaust pipe mounting <i>new</i>                | 1   | \$ 55 ✓                |
| 27                | Rear spare tyre top board <i>new</i>                 | 1   | \$ 49.1 ✓              |
| 28                | Rear spare tyre well <i>Repair</i>                   | 1   | \$ 757 ✓               |
| 29                | Rear spare tyre well insulation @ \$57.20 <i>new</i> | 3   | \$ 171.9 ✓             |
| 30                | Rear boot lid COROLLA emblem                         | 1   | \$ 24.1 ✓              |
| 31                | Rear boot lid VVTI emblem                            | 1   | \$ 41.7 ✓              |
| 32                | Rear boot lid 1.6emblem                              | 1   | \$ 44.5 ✓              |
|                   |                                                      |     | 7655.7                 |

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

LIM WEI TING

BLK641 BEDOK RESERVOIR ROAD

#14-65

S 410641

Date

:05.09.2018

Vehicle no

:SGC 2555 D

Make/Model

:TOYOTA ALTIS

Accident date

:26.08.2018

| No | Description                                | Qty | Amount (\$\$) |
|----|--------------------------------------------|-----|---------------|
| 33 | Rear boot lid ALTIS emblem <i>3 new</i>    | 1   | \$ 65.7 ✓     |
| 34 | Rear boot lid TOYOTA emblem <i>3416.60</i> | 1   | \$ 78 ✓       |
|    | <i>2562.45</i>                             |     | \$ 7799.4     |
|    | Less 25% Disc                              |     | \$ 1949.85    |
|    | <i>SN:40</i> Total                         |     | \$ 5849.55    |

### Special Nett Items

|   |                                                       |   |            |
|---|-------------------------------------------------------|---|------------|
| 1 | Rear bumper reverse sensor <i>Damaged</i>             | 1 | \$ 380-200 |
| 2 | Rear boot lid inner soundproof sticker <i>not new</i> | 1 | \$ 450 x   |
|   | Total                                                 |   | \$ 830     |

### Labour Cost

|    |                                                     |              |
|----|-----------------------------------------------------|--------------|
| 1  | To supply rear windscreen sealant                   | nn \$ 50 +   |
| 2  | To supply rear end panel inner sealant              | nc \$ 200-60 |
| 3  | Remove & reinstall rear windscreen                  | \$ 200 x     |
| 4  | Remove & reinstall reverse sensor                   | \$ 150-50    |
| 5  | Remove & reinstall petrol tank                      | \$ 150 x     |
| 6  | Remove & reinstall exhaust pipe                     | \$ 150 x     |
| 7  | Remove & reinstall boot lid inner garnish           | \$ 200-60    |
| 8  | Remove, replace & repair consistent to the accident | \$ 1800-800  |
| 9  | Respray painting                                    | \$ 1600-800  |
| 10 | Tuff kote                                           | \$ 150-50    |
|    | Total                                               | \$ 4650      |

Grand Total \$ 11329.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4772.45

4/s: 3-8k

06 Days

3810



華明噴漆廠  
**HUA MENG SPRAY PAINTING WORKSHOP**

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883

Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680

Reg. No.: 254678/00M



Your Ref :

Our Ref :

Date: 28-11-2018

Attn: Motor Claims Dept

**ACCIDENT ON 26.08.2018 INVOLVING VEHICLE SGC 2555 D & SLJ 992 S ALONG**

**PIE TOWARDS CHANGI NEAR SIMS AVE**

With regards to the above, we are writing on behalf of the registered owner of vehicle SGC 2555 D which was involved in the above mentioned accident.

We are informed that the above accident was caused solely by the negligence of your insured vehicle SLJ 992 S. As a result of the accident, our client's vehicle was damaged and our client had instructed us to submit his claims for loss and expenses, particulars of which are follows:

|                                  |           |                 |
|----------------------------------|-----------|-----------------|
| 1) Repair cost                   | \$        | 3,800.00        |
| 2) Loss of rental-\$130 X 04days | \$        | 520.00          |
| 3) LTA search                    | \$        | 7.49            |
| <b>Total</b>                     | <b>\$</b> | <b>4,327.49</b> |

We hereby enclosed herewith the following documents for your consideration of the above claim.

a) Final Repair Bill Of SGC 2555 D

c) LTA SEARCH

b) GIA report

d) Owner / Driver NRIC & Driving License

華明噴漆廠  
HUA MENG SPRAY PAINTING WORKSHOP  
AUTOBAY@KAKI BUKIT  
1 KAKI BUKIT AVE 6 #01-34 SINGAPORE 417883  
TEL: 6747 8064, 6746 5519 FAX: 6743 4896

Yours faithfully,

**HUA MENG SPRAY PAINTING WORKSHOP**

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

### CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt                                              | Adj Submitted                                  | Ins Auth'd | Status                                                          |
|------|-----------------------------------------|---------------|---------------------------------------------------|------------------------------------------------------|------------------------------------------------|------------|-----------------------------------------------------------------|
| Main | 27 Aug 2018<br><a href="#">Edit Reg</a> |               | 27 Aug 2018 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$3,800.00</b><br><a href="#">Edit Estimates</a> | <b>S\$3,800.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[\[Created by adjuster\]](#)

|                             |                                                                                                                                               |                        |                                                                               |
|-----------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------|------------------------|-------------------------------------------------------------------------------|
| Insured:                    | <b>Gea Ban Peng</b> , ID: S2501252F                                                                                                           |                        |                                                                               |
| Main Claimant:              | <b>LIM WEI TING</b> , ID: S7936593I                                                                                                           |                        |                                                                               |
| Vehicle Reg. No.:           | <b>SGC2555D</b>                                                                                                                               | Date of Loss:          | 26/08/2018 17:00 - :59<br>[151 Months and 13 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | <b>TP / 2728166215SG</b>                                                                                                                      | Policy/Cover Note No.: | 2100489930 (Comprehensive)                                                    |
| Vehicle Reg. No. (Insured): | <b>SLJ992S</b>                                                                                                                                | Policy No. (Claimant): | PNPV2017-00000021-01                                                          |
|                             |                                                                                                                                               | Excess:                |                                                                               |
| Repairer:                   | <b>Hua Meng Spray Painting Workshop (HQ)</b> No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519 |                        |                                                                               |
| Handling Insurer:           | <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Chan, Kian-Meng</b> ]<br>Kianmeng.Chan1@aig.com  |                        |                                                                               |
| Claimant's Insurer:         | <b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700                                                                                          |                        |                                                                               |
| Adjuster:                   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... <b>[Final Rpt due 06/09/2018]</b>          |                        |                                                                               |

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |





## Claim Documents

**\*SGC2555D (2728166215SG)**  
**[SLJ992S]**  
**TP**  
**LIM WEI TING**  
**Aug 26 2018 5:00PM**  
**[Gea Ban Peng]**  
**Hua Meng Spray Painting Workshop**

|                         |                 |  |                                                                          |  |  |                    |  |  |              |  |  |              |  |  |              |  |  |                                     |  |                                     |  |
|-------------------------|-----------------|--|--------------------------------------------------------------------------|--|--|--------------------|--|--|--------------|--|--|--------------|--|--|--------------|--|--|-------------------------------------|--|-------------------------------------|--|
| Upload Documents        |                 |  | Upload Photos                                                            |  |  | Compose New Letter |  |  | Upload Video |  |  | Upload Audio |  |  | View         |  |  | View in Browser ▼                   |  |                                     |  |
| Letters/Correspondences |                 |  |                                                                          |  |  |                    |  |  |              |  |  |              |  |  | 1 per page ▼ |  |  | <input checked="" type="checkbox"/> |  |                                     |  |
| No                      | Finalized On    |  | LKK Auto Consultants Pte Ltd (HQ)                                        |  |  |                    |  |  |              |  |  |              |  |  |              |  |  | Thumbnail                           |  | Print                               |  |
| 1                       | (Draft)         |  | Third Party Express Settlement – Payment Breakdown                       |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Edit                                |  |                                     |  |
|                         |                 |  |                                                                          |  |  |                    |  |  |              |  |  |              |  |  |              |  |  |                                     |  |                                     |  |
| Assessment Reports      |                 |  |                                                                          |  |  |                    |  |  |              |  |  |              |  |  | 1 per page ▼ |  |  | <input checked="" type="checkbox"/> |  |                                     |  |
| No                      | Finalized On    |  | AIG Asia Pacific Insurance Pte. Ltd. (SG)                                |  |  |                    |  |  |              |  |  |              |  |  |              |  |  | Thumbnail                           |  | Print                               |  |
| 1                       | 29/08/18 11:49  |  | Accident Statement<br>From:SC - Reg. No: SLJ992S, Claimant: GEA BAN PENG |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load HTM                            |  |                                     |  |
|                         |                 |  |                                                                          |  |  |                    |  |  |              |  |  |              |  |  |              |  |  |                                     |  |                                     |  |
| Photos/Images           |                 |  |                                                                          |  |  |                    |  |  |              |  |  |              |  |  | 3 per page ▼ |  |  | <input checked="" type="checkbox"/> |  |                                     |  |
| No                      | Relabel/Reorder |  | LKK Auto Consultants Pte Ltd (HQ)                                        |  |  |                    |  |  |              |  |  |              |  |  |              |  |  | Thumbnail                           |  | Print                               |  |
| 1                       | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 2                       | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 3                       | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 4                       | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 5                       | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 6                       | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 7                       | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 8                       | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 9                       | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 10                      | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 11                      | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 12                      | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 13                      | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 14                      | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 15                      | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 16                      | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 17                      | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 18                      | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 19                      | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 20                      | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 21                      | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 22                      | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 23                      | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 24                      | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 25                      | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 26                      | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 27                      | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |
| 28                      | 20/11/18 16:58  |  | General View                                                             |  |  |                    |  |  |              |  |  |              |  |  | 1            |  |  | Load JPG                            |  | <input checked="" type="checkbox"/> |  |

| Letters/Correspondences |                |                                   | 1 per page ▼                                                                                   | ✓     |
|-------------------------|----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------|
| No                      | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print |
| 29                      | 20/11/18 16:58 | General View                      |  Load JPG   | ✓     |
| 30                      | 20/11/18 16:58 | General View                      |  Load JPG   | ✓     |
| 31                      | 20/11/18 16:58 | General View                      |  Load JPG   | ✓     |
| 32                      | 20/11/18 16:58 | General View                      |  Load JPG   | ✓     |
| 33                      | 20/11/18 16:58 | General View                      |  Load JPG   | ✓     |
| 34                      | 20/11/18 16:58 | General View                      |  Load JPG   | ✓     |
| 35                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG   | ✓     |
| 36                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG   | ✓     |
| 37                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG   | ✓     |
| 38                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG   | ✓     |
| 39                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG   | ✓     |
| 40                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG   | ✓     |
| 41                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG   | ✓     |
| 42                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG   | ✓     |
| 43                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG   | ✓     |
| 44                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG   | ✓     |
| 45                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG   | ✓     |
| 46                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG   | ✓     |
| 47                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG   | ✓     |
| 48                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG | ✓     |
| 49                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG | ✓     |
| 50                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG | ✓     |
| 51                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG | ✓     |
| 52                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG | ✓     |
| 53                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG | ✓     |
| 54                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG | ✓     |
| 55                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG | ✓     |
| 56                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG | ✓     |
| 57                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG | ✓     |
| 58                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG | ✓     |
| 59                      | 20/11/18 16:58 | Reinspection Photo                |  Load JPG | ✓     |
| 60                      | 20/11/18 16:59 | Reinspection Photo                |  Load JPG | ✓     |
| 61                      | 20/11/18 16:59 | Reinspection Photo                |  Load JPG | ✓     |
| 62                      | 20/11/18 16:59 | Reinspection Photo                |  Load JPG | ✓     |
| 63                      | 20/11/18 16:59 | Reinspection Photo                |  Load JPG | ✓     |
| 64                      | 20/11/18 16:59 | Reinspection Photo                |  Load JPG | ✓     |
| 65                      | 20/11/18 16:59 | Reinspection Photo                |  Load JPG | ✓     |
| 66                      | 20/11/18 16:59 | Reinspection Photo                |  Load JPG | ✓     |
| 67                      | 20/11/18 16:59 | Reinspection Photo                |  Load JPG | ✓     |
| 68                      | 20/11/18 16:59 | Reinspection Photo                |  Load JPG | ✓     |
| 69                      | 20/11/18 16:59 | Reinspection Photo                |  Load JPG | ✓     |
| 70                      | 20/11/18 16:59 | Reinspection Photo                |  Load JPG | ✓     |
| 71                      | 20/11/18 16:59 | Reinspection Photo                |  Load JPG | ✓     |
| 72                      | 20/11/18 16:59 | Reinspection Photo                |  Load JPG | ✓     |
| 73                      | 20/11/18 16:59 | Reinspection Photo                |  Load JPG | ✓     |
| 74                      | 20/11/18 16:59 | Reinspection Photo                |  Load JPG | ✓     |
| 75                      | 20/11/18 16:59 | Reinspection Photo                |  Load JPG | ✓     |
| 76                      | 20/11/18 16:59 | Reinspection Photo                |  Load JPG | ✓     |

| Letters/Correspondences |                 |                                   | 1 per page ▼                                                                                   | ✓     |
|-------------------------|-----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------|
| No                      | Finalized On    | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print |
| 77                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG   | ✓     |
| 78                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG   | ✓     |
| 79                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG   | ✓     |
| 80                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG   | ✓     |
| 81                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG   | ✓     |
| 82                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG   | ✓     |
| 83                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG   | ✓     |
| 84                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG   | ✓     |
| 85                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG   | ✓     |
| 86                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG   | ✓     |
| 87                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG   | ✓     |
| 88                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG   | ✓     |
| 89                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG   | ✓     |
| 90                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG   | ✓     |
| 91                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG   | ✓     |
| 92                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG   | ✓     |
| 93                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG   | ✓     |
| 94                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG   | ✓     |
| 95                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG   | ✓     |
| 96                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG | ✓     |
| 97                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG | ✓     |
| 98                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG | ✓     |
| 99                      | 20/11/18 16:59  | Reinspection Photo                |  Load JPG | ✓     |
| 100                     | 20/11/18 16:59  | Reinspection Photo                |  Load JPG | ✓     |
| 101                     | 20/11/18 16:59  | Reinspection Photo                |  Load JPG | ✓     |
| 102                     | 20/11/18 16:59  | Reinspection Photo                |  Load JPG | ✓     |
| 103                     | 20/11/18 16:59  | Reinspection Photo                |  Load JPG | ✓     |
| 104                     | 20/11/18 16:59  | Reinspection Photo                |  Load JPG | ✓     |
| 105                     | 20/11/18 16:59  | Reinspection Photo                |  Load JPG | ✓     |
| 106                     | 20/11/18 16:59  | Reinspection Photo                |  Load JPG | ✓     |
| 107                     | 20/11/18 16:59  | Reinspection Photo                |  Load JPG | ✓     |
| 108                     | 20/11/18 16:59  | Reinspection Photo                |  Load JPG | ✓     |
| 109                     | 20/11/18 16:59  | Reinspection Photo                |  Load JPG | ✓     |
| 110                     | 20/11/18 16:59  | Reinspection Photo                |  Load JPG | ✓     |
| 111                     | 20/11/18 16:59  | Reinspection Photo                |  Load JPG | ✓     |
| 112                     | 20/11/18 16:59  | Reinspection Photo                |  Load JPG | ✓     |
| Documentation           |                 |                                   | 1 per page ▼                                                                                   | ✓     |
| No                      | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print |
| 1                       | 28/08/18 17:07  | TP GIA REPORT                     |  Load PDF |       |
| 2                       | 11/03/19 12:02  | AUTHORISATION TO ACT              |  Load PDF |       |
| 3                       | 11/03/19 12:02  | LETTER TO OI                      |  Load PDF |       |
| 4                       | 11/03/19 12:02  | LTA SEARCH                        |  Load PDF |       |
| 5                       | 11/03/19 12:02  | RELEASE VOUCHER                   |  Load PDF |       |
| 6                       | 11/03/19 12:02  | RENTAL MILEAGE                    |  Load PDF |       |
| 7                       | 11/03/19 12:02  | RENTAL RECEIPT                    |  Load PDF |       |
| 8                       | 11/03/19 12:02  | WORKSHOP INVOICE                  |  Load PDF |       |

## Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer  
Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

|                   |                    |        |                          |
|-------------------|--------------------|--------|--------------------------|
| Vehicle No:       | SLJ992S (Insd veh) | Model: | TOYOTA COROLLA ALTIS 1.6 |
|                   | SGC2555D (TP veh)  |        | (A)                      |
| Date of Accident: | 26/08/2018         |        |                          |

|                                                                                                      |   |                                                 |     |       |           |                        |
|------------------------------------------------------------------------------------------------------|---|-------------------------------------------------|-----|-------|-----------|------------------------|
| Global Sum Settlement                                                                                | : | [ ]                                             | Yes | [ X ] | No        |                        |
| Repair Estimate                                                                                      | : | \$                                              |     |       | 11,329.55 |                        |
| Final Repair Cost                                                                                    | : | \$                                              |     |       | 3,800.00  |                        |
| Loss of Use                                                                                          | : | \$                                              |     |       |           | days at \$0.00 per day |
| Rental (if any)                                                                                      | : | \$                                              |     |       | 400.00    | 4 days                 |
| LTA / GIA Search Fee                                                                                 | : | \$                                              |     |       | 7.49      |                        |
| Others:                                                                                              | : | \$                                              |     |       |           |                        |
|                                                                                                      | : | \$                                              |     |       |           |                        |
| Final Settlement Sum                                                                                 | : | \$                                              |     |       | 4,207.49  |                        |
| Is Third Party Workshop GIA Registered? [ ] YES [ X ] NO (Kindly indicate below)                     |   |                                                 |     |       |           |                        |
| A) For <b>Non GIA Registered Workshop:</b>                                                           |   | Agreed Liability ____ 100 ____ (%)              |     |       |           |                        |
| B) For <b>GIA Registered Workshop:</b>                                                               |   | BOLA Applicable: Yes/ No BOLA Scenario No: ____ |     |       |           |                        |
| BOLA Liability: ____ (%)                                                                             |   | Assessed Liability (*): ____ (%)                |     |       |           |                        |
| * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply. |   |                                                 |     |       |           |                        |
| Remarks _____                                                                                        |   |                                                 |     |       |           |                        |

| Payment Instruction: Payee's Breakdown |                                  |   |             |
|----------------------------------------|----------------------------------|---|-------------|
| 1)                                     | Hua Meng Spray Painting Workshop | : | \$ 4,207.49 |
| 2)                                     |                                  | : | \$          |
| 3)                                     |                                  | : | \$          |
| 4)                                     |                                  | : | \$          |

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

11 Mar  
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG18015624/AJB3S2  
**Date:** 11/03/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100489930  
**Claimant Vehicle No :** SGC2555D **Insured Vehicle No :** SLJ992S  
 Date of Loss: 26/08/2018 Nature of Claim: TP Claim No: 2728166215SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGC2555D**  
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4537292  
 Reg. Date: 13/01/2006 (Man. Year: 2005) Chassis No: MR053ZEC107109132  
 Colour: Gold Odometer: 266237 km  
 Engine Capacity: 1598 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/60R15 Rear Tyre Size: 195/60R15  
 Front Left Side: Crucero 6 mm Rear Left Side: Crucero 6 mm  
 Front Right Side: Crucero 6 mm Rear Right Side: Crucero 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                                  | Repairer's       | Adjuster's      | Difference      | Diff %       |
|-------------------------------------------------|------------------|-----------------|-----------------|--------------|
| Parts                                           | 6,929.55         | 2,862.45        | 4,067.10        | 58.69        |
| Miscellaneous Items                             | 0.00             | 0.00            | 0.00            |              |
| Labour                                          | 4,400.00         | 1,910.00        | 2,490.00        | 56.59        |
| Paintwork Labour                                | 0.00             | 0.00            | 0.00            |              |
| Towing                                          | 0.00             | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>             | <b>11,329.55</b> | <b>4,772.45</b> | <b>6,557.10</b> | <b>57.88</b> |
| <b>Approved Total (Overridden) (S\$)</b>        |                  | <b>3,800.00</b> |                 |              |
| <b>Nett Amount (S\$)</b>                        | <b>11,329.55</b> | <b>3,800.00</b> | <b>7,529.55</b> | <b>66.46</b> |
| <b>+ Car Rental (4.0 x S\$100.00/day) (S\$)</b> |                  | 400.00          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                  | 7.49            |                 |              |
| <b>Nett Liability (S\$)</b>                     |                  | <b>4,207.49</b> |                 |              |

### INSPECTION

Date of Assignment: 27/08/2018  
 Date Inspected: 27/08/2018 Inspected At: Hua Meng Spray Painting Workshop (HQ)  
 No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit  
 Singapore 417883  
 Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING

**Manager:** Joy Irene Bascao

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                             | Condition     | Repairer's | Amount     |
|-----|-----|----------|-----------------------------------------|---------------|------------|------------|
| 1   | 1   |          | *REAR WINDSCREEN RUBBER                 | Not Necessary | 53.80 FL   | *- FL      |
| 2   | 1   |          | *REAR BOOT LID                          | Buckled       | 845.30 FL  | *845.30 FL |
| 3   | 2   |          | *REAR BOOT LID HINGES                   | Not Necessary | 112.80 FL  | *- FL      |
| 4   | 1   |          | *REAR BOOT LID UPPER LOCK               | Not Necessary | 81.70 FL   | *- FL      |
| 5   | 1   |          | *REAR BOOT LID LOWER LOCK               | Not Necessary | 25.50 FL   | *- FL      |
| 6   | 1   |          | *REAR BOOT LID HANDLE                   | Not Necessary | 176.50 FL  | *- FL      |
| 7   | 1   |          | *REAR BOOT LID CENTRE LOGO              | Necessary     | 65.70 FL   | *65.70 FL  |
| 8   | 2   |          | *REAR BOOT LID REFLECTOR                | Not Necessary | 161.20 FL  | *- FL      |
| 9   | 1   |          | *REAR BOOT LID WEATHER STRIP            | Cut           | 143.10 FL  | *143.10 FL |
| 10  | 1   |          | *REAR BOOT LID CABLE                    | Not Necessary | 57.60 FL   | *- FL      |
| 11  | 1   |          | *REAR END PANEL                         | Dented        | 708.30 FL  | *708.30 FL |
| 12  | 1   |          | *REAR END PANEL INNER TOP GARNISH       | Deformed      | 53.60 FL   | *53.60 FL  |
| 13  | 2   |          | *REAR LAMP                              | Cracked       | 599.20 FL  | *599.20 FL |
| 14  | 2   |          | *REAR LAMP HOUSING                      | Repair        | 974.00 FL  | *- FL      |
| 15  | 2   |          | *REAR LAMP LOWER PANEL                  | Bent          | 184.60 FL  | *184.60 FL |
| 16  | 6   |          | *REAR LAMP LOWER PANEL RIVET            | Necessary     | 18.00 FL   | *18.00 FL  |
| 17  | 1   |          | *REAR BUMPER                            | Deformed      | 385.30 FL  | *385.30 FL |
| 18  | 2   |          | *REAR BUMPER SIDE HOLDER                | Necessary     | 34.40 FL   | *34.40 FL  |
| 19  | 2   |          | *REAR BUMPER BRACKET                    | O/s Dented    | 102.40 FL  | *51.00 FL  |
| 20  | 1   |          | *REAR BUMPER CLIPS                      | Necessary     | 25.00 FL   | *25.00 FL  |
| 21  | 1   |          | *REAR LH FENDER                         | Repair        | 758.20 FL  | *- FL      |
| 22  | 2   |          | *REAR FENDER INNER TRIM                 | Not Necessary | 322.40 FL  | *- FL      |
| 23  | 2   |          | *REAR FENDER INNER SHIELD               | Not Necessary | 140.40 FL  | *- FL      |
| 24  | 1   |          | *REAR EXHAUST PIPE                      | Not Necessary | 387.40 FL  | *- FL      |
| 25  | 1   |          | *REAR EXHAUST PIPE MOUNTING             | Not Necessary | 55.00 FL   | *- FL      |
| 26  | 1   |          | *REAR SPARE TYRE TOP BOARD              | Torn          | 49.10 FL   | *49.10 FL  |
| 27  | 1   |          | *REAR SPARE TYRE WELL                   | Repair        | 757.00 FL  | *- FL      |
| 28  | 3   |          | *REAR SPARE TYRE WELL INSULATION        | Not Necessary | 171.90 FL  | *- FL      |
| 29  | 1   |          | *REAR BOOT LID COROLLA EMBLEM           | Necessary     | 24.10 FL   | *24.10 FL  |
| 30  | 1   |          | *REAR BOOT LID VVTI EMBLEM              | Necessary     | 41.70 FL   | *41.70 FL  |
| 31  | 1   |          | *REAR BOOT LID 1.6 EMBLEM               | Necessary     | 44.50 FL   | *44.50 FL  |
| 32  | 1   |          | *REAR BOOT LID ALTIS EMBLEM             | Necessary     | 65.70 FL   | *65.70 FL  |
| 33  | 1   |          | *REAR BOOT LID TOYOTA EMBLEM            | Necessary     | 78.00 FL   | *78.00 FL  |
| 34  | 1   |          | *REAR LAMP RUBBER                       | Necessary     | 72.00 FS   | *40.00 FS  |
| 35  | 1   |          | *REAR BUMPER REVERSE SENSOR             | Damaged       | 380.00 FS  | *200.00 FS |
| 36  | 1   |          | *REAR BOOT LID INNER SOUNDPROOF STICKER | Not Necessary | 450.00 FS  | *- FS      |
| 37  | 1   |          | *REAR WINDSCREEN SEALANT                | Not Necessary | 50.00 FS   | *- FS      |
| 38  | 1   |          | *REAR END PANEL SEALANT                 | Necessary     | 200.00 FS  | *60.00 FS  |

F=Franchise part, S=SpcNett, L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>8,855.40</b> | <b>3,716.60</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | <b>1,925.85</b> | <b>854.15</b>   |
| <b>Total Parts (\$\$)</b>                                  | <b>6,929.55</b> | <b>2,862.45</b> |

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                                          | Lab.Type | Repairer's      | Amount          |
|-------------------------|------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>     |                                                      |          |                 |                 |
| 1                       | REMOVE & REINSTALL REAR WINDSCREEN.                  | New      | 200.00          | 0.00            |
| 2                       | REMOVE & REINSTALL REVERSE SENSOR.                   | New      | 150.00          | 50.00           |
| 3                       | REMOVE & REINSTALL PETROL TANK.                      | New      | 150.00          | 0.00            |
| 4                       | REMOVE & REINSTALL EXHAUST PIPE.                     | New      | 150.00          | 0.00            |
| 5                       | REMOVE & REINSTALL BOOT LID INNER GARNISH.           | New      | 200.00          | 60.00           |
| 6                       | REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT. | New      | 1,800.00        | 850.00          |
| 7                       | RESPRAY PAINTING.                                    | New      | 1,600.00        | 900.00          |
| 8                       | TUFF KOTE.                                           | New      | 150.00          | 50.00           |
| Gross Labour Cost (S\$) |                                                      |          | <b>4,400.00</b> | <b>1,910.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >