

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5151D**AAD1808-174***Not Authorized
61 Sep 8/2001*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHC 5151D
VF1ABL15AUC276533
RENAULT
LATITUDE
20.8.2018
AIG

PART		LIST	
1	FENDER PANEL REAR RH	\$	<i>11</i> 3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	<i>12</i> 671.45
1	WHEELARCH REAR RH	\$	<i>12</i> 543.47
1	ROCKER PANEL INNER GARNISH RH	\$	<i>12</i> 466.51
1	ROCKER PANEL INNER RH	\$	<i>11</i> 1,024.79
1	ROCKER PANEL CENTER RH	\$	<i>11</i> 990.25
1	BUMPER COVER REAR	\$	<i>11</i> 1,108.46
1	BUMPER LOWER REAR	\$	<i>12</i> 768.84
1	BUMPER BRACKET CTR REAR	\$	<i>12</i> 113.47
1	BUMPER BRACKET SIDE RH REAR	\$	<i>12</i> 135.97
1	BUMPER RETAINER RH REAR	\$	<i>12</i> 44.99
1	DOOR MIRROR ASSY RH	\$	<i>11/12</i> 1,483.40
1	DOOR PANEL FRT RH	\$	<i>11</i> 2,844.66
		\$	13,495.39
10%		\$	1,349.54
		\$	12,145.85

Special Nett

1SET	PARKING AID	\$	<i>12</i> 700.00
1SET	REAR BUMPER CLIP	\$	<i>11</i> 66.00
1SET	BUMPER BRACKET CTR CLIP	\$	<i>11</i> 33.00
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>11</i> 10.00
1SET	BUMEP R RETAINER RH CLIP RR	\$	<i>11</i> 20.00
1SET	BUMEP R BRACKET SIDE CLIP LH RR	\$	<i>11</i> 10.00
1SET	BUMEP R RETAINER CLIP LH RR	\$	<i>11</i> 20.00
1SET	BUMPER LOWER REAR RIVET	\$	<i>11</i> 22.00
1SET	BUMPER LOWER REAR CLIP	\$	<i>11</i> 66.00

Trans-cab Auto Services Pte Ltd

AAD1808-174

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5151D

TOTAL \$ 947.00**TOTAL PARTS \$ 13,092.85****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	801
Putty and spray painting of the affected portion.	\$	2,800.00	601
To rust-proofing of the affected areas.	\$	170.00	nn X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	nn X
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	nn X

TOTAL \$ 7,290.00**Over All Total \$ 20,382.85****LUMP SUM (REPAIR DAY)**

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10 DAYS

1 day