

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9703E**AAD1808-157***Not Autharish*
\$3000

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9703E

KL1LA69RJBB125323

CHEVROLET

EPICA 2.0

17.8.2018

AXA

PART			LIST	
1	1	Rear Door LH (Panel A-RR DR LH)	\$	<i>N</i> 1,133.00
2	1	Rear door weatherstrip - Inner	\$	<i>Sm</i> 41.40
3	1	Rear door weatherstrip - 2nd Frame	\$	<i>Sm</i> 25.90
4	1	Rear door top hinge	\$	<i>N</i> 35.00
5	1	Rear door bottom hinge	\$	<i>N</i> 35.00
6	1	Rear door inner lock	\$	<i>N</i> 425.00
7	1	Rear door check / arrestor	\$	<i>Sm</i> 65.00
8	1	Rear door lock striker / latch	\$	<i>N</i> 120.00
9	1	Rear door outer weatherstrip moulding	\$	<i>Sm</i> 85.00
10	1	Side Rocker Panel Garnish LH	\$	<i>Sm</i> 236.40
11	1	Rear Fender LH	\$	<i>N</i> 1,145.00
12	1	Rear Fender Inner Trim LH	\$	<i>Sm</i> 418.44
13	1	Front Side Rocker Panel Garnish LH	\$	<i>Sm</i> 236.40
14	1	Front Side Rocker Panel Outer LH	\$	<i>N</i> 600.00
15	1	Front Side Rocker Panel Inner LH	\$	<i>N</i> 519.30
16	1	Rear Bumper	\$	<i>N</i> 1,202.00
TOTAL			\$	6,322.84
10%			\$	632.28
			\$	5,690.56

Specical Nett

1 Set	Front Bumper Fastener Clip	\$	<i>N</i> 24.00	<i>X</i>
1 Set	Front licence plate with holder	\$	<i>Sm</i> 192.00	<i>X</i>
1 Set	Radiator Grille clip	\$	<i>N</i> 35.00	<i>X</i>
1 Set	Front Fender Liner clip	\$	<i>N</i> 30.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1808-157

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9703E

1	Front Fender RR Bracket LH	\$	<i>na</i> 7.10	X
1	Rear Wheel Rim Hub Cap LH	\$	<i>sn</i> 166.30	X
1	Rear Tyre LH	\$	<i>sn</i> 180.00	X
1	Rear Tyre Rim RLH	\$	<i>sn</i> 126.00	X
1Set	Rear Fender Inner Trim Clip LH	\$	<i>na</i> 30.00	X

TOTAL	\$	790.40
--------------	-----------	---------------

TOTAL PARTS	\$	6,480.96
--------------------	-----------	-----------------

LABOUR

To Check Electrical Lighting Concerned.	\$	<i>na</i> 170.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	<i>100%</i>
Putty and spray painting of the affected portion.	\$	4,000.00	<i>200%</i>
Towing Fees.	\$	<i>na</i> 120.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>na</i> 380.00	X
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00	X
To rust-proofing of the affected areas.	\$	<i>na</i> 170.00	X

Trans-cab Auto Services Pte Ltd

AAD1808-157

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9703E

To check steering geometry and computer wheel alignment \$ *nn* 220.00 X

To transfer of tire, rim and on wheel balancing. \$ *nn* 170.00 X

To transfer of door fittings, attachment and perform water seepage test. \$ *nn* 170.00 X

To transfer of fender fittings, attachment and perform water seepage test. \$ *nn* 170.00 X

TOTAL \$ 10,460.00

Over All Total \$ 16,940.96

Repair Days (Lump Sum)

15 days

1 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: