

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9583J**AAD1808-204***Not Authorised
11 Sep @ 1950h*

Vehicle No.:

SHD 9583J

Chassis No.:

Vehicle Make:

CHEVROLET

Vehicle Model:

EPICA 2.0

Date of Accident :

23.8.2018

Third Party Insurer :

AXA**PART****LIST**

1	1	Front Fender RH	\$	<i>N</i>	837.60	X
2	1	Front Fender Liner RH	\$	<i>Sn</i>	47.00	X
3	1	Front Fender Inner Wheel House Panel RH	\$	<i>N</i>	1,437.00	X
4	1	Front Fender LH	\$	<i>N</i>	837.60	X
5	1	Front Fender Liner LH	\$	<i>Sn</i>	47.00	X
6	1	Front Fender Inner Wheel House Panel LH	\$	<i>N</i>	1,437.00	X
7	1	Front Bumper	\$	<i>Bumper</i>	1,202.00	✓
8	1	Front Bumper Lower Absorber	\$	<i>Sn</i>	180.00	X
9	1	Front Bumper Reinforcement	\$	<i>N</i>	356.00	X
10	1	Front Bumper Retainer RH	\$	<i>Sn</i>	102.00	X
11	1	Front Bumper Retainer LH	\$	<i>Dis</i>	102.00	✓
12	1	Front Bumper Lower Grille	\$	<i>Sn</i>	78.00	X
13	1	Front Bumper Lower Stiffener	\$	<i>N</i>	134.37	X
14	1	Front Bumper Bracket LH	\$	<i>N</i>	10.00	X
15	1	Front Bumper Bracket RH	\$	<i>N</i>	10.00	X
16	1	Bumper Fog Lamp Cover RH	\$	<i>Sn</i>	32.40	X
17	1	Bumper Fog Lamp Cover LH	\$	<i>Dis</i>	32.40	✓
18	1	Bonnet	\$	<i>N</i>	1,250.00	} X
19	1	Bonnet hinge RH	\$	<i>N</i>	36.00	
20	1	Bonnet hinge LH	\$	<i>N</i>	36.00	
21	1	Bonnet Moulding	\$	<i>Sn</i>	161.97	
22	1	Bonnet Lock	\$	<i>N</i>	60.00	
23	1	Bonnet cable	\$	<i>Sn</i>	125.00	
24	1	Front Support Panel Assy	\$	<i>N</i>	1,222.32	
25	1	Headlamp RH	\$	<i>Sn</i>	816.00	} X
26	1	Headlamp LH	\$	<i>mgcm</i>	816.00	
27	1	Windscreen Washer Tank - Filler Neck	\$	<i>Sn</i>	4.80	X
28	1	Windscreen Washer Tank	\$	<i>Sn</i>	62.00	X
29	1	Windscreen Washer Tank Motor	\$	<i>Sn</i>	51.00	X

Trans-cab Auto Services Pte Ltd

AAD1808-204

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9583J

30	1	Washer Tank Hose	\$	Sm	21.00	}	X
31	1	Radiator Assembly	\$	Sm	618.00		
32	1	Radiator upper hose	\$	Sm	30.00		
33	1	Radiator lower hose	\$	Sm	120.00		
34	1	Radiator Grille (Grille A-Rad)	\$	Sm	367.00		
35	1	Radiator Grille Top Cover	\$	Sm	45.02		
36	1	Fan Blade(A/C)	\$	Sm	536.00		
37	1	Fan Blade(Radiator)	\$	Sm	634.00		
38	1	Aircon Condenser	\$	Sm	600.00		
39	1	Aircon hose - condenser to compressor	\$	Sm	450.00		
40	1	Aircon hose - compressor to evaporator	\$	Sm	624.00		
41	1	Aircon hose - condenser to evaporator	\$	Sm	580.00		

TOTAL	\$	11,505.28
10%	\$	1,150.53
	\$	10,354.75

Special Nett

1	1 Set	Front Bumper Fastener Clip	\$	Mr	24.00	✓
2	2	Front Windscreen Sealant	\$	na	100.00	X
3	1	Front Windscreen Inner Sponge Seal	\$	na	100.00	X
4	1 Set	Radiator Grille Top Cover Clip	\$	na	10.00	X
5	1 Set	Front licence plate with holder	\$	CPI	192.00	£52
6	1 Set	Radiator Grille clip	\$	na	35.00	X
7	1 Set	Front Fender Liner clip RH	\$	na	30.00	X
8	1 Set	Louver Cowl Top clip	\$	na	30.00	X
9	2	Bonnet stopper	\$	na	15.00	X

TOTAL	\$	536.00
--------------	----	---------------

TOTAL PARTS	\$	10,890.75
--------------------	----	------------------

LABOUR

To Check Electrical Lighting Concerned.	\$	201 170.00
---	----	---------------

Trans-cab Auto Services Pte Ltd**AAD1808-204**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9583J

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,050.00	2001
Towing Fees.	\$	120.00	nn X
Putty and spray painting of the affected portion.	\$	4,200.00	2001
To Remove And Refit Front And Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	440.00	nn X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	nn X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	nn X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	nn X
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To replace, refix and top up coolant for radiator	\$	170.00	nn X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	nn X
To rust-proofing of the affected areas.	\$	170.00	nn X
To transfer of end panel fittings and conduct water seepage test.	\$	170.00	nn X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	nn X

Trans-cab Auto Services Pte Ltd

AAD1808-204

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9583J

To reinstall rear bumper parking sensor.

\$ *nn* 170.00 X**TOTAL** \$ 11,740.00**Over All Total** \$ 22,630.75**Repair Days**~~15 Days~~*1 1/2 days*

26,809.63#

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: