

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

27-Aug-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8675 U

1 pc	Rear o/s fender <i>X rep. n</i>	\$	1,208.00
1 pc	Rear o/s fender inner shield <i>X</i>	\$	120.00
1 pc	Rear windscreen moulding <i>X</i>	\$	87.00
1 pc	Rear o/s wheel cover <i>—</i>	\$	113.00
1 pc	Rear o/s rim <i>X</i>	\$	246.00
1 pc	Rear o/s lower arm <i>X</i>	\$	351.00
1 pc	Rear o/s shock absorber <i>X</i>	\$	313.00
1 pc	Rear o/s trailing arm <i>X</i>	\$	159.00
1 pc	Rear o/s assist arm <i>X</i>	\$	163.00
1 pc	Rear o/s upper arm <i>X</i>	\$	84.00
1 pc	Rear o/s knuckle arm <i>X</i>	\$	525.00
1 pc	Rear o/s knuckle bearing <i>X</i>	\$	349.00
1 pc	Rear bumper <i>—</i>	\$	696.00
2 pcs	Rear bumper side bracket o/s & o/s @ \$29.00 <i>X</i>	\$	58.00
		\$	4,472.00
		Less 10%	\$ 447.20
			\$ 4,024.80

### S/NETT

1 set	Rear bumper clips <i>X</i>	\$	48.00
1 pc	Rear o/s fender sticker <i>—</i>	\$	60.00
1 set	o/s door stickers <i>—</i>	\$	100.00
1 pc	Rear bumper top protector <i>—</i>	\$	<del>80.00</del> <i>50</i>
1 pc	Tyre <i>—</i> <i>50%</i>	\$	280.00
1 pc	Sealant <i>X</i>	\$	50.00

# ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8675 U

Sundry	\$	<del>50.00</del> 25
To check wheel alignment	\$	<del>80.00</del> 60
To dismantle / refit reverse sensor to new bumper and reset to the same	\$	<del>120.00</del> X
To dismantle and refit the rear windscreen	\$	<del>120.00</del> X
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	<del>180.00</del> 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the o/s rocker panel garnish, rear o/s door, etc	\$	<del>900.00</del> 60
To putty and spray painting on rear o/s fender, rear bumper, rear o/s door, o/s rocker panel garnish	\$	<del>950.00</del> 720
To apply rustproofing on the repaired and replaced panels.	\$	<del>250.00</del> X
	\$	<u>7,292.80</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Kalvin Uley  
N 27/8/18 1610 Lrs  
4 Lys  
Us  
After Repairs