

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLM8919L

Chassis No : JHMGK3850HX200447

Model : JAZZ 1.3LXR CVT 17YM

Owner's Name : OOI SU ZAN

Ins Policy No. :

Date of Accident : 25/8/2018

Document No. : SQT18003775 Page 1

Date : 7. Sep 2018

Customer No. : WZA006

Svc Advisor :

Engine No : L13B11020302

Date | Time : 7. Sep 2018 9:16:36 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	* 11.20	25	8.40	0.59	8.99
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	* 6.30	25	9.45	0.66	10.11
73226-SZW-000	DAMPERSTD 5X5	1	* 8.30	25	6.22	0.44	6.66
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	* 60.00		120.00	8.40	128.40
68100-TAR-U10ZZ	TAILGATE COMP	1	* 716.30	25	537.22	37.61	574.83
74440-T5A-003	WEATHERSTRIPTAILGATE	1	* 92.30	25	69.22	4.85	74.07
74801-T5A-013	LOCK ASSYTAILGATE	1	* 173.20	25	129.90	9.09	138.99
74813-T5A-003	STRIKER ASSYTAILGATE	1	* 24.70	25	18.52	1.30	19.82
84440-T5A-J02ZA	LINING ASSYTAILGATE LOWER	1	* 52.10	25	39.07	2.73	41.80
84441-T5A-003ZB	POCKETTAILGATE LINING PULL	1	* 5.00	25	3.75	0.26	4.01
75722-T5L-T01	EMBLEMRR.	1	* 10.50	25	7.87	0.55	8.42
33500-T5A-J02	TAILLIGHT ASSY,R.	1	* 235.10	25	176.32	12.34	188.66
04715-T5A-000ZZ	FACERR.BUMPER	1	de ✓ 492.70 ✓	25	369.52 ✓	25.87	395.39
71502-T5A-000	GARNISHR.RR.BUMPER	1	* 14.00	25	10.50	0.74	11.24
71507-T5A-000	GARNISHL.RR.BUMPER	1	* 14.00	25	10.50	0.74	11.24
71593-T5A-000	SPACERR.RR.BUMPER	1	nee ✓ 11.50 ✓	25	8.62 ✓	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER	1	nee ✓ 11.50 ✓	25	8.62 ✓	0.60	9.22
91505-TM8-003	CLIPBUMPER	5	nee ✓ 2.00 ✓	25	7.50 ✓	0.53	8.03
84640-T5A-003ZA	LINING ASSYRR.PANEL	1	* 60.80	25	45.60	3.19	48.79
Sum Item					1586.80	111.09	1,697.89



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

Registration No : SLM8919L

Chassis No : JHMGK3850HX200447

Model : JAZZ 1.3LXR CVT 17YM

Owner's Name : OOI SU ZAN

Ins Policy No. :

Date of Accident : 25/8/2018

Document No. : SQT18003775 Page 2

Date : 7. Sep 2018

Customer No. : WZA006

Svc Advisor :

Engine No : L13B11020302

Date | Time : 7. Sep 2018 9:16:36 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOSUN	SUNDRIES	1 30	100.00	✓	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	✓	180.00	12.60	192.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	✓	180.00	12.60	192.60
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	560.00	X	560.00	39.20	599.20
BOMISC1	REMOVE, INSTALL & RESET REAR VIEW CAMERA.(N)	1	380.00	X	380.00	26.60	406.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00	X	560.00	39.20	599.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	560.00	X	560.00	39.20	599.20
BKBU02R	REPLACE RR BUMPER, REPAIR RR PANEL & OTHER DAMAGE	1 1120	3000.00	✓	3000.00	210.00	3210.00
BP03R	SPRAY PAINTING ON TAILGATE, RR BUMPER & RR PANEL	1 900	3000.00	✓	3000.00	210.00	3210.00
Sum Labor					8520.00	596.40	9,116.40

Survey By Tan Jiah 97495349

Date & Time 7/9/18 @ 1030

Excess wp

Status wp

Signature [Signature] 4 days

Bring after before paint
sur@lkkauto.com

Total Amount 10,106.80 707.49 10,814.29

Total (Inclusive of GST) 10,814.29

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 7/9/2018 9:21:08 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)