

AutoSoon Pte Ltd

176 Sin Ming Drive #01-10

Sin Ming AutoCare Singapore 575721

Tel No. : 6452 6657 Fax No. : 6451 4618

E-Mail : autosoon1@gmail.com

Tax Reg. No. : 200709808N Buss. Reg. No. : 200709808N

SUNRANK

BLK 612B, PUNGGOL DRIVE #12-885

SINGAPORE 822612

Contact : 9821 7529

Estimate : ES000285

Date : 25/08/2018

Vehicle Num. : SLQ 4433 B

Make/Model : HONDA SHUTTLE 1.5G CVT-11.07.2017

Chassis/Eng# : GK81005938/L15B3536978

Accident Date : 25/08/2018

Claim No. :

Reference : TP/06/08/18

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	Rear tail gate assy		1,190.00
2.	1	Rear tail gate emblem		68.00
3.	1	Rear tail gate name badge		38.00
4.	1	Rear bumper facial assy		1,150.00
5.	8	Rear bumper facial clip	4.00	32.00
6.	1	Rear end panel		489.00
List Total S\$:				2,967.00
20.00% Discount S\$:				593.40
				2,373.60
LABOUR :				
1		To supply windshield sealant and dam rubber in repair	100	150.00
1		To remove windshield to facilitate tail gate replacment	100	150.00
1		To rewire damaged section and transfer wire harness	30	80.00
1		To supply reverse sensor	NN x	250.00
1		To remove tail gate spoiler, wiper and lock attachment trims, boards and transfer to new tail gate in repair	60	150.00
1		To putty and respray above mentioned panels and bumper	400	680.00
1		To remove/replace tail gate, panel beat damaged section and refix/realign tail gate and bumper in repair	300	580.00
1		To reseal new paint with ceramic coating by specialist include send vehicle to Yishun Industrial St 1	?	580.00
Labour Total S\$:				2,620.00

AutoSoon Pte Ltd

3 Days.

Lumpsum repair.

After repair photos.

Gino @ 282

82860282

30/8/18

Total S\$: 4,993.60

GST @ 7% S\$: 349.55

Amount Due S\$: 5,343.15

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: