

INSURER

INS. CASE OWNER

LYNTHIA

CC4 / AXA1801 5642, 21 W664

LKK

IDAC

Surveyor:

RAM

DOI:

ASSIGNMENT

25/8/18

Date / Time:

25/8/18

Registered in Meriton:

Pre-assign / CCU / FTE



Insured Vehicle No.:

YN 2488T

Name of Insured:

SINA LONG FOODSCUFF TRADING CO PTE

Insured Tel No.:

HP:

25/8/18

Excess Sec II : \$5

D.O.A.:

25/8/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Of GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

GLU 10000



INSRS:
WSP:
Tel:
Liability:
RMKS:

prime



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
25/8/18	GLU 10000 - X	Non-Reporting 1st (1st):	
		Non-Reporting 1st (2nd):	
		Non-Reporting 1st (Final):	
		Notification 1st (if non-pickup):	
		Call Of:	76/11/18 avail.
		After call 1st to Of:	25/8/18
		Documentation Check List: Handler	Typist
		Notification 1st (if non-pickup)	
		After call 1st to Of:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	\$5	(days) Reduction:
FINAL SETTLEMENT	Date/Time: 10/12/18	Confirm with: PICE
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : 27
Repair Cost:	\$5 5726.31	
Loss of Rental (LOR):	\$5 718.20	(7 days) x 79.80
Loss of Use (LOU):	\$5	(5 x days)
Loss of Income (LOI):	\$5	(5 x days)
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOU ☐		(Tick only one)
GIA/LTA Search	\$5	
Medical:	\$5	
Disbursement:	\$5	(e.g. Tow/ Independent)
Legal Cost	\$5	
Total:	\$5 6444.51	Global Sum \$5: 6400.00
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	\$5 6400.00	Name 1: Prime Auto Claims Service Pte Ltd
Payee 2: (Strike if N.A.)	\$5	Name 2:
Payee 3: (Strike if N.A.)	\$5	Name 3:

COPY SENT



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18015642/ub3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 28-08-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 2488T	Veh. Inspected	SLU 1099G	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	28/08/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	25/08/2018	Inspection Date		
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 27.08.2018

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01/02
AXA Tower
Singapore 068811

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SLU1099G TOYOTA AXIO HYBRID

To Supply

1)	1pc	rear bumper		\$	700.00	DE ✓
2)	1set	rear bumper clip		\$	30.00	NE ✓
3)	1pc	rear bumper right side retainer		\$	60.00	NE ✓
4)	1pc	left tail lamp lower bracket		\$	70.00	? X SU ✓
5)	1pc	left tail lamp		\$	450.00	RE ✓
6)	1pc	left tail lamp lower bracket		\$	70.00	? X SU ✓
7)	1pc	right tail lamp		\$	450.00	SU ✓
8)	1pc	right tail lamp lower bracket		\$	70.00	? X SU ✓
9)	1pc	rear boot lid		\$	680.00	HA ✓
10)	1pc	rear boot lid "corolla" emblem		\$	59.60	NE ✓
11)	1pc	rear boot lid "Hybrid Synergy Drive" emblem		\$	61.70	NE ✓
12)	1pc	rear boot lid "Axio" emblem		\$	48.60	NE ✓
13)	1pc	rear boot lid weatherstrip		\$	120.00	RE ✓
14)	2pcs	rear boot lid hinges	@\$157.60	\$	315.20	H ✓
15)	1pc	rear boot lid trim cover		\$	220.00	PO ✓
16)	1pc	rear boot lid lock		\$	90.00	HA ✓
17)	1pc	rear boot lid catch		\$	50.00	BT ✓
18)	1pc	rear boot lid chrome garnish		\$	295.16	CR ✓
19)	2pcs	rear boot no plate lamp	@\$ 61.10	\$	122.20	? X SU ✓
20)	1pc	rear end panel		\$	380.00	HA ✓
21)	1pc	rear end panel top garnish		\$	180.00	DE ✓
22)	1set	rear end panel top garnish clip		\$	20.00	NE ✓

23)	1pc	rear floor panel	\$	1,187.00	repeat X su
24)	1pc	left deck floor box 64997-13051	\$	518.10	X su
25)	1pc	package tray trim, panel assy 64330-12A30	\$	614.00	X su
26)	1pc	package tray trim pad 64334-12380	\$	26.00	su -
27)	1pc	left rear luggage compartment cover 64713-12011	\$	316.00	DE -

Sub total parts	\$	7,203.56	4103.26
Less: 25% discount	\$	(1,800.89)	-1025.57
	\$	5,402.67	3076.69

To supply S.Nett parts

1)	1set	reverse sensor	\$	180.00	su -
2)	1pc	reverse camera (invoice attached)	\$	80.00	? su -
				120.00	

Sub total S.Nett Parts	\$	260.00	300.00
------------------------	----	--------	--------

L/charges

1)	Towing charges (use king trolley)	\$	85.00	✓
2)	To transfer rear boot lid trim board, mechanism parts	\$	50.00	✓
3)	To tuff kote rear portion	\$	150.00	80
4)	To remove & replace reverse sensor & reverse camera	\$	80.00	60
5)	To remove rear bumper, cut / welding rear end panel, floor panel, right & left tail lamp. Replace the above parts. Adjust & align rear boot lid, rear bumper & etc.	\$	1,000.00	800
6)	To putty, respray painting rear boot lid inner & outer, rear bumper, rear end panel & floor panel. To polish	\$	1,100.00	900

Sub total L/charges	\$	2,465.00	1975.00
Estimated total	\$	8,127.67	5351.69

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature: _____
Date: _____

Rasu
Hy 90010068

8 days

P/P

28/8/18 @ 0510

Roy by paint

8 days
P/P

先進汽車音響私營有限公司
ADVANCE AUTO SOUND PTE LTD

BLK 33 SIN MING DRIVE #01-363
SINGAPORE 575707
TEL: 68730013 FAX: 65676104

REG.NO 201221004G
GST Reg No 201221004G

Bill To:

PRIME AUTO CLAIMS SERVICE PTE
LTD
5 BENOI PLACE
SINGAPORE 629926

Ship To:

PRIME AUTO CLAIMS SERVICE PTE
LTD
5 BENOI PLACE
SINGAPORE 629926

Tax Invoice

INVOICE 01808058

P/O NUMBER

DATE 30/08/2018

CHASSIS NO. SLU 1099G

MODEL T-AXIO

TERMS

Phone: 68610908

Fax:

Qty	Description	U/Price	Amount (S\$)
1	CMD E318 REVERSE CAMERA	120.00	120.00

S/C (7/12/16)
Scan by SLU1099G v. 2400

SINGAPORE DOLLARS

One Hundred Twenty-Eight Singapore Dollars and Forty Cents Only

Cheques are to be made payable to "Advance Auto Sound Pte Ltd"

Sale: PRIME AUTO CLAIMS SERVICE PTE LTD

Total	120.00
Freight	0.00
Add: GST 7%	8.40
Total Inc GST	128.40

RECEIVED BY & DATE


Advance Auto Sound Pte Ltd



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 27.08.2018

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01/02
AXA Tower
Singapore 068811

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SLU1099G TOYOTA AXIO HYBRID

To Supply

1)	1pc	rear bumper		\$	700.00	FE -
2)	1set	rear bumper clip		\$	30.00	NE -
3)	1pc	rear bumper right side retainer		\$	60.00	NE -
4)	1pc	left tail lamp lower bracket		\$	70.00	? -
5)	1pc	left tail lamp		\$	450.00	BA - ?
6)	1pc	left tail lamp lower bracket		\$	70.00	? X
7)	1pc	right tail lamp		\$	450.00	SC -
8)	1pc	right tail lamp lower bracket		\$	70.00	? X
9)	1pc	rear boot lid		\$	680.00	PA -
10)	1pc	rear boot lid "corolla" emblem		\$	59.60	NE -
11)	1pc	rear boot lid "Hybrid Synergy Drive" emblem		\$	61.70	NE -
12)	1pc	rear boot lid "Axio" emblem		\$	48.60	NE -
13)	1pc	rear boot lid weatherstrip		\$	120.00	NE -
14)	2pcs	rear boot lid hinges	@\$157.60	\$	315.20	H -
15)	1pc	rear boot lid trim cover		\$	220.00	PD -
16)	1pc	rear boot lid lock		\$	90.00	PA -
17)	1pc	rear boot lid catch		\$	50.00	BT -
18)	1pc	rear boot lid chrome garnish		\$	295.16	CR -
19)	2pcs	rear boot no plate lamp	@\$ 61.10	\$	122.20	? -
20)	1pc	rear end panel		\$	380.00	PA -
21)	1pc	rear end panel top garnish		\$	180.00	FE -
22)	1set	rear end panel top garnish clip		\$	20.00	NE -

23)	1pc	rear floor panel	\$	1,187.00	repair
24)	1pc	left deck floor box 64997-13051	\$	518.10	X
25)	1pc	package tray trim, panel assy 64330-12A30	\$	614.00	X
26)	1pc	package tray trim pad 64334-12380	\$	26.00	✓
27)	1pc	left rear luggage compartment cover 64713-12011	\$	316.00	DB ✓

Sub total parts	\$	7,203.56
Less: 25% discount	\$	(1,800.89)
	\$	5,402.67

To supply S.Nett parts

1)	1set	reverse sensor	\$	180.00	✓
2)	1pc	reverse camera	\$	80.00	?

Sub total S.Nett Parts	\$	260.00
------------------------	----	--------

L/charges

1)	Towing charges (use king trolley)	\$	85.00	✓
2)	To transfer rear boot lid trim board, mechanism parts	\$	50.00	✓
3)	To tuff kote rear portion	\$	150.00	80
4)	To remove & replace reverse sensor & reverse camera	\$	80.00	60
5)	To remove rear bumper, cut / welding rear end panel, floor panel, right & left tail lamp. Replace the above parts. Adjust & align rear boot lid, rear bumper & etc.	\$	1,000.00	800
6)	To putty, respray painting rear boot lid inner & outer, rear bumper, rear end panel & floor panel. To polish	\$	1,100.00	900

Sub total L/charges	\$	2,465.00
Estimated total	\$	8,127.67

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Resue
H 90010068
8 days
PIP
28/08/18 00910
Reg by paint

REPUBLIC OF SINGAPORE DRIVING LICENCE

YONG FOO SOON

Q8132033R

15 Nov 1981

22 May 2014

Valid till 21 May 2019

002307137H




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

CLASS	VEHICLE CLASS	EFFECTIVE DATE
Class 2B	Motorcycles <= 200 cc	22 May 2014
Class 3	Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg	22 May 2014

NP 428A

Q8132033R



信隆食品贸易私人有限公司

SING LONG FOODSTUFF TRADING CO PTE LTD

12 Woodlands Link, Singapore 738740. Tel: 6284 5254 Fax: 6289 7351

GST Reg. No.: M2-0089150-3 Reg. No.: 198904426E

Date: Nov 26, 2018

Re: Letter of Authorisation to drive company vehicle

To whom its may concern:

This letter is to certify that, YONG FOO SOON (FIN G8132033R), is employed by SING LONG FOODSTUFF TRADING COMPANY PTE LTD as the job title of a Driver who given the authority to drive Sing Long owned vehicle to fulfil his obligation assigned.

Regards

A handwritten signature in black ink, appearing to be 'Ng Chin Nyan', is written over a horizontal line.

Ng Chin Nyan (Director)



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 4883
www.police.gov.sg

Our Ref : TP/IP/55169/2018
Date : 17 OCTOBER 2018

YEO KIM SHEIN
BLK 124 KIM TIAN PLACE
#05-195
SINGAPORE 160124

Dear Sir/Madam

ROAD TRAFFIC ACCIDENT INVOLVING YN 2488 T AND SLU 1099 G ALONG JURONG WEST STREET 64 ON 25/08/2018 AT ABOUT 12.20PM

I refer to the above accident.

Please be informed that we have completed our investigations which revealed that the driver of YN 2488 T had committed an offence of **Careless Driving under Rule 29 of the Road Traffic Rules**. Action has been initiated against the driver for the said offence.

Yours faithfully

**HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE**

This is a computer-generated letter. No signature is required.



Re:S8M00TFP- mandate approval

Type

🔔 Question

Message

Mandate approved

Reply



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 10.09.2018

Our Ref: SLU1099G
LKK Ref: CC4/ASM18015642/R1wb3

AXA Insurance (S) Pte Ltd
No. 8 Shenton Way #27-01
AXA Tower
Singapore 068819

Without prejudice
By fax only
Fax: 6880 4838

Attn: Motor Claims Dept

Dear Sir / Madam,

ACCIDENT ON 25.08.2018 INVOLVING VEHICLE NO. SLU1099G & YN2488T

We are on behalf of M/S Section Credit & Motor Leasing Pte Ltd owner of SLU1099G in their third party claim against your insured / driver of vehicle YN2488T

Appended below our client's claim:-

1. Cost of repair	\$ 5,726.31
2. Loss of rental @\$79.80 x 9 days (Incl. 1 Sun)	\$ 718.20
3. GIA search fee	\$ 2.00

Total	\$ 6,446.51

We enclosed herewith copy of our Invoice 2477, GIA search receipt, Authorization to act, car rental agreement & Letter of certification. Please acknowledge receipt. For an amicable settlement, please let us have your offer.

Regards

Yours faithfully,

Ms. Alice Leong
e-mail: aliceleong@primeautoclaims.com

Encl.

Vivian Lau (LKKAUTO)

From: Vivian Lau (LKKAUTO)
Sent: Monday, 26 November, 2018 11:52 AM
To: jason@siemtrading.com.sg
Cc: Admin A
Subject: RE: ACCIDENT INVOLVING YN 2488T & SLU 1099G ALONG BOON LAY WAY ON 25/08/2018

YOUR REF : CC4/ASM18015642/R1wb3
OUR REF : YN 2488T

ACCIDENT INVOLVING YN 2488T & SLU 1099G ALONG BOON LAY WAY ON 25/08/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **Prime Auto Claims Service Pte Ltd** acting on behalf of the owner of SLU 1099G against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to Vivianlau@lkkauto.com within 7 days if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us 6841 8625 or email us at Vivianlau@lkkauto.com

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jason@siemtrading.com.sg [mailto:jason@siemtrading.com.sg]

Sent: Monday, 26 November, 2018 11:06 AM

To: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Subject: RE: ACCIDENT INVOLVING YN 2488T & SLU 1099G ALONG BOON LAY WAY ON 25/08/2018

Dear Vivian

Enclosed, pls find the letter of Authorization signed by company Director confirming Subject is currently an employee of SingLong

Regards

Jason

From: Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Sent: Monday, 26 November 2018 10:04 AM

To: jason@siemtrading.com.sg

Subject: RE: ACCIDENT INVOLVING YN 2488T & SLU 1099G ALONG BOON LAY WAY ON 25/08/2018

Dear Jason,

We refer to the email below.

Please be informed that **letter of authorisation** must have company letterhead.

This letter is to certify that , YONG FOO SOON (FIN G8132033R), is employed by SING LONG FOODSTUFF TRADING COMPANY PTE LTD.

AUTHORISATION TO ACT

In the matters of an accident involving my/our motor vehicle SLU 1099G
And others YN 2488T
on 25.08.2018 along SLIP ROAD OF JURONG WEST ST 64

I / We SECTION CREDIT & MOTOR LEASING PTE. LTD D/Birth NA Sex NA of
5 BENOI PLACE SINGAPORE 629926 Tel No: NA
Occupation NA NRIC No NA
hereby authorize and appoint PRIME AUTO CLAIMS SERVICE PTE. LTD. to act for me/us for
the purpose of making a third party claim in respect of the abovementioned matter.

I / We further authorize the workshop to settle my/ our above mentioned claim in a manner that they
deem fit and the workshop is also authorized to receive any payment further to settlement of my
claim with payment cheque being made in favour of the workshop on my behalf.

I / We also knowledge that any settlement the workshop may reach on my/our behalf is on a "Without
Prejudice and without admission of liability" basis insofar as the driver/ owner/ insurers of the other
vehicle is concerned.

Date the 27TH day of AUGUST month of 2018.




Interpreted and witnessed by
Name:




Signature or Thumb Print
Name:



redefining / insurance

CLAIM REF : S8M00TFP
INSURED : SING LONG FOODSTUFF TRADING COMPANY PTE LTD

DISCHARGE VOUCHER

We/I SECTION CREDIT & MOTOR LEASING PTE LTD hereby agree to accept the sum of dollars Six Thousand Four Hundred Only (S\$ 6,400.00) paid to us/me by **AXA INSURANCE PTE LTD** as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said **AXA INSURANCE PTE LTD** or their Insured or the driver of motor vehicle no. YN 2488T as a result of an accident along JURONG WEST STREET 64 on 25/08/2018 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SLU 1099G.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. YN 2488T in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no YN 2488T.

Dated this 10 day of 12 2018

Claimant's Signature

L. Kiong

NRIC no./ Company Stamp

Occupation/ Business

Address

o/o 21, 6 Bras Basah, S'62789

Telephone No.

Witness's Name

Limy S. K. Chay

Witness's Signature

[Signature]

Witness's NRIC No.

S 2012 1234



TAX INVOICE

No: 2477

**Prime Auto Claims Service Pte Ltd**

6 Benoi Place Singapore 629927

Tel: 6861 0908 Fax: 6515 2948

GST Reg. No: 201606560M

Reg No. 201606560M

MESSRS

AXA Insurance (S) Pte Ltd

8 Shenton Way
 #24-01 AXA Tower
 Singapore 058811

10/9/2018

Date: _____

Works Order No: 2420

Vehicle No: SLU1099G

ITEM	DESCRIPTION	UNIT PRICE	AMOUNT
	Make/Model : Toyota Axio Repair Date : 25/8/2018 Terms of Payment: COD		
	<u>Third Party Claims</u>		
	<u>To Supply</u>		
1.	1 pc rear bumper		\$ 700.00
2.	1 set rear bumper clip		\$ 30.00
3.	1 pc rear bumper right side retainer		\$ 60.00
4.	1 pc right taillamp		\$ 450.00
5.	1 pc rear boot lid		\$ 680.00
6.	1 pc rear boot lid "corolla" emblem		\$ 59.60
7.	1 pc rear boot lid "Hybrid Synergy Drive" emblem		\$ 61.70
8.	1 pc rear boot lid "Axio" emblem		\$ 48.60
9.	1 pc rear boot lid weatherstrip		\$ 120.00
10.	2 pcs rear boot lid hinges	\$ 157.60	\$ 315.20
11.	1 pc rear boot lid trim cover		\$ 220.00
12.	1 pc rear boot lid lock		\$ 90.00
13.	1 pc rear boot lid catch		\$ 50.00
14.	1 pc rear boot lid chrome garnish		\$ 295.16
15.	1 pc rear end panel		\$ 380.00
16.	1 pc rear end panel top garnish		\$ 180.00
17.	1 set rear end panel top garnish clip		\$ 20.00
18.	1 pc package tray trim pad		\$ 26.00
19.	1 pc left rear luggage compartment cover		\$ 316.00
	Sub Total Parts:		\$ 4,102.26
	Less: 25% discount		(\$ 1,025.57)
			\$ 3,076.69

* Compound interests at the rate of 1% per month
 will be charged on late payment.

SUB TOTAL

GST 7%

TOTAL

Prepared by

Prime Auto Claims Service Pte Ltd
 Manager

TAX INVOICE

No: 2478



PRIME GROUP

Prime Auto Claims Service Pte Ltd

6 Benoi Place Singapore 629927

Tel: 6861 0908 Fax: 6515 2948

GST Reg. No: 201606560M

Reg No. 201606560M

MESSRS

AXA Insurance (S) Pte Ltd

8 Shenton Way
 #24-01 AXA Tower
 Singapore 068811

10/9/2018

Date: _____

Works Order No: 2420

Vehicle No: SLU1099G

ITEM	DESCRIPTION	UNIT PRICE	AMOUNT
	Make/Model : Toyota Axio Repair Date : 25/8/2018 Terms of Payment : COD		
	<u>Third Party Claims</u>		
	<u>To Supply S.Nett Parts</u>		
1.	1 set reverse sensor		\$ 180.00
2.	1 pc reverse camera		\$ 120.00
	Sub Total S.Nett Parts:		\$ 300.00
	<u>Labour Charges</u>		
1.	Towing charges (use king trolley).		\$ 85.00
2.	To transfer rear boot lid trim board, mechanism parts.		\$ 50.00
3.	To tuff kote rear portion.		\$ 80.00
4.	To remove & replace reverse sensor & reverse camera.		\$ 60.00
5.	To remove rear bumper, cut/welding rear end panel, floor panel, right & left taillamp. Replace the above parts. Adjust & align rear boot lid, rear bumper & etc		\$ 800.00
6.	To putty, respray painting rear boot lid inner & outer, rear bumper, rear end panel & floor panel. To polish.		\$ 900.00
	Sub Total L/Charges:		\$ 1,975.00

* Compound interests at the rate of 1% per month
 will be charged on late payment.

SUB TOTAL	\$ 5,351.69
GST 7%	\$ 374.62
TOTAL	\$ 5,726.31

Prepared by

 Prime Auto Claims Service Pte Ltd
 Manager



COMFORT LIMOUSINE SERVICES PTE LTD

Member of Prime Group of Companies
Co. Registration No: 201508380W
6 Benoi Place Singapore 629927
Tel: 6862 8878 Fax: 6863 6566

PRIME WEST

GRAB Exclusive Fleet Partner

RENTAL AGREEMENT

REF :

3249

VEHICLE NO SLU1099G	MAKE/MODEL TOYOTA COROLLA AXIO HYBRID	CC 1.5	CHECK OUT/ IN		
			VEHICLE DATE OUT	27-Feb-18	
HIRER'S DETAILS HIRER NAME : YEO KIM SHEIN ADDRESS : BLK 124 KIM TIAN PLACE #05-195 S(160124) EMAIL :			VEHICLE ACTUAL DATE IN		
			AGREED DATE OF RETURN	27-Aug-18	
			COLLISION DAMAGE WAIVER (CDW)		
			NOTE: FURTHER EXCESS OF S\$2,140.00 SHALL APPLY IN ADDITION TO THE AMOUNT STATED IN THIS RENTAL AGREEMENT WHEN AT THE TIME OF AN ACCIDENT THE MOTOR VEHICLE IS DRIVEN BY I) ANY PERSON (WHETHER NAMED / UNNAMED) WHO IS BELOW 30 YEARS OF AGE OR MORE THAN 65 YEARS OF AGE. II) HELD A DRIVING LICENCE FOR LESS THAN 3 YEARS.		
HOME NO.		D.O.B.	31-Dec-54	NON-WAIVERABLE EXCESS PER INCIDENT	
MOBILE	91668265			SINGAPORE	\$2,675.00
IC NO.	S2004616C	COUNTRY	Singapore	MALAYSIA (JOHOR ONLY)	\$3,745.00
LICENSE NO.	S2004616C	COUNTRY	Singapore	TOTAL LOSS	\$10,700.00
EXPIRY DATE				*VEHICLE OUT OF JOHOR AREA WILL NOT BE COVERED. ALL LOSS & EXPENSES WILL BE AT HIRER EXPENSE.	
ADDITIONAL DRIVER NAME : ADDRESS : S() EMAIL :			SIGNATURE		
			PERSONAL ACCIDENT INSURANCE (PAI)		
			ACCEPTS PAI []	DECLINES PAI [x]	
			PREMIUM: \$		
HOME NO.		D.O.B.		SIGNATURE	SIGNATURE
MOBILE				MAINTENANCE CHARGES	
IC NO.		COUNTRY	Singapore	DAILY @ S\$	S\$79.80 X NO. OF DAYS A MONTH
LICENSE NO.		COUNTRY	Singapore	MONTHLY @ S\$	
EXPIRY DATE				PETROL	
REMARKS			WINDSCREEN	S\$0.20 X NO. OF DAYS A MONTH	
			GST @ 7%		
			TOTAL		
			DEPOSIT	S\$2500	
REFUND COLLECTED BY :			PRE-PAYMENT	S\$1000	
			MODE OF PAYMENT		
SIGNATURE			CREDIT CARD []	CASH []	NETS []
AMOUNT COLLECTED : S\$			OTHERS []		
PREPARED BY			NAME		
ATTENDED BY NICOLE			CARD NUMBER		
			EXPIRY DATE		
			CVV		

I HEREBY AGREE TO ABIDE BY THE TERMS AND CONDITIONS STATED ON THIS AGREEMENT AND THE ACCOMPANYING CONTRACT OF EMPLOYMENT

FULL LIABILITY WILL BE IMPOSED ON THE HIRER SHOULD THE VEHICLE BE DRIVEN BY ANY OTHER PERSONS WITHOUT OUR KNOWLEDGE. VEHICLE MUST NOT BE USED FOR ANY ILLEGAL OR IMMORAL ACTIVITIES.

SIGNATURE OF HIRER

COMFORT LIMOUSINE SERVICES PTE LTD



Note: Duration minimum completion of three (03) months.

Refund of deposit will be approximately after 4 weeks upon vehicle return.



**COMFORT LIMOUSINE SERVICES PTE LTD
PRIME TRANSPORT & LIMOUSINE SERVICES PTE LTD
BEST MOTOR LEASING & LIMOUSINE SERVICES PTE LTD**

Member of Prime Group of Companies
6 Benoi Place Singapore 629926
Tel: 6862 8878 Fax: 6863 6566
Co. Registration No: 201508380W
201544118N 201512366W

Your Ref : Please advise

Date : 25-August-2018

To : Whom it May Concern

From : Section Credit & Motor Leasing Pte Ltd


RE : LETTER OF CERTIFICATION FOR MR. YEO KIM SHEIN

This letter serves to confirm that Mr. Yeo Kim Shein of NRIC number S2004616C is a Chauffeur-driven hirer for Section Credit & Motor Leasing Pte Ltd hiring Vehicle Registration Number SLU1099G at a daily rate of Singapore Dollars Seventy-Nine and Cents Eighty (S\$79.80) only.

Should clarification require I can be contacted at 8121 6313.

Thank you with Best Regards.

Yours Sincerely

F.  

.....
Ms Veronica Lim
Deputy Manager

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-130951

Date of Request: 27/08/2018

Your Ref No: Online Purchase

Prime Auto Claims Service Pte Ltd
6 Benoi Place
Singapore 629927

Dear Sir/Madam,

Enquiry Date 27/08/2018
Enquiry By Liu Pei Yee
Vehicle No. YN2488T
Accident Date 26/08/2018

Enquiry Result

IP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
YN2488T	AXA Insurance Pte Ltd	22/08/2018-21/08/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735**TAX INVOICE**

Our Ref No: GR-18-130951

Date of Request: 27/08/2018

Your Ref No: Online Purchase

Prime Auto Claims Service Pte Ltd
6 Benoi Place
Singapore 629927

Dear Sir/Madam,

Enquiry Date 27/08/2018

Enquiry By Liu Pei Yee

Vehicle No. YN2488T

Accident Date 26/08/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	YN 2488T (Insd veh)	Model:	TOYOTA COROLLA AXIO
	SLU 1099G (TP veh)		1.5
Date of Accident:	25/08/2018		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	8,739.41
Final Repair Cost	:	\$	5,726.31
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	718.20 9 days
LTA / GIA Search Fee	:	\$	0.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum (Global Sum)	:	\$	6,400.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability 100 (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	PRIME AUTO CLAIMS SERVICE PTE LTD	:	\$ 6,400.00

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

26/12/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18015642/R1wb3q2

8 SHENTON WAY #24-01

AXA TOWERSINGAPORE 068811

Date : 26-12-2018



ATTN: CYNTHIA LOH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 2488T	Veh. Inspected	SLU 1099G
Policy No.	P1819227	Coverage (\$)	0.00
Claim No.	S8M00TFP	Excess (\$)	0.00
Assign From		Assign Date	28/08/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA AXIO 1.5	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	NKE1657143163	Colour	BLACK
Odometer	59139	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65 R15	WEST LAKE	6 mm
L/H Front Tyre	175/65 R15	WEST LAKE	6 mm
R/H Rear Tyre	175/65 R15	WEST LAKE	6 mm
L/H Rear Tyre	175/65 R15	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	25/08/2018	Inspection Date	28/08/2018
Survey held at	PRIME AUTO CLAIMS SERVICE PTE LTD 6 BENOI PLACE SINGAPORE 629927		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 1099G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	DEFORMED	700.00	700.00
1	SET REAR BUMPER CLIP (CONSISTENT)	NECESSARY	30.00	30.00
1	REAR BUMPER RIGHT SIDE RETAINER (CONSISTENT)	NECESSARY	60.00	60.00
1	LEFT TAIL LAMP LOWER BRACKET (CONSISTENT)	SERVICEABLE	70.00	-
1	LEFT TAIL LAMP (CONSISTENT)	SERVICEABLE	450.00	-
1	LEFT TAIL LAMP LOWER BRACKET (CONSISTENT)	SERVICEABLE	70.00	-
1	RIGHT TAIL LAMP (CONSISTENT)	SCRATCHED	450.00	450.00
1	RIGHT TAIL LAMP LOWER BRACKET (CONSISTENT)	SERVICEABLE	70.00	-
1	REAR BOOT LID (CONSISTENT)	BENT	680.00	680.00
1	REAR BOOT LID 'COROLLA' EMBLEM (CONSISTENT)	NECESSARY	59.60	59.60
1	REAR BOOT LID 'HYBRID SYNERGY DRIVE' EMBLEM (CONSISTENT)	NECESSARY	61.70	61.70
1	REAR BOOT LID 'AXIO' EMBLEM (CONSISTENT)	NECESSARY	48.60	48.60
1	REAR BOOT LID WEATHERSTRIP (CONSISTENT)	NECESSARY	120.00	120.00
2	REAR BOOT LID HINGES @\$157.60 (CONSISTENT)	BENT	315.20	315.20
1	REAR BOOT LID TRIM COVER (CONSISTENT)	DEFORMED	220.00	220.00
1	REAR BOOT LID LOCK (CONSISTENT)	BENT	90.00	90.00
1	REAR BOOT LID CATCH (CONSISTENT)	BENT	50.00	50.00
1	REAR BOOT LID CHROME GARNISH (CONSISTENT)	CRACKED	295.16	295.16
2	REAR BOOT NO PLATE LAMP @\$61.10 (CONSISTENT)	SERVICEABLE	122.20	-
1	REAR END PANEL (CONSISTENT)	BENT	380.00	380.00
1	REAR END PANEL TOP GARNISH (CONSISTENT)	DEFORMED	180.00	180.00
1	SET REAR END PANEL TOP GARNISH CLIP (CONSISTENT)	NECESSARY	20.00	20.00
1	REAR FLOOR PANEL (CONSISTENT)	SERVICEABLE	1,187.00	-
1	LEFT DECK FLOOR BOX 64997-13051 (CONSISTENT)	SERVICEABLE	518.10	-
1	PACKAGE TRAY TRIM ,PANEL ASSY 64330-12A30 (CONSISTENT)	SERVICEABLE	614.00	-
1	PACKAGE TRAY TRIM PAD 64334-12380 (CONSISTENT)	NECESSARY	26.00	26.00
1	LEFT REAR LUGGAGE COMPARTMENT COVER 64713-12011 (CONSISTENT)	DEFORMED	316.00	316.00

Report Ref No. CC4/ASM18015642/R1wb3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-1,800.89	-1,025.57
			5,402.67	3,076.69
	<u>SPECIAL NETT ITEMS</u>			
1	SET REVERSE SENSOR (SN) (CONSISTENT)	NOT WORKING	180.00	180.00
1	REVERSE CAMERA (SN) (CONSISTENT)	NECESSARY	120.00	120.00
			300.00	300.00
	<u>LABOUR</u>			
	TOWING CHARGES (USE KING TROLLEY) .		85.00	85.00
	TO TRANSFER REAR BOOT LID TRIM BOARD .MECHANISM PARTS.		50.00	50.00
	TO TUFF KOTE REAR PORTION .		150.00	80.00
	TO REMOVE & REPLACE REVERSE SENSOR & REVERSE CAMERA.		80.00	60.00
	TO REMOVE REAR BUMPER ,CUT/WELDING REAR END PANEL ,FLOOR PANEL ,RIGHT & LEFT TAIL LAMP .REPLACE THE ABOVE PARTS.AJUST & ALIGN REAR BOOT LID ,REAR BUMPER & ETC.		1,000.00	800.00
	TO PUTTY,RESPRAY PAINTING REAR BOOT LID INNER & OUTER ,REAR BUMPER,REAR END PANEL & FLOOR PANEL .TO POLISH.		1,100.00	900.00
			2,465.00	1,975.00
GRAND TOTAL			8,167.67	5,351.69
RECOMMENDED COST OF REPAIRS				5,351.69

Report Ref No. CC4/ASM18015642/R1wb3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

58H400TTP

Reference

CC4/ASM18015642/RI1wb0a2

Loss Date

25 August 2018

Request Date

27 August 2018

Due Date

Vendor Name

LKX AUTO CONSULTANTS PTE LTD (TPP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

SLU1099G

Make

TMVD TOYOTA

Model

COROLLA-1.5 G AXIO HYBRID (A)

Service Address

...

Primary Contact/Insured

SING LONG FOODSTUFF TRADING COMPANY PTE LTD

12 WOODLANDS LINK, 738740, Singapore

62845254

FOCHIANG@YAHOO.COM

Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

Actions

Next Step

Wait for Approve Invoice

Auto Invoice

Additional Instructions

NON-REPORTED

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

Upload Documents

NAME

TYPE

SUB-TYPE

AUTHOR

DATE UPLOADED

Accident Statement

Reports & Statement

Meritmen

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1 (1).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2018
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2018
 payment breakdown.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2018
 LCD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2018
 LKKinspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2018
 LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2018
 GIA-SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2018
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2018
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2018
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2018
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	28 December 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 MARKED ESTIMATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 November 2018
 LOC.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 November 2018
 PIR.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 November 2018
 Immediate Advice-SU 1099G.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 November 2018
 LKK Inspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 November 2018
 LKK Reinspection Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 November 2018
 Letter of Authorization.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 November 2018
 OLD DL.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 November 2018
 LKK to Stacey.tif	Letters and Correspondence	Investigator / Adjustor	LOH Cynthia	23 November 2018
 UNV BRT.pdf	Reports & Statement	Investigator / Adjustor Report	KUMAR Shalendra	9 November 2018
 To LKK.mng	Letters and Correspondence	Investigator / Adjustor	LOH Cynthia	30 October 2018
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	30 August 2018

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 Non reporting letter.pdf	Letters and Correspondence	Policy Holders / Insured	LAK AUTO CONSULTANTS PTE LTD (TP)	29 August 2018
 P1819227_3fs_00003_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	LOH Cynthia	29 August 2018
 P1819227_CI_00003_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	LOH Cynthia	29 August 2018
 EMAIL RECEIVED FROM WORKSHOP WITH TP GIA REPORT.jpg	Letters and Correspondence	Workshop	RATAN BHOSALE Pragati	27 August 2018