

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 250D

AAD1808-180

Mazda
Not Withheld
Presumy B4 point \$7401

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 250D

VF1ABL15AUC282164

RENAULT

LATITUDE

17.8.2018

AIG**PART****LIST**

1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13	<i>X</i>
1	FENDER PANEL INNER TRIM REAR	\$	<i>Sn</i> 671.45	<i>X</i>
1	WHEELARCH REAR RH	\$	<i>Sn</i> 543.47	
1	ROCKER PANEL INNER GARNISH RH	\$	<i>Sn</i> 466.51	
1	ROCKER PANEL INNER RH	\$	<i>R</i> 1,024.79	
1	ROCKER PANEL CENTER RH	\$	<i>Sn</i> 990.25	
1	BUMPER COVER REAR	\$	<i>R</i> 1,108.46	
1	BUMPER LOWER REAR	\$	<i>Sn</i> 768.84	
1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	
1	BUMPER BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	<i>X</i>
1	BUMPER RETAINER RH REAR	\$	<i>Sn</i> 44.99	

\$ 9,167.33

10% **\$ 916.73**

\$ 8,250.60

Specical Nett

1SET	PARKING AID	\$	<i>Sn</i> 700.00	<i>X</i>
1SET	REAR BUMPER CLIP	\$	<i>nn</i> 66.00	
1SET	BUMPER BRACKET CTR CLIP	\$	<i>nn</i> 33.00	
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nn</i> 10.00	
1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>nn</i> 20.00	
1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	<i>nn</i> 10.00	
1SET	BUMEPR RETAINER CLIP LH RR	\$	<i>nn</i> 20.00	
1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i> 22.00	<i>X</i>
1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i> 66.00	

TOTAL \$ 947.00

Trans-cab Auto Services Pte Ltd

AAD1808-180

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 250D

TOTAL PARTS	\$	9,197.60
--------------------	-----------	-----------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	3000
Putty and spray painting of the affected portion.	\$	2,800.00	2800
To rust-proofing of the affected areas.	\$	170.00	170 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	380 X
To check steering geometry and computer wheel alignment	\$	220.00	220 X
To transfer of tire, rim and on wheel balancing.	\$	170.00	170 X
To Check Electrical Lighting Concerned.	\$	170.00	170 X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	380 X

TOTAL	\$	7,290.00
--------------	-----------	-----------------

Over All Total	\$	16,487.60
-----------------------	-----------	------------------

PART-BY-PART (REPAIR DAY)**10 DAYS****2 days****LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: