

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9838K**AAD1808-205***Not Authored*
*11 Sep 8*Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :**SHB 9838K**
VF1ABL15AUC273347
RENAULT
LATITUDE
24.8.2018
AIG

PART		LIST	
1	BUMPER COVER FRT	\$	CM 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	Sn 181.75 X
1	BUMPER ABSORBER FRT	\$	CM 394.68 ✓
1	BUMPER RETAINER FRT RH	\$	CM 150.77 ✓
1	BUMPER SUPPORT FRT	\$	Sn 123.88 X
1	BUMPER UNDERTRAY FRT	\$	Sn 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	Sn 266.80 X
1	BUMPER FOG LAMP GRILLE RH	\$	RD 207.21 ✓
1	BUMPER BEAM FRT	\$	Bt 914.08 ✓
1	HEADLAMP RH	\$	Bt 1,184.43 ✓
1	HEADLAMP PANEL FRT RH	\$	Bt 152.15 ✓
1	HEADLAMP LH	\$	Sn 1,184.43 X
1	HEADLAMP PANEL FRT LH	\$	R 152.15 X
1	FENDER PANEL FRT RH	\$	Bt 783.83 ✓
1	WHEELARCH FRT RH	\$	CM 278.84 ✓
1	FENDER BRACKET LOWER RH	\$	Sn 15.79 X
1	FENDER INSULATOR RH	\$	Sn 130.84 X
1	DOOR PANEL FRT RH	\$	R 2,844.66 X
1	RADIATOR GRILLE	\$	mz CM 1,707.78 ✓
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	R 225.36 ✓
1	RADIATOR GRILLE FRAME	\$	CM 1,353.75 ✓
1	RADIATOR FAN COWLING	\$	Sn 820.54 X
1	RADIATOR FAN MOTOR LH	\$	Sn 967.36 X
1	RADIATOR FAN MOTOR RH	\$	Sn 1,479.46 X
1	FRAME FULL SUPPORT PANEL	\$	CM 615.90 ✓
1	FRAME FULL SUPPORT BRACKET	\$	R 89.79 X
1	DOOR MIRROR ASSY RH	\$	Sn 1,483.40 X
1	DOOR PANEL FRT RH	\$	R 2,844.66 X
1	BONNET	\$	Bt 1,941.63 ✓
1	BONNET INSULATOR	\$	Sn 405.73 X

Trans-cab Auto Services Pte Ltd**AAD1808-205**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9838K

1	BONNET STRUT LH	\$	88.61	X
1	BONNET STRUT RH	\$	88.61	X
1	BONNET HINGE LH	\$	348.31	—
1	BONNET HINGE RH	\$	348.31	—
1	BONNET LOCK	\$	305.48	} X
1	BONNET CABLE	\$	119.19	
1	BONNET CABLE COVER	\$	161.03	
1	BONNET SEAL OUTER	\$	92.36	
1	BONNET SEAL INNER	\$	157.28	
1	SUBFRAME OUTER FRT	\$	2,652.45	} X
1	SUBFRAME BRACKET OUTER LH	\$	92.36	
1	SUBFRAME BRACKET OUTER RH	\$	92.36	
1	ENGINE UNDERTRAY	\$	564.98	} X
1	A/C CONDENSER	\$	2,020.37	
1	A/C CONDENSER GARNISH LH UPPER	\$	39.67	X
1	A/C CONDENSER GARNISH RH UPPER	\$	39.67	X
1	A/C CONDENSER GARNISH LH	\$	58.81	X
1	A/C CONDENSER GARNISH RH	\$	59.60	X
1	LOWER ARM RH	\$	685.76	?
1	KUNCKLE ARM RH	\$	846.98	?
1	ABSORBER FRT RH	\$	360.54	?
1	STABILIZER BAR FRT	\$	604.65	?
1	DRIVESHAFT RH	\$	1,747.45	?
1	WIPER RESERVOIR	\$	348.25	—
1	WIPER RESERVOIR NECK	\$	136.11	—
1	WIPER RESERVOIR MOTOR	\$	270.06	?

TOTAL	\$	36,963.11
10%	\$	3,696.31
	\$	33,266.80

Special Nett

1SET	BUMPER CLIP FRT	\$	66.00	—
1	BUMPER BRACKET CLIP FRT RH	\$	12.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	X
1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	X

Trans-cab Auto Services Pte Ltd**AAD1808-205**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9838K

2	FRAME FULL SUPPORT PANEL NUT	\$	na 20.00 X
2	FRAME FULL SUPPORT PANEL STUD	\$	na 30.00 X
1SET	WHEELARCH CLIP FRT RH	\$	na 30.50 ✓
6	BONNET INSULATOR CLIP L70Y	\$	na 7.30
2	BONNET STRUT L70Y	\$	na 88.61
2	BONNET CABLE CLIP L70Y	\$	na 6.31
2	BONNET CABLE COVER SCREW L70Y	\$	na 10.85
1	WINDSCREEN SEALANT	\$	na 253.80
1	FRONT WINDSCREEN MOULDING	\$	na 120.00
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na 100.00
1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	\$	na 80.00
1	FRONT RIGHT DOOR STICKER '6555-3333'	\$	na 50.00
1	FRONT RIGHT TYRE	\$	na 330.00
1	FRONT RIGHT TYRE RIM	\$	na 380.00

TOTAL	\$	1,734.88
--------------	-----------	-----------------

TOTAL PARTS	\$	35,001.68
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	4,500.00	600
----	----------	-----

Putty and spray painting of the affected portion.

\$	4,000.00	800
----	----------	-----

To rust-proofing of the affected areas.

\$	170.00	900
----	--------	-----

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	na 380.00	X
----	-----------	---

To check steering geometry and computer wheel alignment

\$	220.00	600
----	--------	-----

To transfer of tire, rim and on wheel balancing.

\$	na 170.00	X
----	-----------	---

Trans-cab Auto Services Pte Ltd**AAD1808-205**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9838K

To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	380.00	1001
To replace, refix and top up coolant for radiator	\$	170.00	501
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	501
To transfer of front windscreen fittings and conduct water seepage test	\$	nn 170.00	X

TOTAL	\$	11,090.00
--------------	-----------	------------------

Over All Total	\$	46,091.68
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)**15 DAYS****5 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: